

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 11 Jan 2019

Preliminary Advice

Vehicle No	: GX9593L	Accident Date	: 04/01/2019
Make	: KIA FRONTIER	Policy No.	: MCV18A00071400
Assignment Date	: 09/01/2019	Excess	: S\$750.00
Date of Inspection	: 11/01/2019	Est. Duration of Repair	: 6 days
Inspection At	: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,793.40
Revised Amount	:S\$	4,388.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,388.80
Lump Sum Repair		:S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	8,000.00
COE / PARF Rebate	:S\$	4,040.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,960.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER WILL REPAIR WITH THE NETT VALUE ON LUMP SUM BASIS.