



ESTIMATE

Date	: 08/01/2019	Reg No	: SKK4177J
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA PREVIA 7 SEATER CVT
Attn.	:	Chassis No	: JTEGD54M40A038821
Office / Mobile	:	Engine No	: 2AZJ003339
Email Address	:	Quotation No.	: 79587
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/01/2019
Attn.	: MELODYTEOHML	Policy No.	:
Office / Mobile	: +65 6484 3683 / 9736-1300	Claim Type	: TP CLAIM
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: KAKI BUKIT

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		FRONT BUMPER / <i>re</i>	1	609.15	-25	456.86	456.86 ✓
2		FRONT BUMPER RETAINER LH X	1	66.20	-25	49.65	49.65 X
3		FRONT BUMPER RETAINER RH / <i>re</i>	1	66.20	-25	49.65	49.65 ✓
4		FRONT BUMPER CLIPS / <i>re</i>	10	5.00	-25	3.75	37.50 ✓
5		FRONT BUMPER BRACKET LH X	1	68.20	-25	51.15	51.15 X
6		FRONT BUMPER BRACKET RH X	1	68.20	-25	51.15	51.15 X
7		FOG LIGHT ASSEMBLY RH X	1	280.15	-25	210.11	210.11 ✓
8		FRONT GRILLE WITH CHROME MOULDING X	1	454.10	-25	340.58	340.58 X
9		FRONT GRILLE LOGO X	1	75.30	-25	56.47	56.47 X
10		HEADLAMP WASHER MOTOR RH X	1	455.90	-25	341.92	341.92 X
11		HEADLAMP WASHER COVER RH X	1	45.30	-25	33.97	33.97 X
12		HEADLAMP ASSEMBLY RH / <i>Cut</i>	1	1,045.95	-25	784.46	784.46 ✓
13		FRONT SUPPORT PANEL / <i>repair</i> X	1	819.40	-25	614.55	614.55 X
14		FRONT SUPPORT TOP GARNISH CLIPS X	10	5.00	-25	3.75	37.50 X
15		FRONT FENDER RH / <i>bu</i>	1	706.10	-25	529.58	529.58 ✓
16		FRONT FENDER EMBLEM (VVT-I) RH / <i>re</i>	1	45.30	-25	33.97	33.97 ✓
17		FRONT FENDER INNER SHIELD RH / <i>re</i>	1	165.90	-25	124.43	124.43 ✓
18		FRONT FENDER INNER SHIELD CLIPS RH / <i>re</i>	10	5.00	-25	3.75	37.50 ✓
19		FRONT A-PILLAR RH ?	1	499.15	-25	374.36	374.36 ?
20		FRONT A-PILLAR INNER GARNISH RH X	1	65.10	-25	48.82	48.82 X
21		FRONT FENDER OUTER ROCKER GARNISH RH / <i>re</i> X	1	145.10	-25	108.82	108.82 X
22		WINDMIRROR ASSEMBLY RH X	1	987.15	-25	740.36	740.36 X
23		WINDMIRROR COVER RH / <i>Cut</i>	1	74.10	-25	55.57	55.57 ✓
24		FRONT DOOR RH / <i>bu</i>	1	1,049.10	-25	786.82	786.82 ✓
25		FRONT DOOR TOP HINGE RH / <i>bu</i>	1	74.10	-25	55.57	55.57 ✓
26		FRONT DOOR BOTTOM HINGE RH / <i>bu</i>	1	74.20	-25	55.65	55.65 ✓
27		FRONT DOOR LOCK RH X	1	509.10	-25	381.83	381.83 X
28		FRONT DOOR CHECKER RH / <i>AT</i>	1	120.10	-25	90.07	90.07 ✓
29		FRONT DOOR LOWER OUTER ROCKER GARNISH RH / <i>Cut</i>	1	99.10	-25	74.32	74.32 ✓
30		ROCKER PANEL RH / <i>repair</i> X	1	549.10	-25	411.83	411.83 X
31		FRONT DOOR OUTER MOULDING RH X	1	161.20	-25	120.90	120.90 X
32		FRONT DOOR WEATHERSTRIP RH ?	1	169.15	-25	126.86	126.86 ?



ESTIMATE

Date	: 08/01/2019	Reg No	: SKK4177J
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA PREVIA 7 SEATER CVT
Attn.	:	Chassis No	: JTEGD54M40A038821
Office / Mobile	:	Engine No	: 2AZJ003339
Email Address	:	Quotation No.	: 79587
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/01/2019
Attn.	: MELODYTEOHML	Policy No.	:
Office / Mobile	: +65 6484 3683	Claim Type	: TP CLAIM
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: KAKI BUKIT

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
33		FRONT DOOR FRAME STICKER RH <i>/ MC.</i>	2	76.10	-25	57.07	114.15 ✓
34		REAR DOOR RH <i>/ BT.</i>	1	1,410.35	-25	1,057.76	1,057.76 ✓
35		REAR DOOR FRAME STICKER RH <i>/ MC.</i>	2	76.10	-25	57.07	114.15 ✓
36		REAR DOOR FRONT OUTER WEATHERSTRIP RH <i>X</i>	1	269.15	-25	201.86	201.86 ✓
37		REAR DOOR LOWER OUTER ROCKER GARNISH RH <i>/ GH.</i>	1	110.25	-25	82.69	82.69 ✓
38		REAR FENDER OUTER ROCKER GARNISH RH <i>/ RL.</i>	1	124.10	-25	93.07	93.07 ✓
39		REAR FENDER INNER SHIELD RH <i>/ RL.</i>	1	165.10	-25	123.82	123.82 ✓
40		REAR FENDER INNER SHIELD CLIPS <i>/ MC.</i>	3	5.00	-25	3.75	11.25 ✓
41		REAR BUMPER <i>/ RL.</i>	1	617.15	-25	462.86	462.86 ✓
42		REAR BUMPER RETAINER LH <i>X</i>	1	110.35	-25	82.76	82.76 X
43		REAR BUMPER RETAINER RH <i>/ RL.</i>	1	65.10	-25	48.82	48.82 ✓
44		REAR BUMPER CLIPS <i>/ MC MC.</i>	10	5.00	-25	3.75	37.50 ✓
45		REAR BUMPER REFLECTOR LH <i>X</i>	1	66.20	-25	49.65	49.65 X
46		REAR BUMPER REFLECTOR RH <i>X</i>	1	66.20	-25	49.65	49.65 X
47		FRONT FENDER INNER SHIELD LH <i>/ MiS</i>	1	124.95	-25	93.71	93.71 ✓
48		FRONT FENDER INNER SHIELD CLIPS LH <i>/ MC</i>	10	5.00	-25	3.75	37.50 ✓
49		BONNET HINGE LH <i>X</i>	1	54.10	-25	40.58	40.58 X
50		BONNET HINGE RH <i>X</i>	1	54.10	-25	40.58	40.58 X
51		FRONT DRIVE SHAFT LH <i>X</i>	1	1,045.10	-25	783.82	783.82 X
52		FRONT DRIVE SHAFT RH <i>?</i>	1	1,245.35	-25	934.01	934.01 ?
53		FRONT STEERING RACK AND PINON ASSEMBLY <i>?</i>	1	5,403.10	-25	4,052.33	4,052.33 ?
54		FRONT UNDERCARRIAGE COVER CENTRE <i>/ RL</i>	1	213.10	-25	159.83	159.83 ✓
55		FRONT UNDERCARRIAGE COVER LH <i>/ STN</i>	1	145.10	-25	108.82	108.82 ✓
56		FRONT UNDERCARRIAGE COVER RH <i>/ STN</i>	1	145.10	-25	108.82	108.82 ✓
57		FRONT UNDERCARRIAGE COVER CLIPS <i>/ MC</i>	10	5.00	-25	3.75	37.50 ✓
58		FRONT SHOCK ABSORBER LH <i>X</i>	1	458.10	-25	343.58	343.58 X
59		FRONT SHOCK ABSORBER RH <i>?</i>	1	458.10	-25	343.58	343.58 ?
60		FRONT SHOCK ABSORBER TOP MOUNTING LH <i>X</i>	1	210.10	-25	157.58	157.58 X
61		FRONT SHOCK ABSORBER TOP MOUNTING RH <i>?</i>	1	210.10	-25	157.58	157.58 ?
62		FRONT WHEEL HUB LH <i>X</i>	1	435.10	-25	326.33	326.33 X
63		FRONT WHEEL HUB RH <i>?</i>	1	435.10	-25	326.33	326.33 ?



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 636894
Tel: +65 6861 0007 Fax: +65 6861 3576 (Sales)
Fax: +65 6863 0425 (Service) +65 8862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No. 1680039E3G

Page 3 / 6

ESTIMATE

Date	: 08/01/2019	Reg No	: SKK4177J
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA PREVIA 7 SEATER CVT
Attn.	:	Chassis No	: JTEGD54M40A038821
Office / Mobile	:	Engine No	: 2AZJ003339
Email Address	:	Quotation No.	: 79587
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/01/2019
Attn.	: MELODYTEOHML	Policy No.	:
Office / Mobile	: +65 6484 3683	Claim Type	: TP CLAIM
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: KAKI BUKIT

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
64		FRONT WHEEL HUB BEARING LH <i>✓ 4mm</i>	1	201.10	-25	150.83	150.83 X
65		FRONT WHEEL HUB BEARING RH	1	201.10	-25	150.83	150.83 X
66		FRONT KNUCKLE ARM LH <i>?</i>	1	545.10	-25	408.83	408.83 ?
67		FRONT KNUCKLE ARM RH <i>?</i>	1	545.10	-25	408.83	408.83 ?
68		FRONT KNUCKLE ARM BEARING LH <i>✓ 4mm</i>	1	201.10	-25	150.83	150.83 ✓
69		FRONT KNUCKLE ARM BEARING RH	1	201.10	-25	150.83	150.83 ✓
70		FRONT LOWER ARM LH <i>?</i>	1	569.10	-25	426.83	426.83 ?
71		FRONT LOWER ARM RH <i>?</i>	1	569.10	-25	426.83	426.83 ?
72		FRONT STABILIZER LINK ROD LH <i>?</i>	1	110.35	-25	82.76	82.76 ?
73		FRONT STABILIZER LINK ROD RH <i>?</i>	1	110.35	-25	82.76	82.76 ?
74		FRONT STABILIZER BAR <i>?</i>	1	458.10	-25	343.58	343.58 ?
75		FRONT SUB FRAME <i>?</i>	1	1,027.10	-25	770.32	770.32 ?
76		FRONT ENGINE TOP MOUNTING RH <i>?</i>	1	201.10	-25	150.83	150.83 ?
77		FRONT DOOR WINDOW REGULATOR RH <i>?</i>	1	269.10	-25	201.83	201.83 ?
78		FRONT DOOR WINDOW REGULATOR MOTOR RH <i>?</i>	1	509.10	-25	381.83	381.83 ?
79		FRONT DOOR INNER TRIM BOARD RH <i>?</i>	1	680.10	-25	510.08	510.08 ?
80		REAR TAILGATE INNER DAMPER LH <i>X</i>	1	299.10	-25	224.33	224.33 X
81		REAR ABSORBER LH <i>?</i>	1	145.10	-25	108.82	108.82 ?
82		REAR ABSORBER RH <i>?</i>	1	145.10	-25	108.82	108.82 ?
83		REAR AXLE BEAM <i>X</i>	1	2,017.10	-25	1,512.82	1,512.82 X
84		FRONT SPORT RIM (17") LH <i>✓ 4mm</i>	1	750.00	-25	562.50	562.50 ✓
85		FRONT SPORT RIM (17") RH <i>✓ 4mm</i>	1	750.00	-25	562.50	562.50 ✓
86		REAR SPORT RIM (17") LH <i>X</i>	1	750.00	-25	562.50	562.50 X
87		REAR SPORT RIM (17") RH <i>✓ 4mm</i>	1	750.00	-25	562.50	562.50 ✓

PARTS TOTAL :

26,858.67

7853.36

biSAFE
ST & R



Certificate No. AIA/ST/101/243

Certificate No. AIA/ST/101/243



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 8862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No. 168003963G

Page 4 / 6

ESTIMATE

Date	: 08/01/2019	Reg No	: SKK4177J
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA PREVIA 7 SEATER CVT
Attn.	:	Chassis No	: JTEGD54M40A038821
Office / Mobile	:	Engine No	: 2AZJ003339
Email Address	:	Quotation No.	: 79587
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/01/2019
Attn.	: MELODYTEOHML	Policy No.	:
Office / Mobile	: +65 6484 3683	Claim Type	: TP CLAIM
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: KAKI BUKIT

SPECIAL NETT ITEMS

1	FRONT TYRE LH (215/55 ZR17) ✓	1	230.00	140
2	FRONT TYRE RH (215/55 ZR17) ✓	1	230.00	140
3	REAR TYRE LH (215/55 ZR17) ✓	1	230.00	140
4	REAR TYRE RH (215/55 ZR17) ✓	1	230.00	140
5	COOLANT X	1	40.00	5
6	POWER STEERING FLUID ?	1	50.00	?
7	SEALANT ?	1	50.00	?
8	AUTO-TRAN FLUID ?	1	50.00	?

PARTS TOTAL: 1110.00

560

11623.56

2097 93.00

bizSAFE
STAIR



Certificate No. AJA/8181921243

Certificate No. AJA/8181921243



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co-Reg No: 158003963G

Page 5 / 6

ESTIMATE

Date	: 08/01/2019	Reg No	: SKK4177J
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA PREVIA 7 SEATER CVT
Attn.	:	Chassis No	: JTEGD54M40A038821
Office / Mobile	:	Engine No	: 2AZJ003339
Email Address	:	Quotation No.	: 79587
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/01/2019
Attn.	: MELODYTEOHML	Policy No.	:
Office / Mobile	: +65 6484 3683	Claim Type	: TP CLAIM
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: KAKI BUKIT

LABOUR CHARGES

1	TO REMOVE AND REFIT AIR-CON SYSTEM AND TOP UP AIR-CON GAS	X	150.00
2	TO REMOVE AND REFIT FRONT RH DOOR COMPONENT	60	120.00
3	TO REMOVE AND REFIT REAR RH DOOR COMPONENT	60	120.00
4	TO REMOVE AND REFIT REAR TAILGATE LH DAMPER	X	50.00
5	TO REMOVE AND REFIT FRONT RH SUSPENSION SYSTEM	100	180.00
6	TO REMOVE AND REFIT FRONT LH SUSPENSION SYSTEM	100	180.00
7	TO REMOVE AND REFIT FRONT SUB FRAME	?	250.00
8	TO REMOVE AND REFIT REAR LH SUSPENSION SYSTEM	100	180.00
9	TO REMOVE AND REFIT REAR RH SUSPENSION SYSTEM	100	180.00
10	TO REMOVE AND REFIT REAR AXLE BEAM ASSEMBLY	?	250.00
11	TO REMOVE AND REFIT FRONT FLOOR CARPET AND SEATS TO ASSIST REPAIR	60	100.00
12	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS TO ASSIST REPAIR OF A-PILLAR	?	180.00
13	TO REMOVE AND REFIT FRONT LH TYRE FOR BALANCING	10	20.00
14	TO REMOVE AND REFIT FRONT RH TYRE FOR BALANCING	10	20.00
15	TO REMOVE AND REFIT REAR LH TYRE FOR BALANCING	10	20.00
16	TO REMOVE AND REFIT REAR RH TYRE FOR BALANCING	10	20.00
17	TO SPRAY PAINT ON AFFECTED AREAS	1500	3000.00
18	TO STRAIGHTEN AND PANEL BEAT	1000	3000.00
19	TO CHECK WIRING SYSTEM	30	80.00
20	TO CONDUCT FULL WHEEL ALIGNMENT	60	150.00



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No. 168003963G

Page 6 / 6

ESTIMATE

Date :	08/01/2019	Reg No :	SKK4177J
To :	AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model :	TOYOTA PREVIA 7 SEATER CVT
Attn. :		Chassis No :	JTEGD54M40A038821
Office / Mobile :		Engine No :	2AZJ003339
Email Address :		Quotation No. :	79587
		Ref. No. :	
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	04/01/2019
Attn. :	MELODYTEOHML	Policy No. :	
Office / Mobile :	+65 6484 3683	Claim Type :	TP CLAIM
Email / Fax No. :	MelodyTeohML@goldbell.com.sg	Workshop :	KAKI BUKIT

LABOUR CHARGES

21	SUNDRIES
22	RUST PROOFING

3270

NN x 60

20.00
100.00

LABOUR TOTAL :	8,370.00
SUB-TOTAL :	36,338.67
GST @ 7% for \$ 36,338.67	2,543.71
GRAND TOTAL (S\$) :	38,882.38

PREPARED BY : MELODYTEOHML

DATE / TIME : 10/1/2019

SURVEYOR : Quo Qian.

MOBILE NO : 8288 0282

OFFICE FAX NO :

EMAIL ADDRESS :

EXCESS AMOUNT :

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 9

REMARKS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

biSAFE
ST & R

AIA

SAC

AIA

UKA

UKA

UKA