

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0021184
Teo Seng Chee

Page: 1 of 1
Your ref.: TP-SHD 4373G India
Job No.: 70139
Our ref.: 19.01.07
Payment
Date: 9/1/2019

Attn

Vehicle No: SDP 2177D
Vehicle Model : Subaru Forester
Accident on ...: 5/1/2019

Not Authorized
Mummy Bepain
Direct settle 4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Front door LH	864.00		<i>Bt</i> 864.00 ✓
1.00	Pc	Front door lower protector LH	216.00		<i>Net</i> 216.00 ✓
1.00	Pc	Front door frame tape LH - 1	20.03		<i>Net</i> 20.03 ✓
1.00	Pc	Front door frame tape LH - 2	20.03		<i>Net</i> 20.03 ✓
1.00	Pc	Rear door lower protector LH	192.00	<i>cm / Sur</i>	192.00 ✓
Labour & Misc:					
1.00		To check/erase fault codes	50.00		50.00 ✓
1.00		To knock dents on rear fender LH + rear door LH and renew of parts	400.00		400.00 <i>360</i>
1.00		To spray paint (Pearl white / including blending front fender LH)	1,000.00		1,000.00 <i>800</i>

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

2,762.06
193.34
S\$ 2,955.40

Acknowledged by Repairer
Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的 ~~零件~~ 及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."