

22/03/2002

ASS. REC. BY:

REF:

CS/FCL19000512/KHbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): CWS Jeanne Yong of FCL Date/Time: 09012019 953am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHC 5190R Insured: SHD 3627Gat Workshop m/s Trans - Cab Tel: _____of No. 2 AMK St 63Policy No: _____ Claim No: D19000240MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 02012019
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' H.O.D. Endorsement: _____

Date/Time: 09012019 254pm Person Contacted: ZheWei Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 5190R - CS / TML150011510 / KHbn2 DA: 09032018
	SHD 3627G - CS / FCL15011417 / KHbn2 DA: 09052019
10/1@3:00pm	revised preli advise

ASS. REC. BY:

REF:

FC21

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SITC 5190R

Yr Regn:

01, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c.

1885

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

484284

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 276727

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M/S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

R/Bal.

6

mm

Rear

R/Bal.

2

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

2/1/19

D.O.I.

9/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/1

File pass to Car

11/1/19 @ 12501 (Red: 25328.50, 95%)

RECEIVED 10 JAN 2019

Date/Time, File Pass to?

10/1 Typist

Date/Time, File Return to?

7



: Prel. Report



: Final Report

Days Of Repair:

2

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

12501

350

TOTAL



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000240MFSH

Date: 10/01/2018

Our Ref: CS/FCI19000512/Ktb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5190R

Please be informed that we had conducted the inspection of the abovementioned vehicle
09/01/2019 at the premises of M/s Trans-Cab have the following to report: -

Workshop Estimate Amount	: S\$ 26,578.50
Revised Estimate Amount	: S\$ 1,250.00
"Check" Items Amount	: S\$ 0.00
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the n/s
Rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	08-01-2019	Our Ref No. D19000240MFSH
Accident Date	02-01-2019	Claim Type. Third Party
Insured Vehicle	SHD3627G	Third Party Vehicle. SHC5190R
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 10 January 2019 3:09 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000240MFSH/1
Attachments: PRELI ADVISED SHC 5190R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 5190R**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 9 January 2019 2:56 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000240MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 9 January, 2019 9:53 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000240MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5190R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Jan 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000803
Chassis No.:	VF1ABL15AUC276727
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	24 Jan 2014
First Registration Date:	24 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jan 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,888.00
COE Rebate Amount:	\$23,242.00
Total Rebate Amount:	\$32,615.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Jan 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHC 5190R**AAD1901-024**

Not Authorised
6/1/2019 @ 1250h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHC 5190R

VF1ABL15AUC276727

RENAULT

LATITUDE

2.1.2019

FCIL

24/1/2014

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>CM</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>SL</i> 768.84	} X
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	
5	1 BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99	
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	
8	1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	
10	1 BUMPER BEAM REAR	\$	<i>N</i> 777.52	
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95	
13	1 OUTER PANEL REAR (End Panel)	\$	<i>N</i> 1,471.77	}
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i> 404.56	
15	1 TAILLAMP LH	\$	<i>SL</i> 552.55	
16	1 TAILLAMP PANEL LH	\$	<i>N</i> 986.70	
17	1 BOOT REAR	\$	<i>N</i> 2,872.68	

\$ **9,957.60**10% \$ **995.76**\$ **8,961.84****Special Nett**

1	1SET PARKING AID	\$	<i>SL</i> 700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>N</i> 66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>N</i> 33.00	✓

Trans-cab Auto Services Pte Ltd**AAD1901-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5190R

4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	}
5 1SET BUMPER RETAINER RH CLIP RR	\$	20.00	
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	
7 1SET BUMPER RETAINER CLIP LH RR	\$	20.00	
8 1SET BUMPER LOWER REAR RIVET	\$	22.00	
9 1SET BUMPER LOWER REAR CLIP	\$	66.00	
10 1 EXHAUST MOUNTING REAR	\$	17.82	
11 2 REAR WINDSCREEN SELANT	\$	80.00	}
12 1 WINDSCREEN MOULDING	\$	100.00	
13 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	

TOTAL \$ 1,244.82**TOTAL PARTS \$ 10,206.66****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1901-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5190R

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 *X*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 *X***TOTAL \$ 7,410.00****Over All Total \$ 26,578.50****(LUMP SUM)****Repair Days****10-DAYS***2 days**17616.65*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000512/Ktbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3627G	Veh. Inspected	SHC 5190R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000240MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	09/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC276727	Colour	METALLIC WHITE / RED	
Odometer	494284	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	6 mm	
L/H Front Tyre	215/60 R16	GITI	6 mm	
R/H Rear Tyre	215/60 R16	GITI	7 mm	
L/H Rear Tyre	215/60 R16	GITI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/01/2019	Inspection Date	09/01/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5190R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR	CRACKED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
	LESS 10% DISCOUNT		-995.76	-110.85
			8,961.83	997.61
SPECIAL NETT ITEMS				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-

Report Ref No. CS/FCI19000512/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			1,244.82	99.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	220.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR,BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,OUTER PANEL REAR (END PANEL),TAILLAMP PANEL LH AND BOOT REAR.		3,000.00	200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,410.00	480.00
GRAND TOTAL			17,616.65	1,576.61
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CS/FCI19000512/Ktbn2



Report Ref No. CS/FCI19000512/Ktbn2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.