

INSURER

INS. CASE OWNER

CC 4/III1900 0513, R296X/0

LKK

IDAC

Surveyor: Rasul

DOI: 11/1/19

Date / Time: 8/1/19

Registered in Merimen: 11/1/19

Pre-assign / CCU / FTE

SHC 3255B



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner? (YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

Insured Liability:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

Insured Liability:

SLV 5251B



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

16/1/19
my

SLV 5251B-X

SHC 3255B-X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS

77003.90

(5

days) Reduction:

83616.14

% 51

Confirm by:

Rasul

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

SS

3749.17

(Agreed / Assessed)

BOLA S/N No.:

72

If NO or B 28, Ass. Lia:

01 VEHICLE WA TPV

Repair Cost:

SS

529.20

(4

days) x

449.80

Loss of Rental (LOR):

SS

529.20

(5

x

days)

Loss of Use (LOU):

SS

529.20

(5

x

days)

Loss of Income (LOI):

SS

529.20

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GL/ATA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$500/-

Total:

SS

4348.37

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4348.37

Name 1:

Tan Chang Motor Sales Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Date / Time	Action / Instruction
-------------	----------------------

Veh No: **SW 5251B** Yr Regn: **2017** / **DE**
 Type: **C** M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make **NISSAN X-TRAIL 2.0** C.O. **1997**
 Colour **Grey** A/C Insured / Std / NI / NA
 Sp Reading **12585** T/Radio: Insured / Std / NI / NA

CINo: JN1JHNT3220010464

Gen. Cond: Good / Fair / Poor / Burnt

Steering: in order / Jammed / Leaked / Burnt or

Brake: Morder / Jammed / Leaked / Burnt or

Modl: NII / 2/Rim / STD A/Rim of

Tyre Size: F: 225/55R19
R: 225/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	14/12/18	D.O.A.	11/01/19
Survey held at		TANC HOUSE	

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

01/ EN

The U/C / Chassis frame / Body Structure affected due to collision

N/S	O/S

Date/Time: File Pass to?

□: Prel. Report

133

☐ : Final Report

Date/Time, File Return to?

5

Report Format :

Lump Sum / I.B.I.: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee: Site Insp (\$

Site Insp	\$
-----------	----

☐ Interview 15

☐ Total Inv: \$

☐ Week-end (S)

Survey Fee

F. J. Beckwith et al.

$$1) \quad 2 + 10 = 12$$

1. Introduction

3. Culture's

TENTAE

--



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC4/III19000513/R1jb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 09-01-2019	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3255B		Veh. Inspected	SLV 5251B
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	09/01/2019
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size		Make	Balance
R/H Front Tyre				mm
L/H Front Tyre				mm
R/H Rear Tyre				mm
L/H Rear Tyre				mm
4. Description of Damages				
5. General Information				
Accident Date	14/12/2018		Inspection Date	11/01/2019
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911 BUKIT TIMAH ROAD SINGAPORE 589623			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Ceciliah

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589622

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0578/2018
DATE : 17-DEC-2018

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MISS TAN YA LI
ADDRESS : 937 BUKIT TIMAH ROAD
#03-35
S(589646)
TELEPHONE NO : 96773911

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHC3255B
VEHICLE NO : SLV5251B
MODEL CODE : JDRHRRST32EMAF---A
MODEL/YEAR : NISSAN X-TRAIL FACELIFT MY2017
ENGINE NO : MR20146612C
CHASSIS NO : JN1JANT32H0010464
MILEAGE : 1 KM
DATE IN : 17/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 14/12/2018

20/08/19

PAID

0/5

PAID

\$140 X 04

= \$560 tax

= \$599.20

TAN CHONG MOTOR SALES PTE. LTD.
 SUKUT TIMAN W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV5251B

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	240.00 ✓
2 RRSCM	REMOVE/REFIX SUSPENSION CROSS MEMBER	120.00	.00
3 RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE RH FRONT	480.00	.00
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	.00
5 WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	103.00 ✓
6 IZ/001	REPAIR AND RENEW RH FRONT FENDER, RH FRONT DOOR	1200.00	780.00 ✓
7 IZ/002	S/PAINT RH FRONT FENDER, RH FRONT DOOR	750.00	500.00 ✓
8 IZ/003	RENEW RH FRONT S/RIM AND CONDUCT WHEEL BALANCING RH FRONT	15.00	15.00 ✓
9 IZ/004	RENEW RH FRONT TYRE 225/55R19 B/S H/L422		
	TOTAL LABOUR CHARGES	3208.00	1638.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5251B

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 225/55R19HL422PLUS R/S TYRE RH FRONT	225/55R19HL422			400.00	X
2 SUNDRIES	NPH			100.00	X
3 MOULDING RH FRONT DOOR	80282-4CA0A	100.70			X
4 MLDG ASSY-FR DOOR RH	80820-4CLOA	157.00			X
5 TAPE-FR DOOR,RH	80818-4CA0B	18.00			X
6 DOOR-FRONT RH	H010M-4CBMA	1032.90			X
7 GROMMET \$2.50 EA 02	76848-JG00A	5.00			OK /
8 CLIP ARC \$2.50 EA X 03	01553-10641	7.50			OK /
9 CLIP ARC \$2.50 EA X 02	76847-JG00A	5.00			OK /
10 CLIP ARC \$2.50 EA X 04	63848-35P00	10.00			OK /
11 CLIP ARC \$3.00 EA X 02	76882-JG10A	6.00			OK /
12 GROMMET FENDER \$4.50 EA X 06	76881-JG00A	27.00			OK /
13 MOULDING ASSY-FRONT ARC RH	63840-4CE1A	170.00			OK /
14 MOUL-FR DOOR,RH	80876-6FR0A	183.90			X
15 FENDER-FRONT RH	F3100-4C0MA	583.40			X
16 ORNAMENT-ROAD	40342-BR02A			32.90	X
17 WHEEL-ROAD AL RH FRONT	D0300-4CB3A			1681.50	OK /
18 INSULATOR-STRUT	54320-4CLOB	96.30			X
19 STOPPER ASSY	54325-00Q0B			74.20	X
20 BUMPER ASSY-BOU	54050-4CLOB			38.20	X
21 SPACER	54034-4BADA			17.60	X
22 SEAT SUSPENSION LOWER	54035-4BAGA	23.30			X
23 STRUT KIT-FRONT	E4302-4CE1C			365.00	X
24 MEMBER COMPL	54400-4CB1C			488.60	X
25 STAY ASSY-FRONT	544C4-EH10B			60.40	X

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5251B

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
26 ROD-STABILIZER	54618-1AA0E	32.30			X
27 LINK COMPL,RH	54500-4CA0A	224.50			X
28 SPDL-KNUCKLE,RH	40014-4CE0A			481.80	X
29 HUB ASSY-ROAD W	40202-4BA0A			272.20	X
30 SHAFT ASSY-FRONT RH	39100-4BB1B			966.20	X
SUB TOTAL		230.50	0.00	1681.50	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-1.00%)		46.10	0.00	0.00	
GRAND TOTAL		184.40	0.00	1681.50	
OVERALL TOTAL		1865.90			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
 Signature:
 Date:

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLV5251B

NETT ITEM	230.50
LESS 20.00%	-46.10
NETT AMOUNT	184.40
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	1681.50
LESS .00%	0.00
SPECIAL NETT AMOUNT	1681.50
TOTAL LABOUR CHARGES	1638.00
TOTAL SPARE PARTS CHARGES	1865.90
TOTAL CHARGES	3503.90
ADD 7 % GST	245.27
GRAND TOTAL	3749.17

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 599421

ESTIMATE : ACCIDENT/ROD REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0578/2018
DATE : 17-DEC-2018

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MISS TAN YA LI
ADDRESS : 937 BUKIT TIMAH ROAD
#03-35
S(589444)
TELEPHONE NO : 96773911

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHC32552
VEHICLE NO : SLV82518
MODEL CODE : J00NRRT32ENAF---A
MODEL/YEAR : NISSAN X-TRAIL FACELIFT MY2017
ENGINE NO : HR20146612C
CHASSIS NO : JN1JANT32E0010464
MILEAGE : 1 KM
DATE IN : 17/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 14/12/2018

10146
18/12/18
DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT ~~WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

1 LKK

APR
11/01/19
122
11/01/19

TAN CHONG MOTOR SALES PTE. LTD.
 SUKUT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV52518

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RP1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	/
2 XASCH	REMOVE/REFIX SUSPENSION CROSS MEMBER	120.00	?X117
3 XAUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE RH FRONT	480.00	?X117
4 SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 01	300.00	X117
5 WD42	CHECK WHEEL ALIGNMENT. ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	/
6 11/001	REPAIR AND RENEW RH FRONT FENDER, RH FRONT DOOR	1200.00	780
7 11/002	S/PAINT RH FRONT FENDER, RH FRONT DOOR	350.00	500
8 11/003	RENEW RH FRONT S/RIM AND CONDUCT WHEEL BALANCING RH FRONT	15.00	/
9 11/004	RENEW RH FRONT TYRE 225/55R19 RFE H/L422		
	TOTAL LABOUR CHARGES	3208.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV52518

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	225/55R19H1422PLUS R/S TYRE RH FRONT X	225/55R19H1422			400.00 X SUC
2	SUNDRIES ?	HPH			100.00 ? X SUC
3	MOULDING RH FRONT DOOR	80282-4CABA	100.70	X SUC	
4	MLDG ASSY-FR DOOR RH	80820-4CLOA	157.00	X SUC	
5	TAPE-FR DOOR, RH	80818-4CAAB	19.00	X SUC	
6	DOOR-FRONT RH	8010N-4CBMA	1032.90	repair	
7	GROMMET \$2.50 EA X 02	76848-3000A	5.00	re	} 20%
8	CLIP ARC \$2.50 EA X 03	01553-10641	7.50	re	
9	CLIP ARC \$2.50 EA X 02	76847-3000A	5.00	re	
10	CLIP ARC \$2.50 EA X 04	63848-35700	10.00	re	
11	CLIP ARC \$3.00 EA X 02	76882-3010A	6.00	re	
12	GROMMET FENDER \$4.50 EA X 06	76881-3000A	27.00	re	
13	MOULDING ASSY-FRONT ARC RH	63860-4CE1A	170.00	see	
14	MOUL-FR DOOR, RH	80876-6F80A	183.90	X SUC	
15	FENDER-FRONT RH	F3100-4CCMA	583.40	repair	
16	ORNAMENT-ROAD	40342-8R02A			32.90 X SUC
17	WHEEL-ROAD AL RH FRONT	00300-4CB3A			1681.50 see in
18	INSULATOR-STRUT	54320-4CLOB	90.30	X SUC	
19	STOPPER ASSY	54325-00QOB			74.20 ?
20	BUMPER ASSY-BOO	54050-4CLOB			38.20 ?
21	SPACER	54034-4BABA			17.60 ?
22	SEAT SUSPENSION LOWER	54035-4BABA	23.30	?	} X SUC
23	STRUT KIT-FRONT	24302-4CE1C			265.00 ?
24	MEMBER COMPL	54400-4C91C			488.60 ?
25	STAY ASSY-FRONT	54404-2H10B			60.40 ?

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5251B

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26 ROD-STABILIZER	54618-1AAGE	32.30	?	
27 LINK COMPL,RH	54500-4CAGA	224.50	?	
28 SPOL-SHOCKLE,RH	60014-4CEGA			481.80 ?
29 SUB ASSY-ROAD W	60202-4BAQA			272.20 ?
30 SHAFT ASSY-FRONT RH	59100-4BS1B			966.30 ?
SUB TOTAL		2676.80	0.00	4978.60
LESS DISCOUNT (NETT-30.00%, LIST-30.00%, S/NETT-.00%)		535.36	0.00	0.00
GRAND TOTAL		2141.44	0.00	4978.60
OVERALL TOTAL		7120.04		

}
 X
 SUC

LEGEND: REMARKS(OK) = APPROVED, REMARKS(?) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLV53518

TOTAL LABOUR CHARGES	3258.00
TOTAL SPARE PARTS CHARGES	7120.04
GRAND TOTAL	10378.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME
SURVEYED DATE
AUTHORIZED DATE
EXCESS CLAUSE
LIABILITY
REMARKS

Perme - Hp 90010068
11/01/19 @ 1110
5 days
0.00
0.00

Resuy b4 paint

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAN/0578/2018
DATE : 17-DEC-2018

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MISS TAN YA LI
ADDRESS : 937 BUKIT TIMAH ROAD
#03-35
S(589646)
TELEPHONE NO : 96773911

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHC32558
VEHICLE NO : SLV5251B
MODEL CODE : JDRHRRRT32ENAF---A
MODEL/YEAR : NISSAN X-TRAIL FACELIFT MY2017
ENGINE NO : MR20146612C
CHASSIS NO : JN1JANT32E0010464
MILEAGE : 1 KM
DATE IN : 17/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 14/12/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

LKK

APR
11/01/19
132
11/12/18

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV5251B

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	/
2	RRSCH	REMOVE/REFIX SUSPENSION CROSS MEMBER	120.00	?
3	RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE RH FRONT	480.00	?
4	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	X
5	WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	/
6	EE/001	REPAIR AND RENEW RH FRONT FENDER, RH FRONT DOOR	1200.00	780
7	EE/002	S/PAINT RH FRONT FENDER, RH FRONT DOOR	750.00	500
8	EE/003	RENEW RH FRONT S/RIM AND CONDUCT WHEEL BALANCING RH FRONT	15.00	/
9	EE/004	RENEW RH FRONT TYRE 225/55R19 B/S H/L422		
TOTAL LABOUR CHARGES			3208.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5251B

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	225/55R19HL422PLUS B/S TYRE RH FRONT X	225/55R19HL422			400.00 X
2	SUNDRIES ?	NPH			100.00 ?
3	MOULDING RH FRONT DOOR	80282-4CA0A	100.70	X	
4	MLDG ASSY-FR DOOR RH	80820-4CL0A	157.00	X	
5	TAPE-FR DOOR,RH	80818-4CA0B	18.00	X	
6	DOOR-FRONT RH	8010M-4CBMA	1032.90	repair	
7	GROMMET \$2.50 EA 02	76848-JG00A	5.00	re-	
8	CLIP ARC \$2.50 EA X 03	01553-10641	7.50	re-	
9	CLIP ARC \$2.50 EA X 02	76847-JG00A	5.00	re-	
10	CLIP ARC \$2.50 EA X 04	63848-35F00	10.00	re-	
11	CLIP ARC \$3.00 EA X 02	76882-JG10A	6.00	re-	
12	GROMMET FENDER \$4.50 EA X 06	76881-JG00A	27.00	re-	
13	MOULDING ASSY-FRONT ARC RH	63860-4CE1A	170.00	scr	
14	MOUL-FR DOOR,RH	80876-6FR0A	183.90	X	
15	FENDER-FRONT RH	F3100-4CCMA	583.40	repair	
16	ORNAMENT-ROAD	40342-BR02A			32.90 X
17	WHEEL-ROAD AL RH FRONT	D0300-4CB3A			1681.50 scr
18	INSULATOR-STRUT	54320-4CL0B	90.30	?	
19	STOPPER ASSY	54325-00Q0B			74.20 ?
20	BUMPER ASSY-BOU	54050-4CL0B			38.20 ?
21	SPACER	54034-4BA0A			17.60 ?
22	SEAT SUSPENSION LOWER	54035-4BA0A	23.30	?	
23	STRUT KIT-FRONT	E4302-4CE1C			365.00 ?
24	MEMBER COMPL	54400-4CB1C			488.60 ?
25	STAY ASSY-FRONT	544C4-EN10B			60.40 ?

TAN CHONG MOTOR SALES PTE. LTD.
 BURIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5251B

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26 ROD-STABILIZER	54618-1AAGE	32.30	?	
27 LINK COMPL,RH	54500-4CA0A	224.50	?	
28 SPDL-KNUCKLE,RH	40014-4CE0A			481.80 ?
29 HUB ASSY-ROAD W	40202-4BA0A			272.20 ?
30 SHAFT ASSY-FRONT RH	39100-4BB1B			366.20 ?
SUB TOTAL		2676.80	0.00	4978.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		535.36	0.00	0.00
GRAND TOTAL		2141.44	0.00	4978.60
OVERALL TOTAL		7120.04		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAN W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLV5251B

TOTAL LABOUR CHARGES	3208.00
TOTAL SPARE PARTS CHARGES	7120.04
GRAND TOTAL	10328.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

AUTHORIZED DATE

EXCESS CLAUSE

LIABILITY

REMARKS

Permu - Hp 90010068

11/01/19 @ 1110

:

0.00

5.00

:

5 days

Resuy b4 paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

SATISFACTORY NOTE

TAN CHONG MOTOR SALES PTE LTD (TCMS)

☒

AUTOLUTION INDUSTRIAL PTE LTD (AIPL)

☐

TC AUTOCLINIC PTE LTD (TCAC)

☐

DATE:

OWNER NAME:

TAN YA LI

NRIC NO.:

ADDRESS:

TYPE OF CLAIM:

☐

OWN DAMAGE (OD)

☐

OWN DAMAGE (OD) & UNINSURED LOSS
(EXCESS & LOSS OF USAGE) VIA
TCMS / AIPL / TCAC

☐

THIRD PARTY THROUGH
TCMS / AIPL / TCAC

☒

THIRD PARTY - OWNER
DIRECT CLAIM AGAINST
THIRD PARTY INSURANCE

☐

WINDSCREEN / GLASS (W/S)

VEHICLE MODEL:

NISSAN X-TRAIL

REGN. NO.:

SLV52513

CHASSIS NO.:

INSURANCE CO.:

ALL - INNOV

CLAIM NO.:

POLICY NO.:

DATE OF ACCIDENT:

14/12/18

DATE RECEIVED:

13/08/19

DATE COMPLETED:

17/08/19

We / I hereby confirmed that the accident repair carried out by Tan Chong Motor Sales Pte Ltd / Autolution Industrial Pte Ltd / TC AutoClinic Pte Ltd and that all necessary repairs as resulted of the accident of the above vehicle have been completed to our / my satisfaction and that We / I have no further claim whatsoever against the above Company in respect thereof. Terms and Conditions as stipulated in the overleaf applies.

We / I have taken delivery of my car after all necessary repair carried out by Tan Chong Motor Sales Pte Ltd / Autolution Industrial Pte Ltd / TC AutoClinic Pte Ltd on*

Note: In the event of an Own Damage Claim, your Insurance Company may under policy terms & conditions, or as standard Industrial Practice, increase the loading on your premium during Insurance Policy renewal. Your NCD [Non Claim Discount] may also be affected, subject to business policy of respective Insurance Company.

X 
(NAME / SIGNATURE OF INSURED)

FOOTNOTE:

☐

TCMS / AIPL / TCAC* WILL CLAIM ON BEHALF
OF OWNER
THROUGH TCMS'S LEGAL AID

☐

DEPOSIT PAID BY OWNER

☐

OWNER WILL MAKE CLAIM AGAINST
THIRD PARTY INSURANCE COMPANY

☐

DOCUMENTS RETURNED TO
OWNER

☐

TCMS / AIPL / TCAC* WILL CLAIM ON BEHALF
OF OWNER UNINSURED LOSS. (EXCESS
PAYMENT & LOSS OF USAGE)

INSURANCE CO. COPY

* Delete When Necessary

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 8 January 2019 2:54 PM
To: Lawrence Teo; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Manivel Priyadarshini
Subject: RE: ACCIDENT INVOLVING SLV5251B & SHC3255B ON 14.12.2018
INS/IC/LAW/0578/2018 DIRECT SETTLEMENT
Attachments: 0886_001.pdf

2:58pm @ 8/1/2019
person@lawrence
VNI yet

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLV5251B and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Lawrence Teo [mailto:lawrenceteo@tanchong.com]
Sent: 08 January, 2019 1:59 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: ACCIDENT INVOLVING SLV5251B & SHC3255B ON 14.12.2018 INS/IC/LAW/0578/2018 DIRECT SETTLEMENT

Dear All,

Please arrange LKK.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472
Email: lawrenceteo@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: 18 December 2018 12:06
To: Lawrence Teo <lawrenceteo@tanchong.com>
Subject: RE: ACCIDENT INVOLVING SLV5251B & SHC3255B ON 14.12.2018 INS/IC/LAW/0578/2018 DIRECT SETTLEMENT

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street, #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Lawrence Teo [<mailto:lawrenceteo@tanchong.com>]
Sent: 18 December, 2018 10:15 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: ACCIDENT INVOLVING SLV5251B & SHC3255B ON 14.12.2018 INS/IC/LAW/0578/2018 DIRECT SETTLEMENT

Dear Office In Charge,

Our customer, TAN YA LI the owner of SLV5251B is insured with AIG Insurance at the material time of the accident. The 3rd party SHC3255B is insured with you at the material time of the accident.

Our customer holds your insured driver liable for the accident and would like to claim against your insured driver. On behalf of our customer, we hereby enquire whether you would like to have a Direct Settlement with our customer.

Our customer's claiming for Cost Of Repair and Loss Of Rental @\$150/Day. GIA Report / Estimate attached for your action.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622

Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472

Email: lawrenceteo@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

From: Singapore Printer <printsg@tanchong.org>

Sent: 18 December 2018 10:10

To: Lawrence Teo <lawrenceteo@tanchong.com>

Subject: Attached Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***SLV5251B (MCT18120433)**

[SHC3255B]

TP

TAN YA LI

Dec 14 2018 1:00PM

[COMFORT TRANSPORTATION PTE LTD]

Tan Chong Motor Sales Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 02/03/2020 10:29 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4348.37) - SLV5251B - Claim Handler: Priya

Approved:4348.37.

...CLAIM SUBFOLDER...(Pending for Survey Report)
Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2019 Edit Reg		08 Jan 2019 00:00 Edit Adj Rpt	\$3,503.90 Edit Estimates	\$3,503.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	TAN YA LI, ID: S8431945G		
Vehicle Reg. No.:	SLV5251B	Date of Loss:	14/12/2018 13:00 - :59 [11 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18120433	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC3255B	Policy No. (Claimant):	1700095124
		Excess:	
Repairer:	Tan Chong Motor Sales Pte Ltd (Bukit Timah) 911, Bukit Timah Road, 589622 Bukit Timah - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/01/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- III_SG (02/03/2020): Alert - Adj Mandate Approved (\$4348.37) - SLV5251B - Claim Handler: Priya
- III_SG (29/07/2019): Alert - Adj Mandate Approved (\$0.00) - SLV5251B - Claim Handler: Priya

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV5251B (MCT18120433)

[SHC3255B]

TP

TAN YA LI

Dec 14 2018 1:00PM

[COMFORT TRANSPORTATION PTE LTD]

Tan Chong Motor Sales Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	02/03/20 10:28	Video - Accident-IV	Load MP4	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/20 12:27	Odometer Reading	Load JPG	☒
2	20/02/20 12:27	Chassis Number	Load JPG	☒
3	20/02/20 12:27	General View	Load JPG	☒
4	20/02/20 12:27	General View	Load JPG	☒
5	20/02/20 12:27	General View	Load JPG	☒
6	20/02/20 12:27	General View	Load JPG	☒
7	20/02/20 12:27	General View	Load JPG	☒
8	20/02/20 12:27	General View	Load JPG	☒
9	20/02/20 12:27	General View	Load JPG	☒
10	20/02/20 12:27	General View	Load JPG	☒
11	20/02/20 12:27	General View	Load JPG	☒
12	20/02/20 12:27	General View	Load JPG	☒
13	20/02/20 12:27	General View	Load JPG	☒
14	20/02/20 12:27	General View	Load JPG	☒
15	20/02/20 12:27	General View	Load JPG	☒
16	20/02/20 12:27	General View	Load JPG	☒
17	20/02/20 12:27	General View	Load JPG	☒
18	20/02/20 12:27	General View	Load JPG	☒
19	20/02/20 12:27	General View	Load JPG	☒
20	20/02/20 12:27	General View	Load JPG	☒
21	20/02/20 12:27	General View	Load JPG	☒
22	20/02/20 12:27	General View	Load JPG	☒
23	20/02/20 12:27	General View	Load JPG	☒
24	20/02/20 12:28	Reinspection Photo	Load JPG	☒
25	20/02/20 12:28	Reinspection Photo	Load JPG	☒
26	20/02/20 12:28	Reinspection Photo	Load JPG	☒
27	20/02/20 12:28	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/01/19 15:03	EMAIL FROM III DD 08012019	Load PDF	
2	09/01/19 15:03	TP EST & GIA REPORT	Load PDF	
3	14/01/19 18:12	TP ESTIMATE- MARKED	Load PDF	
4	20/02/20 12:26	LOD AND LOA	Load PDF	
5	20/02/20 12:26	RENTAL AGREEMENT AND INVOICE	Load PDF	
6	20/02/20 12:26	TAX INVOICE	Load PDF	
7	21/02/20 11:02	WORKSHOP INVOICE	Load PDF	
8	21/02/20 11:02	RENTAL RECEIPT	Load PDF	
9	30/03/20 10:32	AUTHORISATION TO ACT FORM	Load PDF	
10	30/03/20 10:32	DISCHARGE VOUCHER	Load PDF	
11	30/03/20 10:32	LOD	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	10/01/19 09:01	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19000513/R1GA3Q2

Date: 30/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SLV5251B Insured Vehicle No: SHC3255B
 Date of Loss: 14/12/2018 Nature of Claim: TP Claim No: MCT18120433

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV5251B
 Make & Model: NISSAN X-TRAIL, 2.0 (A) Engine No: MR20146612C
 Reg. Date: 30/12/2017 (Man. Year: 2017) Chassis No: JN1JANT32Z0010464
 Colour: Grey Odometer: 12585 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55 R19 Rear Tyre Size: 225/55 R19
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,120.04	1,865.90	5,254.14	73.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,208.00	1,638.00	1,570.00	48.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,328.04	3,503.90	6,824.14	66.07
+ GST 7.00/7.00% (S\$)	722.96	245.27	477.69	66.07
Nett Amount (S\$)	11,051.00	3,749.17	7,301.83	66.07
+ Car Rental (4.0 x S\$149.80/day) (S\$)		599.20		
Nett Liability (S\$)		4,348.37		

INSPECTION

Date of Assignment: 08/01/2019
 Date Inspected: 11/01/2019 Inspected At: Tan Chong Motor Sales Pte Ltd (Bukit Timah)
 911, Bukit Timah Road
 Singapore 589622
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Feb 2020)
Parts:	M1-MPV	NISSAN X-TRAIL 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV5251B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MOULDING RH FRONT DOOR	Serviceable	100.70 FN	*- FN
2	1		*MLDG ASSY -FR DOOR RH	Serviceable	157.00 FN	*- FN
3	1		*TAPE -FR DOOR ,RH	Serviceable	18.00 FN	*- FN
4	1		*DOOR -FRONT RH	Repair	1,032.90 FN	*- FN
5	2		*GORMMET	Necessary	5.00 FN	*5.00 FN
6	3		*CLIP ARC	Necessary	7.50 FN	*7.50 FN
7	2		*CLIP ARC	Necessary	5.00 FN	*5.00 FN
8	4		*CLIP ARC	Necessary	10.00 FN	*10.00 FN
9	2		*CLIP ARC	Necessary	6.00 FN	*6.00 FN
10	6		*GROMMET FENDER	Necessary	27.00 FN	*27.00 FN
11	1		*MOULDING ASSY -FRONT ARC RH	Scratched	170.00 FN	*170.00 FN
12	1		*MOUL-FR DOOR ,RH	Serviceable	183.90 FN	*- FN
13	1		*FENDER -FRONT RH	Repair	583.40 FN	*- FN
14	1		*INSULATOR -STRUT	Serviceable	90.30 FN	*- FN
15	1		*SEAT SUSPENSION LOWER	Serviceable	23.30 FN	*- FN
16	1		*ROD-STABILIZER	Serviceable	32.30 FN	*- FN
17	1		*LINK COMPL-RH	Serviceable	224.50 FN	*- FN
18	1		*225/55R19HL422PLUS B/S TYRE RH FRONT	Serviceable	400.00 FS	*- FS
19	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS
20	1		*ORNAMENT -ROAD	Serviceable	32.90 FS	*- FS
21	1		*WHEEL -ROAD AL RH FRONT	Scratched	1,681.50 FS	*1,681.50 FS
22	1		*STOPPER ASSY	Serviceable	74.20 FS	*- FS
23	1		*BUMPER ASSY -BOU	Serviceable	38.20 FS	*- FS
24	1		*SPACER	Serviceable	17.60 FS	*- FS
25	1		*STRUT KIT-FRONT	Serviceable	365.00 FS	*- FS
26	1		*MEMBER COMPL	Serviceable	488.60 FS	*- FS
27	1		*STAY ASSY -FRONT	Serviceable	60.40 FS	*- FS
28	1		*SPDL-KNUCKLE RH	Serviceable	481.80 FS	*- FS
29	1		*HUB ASSY -ROAD W	Serviceable	272.20 FS	*- FS
30	1		*SHAFT ASSY -FRONT RH	Serviceable	966.20 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	7,655.40	1,912.00
- Nett Item Discount on N Items 20.00/20.00% (S\$)	535.36	46.10
Total Parts (S\$)	7,120.04	1,865.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	240.00	240.00
2	REMOVE/REFIX SUSPENSION CROSS MEMBER	New	120.00	0.00
3	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE RH FRONT	New	480.00	0.00
4	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	300.00	0.00
5	CHECK WHEEL ALIGNMENT ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	New	103.00	103.00
6	REPAIR AND RENEW RH FRONT FENDER ,RH FRONT DOOR	New	1,200.00	780.00
7	S/PAINT RH FRONT FENDER ,RH FRONT DOOR	New	750.00	500.00
8	RENEW RH FRONT S/RIM AND CONDUCT WHEEL BALANCING RH FRONT	New	15.00	15.00
Gross Labour Cost (\$\$)			3,208.00	1,638.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >