

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

10146

18/12/18

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0578/2018
DATE : 17-DEC-2018

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT ~~WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832 FAX : 64697472

OWNER'S NAME : MISS TAN YA LI
ADDRESS : 937 BUKIT TIMAH ROAD
#03-35
S(589646)
TELEPHONE NO : 96773911 ✓ *Mr. CLP.W*

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHC3255B
VEHICLE NO : SLV5251B
MODEL CODE : JDRNRRZT32EWAF---A
MODEL/YEAR : NISSAN X-TRAIL FACELIFT MY2017
ENGINE NO : MR20146612C
CHASSIS NO : JN1JANT32Z0010464
MILEAGE : 1 KM
DATE IN : 17/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 14/12/2018

LKK

APP
11/01/19
302
11/12/18

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV5251B

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	/
2 RRSCM	REMOVE/REFIX SUSPENSION CROSS MEMBER	120.00	?
3 RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE RH FRONT	480.00	?
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	X
5 WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	/
6 ZZ/001	REPAIR AND RENEW RH FRONT FENDER, RH FRONT DOOR	1200.00	780
7 ZZ/002	S/PAINT RH FRONT FENDER, RH FRONT DOOR	750.00	500
8 ZZ/003	RENEW RH FRONT S/RIM AND CONDUCT WHEEL BALANCING RH FRONT	15.00	/
9 ZZ/004	RENEW RH FRONT TYRE 225/55R19 B/S H/L422		
TOTAL LABOUR CHARGES		3208.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5251B

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	225/55R19HL422PLUS B/S TYRE RH FRONT X	225/55R19HL422		400.00 X
2	SUNDRIES ?	NPN		100.00 ?
3	MOULDING RH FRONT DOOR	80282-4CA0A	100.70 X	
4	MLDG ASSY-FR DOOR RH	80820-4CL0A	157.00 X	
5	TAPE-FR DOOR,RH	80818-4CA0B	18.00 X	
6	DOOR-FRONT RH	H010M-4CBMA	1032.90 repair	
7	GROMMET \$2.50 EA 02	76848-JG00A	5.00 5.00	
8	CLIP ARC \$2.50 EA X 03	01553-10641	7.50 7.50	
9	CLIP ARC \$2.50 EA X 02	76847-JG00A	5.00 5.00	
10	CLIP ARC \$2.50 EA X 04	63848-35F00	10.00 10.00	
11	CLIP ARC \$3.00 EA X 02	76882-JG10A	6.00 6.00	
12	GROMMET FENDER \$4.50 EA X 06	76881-JG00A	27.00 27.00	
13	MOULDING ASSY-FRONT ARC RH	63860-4CE1A	170.00 170.00	
14	MOUL-FR DOOR,RH	80876-6FR0A	183.90 X	
15	FENDER-FRONT RH	F3100-4CCMA	583.40 repair	
16	ORNAMENT-ROAD	40342-BR02A		32.90 X
17	WHEEL-ROAD AL RH FRONT	D0300-4CB3A		1681.50 1681.50
18	INSULATOR-STRUT	54320-4CL0B	90.30 ?	
19	STOPPER ASSY	54325-00Q0B		74.20 ?
20	BUMPER ASSY-BOU	54050-4CL0B		38.20 ?
21	SPACER	54034-4BA0A		17.60 ?
22	SEAT SUSPENSION LOWER	54035-4BA0A	23.30 ?	
23	STRUT KIT-FRONT	E4302-4CE1C		365.00 ?
24	MEMBER COMPL	54400-4CB1C		488.60 ?
25	STAY ASSY-FRONT	544C4-EN10B		60.40 ?

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5251B

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
26	ROD-STABILIZER	54618-1AA0E	32.30	?
27	LINK COMPL,RH	54500-4CA0A	224.50	?
28	SPDL-KNUCKLE,RH	40014-4CE0A		481.80 ?
29	HUB ASSY-ROAD W	40202-4BA0A		272.20 ?
30	SHAFT ASSY-FRONT RH	39100-4BB1B		966.20 ?
SUB TOTAL			2676.80	0.00 4978.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			535.36	0.00 0.00
GRAND TOTAL			2141.44	0.00 4978.60
OVERALL TOTAL			7120.04	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLV5251B

TOTAL LABOUR CHARGES	3208.00
TOTAL SPARE PARTS CHARGES	7120.04
GRAND TOTAL	10328.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Peru - Hp 90010068
SURVEYED DATE	:	11/01/19 @ 1110
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 5 days
LIABILITY	:	0.00
REMARKS	:	

Resuy b4 paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.