

23/03/2003

ASS. REC. BY:

REF: CS3/ III 18020765/ A1b-1⁰²

Special Instruction:

Surveyor:

Mennen

ASSIGNMENT (Office)

From (Person):

Stanley Lei

of

III

Date/Time: 09012019

Estimated Cost:

Bill to:

OD ☒ TP/ WS/ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 8341R

Insured:

SHC 8593S

at Workshop m/s

Reliable Carz

Tel:

8166 9797

of

8 kaki Bukit Ave 1 # 05-50

Policy No:

Claim No:

MCT18110457

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/11/2018

CA / REV / REP. / REV 24 HRS

(cup)

H.O.D. Endorsement:

Date/Time:

12:44pm 16/11/18

Person Contacted:

Jusun

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate Insp: 1 kaki Bkt Ave # 01-60 Autobay
	SLT 8341R - NA/INC18020734/24 JUA: 15/11/18
	SHC 8593S - NA/INC18020734/24 JUA: 15/11/18
	Dismantle: 19/11/2018 @ 10am
	lump sum \$10,200/- (Red: 2200, 17%)
	Adays

18/1 - File pass to typist.

RECEIVED 18 JAN 2019

350-170 = 230

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
Person Contacted: _____Veh No: SLT8341R Yr Regn: 2017 / NovType: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Freed Hybrid c.c 1496Colour: White A/C: Insured / Std / Nil / NASp. Reading: 85891 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: 6B71047795Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/65R15R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Newton

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 16/11/18 @ 3:25pmSurvey held at ReliableDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP III PRS

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

12010130

Catherine Chong (LKK Auto)

From: Stanley Lai <stanley.lai@iii.com.sg>
Sent: Wednesday, 9 January, 2019 9:33 AM
To: 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Mekavathanan Sarangapani; Sundari Nagarajan - III
Subject: III REF: MCT18110457 | REQUEST FOR PAPER SURVEY

Dear Sir/Mdm,

Rights granted in Merimen for the above LOD. Kindly proceed with the paper survey.

TP Veh No. : **SLT8341R**

Warmest regards,

Stanley Lai

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

S&P 'A-' rated Company



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

...CLAIM SUBFOLDER...(Pending for Payment)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2018		16 Nov 2018 00:00		28 Nov 2018 14:32 S\$0.00 (S\$139.10)		Pending for Payment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	-, Co. Reg. No.: -			[Created by adjuster]
Main Claimant:	RELIABLE RIDES PTE LTD, Co. Reg. No.: 201611527N			
Vehicle Reg. No.:	SLT8341R	Date of Loss:	15/11/2018 14:00 - :59 [12 Months and 1 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / MCT18110457	Policy/Cover Note No.:	MCOM0016	
Vehicle Reg. No. (Insured):	SHC8593S	Policy No. (Claimant):		
		Excess:		
Repairer:	Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:			
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 27/11/2018]			

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

MCT18110457

RESERVES			
TPPD	PRESERVE	10,000 SLT 83412.	— Arrange Paper Survey.
TPPI	PRESERVE		
UNINSURED LOSS	PRESERVE		
SUBRO	PRESERVE		
LPPN			
INVESTIGATION FEE			
SURVEY FEES			
LEGAL FEES			
OTHERS			
FRAUD CHECK			
UPLOAD TO MERIMEN			
GRANT RIGHTS			

Lat
27/12/18 2

 *** FAX TX REPORT ***

TRANSMISSION OK

JOB NO. 4474
 DESTINATION ADDRESS 964382313
 SUBADDRESS
 DESTINATION ID
 ST. TIME 27/12 09:47
 TX/RX TIME 00'39
 PGS. 1
 RESULT OK

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.6260.2018.RC-PD
 Your Ref: SHC8593S

21 DEC 2018

TO: COMFORT TRANSPORTATION PTE LTD
 383 Sin Ming Drive
 Gas Building
 Singapore 575717

BY CERTIFICATE OF
 POSTING

WITHOUT PREJUDICE

cc: India International Insurance Pte Ltd
 (Motor Claims Dept)
 64 Cecil Street
 #05-02IOB Building
 Singapore 049711

BY PDX

WITHOUT PREJUDICE

MAIN OFFICE
 133 NEW BRIDGE ROAD
 #23-03/04/05
 CHINATOWN POINT
 SINGAPORE 059413
 TEL: 6438 1323
 FAX: 6438 2313

BRANCH OFFICE
 1 JALAN BERSER
 #03-12 NEW WORLD CENTRE
 SINGAPORE 209037

PLEASE SEND ALL
 CORRESPONDENCES TO
 THE MAIN OFFICE

WE DO NOT ACCEPT
 SERVICE BY FAX

Dear Sirs

RELIABLE RIDES PTE LTD
 8 Kaki Bukit Avenue 4
 #05-50 Premier @ Kaki Bukit
 Singapore 415875



We are instructed by the abovenamed to claim damages against you in connection with an accident on 15 November 2018 at about 14:45 hours along AYE (MCE) before Alexandra Road Exit involving our clients' vehicle no. SLT8341R and vehicles registration number SHC8593S & SLC4932B & SLP2140P & SLX3253Z.

We are instructed that the accident was caused by the negligence of your employee, servant and/or agent in the driving, management and control of vehicle registration number SHC8593S.

As a result of the accident, our clients' vehicle registration number SLT8341R was damaged and our clients have been put to loss and expense, particulars of which are as follows:-

A Damages		
a.	Cost of Repairs	\$ 12,400.00
b.	Loss of Rental (14 days x \$180.00 per day) (inclusive of 2 Sundays and 2 days Pre-Repair Inspection Notice)	\$ 2,520.00

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.6260.2018.RC-PD
Your Ref: SHC8593S

21 DEC 2018

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

TO: **COMFORT TRANSPORTATION PTE LTD**
383 Sin Ming Drive
Gas Building
Singapore 575717

BY CERTIFICATE OF
POSTING

WITHOUT PREJUDICE

cc: **India International Insurance Pte Ltd**
(Motor Claims Dept)
64 Cecil Street
#05-02IOB Building
Singapore 049711

BY PDX

WITHOUT PREJUDICE



Dear Sirs

RELIABLE RIDES PTE LTD
8 Kaki Bukit Avenue 4
#05-50 Premier @ Kaki Bukit
Singapore 415875

We are instructed by the abovenamed to claim damages against you in connection with an accident on 15 November 2018 at about 14:45 hours along AYE (MCE) before Alexandra Road Exit involving our clients' vehicle no. SLT8341R and vehicles registration number SHC8593S & SLC4932B & SLP2140P & SLX3253Z.

We are instructed that the accident was caused by the negligence of your employee, servant and/or agent in the driving, management and control of vehicle registration number SHC8593S.

As a result of the accident, our clients' vehicle registration number SLT8341R was damaged and our clients have been put to loss and expense, particulars of which are as follows:-

A Damages			
a.	Cost of Repairs	\$	12,400.00
b.	Loss of Rental (14 days x \$180.00 per day) (inclusive of 2 Sundays and 2 days Pre-Repair Inspection Notice)	\$	2,520.00
B Disbursements			
a.	LTA Search	\$	7.49
b.	Survey Report	\$	1,007.00
C LEGAL COSTS (AT THIS STAGE)		\$	963.00
		\$	16,897.49

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

MCT18110457
Sundari
27/12/18

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

We enclose herewith copies of the following documents in support of our clients' claim:-

- a) GIA Report lodged by the driver of our clients' vehicle no. SLT8341R with sketch plan;
- b) Result of LTA search on your vehicle registration no. SHC8593S;
- c) Repair Invoice from Reliable Carz Pte Ltd;
- d) Vehicle Assessment Report & Invoice from PAL's Appraiser Pte Ltd;
- e) Two Hundred Seven (207) colour photographs depicting the damage to our clients' motor vehicle no. SLT8341R; and
- f) Vehicle Owner Particulars of our clients' vehicle no. SLT8341R.

We have on 15 November 2018 notified your insurers India International Insurance Pte Ltd of the accident and pre-repair inspection of our client's vehicle was carried out by your insurer.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter **within 14 days** of your receipt of this letter, failing which our clients will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our clients arising out of the accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents **within 8 weeks** of your receipt of this letter.

Yours faithfully

CrossBORDER'S LLC

CrossBorders LLC

Email: corene@crossbordersllc.com (secretary)

encs

cc: SLT8341R

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 15/11/2018 16:35
Date Of Accident 15/11/2018 14:45
Exact Location Of Accident AYE (MCE) BEFORE ALEXANDRA RD EXIT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLT8341R
Insured/Policyholder
Name Of Registered Owner RELIABLE RIDES PTE LTD
Co Reg No 201611527N
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-89999999
Vehicle Particulars
Manufacturer HONDA
Model FREED 1.5G HYBRID A
Exact Purpose for which vehicle was being used at time of accident COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5095785788-01
Cover Note Number
Driver
Name of Driver MOHAMAD SALEH BIN ABDUL RAZAK
NRIC No S7922669F
Date Of Birth 02/08/1979
Occupation OUTDOOR
Date Of Driving Pass 01/03/2000
Driving Experience 18 YEARS AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90709524
Fax Number
Contact Number OFFICE-90709524
Email Address NOEMAIL

Address BLK 211B PUNGGOL WALK
 #06-631
 Postcode 822211
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 5
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 7

Passenger 1
 NAME: -
 GENDER: MALE
 Passenger 2
 NAME: -
 GENDER: MALE
 Passenger 3
 NAME: -
 GENDER: FEMALE
 Passenger 4
 NAME: -
 GENDER: FEMALE
 Passenger 5
 NAME: -
 GENDER: FEMALE
 Passenger 6
 NAME: -
 GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG STATED VENUE. VEHICLE IN FRONT JAMMED BRAKE SO I JAMMED BRAKE OF MY VEHICLE ACCORDINGLY. SUDDENLY I FELT AN IMPACT OF MY VEHICLE, I ALIGHT FROM MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION. AFTER AN IMPACT, I COME TO REALIZE THAT THERE WERE TOTAL OF 5 VEHICLES INVOLVED IN THIS ACCIDENT.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES
Remarks/ Reasons: VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC8593S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver NG LYE BENG
NRIC/Passport Number S0890159G
Contact Number 97575611
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 2
Passenger 1
NAME:
GENDER:

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLC4932B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver HEW FOO YOONG
NRIC/Passport Number S6974173H
Contact Number 93857618
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 2
Passenger 1
NAME:
GENDER:

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLP2140P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LIONEL SIM
NRIC/Passport Number S8424623I
Contact Number 91452742
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SLX3253Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

PRIVATE CAR

DENNIS WONG

S8218536D

81020282

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please fill out correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow the insurer to repudiate policy liability.
4. The use of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) As my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) assessing, handling and/or dealing with my claim(s) including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions of responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulations, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/ID No:

Accident Sketch Plan

SKETCH PLAN

390 (6711)

A 517830112
B 51HC85935
C 51C4932B
D 51P2140P
E 51X32532

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement

DECLARATION

particulars are true in every respect


$$\theta = \exp(\theta_0 + \theta_1 x) = e^{\theta_0} e^{\theta_1 x}$$

October 27, 1998

Driver's Signature _____

Date & Time

Date & Time

Reporting Centre Personnel's Signature

Abstract

HRC 21N 460

Enquire Vehicle & Owner Information (Vehicle No. SHC8593S As At 15 Nov 2018 / 14:45:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: AJ.TK.RC

Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHC8593S

Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Insurance Company Name: INDIA INT'L INS PTE LTD

Reliable Carz Pte Ltd

No.8 Kaki Bukit Ave 4 #05-50 Premier@Kaki Bukit Singapore 415875
H/P : 8166 9797

Name : Reliable Rides Pte Ltd
Address : c/o No.8 Kaki Bukit Ave 4
#05-50 Premier@Kaki Bukit
Singapore 415875

Date : 5-Dec-18

Final repair bill for vehicle no. SLT 8341 R

To supply and replace parts, labour charges for
repairing, knocking, welding and to respray painting
(Lump Sum Repair)

\$ 12,400.00

Dollar : Twelve Thousand Four Hundred Only

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883

Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Billing Name & Address

Reliable Rides Pte Ltd

c/o No.8 Kaki Bukit Ave 4

#05-50 Premier@Kaki Bukit

Singapore 415875

Invoice No 11-18026/DY

Date 5 Dec 2018

Vehicle No : SLT 8341 R

Model : Honda Freed

Item	Descriptions	Amount S\$
1	Date of inspection : <u>16 Nov 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>207</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 1007.00</u>
	SDLS : ONE THOUSAND AND SEVEN ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 11-18026/DY / 2018
Date of Report : 5 Dec 2018

Reliable Rides Pte Ltd
c/o No.8 Kaki Bukit Ave 4
#05-50 Premier@Kaki Bukit
Singapore 415875

THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 15 Nov 2018

As per your instruction dated 16 Nov 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLT 8341 R. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLT 8341 R
Model : Honda Freed
Year / Capacity : 2017/1496
Chassis No : GB7-1047795
Engine No : LEB5577267
Mileage : 85890
Colour : White

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 185/65 R15	Neuton	6.00	mm	Normal
REAR	O/S	: 185/65 R15	Dunlop	5.00	mm	Normal
FRONT	N/S	: 185/65 R15	Neuton	6.00	mm	Normal
REAR	N/S	: 185/65 R15	Dunlop	5.00	mm	Normal

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear and front portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Reliable Carz Pte Ltd
No.8 Kaki Bukit Ave 4
#05-50 Premier@Kaki Bukit
Singapore 415875

5. Estimated normal period of repair : 10 working days to complete.
6. Enclosed number of photograph : 207 copies.
7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SLT 8341 R**
 Report No: **TP/ 11-18026/DY / 2018**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear windscreen moulding	Necessary	\$ 79.20	\$ 79.20 ✓
1	Rear tailgate	Damage	\$ 1100.60	\$ 1100.60 ✓
2	Rear tailgate dampers	Damage	\$ 270.80	\$ 270.80 x
1	Rear tailgate inner board	Damage	\$ 288.40	\$ 288.40 ✓
2	Rear tailgate lamps	Damage	\$ 329.50	\$ 329.50 ✓
1	Rear tailgate lock	Damage	\$ 157.20	\$ 157.20 ✓
1	Rear tailgate logo	Necessary	\$ 32.50	\$ 32.50 ✓
1	Rear tailgate inner handle	Damage	\$ 29.50	\$ 29.50 ✓
1	Rear tailgate outer chrome handle	Damage	\$ 320.60	\$ 320.60 ✓
1	Rear tailgate rubber	Necessary	\$ 168.40	\$ 168.40 ✓
1	Rear tailgate 'FREED' emblem	Necessary	\$ 55.40	\$ 55.40 ✓
2	Rear taillamps	Damage	\$ 580.60	\$ 580.60 ✓
1	Rear end panel	Damage	\$ 623.70	\$ 623.70 ✓
1	Rear end panel inner garnish	Damage	\$ 115.40	\$ 115.40 ✓
1	Rear bumper	Damage	\$ 925.40	\$ 925.40 ✓
1	Rear bumper clip (1 set)	Necessary	\$ 55.00	\$ 55.00 ✓
2	Rear bumper reflectors	Damage	\$ 131.80	\$ 131.80 x
2	Rear bumper side retainers	Damage	\$ 49.80	\$ 49.80 ✓
2	Rear bumper undercovers	Damage	\$ 271.40	\$ 271.40 x
2	Rear fender inner garnishes	Damage	\$ 737.20	\$ 737.20 ✓
1	Bonnet lock	Damage	\$ 103.70	\$ 103.70 x
2	Front headlamps	Damage	\$ 3961.20	\$ 3961.20 ✓
2	Front headlamp lower brackets	Necessary	\$ 93.00	\$ 93.00 x
1	Front grille	Damage	\$ 740.20	\$ 740.20 ✓
1	Front bumper	Damage	\$ 1050.80	\$ 1050.80 ✓
1	Front bumper clip (1 set)	Necessary	\$ 55.00	\$ 55.00 ✓
1	Front bumper lower grille	Damage	\$ 165.80	\$ 165.80 ✓
1	Front bumper reinforcement	Damage	\$ 295.80	\$ 295.80 ✓
2	Front bumper side retainers	Damage	\$ 59.00	\$ 59.00 ✓
1	Front bumper tow hook cover	Damage	\$ 25.60	\$ 25.60 x
1	Front support panel	Damage	\$ 702.40	\$ 702.40 x
1	Air con condenser	Damage	\$ 985.40	\$ 985.40 x
1	Radiator	Intact	\$ 1502.60	\$ 1502.60 ✓
Discount 20.0%			\$ 16062.90	\$ 14560.30
			\$ 3212.58	\$ 2912.06
			\$ 12850.32	\$ 11648.24

11976.20
9580.96

List Items Total \$ 12850.32 \$ 11648.24

Vehicle No: **SLT 8341 R**
 Report No: **TP/ 11-18026/DY / 2018**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
		List Items Total c/f	\$ 12850.32	\$ 11648.24
<u>Special Nett Items</u>				
1	Rear windscreen seal	Necessary	\$ 85.00	\$ 85.00-50
1	Rear windscreen sealant	Necessary	\$ 100.00	\$ 60.00-50
1	Rear number plate	Damage	\$ 50.00	\$ 50.00 x 111
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 280.00-20
1	Front number plate	Damage	\$ 50.00	\$ 50.00 ✓
			<u>\$ 565.00</u>	<u>\$ 525.00</u>

350

Spare Parts Total \$ 13415.32 \$ 12173.24

Vehicle No: **SLT 8341 R**
 Report No: **TP/ 11-18026/DY / 2018**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 13415.32	\$ 12173.24
1	To provide towing service charge.	\$ 60.00	\$ 60.00 x
2	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00 30
3	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00 30
4	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 180.00	\$ 120.00 80
5	To remove and refit rear bumper sensor.	\$ 110.00	\$ 80.00 50
6	To remove and refit air-con system, refill gas and test for leakages.	\$ 200.00	\$ 120.00 ✓
7	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00 ✓
8	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1700.00	\$ 1320.00 ✓
9	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1600.00	\$ 1320.00 1100,
10	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 90.00 50
Total		\$ 17695.32	\$ 15483.24

2900

Vehicle No: SLT 8341 R
Report No: TP/ 11-18026/DY / 2018

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
------	------------------	-----------------------	------------------------

Total c/f \$ 17695.32 \$ 15483.24

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 12400.00

SDLS: TWELVE THOUSAND FOUR HUNDRED ONLY


Qualified Appraiser

total: 12830.96
L/S: 10.2K.
29 Days.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CS3/III18020765/Atbe2-1	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 21-01-2019	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8593S	Veh. Inspected	SLT 8341R	
Policy No.		Coverage (\$)	0.00	
Claim No.	MCT18110457	Excess (\$)	0.00	
Assign From	STANLEY LAI	Assign Date	09/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GB71047795	Colour	WHITE	
Odometer	85891	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	NEUTON	6 mm	
L/H Front Tyre	185/65 R15	NEUTON	6 mm	
R/H Rear Tyre	185/65 R15	NEUTON	6 mm	
L/H Rear Tyre	185/65 R15	NEUTON	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/11/2018	Inspection Date	16/11/2018	
Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 8341R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	79.20	79.20
1	REAR TAILGATE	DAMAGED	1,100.60	1,100.60
2	REAR TAILGATE DAMPERS	NOT NECESSARY	270.80	-
1	REAR TAILGATE INNER BOARD	DAMAGED	288.40	288.40
2	REAR TAILGATE LAMPS	DAMAGED	329.50	329.50
1	REAR TAILGATE LOCK	DAMAGED	157.20	157.20
1	REAR TAILGATE LOGO	NECESSARY	32.50	32.50
1	REAR TAILGATE INNER HANDLE	DAMAGED	29.50	29.50
1	REAR TAILGATE OUTER CHROME HANDLE	DAMAGED	320.60	320.60
1	REAR TAILGATE RUBBER	NECESSARY	168.40	168.40
1	REAR TAILGATE 'FREED' EMBELM	NECESSARY	55.40	55.40
2	REAR TAILLAMPS	DAMAGED	580.60	580.60
1	REAR END PANEL	DAMAGED	623.70	623.70
1	REAR END PANEL INNER GARNISH	DAMAGED	115.40	115.40
1	REAR BUMPER	DAMAGED	925.40	925.40
1	SET REAR BUMPER CLIP	NECESSARY	55.00	55.00
2	REAR BUMPER REFLECTORS	NOT NECESSARY	131.80	-
2	REAR BUMPER SIDE RETAINERS	DAMAGED	49.80	49.80
2	REAR BUMPER UNDERCOVERS	NOT NECESSARY	271.40	-
2	REAR FENDER INNER GARNISHES	DAMAGED	737.20	737.20
1	BONNET LOCK	NOT NECESSARY	103.70	-
2	FRONT HEADLAMPS	DAMAGED	3,961.20	3,961.20
2	FRONT HEADLAMP LOWER BRACKETS	NOT NECESSARY	93.00	-
1	FRONT GRILLE	DAMAGED	740.20	740.20
1	FRONT BUMPER	DAMAGED	1,050.80	1,050.80
1	SET FRONT BUMPER CLIP	NECESSARY	55.00	55.00
1	FRONT BUMPER LOWER GRILLE	DAMAGED	165.80	165.80
1	FRONT BUMPER REINFORCEMENT	DAMAGED	295.80	295.80
2	FRONT BUMPER SIDE RETAINERS	DAMAGED	59.00	59.00
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	25.60	-

Report Ref No. CS3/III18020765/Atbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	702.40	-
1	AIR CON CONDENSER	NOT NECESSARY	985.40	-
1	RADIATOR	NOT NECESSARY	1,502.60	-
	LESS 20% DISCOUNT		-3,212.58	-2,395.24
			12,850.32	9,580.96
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEAL (SN)	NECESSARY	85.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	50.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	FRONT NUMBER PLATE (SN)	DAMAGED	50.00	50.00
			565.00	350.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE CHARGE.	NOT NECESSARY	60.00	-
	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		50.00	30.00
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		50.00	30.00
	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS.		180.00	80.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		110.00	50.00
	TO REMOVE AND REFIT AIR-CON SYSTEM, REFILL GAS AND TEST FOR LEAKAGES.		200.00	120.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		1,700.00	1,320.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,600.00	1,100.00

Report Ref No. CS3/III18020765/Atbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		150.00	50.00
			4,280.00	2,900.00
GRAND TOTAL			17,695.32	12,830.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,200.00

Report Ref No. CS3/III18020765/Atbe2-1

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.