



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to survey this
Vehicle thanks

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19000115	Page	1
Registration No	: SLZ744H	Date	: 7. Jan 2019	Customer No.	: WZA006
Chassis No	: MRHFC5650JT000514	Svc Advisor	: LIM CHOU SIONG	Engine No	: R16B25500575
Model	: CIVIC 1.6 VTI YM2018	Date Time	: 7. Jan 2019 9:05:52 PM	Surveyor Name	:
Owner's Name	: ONG CHEE HIAN	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 5/1/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ONG CHEE HIAN OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L ACC DATE: 5/1/2019 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SGP2727G						
BO-NUM-COMP-OPC-L	NUMBER PLATE WITH CASING-OPC-L	1	45.00	✓	45.00	3.15	48.15
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	✓ 25	434.92	30.44	465.36
71102-TBA-A10	GRILLEFR.BUMPER LOWER	1	36.10	? 25	27.07	1.89	28.96
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE	1	18.00	✓ 25	13.50	0.95	14.45
71130-TEA-T00	BEAM COMPFR.BUMPER	1	345.90	? 25	259.42	18.16	277.58
71140-TEA-T00	BEAMR.FR.BUMPER UPPER	1	26.70	✓ 25	20.02	1.40	21.42
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP	1	214.80	? 25	161.10	11.28	172.38
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	✓ 25	7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	X 25	7.80	0.55	8.35
71201-TEA-T00	PLATER.FR.BUMPER SIDE INDUCTN	1	43.30	? 25	32.47	2.27	34.74
91505-TM8-003	CLIP,BUMPER	16	2.30	✓ 25	27.60	1.93	29.53
91512-R21-013	CLIPINNER FENDER	2	0.40	✓ 25	0.60	0.04	0.64
91501-S04-003	CLIPINNER FENDER	4	3.90	✓ 25	11.70	0.82	12.52
71121-TEA-T01	BASE,FR.GRILLE CHROME	1	73.80	✓ 25	55.35	3.87	59.22
71124-TEA-T01	EXTENSION ASSYR.FR.GRILLE	1	85.60	✓ 25	64.20	4.49	68.69
71125-TEA-T01	MOLDINGFR.GRILLE	1	100.40	✓ 25	75.30	5.27	80.57
74127-TEA-T00	COVERFR.BULKHEAD	1	18.20	? 25	13.65	0.96	14.61
74146-TEA-T00	RUBBERHOOD SEAL	1	27.60	? 25	20.70	1.45	22.15
91504-TBA-A01	CLIP,HOOD SEAL	6	0.50	? 25	2.25	0.16	2.41



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLZ744H

Chassis No : MRHFC5650JT000514

Model : CIVIC 1.6 VTI YM2018

Owner's Name : ONG CHEE HIAN

Ins Policy No. :

Date of Accident : 5/1/2019

Document No. : SQT19000115 Page 2

Date : 7. Jan 2019

Customer No. : WZA006

Svc Advisor : LIM CHOU SIONG

Engine No : R16B25500575

Date | Time : 7. Jan 2019 9:05:52 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
75700-TBA-A00	EMBLEM	1	15.00	25	11.25	0.79	12.04	
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37	
33100-TEC-Q01	HEADLIGHT ASSY,R.	1	585.70	25	439.27	30.75	470.02	
34300-TET-H01	LIGHT ASSYR.SIDE TURN	1	33.10	25	24.82	1.74	26.56	
80050-TG7-000	LABLE AIR CON	1	0.80	25	0.60	0.04	0.64	
19043-5AA-E00	LABEL, COOLANT INFORMATION	1	10.00	25	7.50	0.53	8.03	
74101-TEA-T00	FENDERR.FR.INNER	1	51.10	25	38.32	2.68	41.00	
90682-SEA-003	CLIP ABUMPER	2	2.60	25	3.90	0.27	4.17	
91501-TR0-003	CLIP,INNER FENDER	11	2.80	25	23.10	1.62	24.72	
71410-TEA-T01	BULKHEAD ASSYFR.	1	525.90	25	394.42	27.61	422.03	
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	3	23.20	25	52.20	3.65	55.85	
77930-TEA-B11	SENSOR ASSYFR.CRASH	1	71.40	25	53.55	3.75	57.30	
76841-TEA-T01	TANKWASHER	1	26.40	25	19.80	1.39	21.19	
76842-S2K-J11	BRUSH WASHER TANK	1	3.90	25	2.92	0.20	3.12	
76846-TA0-A02	PUMP SETWASHER	1	61.00	25	45.75	3.20	48.95	
38100-TBA-A01	HORN ASSYLOW	1	30.80	25	23.10	1.62	24.72	
38101-TBA-A01	BRACKETHORN	1	12.60	25	9.45	0.66	10.11	
38150-TBA-A01	HORN ASSY	1	30.80	25	23.10	1.62	24.72	
					Sum Item	2456.65	171.97	2,628.62
BO-NUM-SEAL	SEAL NUMBER PLATE.	1	80.00		80.00	5.60	85.60	
					Sum Ext. Service	80.00	5.60	85.60
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50	
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	80.00		80.00	5.60	85.60	
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	200.00		200.00	14.00	214.00	
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	280.00		280.00	19.60	299.60	
BMS00R	RENEW FR R CRASH SENSOR & RESET SRS SYSTEM. (N)	1	560.00		560.00	39.20	599.20	
BKBH01M	CUT OFF & RENEW FR R EXTENSION SET, STRAIGHTEN	1	2100.00	1120	2100.00	147.00	2247.00	

Printed on 8/1/2019 6:45:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

