

## **CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED** PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE** 

Co Reg No : 197701469G

(GAO SHUNCAI)

SINGAPORE 682812

#14-641

Invoice Name & Address

Contact No Mobile: 96967755

GST Reg No : MR-8500111-X Owner Name & Vehicle Info /MR KOE SOON CHYE ANDREW JOSEPH Cust No/Name MR KOE SOON CHYE ANDREW JOSEPH Reg No/Reg Date SLW2327G / 01/02/201 APT BLK 812B CHOA CHU KANG AVE 7 Date In/Mileage MMBSTA13AJH001045 Chassis No Engine No 3A92UGP4257 MIT/18MY ATTRAGE 1.2 CVT Make/Model Colour/Trim PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time P	rinted	CSE	Operator		WIP No	
SM00041	Cash	08/01/2019	/ 14:32	BLC	442 / CocoLu		34990.	
		Description	of Goods	/ Services		Qty l	Jnit Price Dis	
PNT98000 SPRAY PA 54900099 CHECK WI 54900099 CONDUCT WHEELALIG TO CONDUCT SUNDRY TRRANSFE SUNDRY SUNDRY SUNDRY FACE,FR BRACKET, GARNISH,	AINT FOR I	R,LH R,LH	FRT FENDE STEM THE CAR Wheel Alf	R LH, WIND SYSTEM	MIRROR LH	1.00 1.00 1.00 1.00 1.00	696.00 00 13.00 00 126.00 00 458.00 00 632.00 00 680.00 00	.00 13.0 .00 126.0 .00 458.0 .00 632.0
Confirm &	accepted b	ру				7% GST on	Nett 5905.00	5,905. 413.
						·T^+	al Payable	6,318.3
						106	er talants	n'2TO''

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.