

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0019/2018
DATE : 08-JAN-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MISS SWEE LI LI ELAINE (SUN LILI)
ADDRESS : BLK 861 WOODLANDS ST 83
#08-174
S(730861)
TELEPHONE NO : 97973661

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SKU8396P
VEHICLE NO : SLW3257T
MODEL CODE : TDWARDZE12EDAY487Z
MODEL/YEAR : NOTE 1.2 BASE (IV) MY2017
ENGINE NO : HR12277701B
CHASSIS NO : JN1TAAE12Z0980216
MILEAGE : 1 KM
DATE IN : 08/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 28/12/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

Tan Chong 97973661
up
16/1/19 @ 11.20
Resurvey before part
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sure like auto

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLW3257T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	?
4	ZZ/001	REPAIR FRT UPPER PANEL RENEW FRONT BUMPER	375.00	250.
5	ZZ/002	S/PAINT FRONT BUMPER & FRONT UPPER PANEL	400.00	200.
TOTAL LABOUR CHARGES			995.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW3257T

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 CLIP(7.4X2)	01554-0007U	14.80	?	
2 BRACKET-BUMPER RH	62224-3VA0A	24.00	i	
3 BRACKET-BUMPER LH	62225-3VA0A	23.00	ae	
4 EMBLEM RAD GRIL	62890-3VA0A	59.70	ae	
5 GRILLE-RADIATOR	62310-5WC0A	194.40	cut	
6 CLIP(10X1.2)	01553-05933	12.00	ae	
7 FACE-FR BUMPER	62022-5WJ0H	354.90	ae	
8 FRT LICENCE PLATE	FLP		bt	60.00
SUB TOTAL		682.80	0.00	60.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		136.56	0.00	0.00
GRAND TOTAL		546.24	0.00	60.00
OVERALL TOTAL		606.24		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLW3257T

TOTAL LABOUR CHARGES	995.00
TOTAL SPARE PARTS CHARGES	606.24
GRAND TOTAL	1601.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.