

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : XE3278K
Accident Date : 04-Jan-2019

No. : 05903

Date : 05-Jan-2019

Our Ref : 219002 (AXA) / CHAN

PAGE : 1

THAM WAI LOONG
BLK 90 DAWSON ROAD
#38-10
Singapore 142090

Not Authorized
11 Days @ ?
Resurvey After Paint

ESTIMATED COST OF REPAIR FOR NISSAN CEFIRO 2.0A SGE1577L

10 days

1 pc	Front o/s door		<i>Ry</i> 1,215.30	n	✓
1 pc	Front o/s door rubber		145.40	n	?
1 pc	Front o/s door inner lock		382.70	n	?
1 pc	Front o/s door outer moulding		<i>Bur</i> 207.80	n	✓
1 pc	Front o/s door outer handle		<i>Red</i> 229.80	n	✓
1 pc	Frt o/s door press open sensor		<i>Red</i> 35.30	n	✓
1 pc	Front o/s door handle knob		<i>Red</i> 35.30	n	✓
2 pcs	Front o/s door handle seal	@ S\$ 10.00	<i>Red</i> 20.00	n	✓
1 pc	Front o/s door glass regulator gear		<i>Ry</i> 182.30	n	✓
1 pc	Front o/s door glass regulator motor		576.90	n	?
1 pc	Front o/s door lower protector		<i>Red</i> 187.40	n	✓
1 pc	O/s centre pillar		525.00	n	?
1 pc	Rear o/s door		<i>Ry</i> 1,215.30	n	✓
1 pc	Rear o/s door rubber		<i>Got</i> 145.40	n	<i>50% @ Ry</i>
1 pc	Rear o/s door inner lock		<i>Ty</i> 382.70	n	✓
2 pcs	Rear o/s door hinge	@ S\$ 95.80	191.60	n	?
1 pc	Rear o/s door lower protector		<i>Red</i> 187.40	n	✓
1 pc	Rear o/s door outer moulding		<i>Bur</i> 207.80	n	✓
1 pc	Rear o/s door outer handle		<i>Red</i> 105.80	n	✓
1 pc	Rear o/s door handle knob		<i>Red</i> 35.00	n	✓
2 pcs	Rr o/s door outer handle seal	@ S\$ 10.00	<i>Red</i> 20.00	n	✓
1 pc	Rear o/s door glass regulator gear		<i>Ry</i> 103.60	n	✓
1 pc	Rear o/s door glass regulator motor		634.60	n	?
1 pc	Rear o/s fender		<i>Ry</i> 989.40	n	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : XE3278K

Page : 2

1 pc Rear o/s fender inner panel
 1 pc Rear w/s glass moulding
 1 pc Rear o/s fender inner shield

m 415.60 n ?
 130.90 n ✓
 245.60 n ?

 8,753.90

Less 10% : 875.39

7,878.51

1 pc O/s rocker garnish
 1 pc Rear o/s quater glass moulding
 1 pc Rear o/s shock absorber
 1 pc Rear o/s thrust arm
 1 pc Rear o/s lower arm
 1 pc Rear o/s top arm
 1 pc Rear o/s training arm
 1 pc Rear o/s knuckle arm
 1 pc Rear w/s glass sealant
 1 pc Rear o/s tyre
 1 pc Rear o/s sport rim

midy m 343.00 sn ?
 961.40 sn ✓
 180.40 sn ?
 134.70 sn ?
 413.70 sn ?
 316.60 sn ?
 98.70 sn ?
m 363.50 sn ✓
m 60.00 sn 400.
 @140 *m* 300.00 sn 600.
m 400.00 sn ✓

To towing

(Bill) 120.00 ?

To remove & refix rear windscreen
 glass and conduct water leak test.

150.00 1200

To remove roof lining, front and
 rear seats, trim board and carpet

120.00 1000

To apply undersealing

100.00 900

To dismantle and lower rear
 undercarriage

250.00 1800

To check and adjust wheel alignment

65.00 600

To putty and spray replaced parts

1,300.00 10000

Con't Page 3 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : XE3278K

Page : 3

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1000
1,400.00

Total : S\$14,955.51

Singapore Dollars Fourteen Thousand Nine Hundred
and Fifty Five and Cents Fifty One Only