



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



FIRST CAPITAL INSURANCE LIMITED		NAME :		Mr Gwee Aik Chiong		WIP :		39755			
		ADDRESS :		23 Highland Road Singapore 549114		EXCESS :					
						DATE:		7-Jan-19			
ATTN. :		MOTOR CLAIMS		TEL :		97855198					
FAX :											
VEH NO :		SLC9528C		DATE IN :				CONTACT PERSON :		TOMMY/JESS	
CHASSIS NO :		JM6GJ1072G0237798		MILEAGE :				TYPE OF CLAIM :		THIRD PARTY CLAIM	
MODEL :		MAZDA6		DATE REG.:		30-May-16		POLICY NO. :			

NATURE OF WORKS

Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER	1	MGMN3-50-031CBB	\$ 1,154.10	\$ 1,154.10
2	RETAINER LHS	1	MGHP9-50-0U1C	\$ 14.00	\$ 14.00
3	CHROME LHS, FOGLAMP	1	MG46L-50-C22		\$ 97.00
4	COVER(L),HOLE-LAMP GJ/GL	1	MG46L-50-C21A		\$ 21.60
5	TOWING COVER	1	MG46L-50-A11 BB	\$ 31.80	\$ 31.80
6	MESH, FRONT BUMPER	1	MG46L-50-1T1A		\$ 73.30
7	FOAM, FRONT REINFORCEMENT	1	MGHP9-50-111	\$ 73.30	\$ 73.30
8	FASTENER, FOAM	2	MFD01-68-AC3		\$ 11.80
9	FRONT REINFORCEMENT	1	MGHP9-50-070A		\$ 552.00
10	CLIP, FRONT BUMPER	6	MC274-50-133	\$ 21.00	\$ 21.00
11	FASTENER, FRONT BUMPER	2	MB45A-56-146A	\$ 5.60	\$ 5.60
12	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	\$ 5.40	\$ 5.40
13	RIVET, FRONT BUMPER	6	MGHP9-50-355	\$ 27.60	\$ 27.60
14	RIVET, FRONT BUMPER	8	MS51S-51-833	\$ 30.40	\$ 30.40
15	FASTENER, FRONT BUMPER	6	MGD7A-50-EA1	\$ 18.00	\$ 18.00
16	CHROME LHS	1	MG46L-50-7K1	\$ 137.70	\$ 137.70
17	BRACKET LHS, CHROME	1	MG46L-50-161		\$ 35.40
18	CLIP, CHROME	1	MGHP9-50-EB1A		\$ 3.20
19	PROTECTOR LHS, CHROME	1	MG46L-50-B51	\$ 50.10	\$ 50.10
20	FRONT FENDER LHS	1	MGHP9-52-211A	\$ 365.40	\$ 365.40
21	STAY LHS, FENDER	1	MGHP9-52-240D		\$ 46.00
22	MUDGUARD LHS	1	MGHP9-56-140J		\$ 98.00
23	FASTENER, MUDGUARD	17	MB45A-56-146A	\$ 47.60	\$ 47.60
24	HEADLAMP LHS	1	MGML8-51-041E	\$ 3,209.30	\$ 3,209.30
25	CORD SHORT, HEADLAMP	1	MGMG9-51-0K6		\$ 201.30
26	CLIP, HEADLAMP	2	MFB01-50-133C	\$ 7.60	\$ 7.60
27	RIVET, HEADLAMP	1	MB092-51-833	\$ 3.30	\$ 3.30
28	FRONT GRILLE	1	MG46L-50-712A	\$ 114.80	\$ 114.80
29	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A		\$ 5.40
30	GROMMET, FRONT GRILLE	2	MKD45-50-ES1		\$ 5.40
31	RIVET, FRONT GRILLE	2	MEA01-50-037		\$ 15.20

SUPPLEMENTARY ITEMS				
1	PLATE(L), SEAL	1	GHP9 56 253	\$ 30.70 \$ 30.70
2	PLATE, SET	1	G46L 50 1C0A	\$ 72.70 \$ 72.70
3	UNIT (R) , HEADLAMP	1	GML8 51 031E	\$ 3,209.30
			TOTAL PARTS	\$ 5,420.40 \$ 9,795.30
			LESS 10%	\$ 542.04 \$ 979.53
			TOTAL PARTS COST	\$ 4,878.36 \$ 8,815.77
Labour Description				
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER LH. TO REPAIR PANEL SHROUD LH AND ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 1,320.00 \$ 1,980.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER, PANEL SHROUD LH AND FRONT FENDER LH.		\$ 1,260.00 \$ 1,890.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 100.00 \$ 250.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 120.00 \$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 150.00 \$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.		\$ 30.00 \$ 100.00
			TOTAL LABOUR	\$ 2,980.00 \$ 4,820.00
			TOTAL PARTS	\$ 4,878.36 \$ 8,815.77
			TOTAL	\$ 7,858.36 \$ 13,635.77
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 7,858.36
			GST 7%	\$ 550.09 \$ -
			GRAND TOTAL	\$ 8,408.45 \$ -

REMARKS:

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)