



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2015 RENAULT FLUENCE 1.5 DCI (SKR5916A)
Date of Loss	31 December 2018
Time of Loss	11.50
Loss Description	SKR5916A (INSD) C/W GW7517B (TP)
Comment	

Workshop Details

Total Rebate Amount	41670
Nett Loss Amount	\$6,330.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	117



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SKR5916A

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

23/02/2015



Mileage

64814

Age of Vehicle

3

Driver Details

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2015

2014

Make

RENAULT

RENAULT

Model

FLUENCE 1.5 DCI

FLUENCE 1.5L DCI

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

SAMMANDA
VIVEKANANDAN

Date of Birth

25 August 1953

dd/mm/yyyy



Age

65

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	VF1LZLF0E52015791	VF1LZLF0E520157
Engine No	K9KN837D173649	K9KN837D173649
Engine Capacity		1461
Sum Insured	0	0
Market Value	0	48000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	26	
Driver License #		
License Type		
License Issue Date		dd/mm/
License Expiration Date		dd/mm/
Address	662B JURONG WEST STREET 64, #05-324, 642662, Singapore	
Address type	Residential	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Married	
Identification #	S2647719J	



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

10/01/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/60R16

Rear Tyre Size

205/60R16

Front left side

GOODYEAR6mm

Rear left side

GOODYEAR6mm

Front right side

GOODYEAR6mm

Rear right side

GOODYEAR6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add Approve Deny Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			L/R DOOR			Repair	0	0	0	0	0	Deny	
		2	1			REAR BUMPER (WCP) (10%)			Deformed	715				715	Reviewing	
		3	1			L/R BUMPER BRACKET (WCP) (10%)			Necessary	66				66	Reviewing	
		4	1			R/R BUMPER BRACKET			Serviceable	0	0	0	0	0	Deny	
		5	1			RR BUMPER CLAMP KIT (WCP) (10%)			Necessary	33				33	Reviewing	
		6	1			REAR SCREEN BOND KIT (NPA)			Necessary	0				0	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		7	1			SET REAR SCREEN FIX (NPA)			Necessary	0				0	Reviewing	
		8	1			REAR SCREEN SPACER (NPA)			Necessary	0				0	Reviewing	
		9	1			L/R OUTER LAMP			Serviceable	0	0	0	0	0	Deny	
		10	1			L/R INNER LAMP			Serviceable	0	0	0	0	0	Deny	
		11	1			L/R SIDE PANEL (WCP) (10%)			Bent	1408				1408	Reviewing	
		12	1			L/R WHEEL (WCP) (10%)			Cut	605				605	Reviewing	
		13	1			R/R WHEEL (NPA)			Serviceable	0	0	0	0	0	Deny	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		ANTI-RUST	40	0	0	Reviewing		
		2		224.0 WU X 45.00 SGD/H	1179	0	0	Reviewing		
		3		LABOUR COST 72.0 WU X 45.00 SGD/H	351	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		4		MATERIAL COST	93.57	0	0	Reviewing		



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR :
8 DAYS

Reviewing



2

BODY
SEALANT

Reviewing

80

NECESSARY



3

SEALANT

Reviewing

40

NECESSARY



4

BODY
SEALANT

Deny

0

NOT NECESSARY



5

REAR LH
TYRE
(\$250.00)
(80%)

Reviewing

200

CUT



EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		6	L/REAR FENDER UNDER LINER (WCP) (10%)	Reviewing	214.5	DEFORMED (SUPPLEMENTARY)	
		7	REVERT L/SIDE BRACKET REAR BUMPER- 4PCS (WCP) (10%)	Reviewing	13.2	NECESSARY (SUPPLEMENTARY)	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$4,638.27

Claim Amount

\$4,638.27

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$2,827.00	\$2,827.00
Labour	\$1,663.57	\$1,663.57
Miscellaneous	\$547.70	\$547.70
Excess	-\$400.00	-\$400.00

Submit for Review