

ASS. REC. BY:

REF: CS/EGII9000532/T1td3/n2

Special Instruction:

Surveyor: Tauhikh

ASSIGNMENT (Office)

From (Person): SA A'fikah

of EGF

Date/Time: 9/11/19 @ 1.44pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD1081T

Insured: SJC 965G

at Workshop m/s Premier Automotive

Tel: 6544 6676

of 23 Cheringi South Ave 2 # 01-02

Policy No:

Claim No: SJC 965G / 8L / SA

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 09/01/2019

CA / REV / REP. / REV 24 HRS ^{1up}

H.O.D. Endorsement:

Date/Time: 2.02pm @ 9/1/19

Person Contacted: Beny

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD1081T-CC3/AXA13069350/M/pb3c3 <u>Surf: 23/5/13</u>
	SJC 965G-X
	<u>10/1/2019 @ 5:34pm REVERT VIA PREU ADVISE EMAIL</u>

Signature

Taylor

REF:

EG1

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3-Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD 1081 T Yr Regn: 2015, Oct.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Kia Optima C.C. 1685
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 504894 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNA Gm 414MF 563 9175
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Bm / STD A/Rim or
 Tyre Size: F: 205/60R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Achilles
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 9/1/19
 Survey held at Premier
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

lump sum \$5000/- (red: 3901.30: 43%)

RECEIVED 18 FEB 2019

Date/Time: File Pass to? : Prel. Report
 : Final Report
 1) 15/2 Typist
 Date/Time: File Return to?

Days Of Repair: 6
 Resurvey No. of Trip: 1

Survey Fee:	
Transportation	
\$ + RS. St	
Photos	
Others	
TOTAL	250

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Invs (\$)
 Weekend (\$)

Report Format: TP
 Lump Sum / I.B.I: (\$ 5000/-)

Nivitha (LKK Auto)

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Wednesday, 9 January 2019 1:44 PM
To: admin-d@lkkauto.com
Cc: sur@lkkauto.com; Survey Report (ERGO Insurance Pte. Ltd.); Steve Lim
Subject: PRS IRO SHD1081T | OI : SJC965G | DOA: 09/01/19 | ERGO REF: SJC965G/SL/sa
Attachments: 09012019130411-0001.pdf

Hi LKK,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company to be the "Single Joint Expert".

Please conduct this survey request on without prejudice basis and to try finalise with the repairer on the repairs.
(Note: No repair estimate was provided to us and our driver has not lodge the accident report to us)

Attached are the necessary documents for your further actions.

Kindly acknowledge receipt of this email.

Thank you

Siti Athikah
Claims Department

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 338985
DID: +65 6820 9170
Siti.Rahman@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Gary Shi [<mailto:gary.shi@premiertaxi.com>]
Sent: Wednesday, 9 January, 2019 1:21 PM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Cc: Goh Wee Dek; Vincent Chua
Subject: Pre-inspection / Accident involving SHD1081T & SJC965G on 09.01.19

Dear all,

We refer to the above mentioned.

Kindly arrange for survey.

****We prefer LKK Auto as the SJE.**

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. **SAVE OUR TREES and REDUCE POLLUTION**

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	16 Oct 2015 / 09:11:42	Receipt No.:	AACCK001-AX239-151016-000015
Asset Type:	Vehicle	Transaction Amount:	\$68,676.00
Asset ID:	SHD1081T	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151016091142543641		

Vehicle No.:	SHD1081T
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	16 Oct 2015
Original Registration Date:	16 Oct 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5639175
Engine No.:	D4DFDH314131
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$22,212.00
Minimum PARF Benefit:	\$13,858.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	16 Oct 2015 09:11:42
COE No.:	2015101601003635H
COE Expiry Date:	15 Oct 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$45,439.00
Lifespan Expiry Date:	15 Oct 2023

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

ER60

9-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1081 T

1 pc	Boot lid	\$	1,119.00 <i>bt</i>
1 pc	Boot lid lock	\$	99.00 <i>bt</i>
1 pc	Bootlid lock cable	\$	35.00 <i>x nn</i>
1 pc	Bootlid striker	\$	21.00 <i>bl</i>
1 pc	Bootlid emblem	\$	27.00 <i>nc</i>
1 pc	Bootlid CRDi	\$	29.00 <i>nc</i>
1 pc	Boot lid rubber weatherstrip	\$	96.00 <i>hu</i>
1 pc	Boot lid lower garnish	\$	290.00 <i>de</i>
2 pcs	Bootlid hinges @ \$66.00	\$	132.00 <i>Rx</i>
1 pc	Bootlid inner trim	\$	190.00 <i>x nn</i>
1 pc	End panel	\$	250.00 <i>bl</i>
1 pc	End panel inner garnish	\$	74.00 <i>de</i>
1 pc	Rear bumper	\$	696.00 <i>de</i>
1 pc	Rear bumper lower cover	\$	206.00 <i>de</i>
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00 <i>nc</i>
1 pc	Rear bumper inner sponge	\$	114.00 <i>nc</i>
1 pc	Rear bumper reinforcement	\$	607.00 <i>nc</i>
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00 <i>x nn</i>
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00 <i>?x nn</i>
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00 <i>?x nn</i>
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00 <i>x nn</i>
2 pcs	n/s & o/s tail lamp @ \$421.00	\$	842.00
2 pcs	n/s & o/s reflector @ \$350.00	\$	700.00
		\$	5,857.00
	Less 10%	\$	585.70
		\$	5,271.30

S/NETT

1 set	Rear bumper clips	\$	48.00 <i>nc</i>
1 set	End panel inner garnish clips	\$	30.00 <i>nc</i>
1 set	Bootlid inner trim clips	\$	52.00 <i>x nn</i>
1 set	Bootlid lower garnish clips	\$	60.00 <i>nc</i>
1 set	Bootlid stickers	\$	100.00 <i>nc</i>
1 set	Reverse sensor	\$	280.00 <i>200mm</i>
1 pc	Rear bumper top protector	\$	80.00 <i>x nn</i>

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1081 T

Sundry <i>nc</i>	\$	50.00 ²⁰
Towing Fee	\$	50.00 ^{2 Party}
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 ³⁰
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 ⁴⁰
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, etc.	\$	1,200.00 ⁸⁰⁰
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel	\$	1,200.00 ⁸⁰⁰
To apply rustproofing on the repaired and replaced panels.	\$	180.00 ⁴⁰
		<hr/>
	\$	<u>8,901.30</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495449
"up"
Lumpsum
Resurvey after repair
tanpin@lkkauto.com
to Coleys.
9/1/19

CASH SALE/WORK ORDER

No:AD 4834



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 9.1.19

寶號 Premier

Messrs:

車號

Vehicle No:

SHD10817 車型

Model No:

OPTIMA

由

From:

Marine Terrace CKS1

到

To:

Omega

其他

Remark:

(1 key)

時間

Time:

03:27-04:09:44

AMOUNT: \$

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

收貨人

Received by:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI19000532/T1td3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 18-02-2019	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJC 965G	Veh. Inspected	SHD 1081T
Policy No.		Coverage (\$)	0.00
Claim No.	SJC965G/SL/sa	Excess (\$)	0.00
Assign From	SITI A'THIKAH	Assign Date	09/01/2019
2. Vehicle Particulars & Condition			
Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KNAGM414MF5639175	Colour	SILVER
Odometer	504894	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R15	ACHILLES	6 mm
L/H Front Tyre	205/60 R15	ACHILLES	6 mm
R/H Rear Tyre	205/60 R15	ACHILLES	6 mm
L/H Rear Tyre	205/60 R15	ACHILLES	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/01/2019	Inspection Date	09/01/2019
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1081T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	BENT	1,119.00	1,119.00
1	BOOT LID LOCK	BENT	99.00	99.00
1	BOOTLID LOCK CABLE	NOT NECESSARY	35.00	-
1	BOOTLID STRIKER	BENT	21.00	21.00
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	TWISTED	96.00	96.00
1	BOOT LID LOWER GARNISH	DEFORMED	290.00	290.00
2	BOOTLID HINGES @\$66.00	TO REPAIR SEE LABOUR	132.00	-
1	BOOTLID INNER TRIM	NOT NECESSARY	190.00	-
1	END PANEL	BENT	250.00	250.00
1	END PANEL INNER GARNISH	DEFORMED	74.00	74.00
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	DEFORMED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	NECESSARY	58.00	58.00
1	REAR BUMPER INNER SPONGE	CRACKED	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S	NOT NECESSARY	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	NOT NECESSARY	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	NOT NECESSARY	36.00	-
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	O/S CRACKED / N/S NOT NECESSARY	92.00	46.00
2	N/S & O/S TAIL LAMP @\$421.00	O/S CUT / N/S NOT NECESSARY	842.00	421.00
2	N/S & O/S REFLECTOR @\$350.00	O/S CRACKED / N/S NOT NECESSARY	700.00	350.00
	LESS 10% DISCOUNT		-585.70	-450.30
			5,271.30	4,052.70



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	SET BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	52.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NECESSARY	60.00	60.00
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NOT NECESSARY	80.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			700.00	458.00
LABOUR				
TOWING FEE.			50.00	50.00
TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.			120.00	30.00
TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.			180.00	40.00
TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FLOORBOARD COMPARTMENT, ETC. INCLUSIVE OF THE REPAIR OF BOOTLID HINGES.			1,200.00	800.00
TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, FLOORBOARD COMPARTMENT, END PANEL.			1,200.00	800.00
TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.			180.00	40.00
			2,930.00	1,760.00
GRAND TOTAL			8,901.30	6,270.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS/EGI19000532/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.