

ASS. REC. BY:

REF:

es/FCI19000537/Kvcb

P2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

May chuan

of

PEI

Date/Time: 11:31am @ 9/1/19

Estimated Cost:

Bill to:

OD (TP) WS / TT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8FQ 3797D

Insured:

SHA 3550J

at Workshop m/s:

Siong Jee Motor

Tel:

64531255

of

160 Sin Ming Drive # 02-07

Policy No:

Claim No:

D19000250MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/01/2019

CA / REV / REP. / REV 24 HRS

1wpl

H.O.D. Endorsement:

Date/Time:

12:01pm @ 9/1/19

Person Contacted:

Kwee pin

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

8FQ 3797D - CC3 / ATG10023548 / G1126

Jury: 15/11/10

SHA 3550J - CC3 / FCI17016387 / T1gbe2

Jury: 21/8/12

10/1/19

Email preli. revised to FCI

28/12

11 Rys @ 6:00 email & confirmed (Red 5179.15, 439)

ASS. REC. BY:

REF:

15021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKQ 37970

Yr Regn:

03, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Rush

c.c.

1495

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

203572

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

J2009

0012425

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/75R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

3/1/19

D.O.I.

9/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/1

File pass to Car

Note:

MV: \$22K (EST) LTA: \$15,108 NV: \$6892

RECEIVED 28 FEB 2019

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trlp:

2

Survey Fee:

Transportation:

S + P.S. \$

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

170 + 15

50

50 + 50

27

362

Report Format:

CWS

Lump Sum / I.B.I. (\$

6800/-



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000250MFSH

Our ref: CS/FCI19000537/Kvd3

Date : 10/1/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SFQ 3797D


We thank for your instruction on 9/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 9/1/2019 at the premises of M/s SIONG LEE MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$11,979.15
Revised Estimate Amount	: S\$6,808.80
"Check" Items Amount	: S\$2,974.04
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	08-01-2019	Our Ref No. D19000250MFSH
Accident Date	05-01-2019	Claim Type. Third Party
Insured Vehicle	SHA3550J	Third Party Vehicle. SFQ3797D
Survey Location	160 SING MING DRIVE #02-07 AUTOCITY	
Contact Person.	MR TAN / MS KWEE PIN	
Contact No.	6453 1255/ 64531255	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIONG LEE MOTOR	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 10 January 2019 1:24 PM
To: 'CWS Motor Claims'
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000250MFSH/1, SFQ 3797D
Attachments: SFQ 3797D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SFQ 3797D
Date of survey: 9/1/2019
Number of days : 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 9 January 2019 12:05 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000250MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 9 January 2019 11:31 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000250MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

Approval
Email

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3709D
Vehicle Details	
Vehicle No.:	SFQ3797D
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	RUSH 1.5 A
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	3SZ1798292
Chassis No.:	J200E0012725
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,471.00
Original Registration Date:	22 Mar 2007
First Registration Date:	22 Mar 2007
Transfer Count:	2
Actual ARF Paid:	\$18,119.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Mar 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$24,715.00
COE Rebate Amount:	\$15,108.00
Total Rebate Amount:	\$15,108.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 Feb 2019

OK



松 利 摩 哆
SIONG LEE MOTOR

Sin Ming AutoCity
160 Sin Ming Drive #02-07 Singapore 575722
Tel: 6457 0410, 6453 1255 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

7 January 2019

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: LIM TECK LYE

H/P: 9877 9457

Dear Sirs / Madam,

Accident Claim for Vehicle No.SFQ 3797 D , Involving Vehicle No.SHA 3550 J.
Accident on 05 JANUARY 2019, AT POTONG PASIR AVE 1 - BLK 122

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	HEADLAMP <i>Mg cm</i>	2PCS	\$ 1,503.80
2	FRONT BUMPER	1PC	\$ 557.90
3	FRONT BUMPER RETIANER	2PCS	\$ 120.20
4	FRONT BUMPER REINFORCEMENT	1PC	\$ 761.90
5	FRONT BUMPER FOG LAMP - RH	1PC	\$ 382.90
6	FRONT BUMPER FOG LAMP COVER - RH	1PC	\$ 108.10
7	FRONT BONNET	1PC	\$ 1,282.60
8	FRONT BONNET HINGES <i>c/s dir</i>	2PCS	\$ 99.70 199.40
9	FRONT BONNET INSULATOR <i>sn</i>	1PC	\$ 258.30
10	FRONT BONNET GRILLE <i>red</i>	1PC	\$ 571.70
11	FRONT BONNET GRILLE BADGE <i>sn</i>	1PC	\$ 35.00
12	FRONT BONNET LOCK <i>Bz</i>	1PC	\$ 148.90
13	FRONT BONNET LOCK PILLAR <i>Bz</i>	1PC	\$ 126.40
14	FRONT SUPPORT PANEL <i>SFQ-45</i>	1PC	\$ 1,221.60
15	FRONT SUPPORT PANEL SIDE GARNISH <i>o/s cm</i>	2PCS	\$ 91.70 183.40
16	HORN <i>sn</i>	1PC	\$ 130.70
17	AIRCON CONDENSOR	1PC	\$ 1,401.90
18	AIR CLEANER HOSE <i>sn</i>	1PC	\$ 195.80
19	RADIATOR	1PC	\$ 1,553.75
20	RADIATOR SPARE TANK <i>sn</i>	1PC	\$ 298.40
21	RADIATOR FAN COWLING <i>sn</i>	1PC	\$ 260.94
22	FRONT FENDER - RH <i>Bz</i>	1PC	\$ 482.75
23	FRONT FENDER COWLING- RH <i>sn</i>	1PC	\$ 187.60

Not Authorized!
Lim & 8000: Max
Recovery After Repair
6 days

	TOTAL LIST PRICE		\$ 11,973.94
	LESS 20%		\$ (2,394.79)
	TOTAL AMOUNT		\$ 9,579.15

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	FRONT NUMBER PLATE <i>Red</i>	1PC	\$ } 45 <i>Red</i> 30.00
2	FRONT NUMBER PLATE CASING	1PC	\$ } 45 <i>Red</i> 30.00
3	FRONT BONNET INSULATOR CLIPS <i>Red</i>	1SET	\$ ✓ 40.00
4	COOLANT <i>Red</i>	1BOT	\$ } 20 <i>Red</i> 60.00
	TOTAL SPECIAL NETT PRICE		\$ 160.00

	LABOUR :		
1	LABOUR TO SPRAY PAINT	\$	800 <i>Red</i> 1,000.00
2	LABOUR TO PANEL BEATING	\$	700 <i>Red</i> 980.00
3	LABOUR TO FOCUS HEADLAMP	\$	20 <i>Red</i> 40.00
4	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS	\$	90 <i>Red</i> 100.00
5	LABOUR TO DISMANTLE AND REFIX AIRCON COOLING SYSTEM FOR REPLACE AIRCON PARTS.	\$	100 <i>Red</i> 120.00
	TOTAL LABOUR	\$	2,240.00
	TOTAL AMOUNT	\$	11,979.15

THANK YOU

FROM:
SIONG LEE MOTOR
 Mr Tan Leng Huat

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19000537/Kvd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 01-03-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3550J	Veh. Inspected	SFQ 3797D
Policy No.		Coverage (\$)	0.00
Claim No.	D19000250MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	09/01/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA RUSH (A)	c.c	1495
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	J200E0012725	Colour	METALLIC GREY
Odometer	203572	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/65 R16	TOYO	7 mm
L/H Front Tyre	215/65 R16	TOYO	7 mm
R/H Rear Tyre	215/65 R16	TOYO	7 mm
L/H Rear Tyre	215/65 R16	TOYO	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/01/2019	Inspection Date	09/01/2019
Survey held at	160 SIN MING DRIVE# 02-07		
Repairer	SIONG LEE MOTOR		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFQ 3797D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	HEADLAMP	MTG CRACKED	1,503.80	1,503.80
1	FRONT BUMPER	BENT	557.90	557.90
2	FRONT BUMPER RETAINER	DISTORTED	120.20	120.20
1	FRONT BUMPER REINFORCEMENT	BUCKLED	761.90	761.90
1	FRONT BUMPER FOG LAMP-RH	SERVICEABLE	382.90	-
1	FRONT BUMPER FOG LAMP COVER-RH	SERVICEABLE	108.10	-
1	FRONT BONNET	BENT	1,282.60	1,282.60
2	FRONT BONNET HINGES	O/S DISTORTED	199.40	99.70
1	FRONT BONNET INSULATOR	SERVICEABLE	258.30	-
1	FRONT BONNET GRILLE	DENTED	571.70	571.70
1	FRONT BONNET GRILLE BADGE	NECESSARY	35.00	35.00
1	FRONT BONNET LOCK	BENT	148.90	148.90
1	FRONT BONNET LOCK PILLAR	BENT	126.40	126.40
1	FRONT SUPPORT PANEL	BUCKLED	1,221.60	972.45
2	FRONT SUPPORT PANEL SIDE GARNISH	O/S CRACKED	183.40	91.70
1	HORN	SERVICEABLE	130.70	-
1	AIRCON CONDENSOR	BENT / PUNCTURE	1,401.90	1,401.90
1	AIR CLEANER HOSE	SERVICEABLE	195.80	-
1	RADIATOR	HOUSING CRACKED	1,553.75	1,553.75
1	RADIATOR SPARE TANK	SERVICEABLE	298.40	-
1	RADIATOR FAN COWLING	SERVICEABLE	260.94	-
1	FRONT FENDER-RH	BUCKLED	482.75	482.75
1	FRONT FENDER COWLING-RH	SERVICEABLE	187.60	-
	LESS 20% DISCOUNT		-2,394.79	-1,942.13
			9,579.15	7,768.52
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN) }	DENTED	30.00	45.00
1	FRONT NUMBER PLATE CASING (SN) }	DENTED	30.00	-
1	SET FRONT BONNET INSULATOR CLIPS (SN)	NECESSARY	40.00	40.00

Report Ref No. CS/FCI19000537/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOT COOLANT (SN)	NECESSARY	60.00	20.00
			160.00	105.00
	<u>LABOUR</u>			
	LABOUR TO SPRAY PAINT.		1,000.00	800.00
	LABOUR TO PANEL BEATING.		980.00	700.00
	LABOUR TO FOCUS HEADLAMP.		40.00	20.00
	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS.		100.00	90.00
	LABOUR TO DISMANTLE AND REFIX AIRCON COOLING SYSTEM FOR REPLACE AIRCON PARTS.		120.00	100.00
		2,240.00	1,710.00	
GRAND TOTAL			11,979.15	9,583.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,800.00

Report Ref No. CS/FCI19000537/Kvd3n2

MARKET VALUE: \$22,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$15,108.00=NETT VALUE: \$6,892.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.