

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5799K

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

PART

- | | |
|---|-----------------------------|
| 1 | FENDER PANEL FRT LH |
| 1 | WHEELARCH FRT LH |
| 1 | FENDER BRACKET LOWER LH |
| 1 | FENDER INSULATOR LH |
| 1 | DOOR PANEL FRT LH |
| 1 | DOOR HINGE UPPER LH |
| 1 | DOOR HINGE LOWER LH |
| 1 | DOOR CHECK FRT LH |
| 1 | DOOR LOCK FRT LH |
| 1 | DOOR CATCH FRT LH |
| 1 | DOOR HANDLE OUTER FRT LH |
| 1 | DOOR HANDLE COVER FRT LH |
| 1 | DOOR HANDLE MODULE FRT LH |
| 1 | DOOR REGULATOR FRT LH |
| 1 | DOOR REGULATOR MOTOR FRT LH |
| 1 | DOOR REGULATOR GUIDE FRT LH |
| 1 | DOOR MIRROR ASSY LH |

SHC 5799K

VF1ABL15AUC281407

RENAULT

LATITUDE

6.1.2019

EQ

6/3/2015

LIST

\$	B ₁ 783.83 ✓
\$	S ₂ 278.84
\$	S ₂ 15.79
\$	S ₂ 130.84
\$	N 2,844.66
\$	N 261.28
\$	N 300.55
\$	S ₂ 194.77
\$	N 908.75
\$	S ₂ 131.23
\$	S ₂ 477.76
\$	S ₂ 13.22
\$	S ₂ 133.60
\$	S ₂ 505.19
\$	S ₂ 796.46
\$	S ₂ 120.97
\$	S ₂ 1,483.40

\$	9,381.15
----	-----------------

10% \$	938.11
--------	---------------

\$	8,443.03
----	-----------------

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	N ₂ 80.00 60% ✓
1	FRONT DOOR STICKER 'Chassis'	\$	N ₂ 50.00 15% ✓
1	DOOR CHECK BOLT	\$	S ₂ 22.69 X
1	DOOR GUIDE SCREW	\$	S ₂ 10.85 X
1	DOOR HINGE BOLT	\$	S ₂ 10.85 X

Trans-cab Auto Services Pte Ltd**AAD1901-041**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5799K

1	DOOR HINGE NUT RH	\$	S _L 14.60	}	X
1	DOOR CHECK BOLT	\$	S _L 22.69		
1	DOOR CHECK NUT	\$	S _L 3.75		
1	DOOR LOCK SCREW L70Y	\$	S _L 6.12		
1	DOOR CATCH SCREW L70Y	\$	S _L 10.06		
1	FRONT LEFT TYRE	\$	S _L 330.00		
1	FRONT LEFT TYRE RIM	\$	S _L 380.00		

TOTAL \$ 941.63**TOTAL PARTS \$ 9,384.66****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	300/
Putty and spray painting of the affected portion.	\$	3,000.00	440/
To rust-proofing of the affected areas.	\$	170.00	30/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	~ X
To check steering geometry and computer wheel alignment	\$	220.00	~ X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00	~ X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ X
To Check Electrical Lighting Concerned.	\$	170.00	15/
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	~ X

Trans-cab Auto Services Pte Ltd**AAD1901-041**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5799K

To transfer of front door fittings, attachment and
perform water seepage test.

\$ *~* 380.00 X**TOTAL \$ 8,250.00****Over All Total \$ 17,634.66****LUMP SUM (REPAIR DAY)****~~10~~ DAYS***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: