

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

4, Jan 2019

China Taiping Insurance (S)PL
105 Cecil Street #18-00
The Octagon S 069534

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: YN7390H
Accident involving vehicle no: SME1729U/YN7390H
DOA: 02/01/2019 AT PIE twds City On left lane twds PIE

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SME1729U

Description	Qty	Amount
Lid	1	610.40 ✓
Lid reflector @202.30	2	404.60 ✓
Lid-1.8 emblem	1	24.50 ✓
Lid-H logo	1	24.70 ✓
Lid-I VTec emblem	1	33.50 ✓
Lid lock	1	194.00 X
Lid hinge @62.60	2	125.20 X
End panel	1	300.80 ?
End panel top garnish	1	66.00 ?
Boot weatherstrip	1	107.00 50% @53.50
Exhaust tailpipe	1	656.00 X
Exhaust mounting @42	2	84.00 X
Taillamp @308	2	616.00 ✓
Spare tyre panel	1	536.50 X
Tool compartment	1	194.00 X
Spare tyre board	1	172.00 X
Rear bumper	1	635.00 ✓
Rear bumper retainer @28	2	56.00 ✓
Parts		4,840.20
Parts less 20%		968.04
		3,872.16

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not within
11 days &?
Resurvey After Paint
5 days*

Vehicle no: SME1729U

Reverse sensor

SL 220.00 X

To remove damaged parts and attachments.

Cut n weld damaged panel.

Straighten rear chassis .

Repair/reshape dented/damaged areas.

To replace/realign all parts into position.

1,100.00 7501

To spray paint.

800.00 7201

5,992.16