

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJY4859M/1901004

08th January 2019

The Manager
 Motor Claim Department
 AIG Asia Pacific Insurance Pte Ltd
 CHARTIS Building
 78 Shenton Way #07-16
 Singapore 079120

Not Acc'd
 hll
 2/5
 6 dy.
 10/1/19
 To highlight the repair

Date of Accident : 08th January 2019
 Location : Ubi Road 2
 Third Party Claim Vehicle No : SKJ 2323 Y
 Repair Cost For Vehicle No : SJY 4859 M Porsche 911 Carrera

Estimate Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>	
1	Front door assy RH	1	3,220.00	\$ 3,220.00	✓
2	Front door w/strip RH	1	485.00	\$ 485.00	✓
3	Rear fender RH	1	4,000.00	\$ 4,000.00	✓
4	Rear fender sticker RH	1	123.00	\$ 123.00	✓
5	Rear fender quarter glass with moulding RH	1	580.00	\$ 580.00	X
6	Rear knuckle arm RH	1	385.00	\$ 385.00	?
7	Rear lower arm RH	1	1,130.00	\$ 1,130.00	X
8	Rear upper arm RH	1	650.00	\$ 650.00	X
9	Rear control arm RH	1	484.00	\$ 484.00	?
10	Rear wheel hub RH	1	613.00	\$ 613.00	?
11	Rear wheel bearing RH	1	210.00	\$ 210.00	?
12	Rear stabilizer bar	1	613.00	\$ 613.00	X
13	Rear stabilizer bar link	1	100.00	\$ 100.00	X
14	Rear shock absorber RH	1	1,400.00	\$ 1,400.00	X
15	Rear quarter glass sealant (s/net)	1	60.00	\$ 60.00	40
16	Rear wheel rim RH (s/net)	1	4,450.00	\$ 4,450.00	2800
17	Rear wheel tyre RH (s/net) LP400	1	1,200.00	\$ 1,200.00	600
				<u>\$19,703.00</u>	

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJY4859M/1901004

08th January 2019

Balance b/f \$19,703.00

Labour Charges :-

Amounts

Cut out, renew, knocking & welding front door assy RH, rear fender RH, remove & install all damage parts & re-align body	\$ 2,200.00	1200
Remove & install front door glass, door board, lock & etc	\$ 280.00	100
Remove & install rear quarter glass	\$ 120.00	80
Tuff-kote on damage parts	\$ 80.00	✓
Computerise wheel alignment	\$ 280.00	120
Spray painting on damage parts	\$ 1,980.00	1000
Remove & install rear seats, carpets, riif upholstery & etc	\$ 480.00	200
Remove & replace rear undercarriage	\$ 380.00	?
Diagnostic & reset	\$ 380.00	X

Labour Charge \$ 6,180.00

Total Amount \$25,883.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: