TOUSTL	Marcus	ASSIGN	MENT (Office)		1 7 3
rotti (Person	Chin fee Ying	of	A16	Date.	Time: 9/1/19 @ 1.10pm
stimated Cos			Bill to:		
D FTP JWS	STTP RES / OD RES /	EVA / INV / MV	7 CS		
o Inspect Ve	hicle No:	SMC 1111	67 .	Insured:	3KR 6280T.
Workshop i	n/s	Graffiti	Greepts	Tel.	8608 3456
f		Buleit Rd	4 #-06-3	26 synary	У
olicy No:	1700091478	1 -		924077	
um Insured:			Excess:		
Make of Veh		- E		D.O.	A. 03/01/2018
		Caul		10	01119
A / KEV	REP. / REV 24 HRS		\sim	H.	O.D. Endorsement
Pate/Time:	224pm@ 9/1119	Person Contacte	d. Done	Vehic	(IN) OUT
Date/Time	Action/Instruction (X) Estima	to Insp. 1k	akisht Ave	6401-59
	SMC 11167 -	· · · · · · · · · · · · · · · · · · ·			
	3KE 62807-	1			
		· × ·			
	After repair: 11	1 2019			
		1			

(08/11/13) wef	
ASS. REC. BY: MOVILS REF:	Mu /
ASS	IGNMENT
From: Date:	Veh No: SMC11/6+ Yr Regn: Jun, 15
Estimated Cost:	Type: M.Car1 M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or CA7
To Inspect Vehicle No: 5mc///62	Males 1/2/1/10 / / 1000
at Workshop m/s GNA ffete concepts	Colour 3/acle A/C: Insured/Std/NI/NA
of	Sp. Reading # 2077 T/Radio: Insured / Std / NI / NA
Insured:	+ 3 0 3 /
Policy No.	Eng/No:
Claims No.	C/No: W VWZZZ162 FMO 0183
Sum Insured: Excess:	Gen. Cond. Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	
	Modi: Nil / S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F:
(Policy Condition)	R: 225/60 R/f
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	TOYO/YOKO or Cantingsto
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal mm L/Bal mm
Est. Repairs: J days Res.: Yes or No	D.O.A. D.O.I. 10/1/5
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	The ord / chassis frame / body structure affected due to collision.
DRS. only rear L	ende riji
250 Colon of party	
* ()	
	*
1	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee	: Site Insp (\$)s+Rssi
ation to	: Interview (\$) Photos
Report Format: DAR	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$: Weekend (\$
	TOTAL

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE ...

From:

Chin, Lee-Ying

To:

assignments, Admin A

Cc:

Fong, Andy-SY

Sent:

9/1/2019 1:10:02 PM

Attachments

NEW PRI - SKR6280T-.tif PRI SKR6280T.tif

Hi LKK.

Kindly arrange survey at Autobay #01-59 after 1pm today.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Advocates & Solicitors

Our Ref:

DY.01.0002.2019.dc

Your Ref:

Please advise

8 January 2019

AIG ASIA PACIFIC INSURANCE PTE, LTD.

VIA FAX (6415 3727) & POST

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attention:

Pre-Repairs Inspection

Dear Sirs

PRE-REPAIR SURVEY - NOTIFICATION OF INSPECTION
ACCIDENT INVOLVING SMC 1116Z AND SKR 6280T AT BLK 312B CLEMENTI AVENUE
4 SERVICE ROAD ON 03.01.2019

We are instructed by M/s D's Graffiti Concepts Pte Ltd to notify you of a road traffic accident on 3 January 2019 at Blk 312B Clementi Avenue 4 Service Road involving our client's vehicle registration number SMC 1116Z and vehicle registration number SKR 6280T driven by your insured at the material time. A copy of the Singapore Accident Statement is enclosed herewith.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

DAVID YONG KHUNG LIN

(YANG KONGLIN)

Encl.

MKKH10001815 / K Kim Hin Auto Fte Ltd - HQ ENTRY DATE & TIME: 04/01/2019 17:21 SUBMITTED BY: Wong \$hu Man

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as Iruthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the Concret insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the ledgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforeasid.

A STATE OF THE STA	ACCIDENT STATEMENT	- Carone
Date Of Report	04/01/2019 17:21	
Date Of Accident	03/01/2019 16:20	
Exact Location Of Accident	BLK 312B CLEMENTI AVE 4 SERVICE ROAD	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vahicle Registration Number	SMC1116Z	New York
Insured/Policyholder		
Name Of Registered Owner	TAN LAK THONG	
NRIC No	\$80070341	
Email Address	DAVIS.TANLK@GMAIL.COM	
Mobile Phane No	(LOCAL) +65-83333953	
Alternative Phone No	OFFICE-83333953	
Vehicle Particulars	The state of the second st	
Manufacturer	VOLKSWAGEN	· (11 14
Model	JETTA	
Exact Purpose for which vehicle was being used a time of accident	it .	
Are you claiming under your own insurance policy for repair to your vehicle?	NO	
If No, Please state action to be taken	THIRD PARTY	
Vehicle Category	PRIVATE CAR	
Insurance Company	The second section of the second seco	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD	
Type Of Coverage	COMPREHENSIVE	
Fleet Policy	NO	
Policy Number	5102495728	
Cover Note Number		
Driver		
Name of Driver	TAN LAK THONG	- 1
NRIC No	\$80070341	
Date Of Birth	14/03/1980	
Occupation	INDOOR	
Date Of Driving Pass	02/07/1999	
Driving Experience	19 YEARS AND 6 MONTHS	
Gender	MALE	
Mobile Number	(LOCAL) +65-83333953	
Fax Number		

OFFICE-83333953

DAVIS.TANLK@GMAIL.COM

Page: 3/17

62922088

BLK 312B CLEMENTI AVE 4 #27-179 Address 122312 Postcode Was driver an employee of the Insured's Company NO If No. Relationship of the Driver with the Insured OWNER Vehicle Registration Number of Driver's Own Vehicle Insurance Company of Driver's Own Vehicle General Information of the Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED Type Of Accident CLEAR Weather Conditions DRY Road Surface Other Information NO Was any foreign vehicle involved in this accident? Number of vehicles (including own vehicle) involved in the accident NO Was any body Injured in the Accident? Was any injured conveyed to hospital by NO ambulance? YES Was any other material or property damaged? I have been approached by unknown person(s) NO soliciting/offering accident claims assistance. 0 Number of Passengers (Including Driver) Details of Police Action YES Was the accident reported to the police? If Yes, Please state which Police Station TRAFFIC POLICE DIVISION HQ Police Station Name ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: Police Station Address SINGAPORE TEL NO: 65470000 - FAX NO: Police Station Contact NO Was notice of intended Prosecution given? If Yes, against whom? Circumstances of Accident PLEASE REFER TO SKETCH PLAN. Attachment(s) YES Are eccident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKR6280T

Vehicle Make/Model/Colour

VOLVO S60

Dotails Of Properties

Vehicle Category

Name of Driver

PRIVATE CAR

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

> Back to OneMotoring

quire Transfer Fee Vehicle Details			
	SMC1116Z		
Vehicle No.:	P10 - Passenger Motor Car		
Vehicle Type :			
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	VOLKSWAGEN		
Vehicle Model :	JETTA GP 1.4 TSI 90 A/T HL 1634G5		
Chassis No. :	WVWZZZ16ZFM001833		
Propellant:	Petrol		
Engine No.:	CAXF17156		
Engine Capacity :	1390 cc		
Maximum Power Output:	90.0 kW (120 bhp)		
Maximum Laden Weight:	1870 kg		
Unladen Weight:	1417 kg		
Year Of Manufacture :	2014		
Original Registration Date:	18 Jun 2015		
Lifespan Expiry Date :	2		
COE Category:	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$66,000.00		
COE Expiry Date :	17 Jun 2025		
Road Tax Expiry Date:	17 Jun 2019		
PARF Eligibility Expiry Date:	17 Jun 2025		
Inspection Due Date :	17 Jun 2020		
Intended Transfer Date :	16 Jan 2019		
CO2 Emission :	138.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$10,000.00		
CO Emission :	2		
HC Emission :			
NOx Emission :	*		
PM Emission :	•		
Late renewal fee(s) will be impos	ed if road tax / lay up has expired. Please use Enqu	ire Road Tax Payable for fee(s) pay	able.
Road tax, including Over Payme Amount Payable	nt (if any), of a vehicle will follow the vehicle to the	new registered owner when its own	nership is being transferred.
Program de année de la Paris (1707)	Amount Before GST	GST Amount	Amount After GST
	(5\$)	(S\$)	(S\$)
Transfer Fee :	25.00	192	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Enquire PARF/COE Repare for Registered v	CHILLIE	
Vehicle Owner Particulars	Singapore NRIC	
Owner ID Type:	7034I	
Owner ID:	70341	
Vehicle Details Vehicle No.:	SMC1116Z	
Vehicle to be Exported:	No	
Intended Deregistration Date:	16 Jan 2019	
Vehicle Make:	VOLKSWAGEN	
	JETTA GP 1.4 TSI 90 A/T HL 1634G5	
Vehicle Model:		
Primary Colour:	Black	
Manufacturing Year:	2014	
Engine No.:	CAXF17156	
Chassis No.:	WVWZZZ16ZFM001833	
Maximum Power Output:	90.0 kW (120 bhp)	
Open Market Value:	\$19,625.00	
Original Registration Date:	18 Jun 2015	
First Registration Date:	18 Jun 2015	
Transfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$9,625.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	17 Jun 2025	
PARF Rebate Amount: Intended COE Rebate Details	\$7,218.00	
COE Expiry Date:	17 Jun 2025	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$66,000.00	
COE Rebate Amount:	\$42,368.00	
Total Rebate Amount:	\$49,586.00	

The information contained herein is correct as at 16 Jan 2019

OK

Rear Portlon

	~INC	Item	CON	AC	Qty
1137		Rear Number Plate			
1138		Rear Number Plate Base			
1139		Rear Number Plate Garnish	,		
1140	993032	Reaf Number Plate Lamp		_	
1141		Rear Bumper			
1143	993083	Rear Bumper Upper	-	_	_
1144	293017	Rear Bumper Lower	1	_	-
-	993054	Rear Bumper Side		_	_
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1152	993077	Rear Bumper Sponge		-	
1153	993040	Rear Bumper Damper Rear Bumper Protector	-	-	-
	993036	Rear Bumper Pad	-	-	-
1155	993026	Rear Bumper Moulding	-	+	-
1156	993044	Rear Bumper Reflector	-	-	-
1157	903022	Rear Bumper Lower Spoiler		-	-
1158	994023	Reverse Sensor	-	-	-
1159		Rear End Panel	-	+	+
1160		Rear End Panel Top Garnish		+-	+
1161	993333	Rear End Panel Inner Trim	-	+-	+-
1162	990333	Boot Compartment Inner Trim		╁	+-
1163	993851	Rear LH Taillamp	-	+	-
1164	993853	Rear LH Taillamp Gamish	-	+-	+
1165	993859	Rear LH Taillamp Panel		1	+
1166	995110	Rear RH Taillamp		1	1
1167	993853	Rear RH Taillamp Garnish		1	
1168	993859	Rear RH Taillamp Panel		1	1
1169	-	Rear Apron Panel		T	
1170		Bootlid			
1171		Bootlid Emblem			
1172		Bootlid Handle			
1173		Bootlid Moulding			
1174	990376	Bootlid Reflector	0.0		
1175	995222	Bootlid Lamp LH			
1177	992899	Bootlid Lamp RH Bootlid Lock	-	-	-
1178	990377	Bootlid Rubber	-	+	-
1179		Bootlid Hinge		+	+-
1180		Bootlid Spoiler	7	1	-
1181	994543	Tailgate	-	+	-
1182	The second second	Tailgate Emblem	-	1	-
1183		Tailgate Outer Handle		+	1
1184		Tailgate Moulding		1	-
1185		Tailgate Garnish		+	+
1186	-	Tailgate Reflector /	-	1	+
1187	994549	Tailgate Lamp	-	+	+
1188	994646	Tailgate Protector		+	+
1189	994676	Tailgate Wiper Arm			1
1190		Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle	34 -07		
1192	99455	Tailgate Wiper Motor	12 20 20		
1193		2 Tailgate Glass.			
1194		6 Tailgate Glass Rubber		1	
1195		4 Tailgate Glass Moulding		+	+
1196	99460	7 Tailgate Glass Sealant	1	+	+
1197			-	+	+
1198	THE PERSON NAMED IN COLUMN	and the control of th		-	+
	THE RESERVE OF THE PERSON NAMED IN	l Tailgate Hinge		T	+
1199		· · · · · · · · · · · · · · · · · · ·		- 1	- 4
1199		4 Tailgate Damper		1	

Vehicle No:

		Velilcle No: .			_
NAC	INC	Item	CON	AC	Qt
	-	Spare Tyre Board			
		Spare Tyre Panel			
		Spare Tyre			
		Spare Tyre Lock Screw			
		Spare Tyre Covér		- 1	
		Triangle Breakdown Sign			
		CD Changer Assy			-
		Antenna			-
		Centre Exhaust Pipe Assy .	-		-
		The state of the s	-	_	-
	and the second second	Centre Exhaust Mounting		_	-
		Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
		Rear Exhaust Mounting		_	-
		Rear Exhaust Heat Shield	-	_	1
		Rear LH Chassis Member	-	-	1
		Rear RH Chassis Member	-	-	+
1218		Rear LH Fender	-	-	1
		Rear LH Pender Protector	-	-	+
		Rear LH Fender Inner Panel	-	-	1
	993431		-	1	1
		Rear LH Fender Inner Garnish	-	-	1
		Rear LH Pender Inner Shield	-	+	+
		Rear LH Mudflap	-	-	+
		Rear LH Wheel Rim	-	-	+
		Rear LH Rim Cover	-	-	+
		Rear-LH Tyre Rear RH Fender	0	R	+
			10	10	+
		Rear RH Fender Protector	1	+	+
		Rear RH Fender Inner Panel Rear RH Fender Inner Trim	-	-	+
		Rear RH Fender Inner Garnish	-	+	╁
		Rear RH Fender Inner Shield	-	-	+
		Rear RH Mudflap	-	+	+
		Rear RH Wheel Rim	1	+	+
		Rear RH Rim Cover	1	+	+
		Rear RH Tyre	1	+	+
1238		Rear Fender Extension Panel LH	+	+	+
1239		Rear Fender Extension Panel RH		+	+
1240	003430	Rear Fender Liner Top Gamish	-	+	+
		Rear Pender 1/4 Glass .	+	+	+
		Rear Fender 1/4 Glass Rubber	1	+	+
		Rear Fender 1/4 Glass Scalant	1	1	+
1244	993949	Rear Windscreen Glass			T
		Rear Windscreen Rubber			T
1246		Rear Windscreen Moulding		T	
1247		Rear Windscreen Sealant		L	
		Third Brake Light		1	1
		Rear Fender Air Grille	1		1
		Fuel Lid			1
		Fuel Neck			
1252	992179	Fuel Tank		1	1
		Fuel Tank Bracket	-	1	1
		Fuel Tank Float	-	1	1
31136	990247	Sticker	-	-	1
			-	-	+
			-	1	1
A Page	100		-	-	1
100					1
					1
-		31	1	1	1
1000	-			T	1
			- A		
<u> </u>		· · · · · · · · · · · · · · · · · · ·		1	1
Ė				+	1

...CLAIM SUBFOLDER...(Pending for Survey Report)

AIM SUB	FOLDER TRA	CKING							-	
Case	Notified	Est Submitted	Ad) Assigned	Adj Rpt		Adj Subi	mitted	Ins Auth'ed	Status	
Main	09 Jan 2019 Edit Reg		09 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Est	imates	S\$0.00 View Rp			Report Cancel	
	Main	Re	ference		Claim	Details		Documer	nts	Show All
CLAIM SU	BFOLDER DE	TAILS					[Create	ed by adjuster]		
insured:	LIM JUIN	MENG NOAH (LI	N JUNMING),	1D: S760	9121H					
Main Claimant:	TAN LAK	THONG, ID: S8	007034I							
Vehicle Reg No.:	SMC111	.6Z		Date	e of Loss:		03/01/2019 16:00 - :59 [42 Months and 16 Days From LTA Reg Date (Man Yr)			
Claim Type	TP / 924	40771188SG			100000	cy/Cover e No.:	11/00091478			
Vehicle Reç No. (Insured):	SKR6280	т				y No. imant):				
1					Exce	ess:				
Repairer:		ti Concepts (HQ								
Handling Insurer:	WZ.Tan@a	aig.com						ed by Tan, Benni		10
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-356	51 [Ha	ndled by I	MARCUS	CHUA] [Fina	I Rpt due	18/01/2019]
ASSOCIA	TED MAIL RE	CEIVED							View All	Compose Case M
		NO OI GIA REP								
ALL ASSO	CIATED TAS	sks [⊡]					View A	All Search Tasks	Create N	New Task Comple
Due Dat	e Priority	Type Task	Group Sub	ject H	andler	Assign	ned By	Completed O	n Cre	eated On Dor

Claim Documents

*SMC1116Z (9240771188SG)

[SKR6280T]

TP

TAN LAK THONG

Jan 3 2019 4:00PM

[LIM JUIN MENG NOAH (LIN JUNMING)]

D's Graffiti Concepts

Pho	tos/Images		3 per page ▼	1
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail P	rint
1	11/01/19 08:38	Odometer Reading	€ Load JPG	1
2	11/01/19 08:38	Chassis Number	1 Load JPG	1
3	11/01/19 08:38	General View	Load JPG	1
4	11/01/19 08:38	General View	■ Load JPG	1
5	11/01/19 08:38	General View	■ Load JPG	•
6	11/01/19 08:38	General View	€ Load JPG	•
7	11/01/19 08:38	General View	Load JPG	•
8	11/01/19 08:38	General View	6 Load JPG	•
9	11/01/19 08:38	General View	⑤ Load JPG	•
10	11/01/19 08:38	General View	6 Load JPG	1
11	11/01/19 08:38	General View	1 Load JPG	•
12	11/01/19 08:38	General View	1 Load JPG	•
13	11/01/19 08:38	General View	1 Load JPG	•
14	11/01/19 08:38	General View	6 Load JPG	•
15	11/01/19 08:38	General View	1 Load JPG	•
16	11/01/19 08:38	General View	● Load JPG	•
17	11/01/19 08:38	General View	1 Load JPG	~
18	11/01/19 08:38	General View	1 Load JPG	•
19	11/01/19 08:38	General View	● Load JPG	1
20	11/01/19 19:48	Reinspection Photo	Load JPG	•
21	11/01/19 19:48	Reinspection Photo	€ Load JPG	•
22	11/01/19 19:48	Reinspection Photo	● Load JPG	•
23	11/01/19 19:48	Reinspection Photo	⑤ Load JPG	•
24	11/01/19 19:48	Reinspection Photo	Load JPG	•
25	11/01/19 19:48	Reinspection Photo	● Load JPG	•
26	11/01/19 19:48	Reinspection Photo	1 Load JPG	•
27	11/01/19 19:48	Reinspection Photo	1 Load JPG	•
28	11/01/19 19:48	Reinspection Photo	1 Load JPG	1
29	11/01/19 19:48	Reinspection Photo	Load JPG	1

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
The second secon	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG19000550/UCD3S2

Date:

17/01/2019

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700091478

Claimant Vehicle No:

SMC1116Z

Insured Vehicle No:

SKR6280T

Date of Loss:

03/01/2019

Nature of Claim:

TP

9240771188SG Claim No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMC1116Z

Make & Model:

VOLKSWAGEN JETTA, 1.4 (A) 18/06/2015 (Man. Year: 2014)

Engine No: Chassis No: Odometer:

CAXF17156 WVWZZZ16ZFM001833

83037 km

Reg. Date: Colour:

Black

Engine Capacity:

Market Value/New Car Price:

1390 cc

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Yes

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Yes

Engine Modification:

No

Front Tyre Size: Front Left Side:

225/40R18 Continental 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 225/40R18 Continental 6 mm Continental 6 mm

Continental 6 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

09/01/2019

D's Graffiti Concepts Pte Ltd

Date Inspected:

10/01/2019

Inspected At:

25 Kaki bt Road 4 #06-26 Synergy @ KB

Singapore 417800

Estimated Period of Repair:

2.0 days

MARCUS CHUA Adjuster:

Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*REAR RH FENDER	Repair	0.00 F	*- F
F=Franchise part.				Section 2
		Total Parts (S\$)	0.00	0.00
	Report was ur	submitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >