

Not Notified
 1/1 Png & ?
 Resurvey After Pain
 4 days



ESTIMATE TO REPAIR

VEHICLE NO. : SFN 1108 Y
 MAKE : RENAULT
 MODEL : KOLEOS 2.5 CVT
 YEAR : 2009
 CHASSIS NO : VFIVYOCOVUC284232

SURVEYOR NAME :
DATE OF SURVEY : 10 JAN 2019
TIME OF SURVEY :

DATE : 9-Jan-19
 DATE OF ACCIDENT : 6-Jan-19
 THIRD PARTY REF : SLX 7155 Y / CHINA TAIPING

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper			Bn \$1,500.00	✓
1 pc	n/s rear bumper bracket			\$120.00	?
1 pc	rear bumper reinforcement			\$900.00	?
1 pc	n/s tail lamp			Sm \$300.00	X
1 pc	tail gate lower			B1 \$1,550.00	✓
1 pc	tail gate lamp			Pn \$300.00	X
				\$4,670.00	
	Less 10%			\$467.00	
				\$4,203.00	
1 set	rear bumper sensor	s.nett		CM \$280.00	200sm
	To putty & spray paint.			\$700.00	550h 400h
	To transfer tail gate fitting.			\$80.00	50l
	To anti-rust.			\$50.00	30l
	Labour Charges.			\$500.00	400l
TG-VL/-	Total				\$5,813.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg
 Co.Reg No.199307277D GST Reg No.M2-0019086-0