

ASS. REC. BY:

REF

CS/SMO19000578/Asd3ⁿ²

Special Instruction:

Survivor
Meimen

Adrian

ASSIGNMENT (Office)

From (Person):

Hun Cheung Yung Bernard

SMO

Date/Time: 10/01/2019 @ 9:27am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 5465D

Insured:

SKQ 8242X

at Workshop m/s:

Yi Heng Motor

Tel:

6509 0052

of

1 Kaki Bukit Ave 6 # 02-19

Policy No:

D18MTPV01019750

Claim No:

CMTD1900210

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/01/2019

CA / REV / REP. / REV 24 HRS ^{lup}

H.O.D. Endorsement:

Date/Time:

9:41am @ 10/01/2018

Person Contacted:

wan ping

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLT 5465D - CC3 / AIG 19000553 / hb3

DoA: 8/01/2019

SKQ 8242X - X

11/01/19

@ 16:05 p.m. revert pending estimate from repairer to Bernard Han via email.

REF: SMO

ASSIGNMENT

From: Date: 10/01/19

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SLL 5465 D
at Workshop m/s: Yi Heng Motor
of 1 kaki Bkt Ave 6 #02-19

Insured

Policy No

Claims No


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLL 5465 D Yr Regn: 2012, May

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Veloster c.c 1591

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 99629 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHTC61DVCU077579

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I.

10/01/19

Survey held at

Yi Heng

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Sample
23/04/19	Confirmed 115 @ 12,000/- @ 9 days with Adrian (@ 19,320.72 Red - 62%) MV: 42K PV: 29.7K Nett: 12.3K
	RECEIVED 23 APR 2019
	RECEIVED 15 MAY 2019

Date/Time, File Pass to?

23/04/19

1)

Typ

Date/Time, File Return to?

2)

☐ : Prel. Report☒ : Final Report

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 12,000/- HS)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)450
10

460

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2019		10 Jan 2019 09:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LEONG KONG KHEONG, ID: S1434819J			
Main Claimant:	UNKNOWN0210			
Vehicle Reg. No.:	SLL5465D	Date of Loss:	08/01/2019 07:00 - :59	
Claim Type:	TP / CMTD1900210	Policy/Cover Note No.:	D18MTPV01019750 (Comprehensive)	
Vehicle Reg. No. (Insured):	SKQ8242X	Policy No. (Claimant):		
		Excess:		
Repairer:	Yi Heng Motor Workshop (HQ) Blk 1 Kaki Bt Ave 6 #02-19, 417883 Kaki Bukit - Tel:			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by HAN CHEUNG YONG BERNARD - 6322 4659]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/01/2019]			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

Company Registration No. 200721148H

ERIC NG CHENG BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI DO MUNIANDY
ANG KIM NOI DIANE
RAVINDRA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI ER
SONIA LIM WEI LEE

Head Office:
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Branch:
490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

HEAD OFFICE:

TEL : 65342811 (Hunting)
FAX : 65356802 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH

TEL : 63580703
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to **HEAD OFFICE** for this matter

OUR REF: AKN-atv-INS-Y44-SLL5465D-2019 - please reply to: annatan@visionlawllc.com
YOUR REF: **SKQ8242X**

9 January 2019

SOMPO INSURANCE COMPANY LTD

50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Attn: Motor Claims Department

BY FAX 6221 3147 & EMAIL
motorsurvey@sompo.com.sg

Dear Sirs

NAME OF CLAIMANT: JOE LIM HANG MONG
VEHICLE NUMBER: SLL 5465 D
YOUR INSURED VEHICLE NUMBER: SKQ 8242 X
ACCIDENT ALONG SLE TOWARD WOOLDANDS (BEFORE MANDAI) AT ABOUT 0720HOURS
ON 8 JAN 2019

We refer to your email dated 8 JAN 2019 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **LKK AUTO CONSULTANTS** the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

YI HENG MOTOR WORKSHOP
1 KAKI BUKIT AVENUE 6
#02-19 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883
TEL: 6509 0052 (WAN PING)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

(Head Office)

cc. **SLL 5465 D** - By fax 6747-9402 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature) :

Date & Time of Inspection :

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

View Sent Message

This mail is associated with :

***SLL5465D (CMTD1900210)
[SKQ8242X]**

TP
UNKNOWN0210
Jan 8 2019 7:00AM
[LEONG KONG KHEONG]
Yi Heng Motor Workshop

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 11/01/2019 16:05 PM.
To Bernard.han@sompo.com.sg
CC sur@lkkauto.com
Subject SLL5465D (CMTD1900210) [SKQ8242X] TP

Dear Bernard,

Please be informed that we have inspected the vehicle SLL 5465D on 10/01/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

Wide selection of Inchcape Certified Pre-owned LEXUS & TOYOTA

Christmas Sale

Free Tyre & Service Credits up to \$3,000

Interest Rate 2.28%

Extended Warranty 1yr

6303 6303

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad | Advertiser Login | Ways of Selling

CNY Sales! Nov 2012 Honda Stream On Offer \$53,800!

In House Finance Available!
Facelift Model! Low Depreciation!
Special Motoring - StarAd

PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Save Search
 Print

Sort by Date Posted

20 results/page

2 vehicles | **Search**

Advanced Search Search View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection	veloster	Any	Any	2012	Any	Any	Any	Available
	☐ Hyundai Veloster 1.6A GDI Turbo	\$46,800	\$10,220 /yr	05-Oct-2012	1,591 cc	132,000 km	Hatchback	Available
Agent Unit! Genuine Mileage! Free 1 Year Warranty From MBM Wheelpower, Immaculate Condition, Trade In And Consignment Options Available, All Offers Considered.								
Cars & Yachts Pte Ltd								
☆ Posted: 05-Jan-2019 Tags: 2012 Hyundai Veloster, 2012 Hyundai veloster, Hyundai Veloster, Hyundai veloster, Hyundai Veloster, veloster, Used Hyundai								
	☐ Hyundai Veloster 1.6A GDI Turbo	\$48,000	\$10,360 /yr	06-Nov-2012	1,591 cc	69,000 km	Hatchback	Available
Sporty Yellow Hot Hatch For Sale! Own This Powerful And Reliable Sport Hatch At Low Depreciation And Mileage! Well Maintained And Regularly Serviced By Meticulous Owner With Available Records. Easy 80...								
Bavarian Marques Pte Ltd								
☆ Posted: 03-Jan-2019 Tags: 2012 Hyundai Veloster, 2012 Hyundai veloster, Hyundai Veloster, Hyundai veloster, Hyundai Veloster, veloster, Used Hyundai								

Save this search criteria, to get email alerts whenever a match is found. Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	8477Z

Vehicle Details

Vehicle No.:	SLL5465D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Jan 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	VELOSTER FS 1.6 GDI DCT ABS D/AB SR 4DR
Primary Colour:	Red
Manufacturing Year:	2012
Engine No.:	G4FDCU861520
Chassis No.:	KMHTC61DVCU077579
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$16,517.00
Original Registration Date:	19 May 2012
First Registration Date:	19 May 2012
Transfer Count:	2
Actual ARF Paid:	\$16,517.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 May 2022
PARF Rebate Amount:	\$10,736.00

Intended COE Rebate Details

COE Expiry Date:	18 May 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$56,551.00
COE Rebate Amount:	\$19,002.00
Total Rebate Amount:	\$29,738.00

The information contained herein is correct as at 08 Jan 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8477Z
Vehicle Details	
Vehicle No.:	SLL5465D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Jan 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	VELOSTER FS 1.6 GDI DCT ABS D/AB SR 4DR
Primary Colour:	Red
Manufacturing Year:	2012
Engine No.:	G4FDCU861520
Chassis No.:	KMHTC61DVCU077579
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$16,517.00
Original Registration Date:	19 May 2012
First Registration Date:	19 May 2012
Transfer Count:	2
Actual ARF Paid:	\$16,517.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 May 2022
PARF Rebate Amount:	\$10,736.00
Intended COE Rebate Details	
COE Expiry Date:	18 May 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$56,551.00
COE Rebate Amount:	\$18,971.00
Total Rebate Amount:	\$29,707.00

The information contained herein is correct as at 10 Jan 2019

OK

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

10-01-19

OUR REF NO. : SLL 5465D

JOE LIM HANG MONG
3, RIVERVALE LINK
#12-22
SINGAPORE 545119

TP Sompd
Shiray

KMHTC61DVCU077579.

ESTIMATE BILL FOR VEHICLE NO. SLL 5465D MODEL : HYUNDAI VELOSTER

LIST ITEM

1) BOOT LID		1,479.00 +
2) BOOT LID WEATHERSTRIPE		289.00 x
3) BOOT LID DAMPER	2 PCS @ \$ 229.00	458.00 x
4) BOOT LID STOPPER	2 PCS @ \$ 18.00	36.00 +
5) BOOT LID LOCK		213.00 +
6) BOOT LID STRIKER		26.00 +
7) BOOT LID EMBLEM "VELOSTER"		80.00 +
8) TAIL LAMP ASSY	2 PCS @ \$ 1086.00	2,172.00 ✓
9) TAIL LAMP BASE PANEL	2 PCS @ \$ 387.00	774.00 +
10) TAIL LAMP LOWER BRACKET	2 PCS @ \$ 69.00	138.00 +
11) REAR BUMPER		684.00 ✓
12) REAR BUMPER CLIPS	8 PCS @ \$ 4.50	36.00 ✓
13) REAR BUMPER SIDE ATTACHMENT	2 PCS @ \$ 54.00	108.00 ✓
14) REAR BUMPER SIDE REFLECTOR	2 PCS @ \$ 128.00	256.00 +
15) REAR BUMPER DEFUSER		328.00 ✓
16) REAR BUMPER EXHAUST CHROME		473.00 ✓
17) REAR BUMPER REINFORCEMENT		612.00 ✓
18) REAR BUMPER REINFORCEMENT BRACKET	2 PCS @ \$ 117.00	234.00 ✓
19) REAR BUMPER PLASTIC BRACKET	2 PCS @ \$ 37.00	74.00 ✓
20) REAR ANTENA SENSOR		178.00 ✓

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

21) REAR BUMPER SPLASH SHIELD	<i>2nd</i> 2 PCS @ \$ 178.00	356.00	✓
22) REAR BUMPER SPLASH SHIELD CLIPS	8 PCS @ \$ 4.50	36.00	+
23) REAR LICENSE PLATE LAMP	<i>cracked</i> 2 PCS @ \$ 66.00	132.00	✓
24) REAR SENSOR WIRE HARDNESS	<i>Not new</i>	248.00	+
25) REAR EXHAUST SILENCER	<i>Repair</i>	896.60	+
26) REAR EXHAUST MOUNTING	<i>3 new</i>	23.00	+
27) SPARE TYRE BOARD	<i>1 new</i>	278.00	+
28) SPARE TYRE PANEL	<i>Repair</i>	878.00	+
29) SPARE TYRE NUT	<i>Not new</i>	87.00	+
30) SPARE TYRE PANEL INSULATOR CLOTH	<i>Not new</i>	\$ 380.00	+
31) REAR FENDER INNERBOARD	<i>Behind</i> 2 PCS @ \$ 247.00	494.00	✓
32) REAR FENDER INNERBOARD CLIPS	<i>new</i> 10 PCS @ \$ 4.50	45.00	✓
33) REAR END PANEL	<i>Dented</i>	499.30	✓
34) REAR PANEL INNER GARNISH	<i>Behind</i>	289.00	✓
35) REAR PANEL INNER GARNISH CLIPS	<i>new</i> 3 PCS @ \$ 4.50	13.50	✓
36) REAR FENDER	<i>Repair</i> 2 PCS @ \$ 1373.00	2,746.00	+
37) BONNET	<i>Dented</i>	1,017.00	✓
38) BONNET HINGE	<i>2 new</i> 2 PCS @ \$ 78.00	156.00	+
39) BONNET HEAT LINING	<i>3 new</i>	221.00	+
40) BONNET HEAT LINING CLIPS	9 PCS @ \$ 4.50	40.50	+
41) BONNET STOPPER (SMALL)	<i>3 new</i> 2 PCS @ \$ 14.00	28.00	+
42) BONNET STOPPER (ROUND)	<i>1 new</i> 2 PCS @ \$ 21.00	42.00	+
43) BONNET LOCK	<i>3 new</i>	153.00	+
44) BONNET CABLE	<i>1 new</i>	74.00	+
45) FRONT GRILLE	<i>cracked</i>	289.00	✓
46) FRONT GRILLE BADGE	<i>new</i>	48.00	✓

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

47) FRONT GRILLE CHROME	<i>cracked</i>		211.00	✓
48) FRONT GRILLE CLIPS	<i>new</i>	2 PCS @ \$ 4.50	9.00	✓
49) HEADLAMP ASSY	<i>cracked</i>		2,234.00	✓
50) FRONT BUMPER	<i>behind</i>		587.00	✓
51) FRONT BUMPER CLIPS	<i>new</i>	8 PCS @ \$ 4.50	36.00	✓
52) FRONT BUMPER LOWER GRILLE	<i>cut</i>		286.00	✓
53) FRONT BUMPER LOWER GRILLE CHROME			148.00	✓
54) FRONT BUMPER REINFORCEMENT	<i>Best</i>		483.00	✓
55) FRONT BUMPER SPONGE	<i>cracked</i>		210.00	✓
56) FRONT BUMPER REINFORCEMENT BRACKET	<i>new</i>		47.00	+
57) FRONT BUMPER FOGLAMP		2 PCS @ \$ 218.00 <i>new</i>	436.00	+
58) FRONT FENDER	<i>type</i>	2 PCS @ \$ 445.00	890.00	+
59) FRONT SUPPORT PANEL	<i>cracked</i>		809.00	+
60) FRONT LICENCE PLATE GARNISH	<i>behind</i>		211.00	✓
61) AIR-CON CONDENSOR	<i>Best</i>		986.00	+
			25,700.90	
LESS DISCOUNT - 20%			5,140.18	
			20,560.72	

SPECIAL NETT ITEM

1) SPARE TYRE PANEL INSULATOR	<i>new</i>		350.00	180
2) FRONT LICENCE PLATE (EMBOSS)	<i>Best</i>		55.00	✓
3) REVERSE SENSOR WITH CONTROL UNIT	<i>2 pieces</i>	4 PCS @ \$ 280.00	1,120.00	560
4) REAR WINDSCREEN INNERSEAL	<i>3 pcs</i>		60.00	+
5) REAR WINDSCREEN GUM	<i>in</i>		60.00	+
6) REAR LICENCE PLATE (EMBOSS)	<i>Best</i>		55.00	✓
			1,700.00	

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM	80.00	60
2) TO APPLY UNDERSEALING ON EFFECTED AREAS	260.00	40

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

3) TO MOUNT VEHICLE ON CAR O-LINER	480.00	X
4) TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT	120.00	50
5) TO REMOVE/REFIX BOOT LID LINING	120.00	X
6) TO REMOVE/REFIX REAR EXHAUST SILENCER AND CENTRE EXHAUST PIPE	180.00	80
6) TO REMOVE/REFIX PETROL TANK, PIPING SYSTEM, BRACKET & ETC	220.00	X
7) TO REMOVE/REFIX CUSHION, FLOORBOARD, ROOF LINING TRIM, GARNISH, UPHOSTERY AND ETC	250.00	60
8) TO REMOVE/REFIX SOUND WOOFER ASSY AND RESET	200.00	X
9) TO REMOVE AND REFIX HEAD LAMP ASSY AND REALIGNMENT LIGHTING SYSTEM	120.00	30
10) TO REMOVE/REFIX RADIATOR ASSY AND CONDUCT PRESSURE TEST	180.00	X
11) TO REMOVE/REFIX AIR-CON CONDENSOR PIPING SYSTEM AND TOP UP GAS	250.00	X
12) TO REPLACE NEW PART, CUT, WELD, KNOCK ETC	3,740.00	1800
13) TO RESPRAY ON EFFECTED AREAS	2,860.00	1000
		9,060.00
GRAND TOTAL		31,320.72

3120

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
2/5 10/01/19
09 Days.

total: 15118.64.
2/5 : 12K

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19000578/ASD3N2

Date: 16/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01019750
Claimant Vehicle No :	SLL5465D	Insured Vehicle No :	SKQ8242X
Date of Loss:	08/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900210

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL5465D	Engine No:	G4FDCU861520
Make & Model:	HYUNDAI VELOSTER, 1.6 (A)	Chassis No:	KMHTC61DVCU077579
Reg. Date:	19/05/2012 (Man. Year: 2012)	Odometer:	99629 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	22,260.72	11,998.64	10,262.08	46.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,060.00	3,120.00	5,940.00	65.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,320.72	15,118.64	16,202.08	51.73
Approved Total (Overridden) (\$\$)		12,000.00		
Nett Amount (\$\$)	31,320.72	12,000.00	19,320.72	61.69

INSPECTION

Date of Assignment:	10/01/2019	Inspected At:	Yi Heng Motor Workshop (HQ)
Date Inspected:	10/01/2019		Blk 1 Kaki Bt Ave 6 #02-19
			Singapore 417883
Estimated Period of Repair:	9.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2019)
Parts: M1-COUPE	HYUNDAI VELOSTER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL5465D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Not Necessary	1,479.00 FL	*- FL
2	1		*BOOT LID WEATHERSTRIPE	Not Necessary	289.00 FL	*- FL
3	2		*BOOT LID DAMPER	Not Necessary	458.00 FL	*- FL
4	2		*BOOT LID STOPPER	Not Necessary	36.00 FL	*- FL
5	1		*BOOT LID LOCK	Not Necessary	213.00 FL	*- FL
6	1		*BOOT LID STRIKER	Not Necessary	26.00 FL	*- FL
7	1		*BOOT LID EMBLEM VELOSTER	Not Necessary	80.00 FL	*- FL
8	2		*TAIL LAMP ASSY	Cracked	2,172.00 FL	*2,172.00 FL
9	2		*TAIL LAMP BASE PANEL	Not Necessary	774.00 FL	*- FL
10	2		*TAIL LAMP LOWER BRACKET	Not Necessary	138.00 FL	*- FL
11	1		*REAR BUMPER	Deformed	684.00 FL	*684.00 FL
12	8		*REAR BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
13	2		*REAR BUMPER SIDE ATTACHMENT	Necessary	108.00 FL	*108.00 FL
14	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	256.00 FL	*- FL
15	1		*REAR BUMPER DEFUSER	Deformed	328.00 FL	*328.00 FL
16	1		*REAR BUMPER EXHAUST CHROME	Bent	473.00 FL	*473.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Cracked	612.00 FL	*612.00 FL
18	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	234.00 FL	*234.00 FL
19	2		*REAR BUMPER PLASTIC BRACKET	Damaged	74.00 FL	*74.00 FL
20	1		*REAR ANTENA SENSOR	Cracked	178.00 FL	*178.00 FL
21	2		*REAR BUMPER SPLASH SHIELD	Not Necessary	356.00 FL	*- FL
22	8		*REAR BUMPER SPLASH SHIELD CLIPS	Not Necessary	36.00 FL	*- FL
23	2		*REAR LICENSE PLATE LAMP	Cracked	132.00 FL	*132.00 FL
24	1		*REAR SENSOR WIRE HARDNESS	Not Necessary	248.00 FL	*- FL
25	1		*REAR EXHAUST SILENCER	Repair	896.60 FL	*- FL
26	1		*REAR EXHAUST MOUNTING	Not Necessary	23.00 FL	*- FL
27	1		*SPARE TRYE BOARD	Not Necessary	278.00 FL	*- FL
28	1		*SPARE TRYE PANEL	Repair	878.00 FL	*- FL
29	1		*SPARE TRYE NUT	Not Necessary	87.00 FL	*- FL
30	1		*SPARE TRYE PANEL INSULATOR CLOTH	Not Necessary	380.00 FL	*- FL
31	2		*REAR FENDER INNERBOARD	Deformed	494.00 FL	*494.00 FL
32	10		*REAR FENDER INNERBOARD CLIPS	Necessary	45.00 FL	*45.00 FL
33	1		*REAR END PANEL	Dented	499.30 FL	*499.30 FL
34	1		*REAR PANEL INNER GARNISH	Deformed	289.00 FL	*289.00 FL
35	3		*REAR PANEL INNER GARNISH CLIPS	Necessary	13.50 FL	*13.50 FL
36	2		*REAR FENDER	Repair	2,746.00 FL	*- FL
37	1		*BONNET	Dented	1,017.00 FL	*1,017.00 FL
38	2		*BONNET HINGE	Not Necessary	156.00 FL	*- FL
39	1		*BONNET HEAT LINING	Not Necessary	221.00 FL	*- FL
40	9		*BONNET HEAT LINING CLIPS	Not Necessary	40.50 FL	*- FL
41	2		*BONNET STOPPER (SMALL)	Not Necessary	28.00 FL	*- FL
42	2		*BONNET STOPPER (ROUND)	Not Necessary	42.00 FL	*- FL
43	1		*BONNET LOCK	Not Necessary	153.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*BONNET CABLE	Not Necessary	74.00 FL	*- FL
45	1		*FRONT GRILLE	Cracked	289.00 FL	*289.00 FL
46	1		*FRONT GRILLE BADGE	Necessary	48.00 FL	*48.00 FL
47	1		*FRONT GRILLE CHROME	Cracked	211.00 FL	*211.00 FL
48	2		*FRONT GRILLE CLIPS	Necessary	9.00 FL	*9.00 FL
49	1		*HEADLAMP ASSY	Cracked	2,234.00 FL	*2,234.00 FL
50	1		*FRONT BUMPER	Deformed	587.00 FL	*587.00 FL
51	8		*FRONT BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
52	1		*FRONT BUMPER LOWER GRILLE	Cut	286.00 FL	*286.00 FL
53	1		*FRONT BUMPER LOWER GRILLE CHROME	Cut	148.00 FL	*148.00 FL
54	1		*FRONT BUMPER REINFORCEMENT	Bent	483.00 FL	*483.00 FL
55	1		*FRONT BUMPER SPONGE	Cracked	210.00 FL	*210.00 FL
56	1		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	47.00 FL	*- FL
57	2		*FRONT BUMPER FOGLAMP	Not Necessary	436.00 FL	*- FL
58	2		*FRONT FENDER	Repair	890.00 FL	*- FL
59	1		*FRONT SUPPORT PANEL	Cracked	809.00 FL	*809.00 FL
60	1		*FRONT LICENCE PLATE GARNISH	Deformed	211.00 FL	*211.00 FL
61	1		*AIR-CON CONDENSOR	Bent	986.00 FL	*986.00 FL
62	1		*SPARE TYRE PANEL INSULATOR	Necessary	350.00 FS	*180.00 FS
63	1		*FRONT LICENCE PLATE (EMBOSS)	Bent	55.00 FS	*55.00 FS
64	1		*REVERSE SENSOR WITH CONTROL UNIT (4 Pcs)	Damaged (2 Pcs only)	1,120.00 FS	*560.00 FS
65	1		*REAR WINDSCREEN INNERSEAL	Not Necessary	60.00 FS	*- FS
66	1		*REAR WINDSCREEN GUM	Not Necessary	60.00 FS	*- FS
67	1		*REAR LICENCE PLATE (EMBOSS)	Bent	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	27,400.90	14,785.80
- List Item Discount on L Items 20.00/20.00% (S\$)	5,140.18	2,787.16
Total Parts (S\$)	22,260.72	11,998.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	80.00	60.00
2	TO APPLY UNDERSEALING ON EFFECTED AREAS	New	260.00	40.00
3	TO MOUNT VEHICLE ON CAR O-LINER	New	480.00	0.00
4	TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT	New	120.00	50.00
5	TO REMOVE/REFIX BOOT LID LINING	New	120.00	0.00
6	TO REMOVE/REFIX REAR EXHAUST SILENCER AND CENTRE EXHAUST PIPE	New	180.00	80.00
7	TO REMOVE/REFIX PETROL TANK, PIPING SYSTEM, BRACKET & ETC	New	220.00	0.00
8	TO REMOVE/REFIX CUSHION, FLOORBOARD, ROOF LINING TRIM, GARNISH, UPHOLSTERY AND ETC	New	250.00	60.00
9	TO REMOVE/REFIX SOUND WOOFER ASSY AND RESET	New	200.00	0.00
10	TO REMOVE AND REFIX HEAD LAMP ASSY AND REALIGNMENT LIGHTING SYSTEM	New	120.00	30.00
11	TO REMOVE/REFIX RADIATOR ASSY AND CONDUCT PRESSURE TEST	New	180.00	0.00
12	TO REMOVE/REFIX AIR-CON CONDENSOR PIPING SYSTEM AND TOP UP GAS	New	250.00	0.00
13	TO REPLACE NEW PART, CUT, WELD, KNOCK ETC	New	3,740.00	1,800.00
14	TO RESPRAY ON EFFECTED AREAS	New	2,860.00	1,000.00
Gross Labour Cost (\$\$)			9,060.00	3,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >