

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9639T**AAD1901-069***Not Authored
61 Sup \$35501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9639T

KL1LA69RJBB123520

CHEVROLET

EPICA 2.0

8.1.2019

AIG

2/5/2013

PART**LIST**

1	1	Rear Bumper	\$	B ₁	1,202.00	✓
2	1	Rear Bumper Beam	\$	B ₂	239.94	✓
3	1	Rear Bumper Centre Absorber	\$	CM ₃	260.00	✓
4	1	Rear Bumper Side Retainer RH	\$	SL ₄	68.76	X
5	1	Rear Bumper Side Retainer LH	\$	CL ₅	68.76	✓
6	1	Rear Bumper Reflectors RH	\$	SL ₆	119.74	X
7	1	Rear Bumper Reflectors LH	\$	BL ₇	119.74	✓
8	1	Rear Bumper Tow Hook Cover	\$	SL ₈	93.00	X
9	1	Rear End Panel Outer	\$	B ₉	623.76	✓
10	1	Rear End Panel Inner Trim	\$	Dir	263.84	✓
11	1	Rear Luggage Floor Panel	\$	R	2,911.70	X
12	1	Rear Luggage Floor Panel Insulator	\$	SL ₁₂	1,991.70	X
13	1	Rear Luggage Floor Panel Trim Board	\$	SL ₁₃	2,011.60	X
14	1	Bootlid	\$	B ₁₄	973.00	✓
15	1	Bootlid inner trim board	\$	SL ₁₅	400.00	X
16	1	Bootlid Weatherstrip	\$	CM	344.28	50% 172.14
17	1	Bootlid Lock - Top	\$	R	466.56	X
18	1	Bootlid 'CHEVROLET' Badge	\$	SL ₁₈	120.62	✓
19	1	Bootlid Logo	\$	SL ₁₉	138.84	✓
20	1	Bootlid 'EPICA LT' Badge	\$	SL ₂₀	119.84	✓
21	1	Bootlid Reflector Centre	\$	SL ₂₁	217.97	X
22	1	Bootlid Reflector RH	\$	SL ₂₂	128.40	X
23	1	Bootlid Reflector LH	\$	CL ₂₃	128.40	✓
24	1	Rear Tail Lamp RH	\$	SL ₂₄	479.30	X
25	1	Rear Tail Lamp LH	\$	CL ₂₅	479.30	✓
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R	1,110.00	X
27	1	Rear Fender LH	\$	R	1,145.00	X
28	1	Rear Fender Inner Trim LH	\$	Ref ₂₈	418.44	✓
29	1	Rear Windscreen Inner Sponge Seal	\$	SL ₂₉	80.00	X

Trans-cab Auto Services Pte Ltd

AAD1901-069

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9639T

30	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>n</i>	1,110.00	} <i>X</i>
31	1	Shield -RR Muffler Protv	\$	<i>n</i>	66.00	
32	1	Rear Exhaust Box (Box-DPF) (Centre)	\$	<i>n</i>	9,435.00	
33	1	Rear Exhaust Mounting	\$	<i>SL</i>	7.00	
34	1	Rear Exhaust Pipe	\$	<i>n</i>	1,110.00	

TOTAL	\$	28,452.49
10%	\$	2,845.25
	\$	25,607.24

Specical Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i>	40.00	<i>X</i>
2	1Set	Rear Bumper Parking Sensor	\$	<i>nd</i>	300.00	✓
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i>	44.00	✓
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i>	30.00	} <i>X</i>
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i>	30.00	
6	1	Rear Exhaust Mounting	\$	<i>SL</i>	300.00	
7	2	Rear Windscreen Sealant	\$	<i>nn</i>	80.00	
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	100.00	
9	1	Spare Tyre	\$	<i>SL</i>	180.00	
10	1	Spare Wheel Rim	\$	<i>SL</i>	126.74	
11	1	Rear Exhaust Heat Shield	\$	<i>n</i>	57.00	
12	1	Rear exhaust box - J hook	\$	<i>SL</i>	25.00	
13	1	Rear exhaust box chrome pipe	\$	<i>n</i>	791.00	
14	1	Rear Exhaust Mounting Bracket	\$	<i>n</i>	27.00	
15	1	Centre Exhaust Pipe	\$	<i>n</i>	403.00	

TOTAL	\$	2,533.74
--------------	-----------	-----------------

TOTAL PARTS	\$	28,140.98
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 4,500.00 *Soal*

Putty And Spray Painting Of The Affected Portion.

\$ 4,500.00 *Soal*

Trans-cab Auto Services Pte Ltd**AAD1901-069**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9639T

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	801
To transfer of boot fittings and conduct water seepage test.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00	X
To Dismantle And Refit Rear Undercarriage Parts, Final Checking And Testing.	\$	nn 350.00	X
To Dismantle And Refit Rear Axle Housing Assy, Remove And Renewal Of Parts, Final Checking And Testing.	\$	nn 350.00	X
Labour Charge To Mount And Dismount Vehicle On Jig Bench, To Facilitate Repair.	\$	nn 350.00	X
To transfer of Rear Bumper fittings and conduct water seepage test.	\$	nn 170.00	X

\$ 11,500.00

Repair Days (LUMP SUM)	TOTAL \$	39,640.98
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • To provide resurvey confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		
		15 DAYS 6 days