



ESTIMATE TO REPAIR

VEHICLE NO. : PA 9563 M
MAKE : TOYOTA
MODEL : HAICE-3.0 D HIGH-ROOF 14 SEATER
YEAR : 2010
CHASSIS NO : JTFST22P500008530

SURVEYOR NAME :
DATE OF SURVEY : 16 JAN 2019
TIME OF SURVEY :

DATE : 9-Jan-19
DATE OF ACCIDENT : 8-Jan-19
THIRD PARTY REF : SKD 1798 Z / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper				\$523.20
1 pc	n/s front bumper bracket				\$143.20
1 pc	n/s head lamp				\$568.50
					\$1,234.90
	less 25%				\$308.73
					\$926.18
	n/s front door logo & body letting	S.NETT			\$380.00
	To putty & respray paint.				\$380.00
	To check front wiring & focus head lights.				\$30.00
	Labour Charges.				\$300.00
VL-TG/-	Total				\$2,016.18

Not withash
1/1/19
Resurvey After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• Website: www.ltm.sg
• No. 0019086-9
This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575221
Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg
Co.Reg No.199307277D GST Reg No.M3-0019086-9

Acknowledged by Repairer
Signature:
Date:

