

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKT8997K
Accident Date : 05-Jan-2019

No. : 05904

Date : 09-Jan-2019

Our Ref : 219003 (AXA) / CHAN

PAGE : 1

CROWN PACIFIC BIOTECHNOLOGY PTE LTD
38 PENJURU LANE
Singapore 609204

Not Withheld
1/18/8?

5-6 days

ESTIMATED COST OF REPAIR FOR VOLKSWAGEN MULTIVAN 2.0 TDI SKP2360H

1 pc	Tail gate			<i>Rs</i> 2,880.00	—
1 pc	Tail gate rubber			<i>Rs</i> 160.00	—
1 pc	Tail gate inner lock			<i>Rs</i> 290.00	—
1 pc	Tail gate wiper motor			280.00	?
1 pc	Tail gate glass moulding			<i>Rs</i> 550.00	<i>sn?</i>
1 pc	Tail gate inner trim			720.00	?
1 pc	Tail gate logo			<i>Rs</i> 75.00	—
1 pc	Tail gate "MULTIVAN" emblem			<i>Rs</i> 55.00	—
1 pc	Tail gate "TDi" emblem			<i>Rs</i> 45.00	—
1 pc	Tail gate outer garnish			<i>Warp</i> 270.00	—
1 pc	Tail gate lower outer handle			230.00	?
1 pc	Rear bumper fascia			<i>Rs</i> 1,200.00	—
2 pcs	Rear bumper reflector	@ S\$ 50.00	<i>CM</i>	100.00	—
1 pc	Rear bumper reinforcement			600.00	?
1 pc	Rear bumper inner parts			95.00	?
2 pcs	Rear bumper side retainer	@ S\$ 40.00	<i>Rs</i>	80.00	X
				7,630.00	
Less 10% :				763.00	

1 pc Tail gate lower chrome mouldig
1 pc Tail gate sealnt
1 pc Rear no. plate with box
1 pc Rear bumper reverse sensor (~~4~~pc 2)

To remove & renew rear windscreen
glass and conduct water leak test.

6,867.00
CM 180.00 *sn*
Rs 40.00 60.00 *sn*
Rs 50.00 *sn*
400.00 *sn* *4+*

150.00 *120*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKT8997K

Page : 2

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *601*

To apply undersealing

80.00 ?

To putty and spray replaced parts

750.00 *6001*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00 *5401*

Total : S\$ 9,457.00

=====

Singapore Dollars Nine Thousand Four Hundred
and Fifty Seven Only