

190200

INS. CASE OWNER:

CC / FWD1900

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Meriten:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L (YES) / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PDR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

6

days

Reduction: \$5121.40 = 46

Email

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

SS

100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28. Ass. Lia:

Repair Cost:

SS

6430.00

on PIPE INDEX TP.

Loss of Rental (LOR):

SS

856.00

(8

days)

x

107

Loss of Use (LOU):

SS

15

(5

days)

Loss of Income (LOI):

SS

15

(5

days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

SS

8.00

Medical:

SS

Disbursement:

SS

Legal Cost:

SS

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

7124.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

7124.00

Name 1:

Precise Auto Service

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF: FWD

ASSIGNMENT

From Date: 10/01/2018

Estimated Cost:

OD TP RES / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJK 8801B

at Workshop n/s:

precise auto

at

1 kaki Bkt Ave 6 #02-33 / 34

Insured

Policy No.

Claims No.

Sum Insured:

Excess

(Client's Record)

Make of Vch:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS up

6/11/2018
Vehicle IN / OUT

Date:

Person Contacted:

Veh No: SJK 8801B

Vt Regn: 11 of

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make:

Toyota premio

G.S.

1496

Colour:

s. her

Insured / Std / NI / NA

Sp. Reading:

181133

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

N2T260 30.34156

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

9/1/18

D.O.I.

10/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 28137 Pyrs 10th.

HS #6000

(Red = \$5121.40 / 46%)

* 6 repair days + 1 Sunday + 2 PRS = 9 days.

Date/Time, File Page to?

☐

Prel. Report

11

☐

Final Report

Date/Time, File Return to?

23

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) G + RS \$

) Poles

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CC4/FWD19000611/Ueb3

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 10-01-2019



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 6853P	Veh. Inspected	SJK 8801B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/01/2019

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/01/2019	Inspection Date	10/01/2019
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

Handwritten: *W.D. 9 6000*

26/06/2019

Date Of Accident : 09-01-2019

OUR REF : SJK 8801B/T/19

KOH SWEE YONG

BLK 149 SERANGOON NORTH AVE 1

#02-919

SINGAPORE 550149

Handwritten: *Like - Mercedes*
Date Inpart: 09-01-19 to 18-01-19

Handwritten: *Not A part*
2/5 @ 6000
6 day

ESTIMATE BILL ON VEH. NO. : SJK 8801B

MODEL : TOYOTA PREMIO

CHASSIS NO. : NZT2603034156

LIST ITEM

Boot Lid		20/3uc	972.45
Boot Lid Hinges	2pcs @ 182.25	2	364.50 X
Boot Lid Weather Stripe		to-n	287.75
Boot Lid Lock		7w1	289.90
Boot Lid Lock Striker		11	43.75 X
Boot Lid Reflector	2pcs @ 121.25	Cna	242.50
Boot Lid Reflector Sealant	2pcs @ 50.00	11	100.00 X
Boot Lid Emblem		nu	29.71
Premio Premio Badge		nu	28.85
F. Badge		nu	27.70
Boot Lid Chorme		Cna	281.90
Boot Lid Inner Padding		2001 / Cna	561.60
Boot Lid Lock - Sensor		duhd / Cna	481.40
Rear Bumper Fascia		7.1	481.90
Rear Bumper Clips	10pcs @ 12.90	nu	129.00 X
Rear Bumper Side Retainer	2pcs @ 131.35	ns 3erf	262.70 IPC
Rear Bumper Side Attachment	2pcs @ 122.25	11	244.50
Rear Bumper Stay	2pcs @ 132.10	ns 20	264.20 IPC

Rear Bumper Sponge

NZ 218.40

Tail Lamp Assy - LH

CN 371.45

Tail Lamp Sealant

11 50.00X

Tail Lamp Clips

2pcs @ 12.90

11 25.80X

Tail Lamp Base Panel - n/s

Self 374.70

Rear End Panel

Body 781.90

Rear End Panel Top Trim

Trim 394.45

Rear End Panel Top Trim Clips

4pcs @ 12.90

11 56.10X

Spare Tyre Board

Self 374.45

Tail Lamp Assy RH

371.45

CN 378.45

Rear Fender Inner Trim - n/s

341.10

Self 781.90

Rear Fender Inner Trim Clips

8pcs @ 12.90

11 103.20X

7008.61
5286.45

Less Discount 25%:

9,005.11

2,251.28

6,753.83

SPECIAL NETT ITEM

Reverse Sensor

Self

Self

380.00

2005.2

LABOUR CHARGE

Towing,

11 80.00X

To Tuff Coat Affected Areas.

60 180.00

To Check Electrical System & Snap Wiring.

30 120.00

To Transfer Boot Lid Mechanism Into New Boot Lid.

60 120.00

To Install Reverse Sensor.

50 120.00

to Remove & Refix Interior Upholstery.

80 90.00

To Renew Damaged Parts, Straighten Spare Tyre Panel & Aligned All Parts.

800 1,300.00

To Respray Affected Areas.

1000 1,250.00

10,393.83

GST 7%:

727.57

AMOUNT DUE:

11,121.40

7536.45
6029

1/9/2019

Vehicle Hub

Enquire Vehicle & Owner Information (Vehicle No. SKD6853P As At 09 Jan 2019 / 09:05:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: PRECISE - SJK8801B

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: 58618120G

Owner Name: DONN PRAABU DENNIS

Registered Address Type: HDB / HUDC

Registered Block/House No.: 502D

Registered Street Name: YISHUN STREET 51

Registered Unit No.: # 06 - 456

Registered Building Name: -

Registered Postal Code: 764502

Current Vehicle Details

Vehicle No.: SKD6853P

Make Description/Model: CHEVROLET / CRUZE 1.6 AT ABS AIRBAG 2WD 5DR SR

Insurance Company Name: FWD SINGAPORE PTE. LTD.

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 24 January 2019 5:57 PM
To: Shu Pei (LKKAUTO); Precise Auto Service
Cc: Admin A
Subject: RE: Required of GIA report for SKD 6853P. Accident Involving between SJK 8801B on 09-01-2019 along Outram Road Exit to CTE (SLE)

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Shu Pei (LKKAUTO)
Sent: Thursday, 10 January 2019 3:33 PM

To: Precise Auto Service <Support@preciseauto.sg>

Cc: Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: RE: Required of GIA report for SKD 6853P. Accident Involving between SJK 8801B on 09-01-2019 along Outram Road Exit to CTE (SLE)

Dear Arine,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Precise Auto Service <Support@preciseauto.sg>

Sent: Thursday, 10 January 2019 2:57 PM

To: Admin A <admin-a@lkkauto.com>

Subject: Required of GIA report for SKD 6853P. Accident Involving between SJK 8801B on 09-01-2019 along Outram Road Exit to CTE (SLE)

Dear Sir,

We refer to the above mentioned matter. Your company surveyor (Mr. Marcus Chua) came to survey our client vehicle.

Kindly provide us a copy of GIA report of your insured (SKD 6853P).

Herewith enclosed our client GIA Rerport for your attention.

Thank You.

Best Regards

Arine

--

T : 6745 7367 | **F :** 6841 3390

E : support@preciseauto.sg

W: www.preciseauto.sg

A: No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



PRECISE AUTO SERVICE

準 確 汽 車 服 務

Follow us on social media:



Instagram <https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>

Print Received Message

This mail is associated with :

***SJK8801B (1201900001525)**
[SKD6853P]
TP
KOH SWEE HENG
Jan 9 2019 9:00AM
[Donn Praabu Dennis]
Precise Auto Service

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 08/08/2019 14:14 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7188.00) - SJK8801B - Claim Handler: Josey Loh

Approved:7188.00:Hi! Please offer LOU at 1 day

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4529A
Vehicle Details	
Vehicle No.:	SJK8801B
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PREMIO 1.5F A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1NZD225197
Chassis No.:	NZT2603034156
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,849.00
Original Registration Date:	07 Nov 2008
First Registration Date:	07 Nov 2008
Transfer Count:	0
Actual ARF Paid:	\$14,849.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Nov 2028
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$29,670.00
COE Rebate Amount:	\$29,137.00
Total Rebate Amount:	\$29,137.00

The information contained herein is correct as at 11 Jan 2019

OK

Nivitha (LKK Auto)

From:

Sent:

To:

Cc:

Subject:

Attachments:

motorclaims.sg@fwd.com

Wednesday, 9 January 2019 3:31 PM

assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com

motorclaims.sg@fwd.com

FW: Pre-repair Inspection for SJK 8801B. Your Insured Vehicle no : SKD 6853P (Our

Ref: PNPV2018-00007140)

09012019144839.pdf

432pm @ 9/1/19

A fine
vehicle in
average on 10/1/19

Hi LKK team,

Please refer to the attached and liaise with TP repairer for PRS.

Please create the case in Merimen.

Thank you.

Kind Regards

Josey Loh

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg

FWD
insurance



From: Precise Auto Service [mailto:Support@preciseauto.sg]

Sent: Wednesday, 9 January, 2019 2:54 PM

To: Motor Claims SG - SG Common

Subject: Pre-repair Inspection for SJK 8801B. Your Insured Vehicle no : SKD 6853P.

Dear Sir,

We refer to the above mentioned matter, herewith enclosed a 2 days notice for your attention.

View Received Message

This mail is associated with :

***SJK8801B (1201900001525)**
[SKD6853P]

TP
KOH SWEE HENG
Jan 9 2019 9:00AM
[Donn Praabu Dennis]
Precise Auto Service

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 09/09/2019 15:30 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7284.00) - SJK8801B - Claim Handler: Josey Loh

Approved:7284.00:Hi! Please amend settlement breakdown in survey report

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jan 2019 Edit Reg		09 Jan 2019 00:00 Edit Adj Rpt	\$56,000.00 Edit Estimates	\$56,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Donn Praabu Dennis, ID: S8618120G								
Main Claimant:	KOH SWEE HENG, ID: S0024529A								
Vehicle Reg. No.:	SJK8801B	Date of Loss:	09/01/2019 09:00 - :59 [122 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900001525	Policy/Cover Note No.:	PNPV2018-00007140 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKD6853P	Policy No. (Claimant):	GA402951						
		Excess:							
Repairer:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- FWD_SG (27/09/2019): Alert - Adj Mandate Maintained - SJK8801B - Claim Handler: Josey Loh - FWD_SG (09/09/2019): Alert - Adj Mandate Approved (\$57284.00) - SJK8801B - Claim Handler: Josey Loh - FWD_SG (08/08/2019): Alert - Adj Mandate Approved (\$57188.00) - SJK8801B - Claim Handler: Josey Loh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJK8801B (1201900001525)
[SKD6853P]

TP
KOH SWEE HENG
Jan 9 2019 9:00AM
[Donn Praabu Dennis]
Precise Auto Service

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Letters/Correspondences

1 per page

☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit

Photos/Images

3 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/08/19 13:28	General View	Load JPG	☒
2	05/08/19 13:28	General View	Load JPG	☒
3	05/08/19 13:28	General View	Load JPG	☒
4	05/08/19 13:28	General View	Load JPG	☒
5	05/08/19 13:28	General View	Load JPG	☒
6	05/08/19 13:28	General View	Load JPG	☒
7	05/08/19 13:28	General View	Load JPG	☒
8	05/08/19 13:28	General View	Load JPG	☒
9	05/08/19 13:28	General View	Load JPG	☒
10	05/08/19 13:28	General View	Load JPG	☒
11	05/08/19 13:28	General View	Load JPG	☒
12	05/08/19 13:28	General View	Load JPG	☒
13	05/08/19 13:28	General View	Load JPG	☒
14	05/08/19 13:28	General View	Load JPG	☒
15	05/08/19 13:28	General View	Load JPG	☒
16	05/08/19 13:28	General View	Load JPG	☒
17	05/08/19 13:28	General View	Load JPG	☒
18	05/08/19 13:28	General View	Load JPG	☒
19	05/08/19 13:28	General View	Load JPG	☒
20	05/08/19 13:28	General View	Load JPG	☒
21	05/08/19 13:28	General View	Load JPG	☒
22	05/08/19 13:28	General View	Load JPG	☒
23	05/08/19 13:28	General View	Load JPG	☒
24	05/08/19 13:28	General View	Load JPG	☒
25	05/08/19 13:28	General View	Load JPG	☒
26	05/08/19 13:28	General View	Load JPG	☒
27	05/08/19 13:28	General View	Load JPG	☒
28	05/08/19 13:28	General View	Load JPG	☒
29	05/08/19 13:28	General View	Load JPG	☒
30	05/08/19 13:28	General View	Load JPG	☒
31	05/08/19 13:28	General View	Load JPG	☒
32	05/08/19 13:28	General View	Load JPG	☒
33	05/08/19 13:28	General View	Load JPG	☒
34	05/08/19 13:28	General View	Load JPG	☒
35	05/08/19 13:28	General View	Load JPG	☒
36	05/08/19 13:28	General View	Load JPG	☒
37	05/08/19 13:28	General View	Load JPG	☒
38	05/08/19 13:28	General View	Load JPG	☒
39	05/08/19 13:28	General View	Load JPG	☒
40	05/08/19 13:28	General View	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	05/08/19 13:28	General View		☒
42	05/08/19 13:28	General View		☒
43	05/08/19 13:28	General View		☒
44	05/08/19 13:28	General View		☒
45	05/08/19 13:28	General View		☒
46	05/08/19 13:28	General View		☒
47	05/08/19 13:28	General View		☒
48	05/08/19 13:28	General View		☒
49	05/08/19 13:28	General View		☒
50	05/08/19 13:28	General View		☒
51	05/08/19 13:28	General View		☒
52	05/08/19 13:28	General View		☒
53	05/08/19 13:28	General View		☒
54	05/08/19 13:28	General View		☒
55	05/08/19 13:28	General View		☒
56	05/08/19 13:28	General View		☒
57	05/08/19 13:28	General View		☒
58	05/08/19 13:28	General View		☒
59	05/08/19 13:28	General View		☒
60	05/08/19 13:28	General View		☒
61	05/08/19 13:28	General View		☒
62	05/08/19 13:28	General View		☒
63	05/08/19 13:28	General View		☒
64	05/08/19 13:28	General View		☒
65	05/08/19 13:28	General View		☒
66	05/08/19 13:28	General View		☒
67	05/08/19 13:28	General View		☒
68	05/08/19 13:28	General View		☒
69	05/08/19 13:28	General View		☒
70	05/08/19 13:28	General View		☒
71	05/08/19 13:28	General View		☒
72	05/08/19 13:28	General View		☒
73	05/08/19 13:28	General View		☒
74	05/08/19 13:28	General View		☒
75	05/08/19 13:28	General View		☒
76	05/08/19 13:28	General View		☒
77	05/08/19 13:28	General View		☒
78	05/08/19 13:28	General View		☒
79	05/08/19 13:28	General View		☒
80	05/08/19 13:28	General View		☒
81	05/08/19 13:28	General View		☒
82	05/08/19 13:28	General View		☒
83	05/08/19 13:28	General View		☒
84	05/08/19 13:28	General View		☒
85	05/08/19 13:28	General View		☒
86	05/08/19 13:28	General View		☒
87	05/08/19 13:28	General View		☒
88	05/08/19 13:28	General View		☒
89	05/08/19 13:28	General View		☒
90	05/08/19 13:28	General View		☒
91	05/08/19 13:28	General View		☒
92	05/08/19 13:28	General View		☒
93	05/08/19 13:28	General View		☒
94	05/08/19 13:28	General View		☒
95	05/08/19 13:28	General View		☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	05/08/19 13:28	General View		☒
97	05/08/19 13:28	General View		☒
98	05/08/19 13:28	General View		☒
99	05/08/19 13:28	General View		☒
100	05/08/19 13:28	General View		☒
101	05/08/19 13:28	General View		☒
102	05/08/19 13:28	General View		☒
103	05/08/19 13:28	General View		☒
104	05/08/19 13:28	General View		☒
105	05/08/19 13:28	General View		☒
106	05/08/19 13:28	General View		☒
107	05/08/19 13:28	General View		☒
108	05/08/19 13:28	General View		☒
109	05/08/19 13:28	General View		☒
110	05/08/19 13:28	General View		☒
111	05/08/19 13:28	General View		☒
112	05/08/19 13:28	General View		☒
113	05/08/19 13:28	General View		☒
114	05/08/19 13:28	General View		☒
115	05/08/19 13:29	Reinspection Photo		☒
116	05/08/19 13:29	Reinspection Photo		☒
117	05/08/19 13:29	Reinspection Photo		☒
118	05/08/19 13:29	Reinspection Photo		☒
119	05/08/19 13:29	Reinspection Photo		☒
120	05/08/19 13:29	Reinspection Photo		☒
121	05/08/19 13:29	Reinspection Photo		☒
122	05/08/19 13:29	Reinspection Photo		☒
123	05/08/19 13:29	Reinspection Photo		☒
124	05/08/19 13:29	Reinspection Photo		☒
125	05/08/19 13:29	Reinspection Photo		☒
126	05/08/19 13:29	Reinspection Photo		☒
127	05/08/19 13:29	Reinspection Photo		☒
128	05/08/19 13:29	Reinspection Photo		☒
129	05/08/19 13:29	Reinspection Photo		☒
130	05/08/19 13:29	Reinspection Photo		☒
131	05/08/19 13:29	Reinspection Photo		☒
132	05/08/19 13:29	Reinspection Photo		☒
133	05/08/19 13:29	Reinspection Photo		☒
134	05/08/19 13:29	Reinspection Photo		☒
135	05/08/19 13:29	Reinspection Photo		☒
136	05/08/19 13:29	Reinspection Photo		☒
137	05/08/19 13:29	Reinspection Photo		☒
138	05/08/19 13:29	Reinspection Photo		☒
139	05/08/19 13:29	Reinspection Photo		☒
140	05/08/19 13:29	Reinspection Photo		☒
141	05/08/19 13:29	Reinspection Photo		☒
142	05/08/19 13:29	Reinspection Photo		☒
143	05/08/19 13:29	Reinspection Photo		☒
144	05/08/19 13:29	Reinspection Photo		☒
145	05/08/19 13:29	Reinspection Photo		☒
146	05/08/19 13:29	Reinspection Photo		☒
147	05/08/19 13:29	Reinspection Photo		☒
148	05/08/19 13:29	Reinspection Photo		☒
149	05/08/19 13:29	Reinspection Photo		☒
150	05/08/19 13:29	Reinspection Photo		☒
151	05/08/19 13:29	Reinspection Photo		☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
152	05/08/19 13:29	Reinspection Photo		Load JPG	☒
153	05/08/19 13:29	Reinspection Photo		Load JPG	☒
154	05/08/19 13:29	Reinspection Photo		Load JPG	☒
155	05/08/19 13:29	Reinspection Photo		Load JPG	☒
156	05/08/19 13:29	Reinspection Photo		Load JPG	☒
157	05/08/19 13:29	Reinspection Photo		Load JPG	☒
158	05/08/19 13:29	Reinspection Photo		Load JPG	☒
159	05/08/19 13:29	Reinspection Photo		Load JPG	☒
160	05/08/19 13:29	Reinspection Photo		Load JPG	☒
161	05/08/19 13:29	Reinspection Photo		Load JPG	☒
162	05/08/19 13:29	Reinspection Photo		Load JPG	☒
163	05/08/19 13:29	Reinspection Photo		Load JPG	☒
164	05/08/19 13:29	Reinspection Photo		Load JPG	☒
165	05/08/19 13:29	Reinspection Photo		Load JPG	☒
166	05/08/19 13:29	Reinspection Photo		Load JPG	☒
167	05/08/19 13:29	Reinspection Photo		Load JPG	☒
168	05/08/19 13:30	Reinspection Photo		Load JPG	☒
169	05/08/19 13:30	Reinspection Photo		Load JPG	☒
170	05/08/19 13:30	Reinspection Photo		Load JPG	☒
171	05/08/19 13:30	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/01/19 15:32	EMAIL FROM FWD DD 09012019		Load PDF	
2	10/01/19 15:32	TP GIA REPORT		Load PDF	
3	02/08/19 10:10	WORKSHOP INVOICE		Load PDF	
4	02/08/19 10:10	RENTAL RECEIPT		Load PDF	
5	02/08/19 10:10	LTA SEARCH		Load PDF	
6	02/08/19 10:10	LOD		Load PDF	
7	14/11/19 13:35	AUTHORISATION TO ACT FORM		Load PDF	
8	14/11/19 13:35	Release Voucher		Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	14/01/19 16:38	OT GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKD6853P (Insd veh)	Model:	TOYOTA PREMIO 1.5 (A)
	SJK8801B (TP veh)		
Date of Accident:	09/01/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	11,121.40
Final Repair Cost	:	\$	6,420.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	856.00 8 days
LTA / GIA Search Fee	:	\$	8.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,284.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Precise Auto Service	:	\$ 7,284.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

14 Nov
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19000611/UGB3Q2

Date: 14/11/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00007140
 Claimant: SJK8801B Insured Vehicle No: SKD6853P
 Vehicle No: SJK8801B
 Date of Loss: 09/01/2019 Nature of Claim: TP Claim No: 1201900001525

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK8801B
 Make & Model: TOYOTA PREMIO, 1.5 (A) Engine No: 1N2D225197
 Reg. Date: 07/11/2008 (Man. Year: 2008) Chassis No: NZT2603034156
 Colour: Silver Odometer: 181133 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,133.83	5,456.46	1,677.37	23.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	2,080.00	1,180.00	36.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,393.83	7,536.46	2,857.37	27.49
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	10,393.83	6,000.00	4,393.83	42.27
+ GST 7.00/7.00% (S\$)	727.57	420.00	307.57	42.27
Nett Amount (S\$)	11,121.40	6,420.00	4,701.40	42.27
+ Car Rental (8.0 x S\$107.00/day) (S\$)		856.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		7,284.00		

INSPECTION

Date of Assignment: 09/01/2019
 Date Inspected: 10/01/2019 Inspected At: Precise Auto Service (HQ)
 No 1 Kaki Bukit Ave 6, #02-34/36
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2019)
Parts:	143	TOYOTA PREMIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK8801B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented / Buckled	972.45 FL	*972.45 FL
2	2		*BOOT LID HINGES	Repair	364.50 FL	*- FL
3	1		*BOOT LID WEATHERSTRIP	Torn	287.75 FL	*287.75 FL
4	1		*BOOT LID LOCK	Twisted	289.90 FL	*289.90 FL
5	1		*BOOT LID LOCK STRIKER	Not Necessary	43.75 FL	*- FL
6	2		*BOOT LID REFLECTOR	Cracked	242.50 FL	*242.50 FL
7	2		*BOOT LID REFLECTOR SEALANT	Not Necessary	100.00 FL	*- FL
8	1		*BOOT LID EMBLEM	Necessary	29.71 FL	*29.71 FL
9	1		*PREMIO BADGE	Necessary	28.85 FL	*28.85 FL
10	1		*F. BADGE	Necessary	27.70 FL	*27.70 FL
11	1		*BOOT LID CHROME	Cracked	281.90 FL	*281.90 FL
12	1		*BOOT LID INNER PADDING	Torn / Cracked	561.60 FL	*561.60 FL
13	1		*BOOT LID LOCK SENSOR	Shorted / Cracked	481.40 FL	*481.40 FL
14	1		*REAR BUMPER FASCIA	Distorted	481.90 FL	*481.90 FL
15	10		*REAR BUMPER CLIPS	Necessary	129.00 FL	*50.00 FL
16	1		*REAR BUMPER SIDE RETAINER	N/S Bent	262.70 FL	*131.35 FL
17	2		*REAR BUMPER SIDE ATTACHMENT	Not Necessary	244.50 FL	*- FL
18	1		*REAR BUMPER STAY	N/S Dented	264.20 FL	*132.10 FL
19	1		*REAR BUMPER SPONGE	Not fitted	218.40 FL	*- FL
20	1		*TAIL LAMP ASSY - LH	Cracked	371.45 FL	*371.45 FL
21	1		*TAIL LAMP SEALANT	Not Necessary	50.00 FL	*- FL
22	2		*TAIL LAMP CLIPS	Not Necessary	25.80 FL	*- FL
23	1		*TAIL LAMP BASE PANEL - N/S	Bent	374.70 FL	*374.70 FL
24	1		*REAR END PANEL	Badly Dented	781.90 FL	*781.90 FL
25	1		*REAR END PANEL TOP TRIM	Twisted	394.45 FL	*394.45 FL
26	4		*REAR END PANEL TOP TRIM CLIPS	Not Necessary	56.10 FL	*- FL
27	1		*SPARE TYRE BOARD	Torn	374.45 FL	*374.45 FL
28	1		*TAILLAMP ASSY RH	Cracked	378.45 FL	*371.45 FL
29	1		*REAR FENDER INNER TRIM - N/S	Deformed	781.90 FL	*341.10 FL
30	8		*REAR FENDER INNER TRIM CLIPS	Not Necessary	103.20 FL	*- FL
31	1		*SET REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,385.11	7,208.61
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,251.28	1,752.15
Total Parts (\$\$)	7,133.83	5,456.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING.	New	80.00	0.00
2	TO TUFF COAT AFFECTED AREAS.	New	180.00	60.00
3	TO CHECK ELECTRICAL SYSTEM & SNAP WIRING.	New	120.00	30.00
4	TO TRANSFER BOOT LID MECHANISM INTO NEW BOOT LID.	New	120.00	60.00
5	TO INSTALL REVERSE SENSOR.	New	120.00	50.00
6	TO REMOVE & REFIX INTERIOR UPHOLSTERY.	New	90.00	80.00
7	TO RENEW DAMAGED PARTS, STRAIGHTEN SPARE TYRE PANEL & ALIGNED ALL PARTS.	New	1,300.00	800.00
8	TO RESPRAY AFFECTED AREAS.	New	1,250.00	1,000.00
Gross Labour Cost (S\$)			3,260.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >