

# PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

WWD J Seolia

26/06/2019

Date Of Accident : 09-01-2019

OUR REF : SJK 8801B/T/19

KOH SWEE YONG

BLK 149 SERANGOON NORTH AVE 1

#02-919

SINGAPORE 550149

Lik - Mercedes

Date In/Out: 09-01-19 to 18-01-19

W. f. Abdul  
Nlu  
1/5 @ 6000/  
6 day.

**ESTIMATE BILL ON VEH. NO. : SJK 8801B**

**MODEL : TOYOTA PREMIO**

**CHASSIS NO. : NZT2603034156**

## LIST ITEM

|                             |               |             |               |
|-----------------------------|---------------|-------------|---------------|
| Boot Lid                    |               | 20/3uc      | 972.45        |
| Boot Lid Hinge              | 2pcs @ 182.25 | 2           | 364.50 X      |
| Boot Lid Weather Stripe     |               | 10-1        | 287.75        |
| Boot Lid Lock               |               | 7w1         | 289.90        |
| Boot Lid Lock Striker       |               | 11          | 43.75 X       |
| Boot Lid Reflector          | 2pcs @ 121.25 | Cna         | 242.50        |
| Boot Lid Reflector Sealant  | 2pcs @ 50.00  | 11          | 100.00 X      |
| Boot Lid Emblem             |               | nu          | 29.71         |
| Premio<br>Premio Badge      |               | nu          | 28.85         |
| F. Badge                    |               | nu          | 27.70         |
| Boot Lid Chorme             |               | Cna         | 281.90        |
| Boot Lid Inner Padding      |               | 2000 / Cna  | 561.60        |
| Boot Lid Lock - Sensor      |               | chubb / Cna | 481.40        |
| Rear Bumper Fascia          |               | 7-1         | 481.90        |
| Rear Bumper Clips           | 10pcs @ 12.90 | nu          | 129.00 X      |
| Rear Bumper Side Retainer   | 2pcs @ 131.35 | nls sent    | 262.70<br>1pc |
| Rear Bumper Side Attachment | 2pcs @ 122.25 | 11          | 244.50        |
| Rear Bumper Stay            | 2pcs @ 132.10 | nls 20      | 264.20<br>1pc |

Rear Bumper Sponge

nt 218.40 X

Tail Lamp Assy - LH

one 371.45

Tail Lamp Sealant

12 50.00 X

Tail Lamp Clips

2pcs @ 12.90

12 25.80 X

Tail Lamp Base Panel - n/s

3ref 374.70

Rear End Panel

Body 781.90

Rear End Panel Top Trim

2m 394.45

Rear End Panel Top Trim Clips

4pcs @ 12.90

11 56.10 X

Spare Tyre Board

1.0 374.45

Tail Lamp Assy R/H

371.45

one 378.45

Rear Fender Inner Trim - n/s

341.10

one 781.90

Rear Fender Inner Trim Clips

8pcs @ 12.90

12 103.20 X

7008.61  
5256.45

Less Discount 25%:

9,005.11

2,251.28

6,753.83

### SPECIAL NETT ITEM

Reverse Sensor

1ref

LKK Auto Consultants hereby notify the Requester of the following:

- To reserve information spray painting
- To display damaged panels during respray
- Parts prices are subject to confirmation
- Towing costs will be on a "Without Prejudice" basis
- Respray of metal surfaces is allowed
- Supplementary work may be required and is subject to prior approval from Insurance Company

Acknowledged by Requester

Signature:

Date:

8hole

380.00

2005.00

### LABOUR CHARGE

Towing,

11 80.00 X

To Tuff Coat Affected Areas.

60 180.00

To Check Electrical System & Snap Wiring.

30 120.00