

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

9-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6344 H

| | | | | |
|--|-------------------------------------|---|----------|-----|
| 1 pc | Front bumper | \$ | 531.00 | de |
| 1 pc | Front bumper emblem | \$ | 44.00 | de |
| 1 pc | Front bumper n/s side retainer | \$ | 16.00 | de |
| 1 pc | Front n/s wheel cover | \$ | 116.00 | de |
| 1 pc | Front n/s fender | \$ | 384.00 | de |
| 1 pc | Front n/s fender inner shield | \$ | 120.00 | de |
| | | \$ | 1,211.00 | |
| | | \$ | 121.10 | |
| | | \$ | 1,089.90 | |
| | | <div><p>LKK Auto Consultants hence notify the Repairer of the following:</p><ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company<p>Acknowledged by Repairer</p><p>Signature: _____</p><p>Date: _____</p></div> | | |
| S/NETT | | | | |
| 1 set | Front bumper clips | \$ | 48.00 | de |
| 1 pc | Front n/s fender sticker | \$ | 30.00 | de |
| 1 set | Front n/s fender inner shield clips | \$ | 28.00 | de |
| 1 pc | Tyre | \$ | 200.00 | X |
| Sundry | | \$ | 50.00 | 20 |
| To check front n/s wheel alignment | | \$ | 80.00 | ✓ |
| To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. | | \$ | 180.00 | X |
| To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same | | \$ | 650.00 | 300 |
| To putty and spray painting on front bumper, front n/s fender | | \$ | 400.00 | ✓ |
| To apply rustproofing on the repaired and replaced panels. | | \$ | 80.00 | 20 |
| | | \$ | 2,835.90 | |

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tan Jiah 97495745
wp
Lump sum
Repair after repair.
3-4 days
9/1/19
9/1/19 @ 14hantam
205/15/15. Activities