

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

Chm

8-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1854 E

1 pc	Bootlid	\$	1,119.00	bt
1 pc	Bootlid emblem	\$	27.00	net
1 pc	Bootlid CRDi	\$	29.00	net
1 pc	Bootlid lower garnish	\$	290.00	Rx
1 pc	Rear bumper	\$	696.00	del
1 pc	Rear bumper lower cover	\$	206.00	del
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	net
1 pc	Rear bumper inner sponge	\$	114.00	?
1 pc	Rear bumper reinforcement	\$	607.00	?
2 pcs	Rear bumper n/s & o/s stay @ \$53.00	\$	106.00	?
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	?
		\$	3,324.00	
		\$	367.40	
		\$	2,956.60	
		\$	48.00	net
		\$	100.00	net
		\$	280.00	200mm
		\$	80.00	net
		\$	50.00	no
		\$	120.00	30
		\$	180.00	40
		\$	950.00	600
		\$	800.00	600
		\$	150.00	30
		\$	5,714.60	

S/NETT

1 set	Rear bumper clips
1 set	Bootlid stickers
1 set	Reverse sensor
1 pc	Rear bumper top protector

Sundry

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel

To apply rustproofing on the repaired and replaced panels.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tan Guan 9749544
9/1/19
Lumpsum
Repair 4-5 days