

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. NO. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

09 JAN 2019

E S T I M A T E

Page No. : 1 of 5

Estimate No. : b1 49696
Date Estimated : 09/01/2019
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR -
Eng Hua Furniture Manufacturing Pte
5 Sungei Kadut Drive

Singapore 729558

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX1129A	G389825	27/11/2015	528iA	0

DESCRIPTIONVALUE

Replacing rear bumper panel, bootlid, rework tail panel,
etc to knock out dents caused by the accident

2550 3,400.00

Spray rear bumper, bootlid, tailpanel

2537 2,819.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries

7 150.00

To supply rear emboss number plate.

bt ✓ 83.00

Total Labour 1: **7,018.00**

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,642.45	677 1,642.45
RR BUMPER CARRIER	1	772.05	? 772.05
ADAPTOR	1	72.30	? 72.30
REAR BUMPER CENTRE GUIDE	1	61.55	? 61.55
RR LH MOUNT	1	192.15	? 192.15
RR RH MOUNT	1	198.30	? 198.30
REAR BUMPER PRIMED (PDC)	1	1,563.25	del 1,563.25
REAR BUMPER TOWING EYE COVER PRIMED	1	47.60	mis 47.60
EMBLEM GROMMET	2	0.80	ner 1.60
MODEL LETTERING 528I	1	64.10	ner 64.10
BMW EMBLEM	1	71.25	ner 71.25
BOOTLID SEALING	1	115.25	? 115.25
REAR RH REFLECTOR	1	36.80	del 36.80
RR RH LIGHT IN SIDE PANEL	1	609.95	ner 609.95

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 2 of 5

Estimate No. : b1 49696
Date Estimated : 09/01/2019
Prepared By : Joseph Yaguel

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX1129A	G389825	27/11/2015	528iA	0

DESCRIPTION	QTY	PRIC	VALUE
RR RH LIGHT IN TRUNK LID	1	360.25	360.25
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
			5,829.05

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 2811192105 Claim No. _____

Date & Time Tanfu Excess \$S _____

Surveyor's Name 97445749 Sign hjs

Surveyor's Tel NP Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail tanfu@khandan

No. of Working Days Recommend 6 days

PIK 275/40R18



Labour 1	:	7,018.00
Parts	:	5,829.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	899.29
Grand Total	:	13,746.34

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **