

ISSUE

INS. CASE OWNER

Winnie

CC of Reg. AXA1900 0622, R216/2

LKK
IDAC

Surveyor:

Rasm

DOI:

ASSIGNMENT

11/11/19

Date / Time:

10/11/19

Registered in Meriton:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SDB 88P

Claim No. :

990618W0 (anget)

Name of Insured :

WINNIE WINNY

Policy No. :

116877A1

Insured Tel No. :

HP:

Make / Model :

Bmw

Excess Sec II : \$5

D.O.A. :

11/11/19

Place of Accident :

21W ANGE QUEIT

Is driver the owner? (YES / NO)

(YES / NO)

Name of Accident :

If NO, Driver Name / Age :

LIHW 501 KM1

OI GIA REPORT (YES / NO)

(YES / NO)

TP GIA REPORT (YES / NO)

Driver Tel No. :

(V/L : YES / NO)

Insured Liabi

SLH 21677



INSRS:
WSP:
Tel:
Liability:
RMKS:

Tan Chong



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

SC status is canceled. Just submit LKK bill & rpt.

Date / Time	Remarks	Documentation Check List	Handler	Typist
11/11/19	SLH 21677 - 4			
11/11/19	SLH 21677 - 4			
22/10/19	Agmmt claim			
30/11/19	File -> Super follow up			

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$5 (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % (Agreed / Assessed) BOLA S/N No. : 27

Repair Cost: \$5

Loss of Rental (LOR): \$5 (days)

Loss of Use (LOU): \$5 (5 x days)

Loss of Income (LOI): \$5 (5 x days)

LOR only LOU only LOR + LOU LOR + LOI (Tick only one)

GIA/LTA Search: \$5

Medical: \$5

Disbursement: \$5 (e.g. Tow/ Independent)

Legal Cost: \$5

Total: \$5 Global Sum \$5:

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$5 Name 1: _____

Payee 2: (Strike if N.A.) \$5 Name 2: _____

Payee 3: (Strike if N.A.) \$5 Name 3: _____

COPIES SENT 10/11/19

1) Claim status: Normal/Reject/Private Settle
2) Report Format: # 250
3) Survey fee: # 250


Passive

REF:

98486

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / P / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLH 3167Z
 at Workshop with TAN CHANG
 of 911, BUKIT TIMAH
 Insured: ASM (CAR)
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition) Have Lantone
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SLH 3167Z Yr Regn: 2016 / BC
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: NISSAN QASHQAI 1.2 c.c: 1197
 Colour: GRAY A/C: Insured / Std / NI / NA
 Sp. Reading: 17417 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 ChNo: SJN FGA J11U1720526
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/60R17
 R: 1.
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. 02/01/19 D.O.I. 11/01/19
 Survey held at TAN CHANG
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PIP # 1535-76 / 2785-68 / 6440
	- excluded chert items \$1192.6

Date/Time. File Pass to? : Preli. Report
 : Final Report
 Date/Time. File Return to? _____
 Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____
 1) _____
 2) _____
 3) _____
 4) _____
 5) _____
 TOTAL _____

Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Invs (\$ _____)
 Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19000622/R1hb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 10-01-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SDB 88P	Veh. Inspected	SLH 3167Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/01/2019
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/01/2019	Inspection Date	11/01/2019
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911 BUKIT TIMAH ROAD SINGAPORE 589623		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0026/2019
DATE : 09-JAN-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN: MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MDM U'REN MAUREEN PRISCILLA
ADDRESS : 45 JALAN WAJEK

TELEPHONE NO : 64668585/96653646
(588497)

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SDB88P
VEHICLE NO : SLH3167E
MODEL CODE : FRLARBEJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2301464A
CHASSIS NO : SJHVEAJ11U1720526
MILEAGE : 1 KM
DATE IN : 09/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 02/01/2019

09034
u
10(01/19

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832 FAX : 64697472

CLIC.
CITAM

67418474

ca
12/01/19
11am
1977

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGH NO SLH3167E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RP1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	X u u
2	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	/
3	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X u u
4	EZ/001	REPAIR END PANEL AND RENEW REAR BUMPER	900.00	350 370 250
5	EZ/002	S/PAINT REAR BUMPER (2 TONE) AND END PANEL	750.00	250 300
TOTAL LABOUR CHARGES			2100.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR3167E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SUNDRIES	NPN			100.00 ?
2	REVERSE SENSOR(J11 & T32)	SENSOR-TES140			210.00 ct ✓
3	FENDER LH REAR ARC	93829-4EA0A	483.00 ?		
4	GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40 ✓
5	BRACKET-BUMPER RH	85220-4EA0A	35.90 ? X ✓		
6	GROMMET BUMPER \$2.50 EA X 04	63846-5V000	10.00 ✓		
7	RETAINER-BUMPER RH	79184-4EA0A	23.80 X ✓		
8	CANOE RIVET BUMPER \$6.50 EA X 02	76882-0M000	13.00 ✓		
9	RETAINER-BUMPER LH	79185-4EA0A	23.80 ✓		
10	BRACKET-BUMPER LH	85221-4EA0A	35.90 ✓		
11	STAY ASSY-REAR RH	H5210-4EAMA	126.00 ? X ✓		
12	STAY ASSY-REAR LH	H5211-4EAMA	126.00 ?		
13	REINF-BUMPER RR	H5030-4EAMA	619.20 ?		
14	ENERGY ABSORBER	85090-4EAGB	126.40 ?		
15	CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20 ✓		
16	CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80 ✓		
17	FINISHER-REAR BUMPER TOW	85071-4EAGA	14.80 X ✓		
18	PASCIA-RR BUMP	85022-4EA0H	717.00 DE ✓		
SUB TOTAL			2383.80	0.00	314.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			476.76	0.00	0.00
GRAND TOTAL			1907.04	0.00	314.40
OVERALL TOTAL			2221.44		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGM NO SLE3167E

TOTAL LABOUR CHARGES	2100.00
TOTAL SPARE PARTS CHARGES	2221.44
GRAND TOTAL	4321.44 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Rasue - Hp 90010068
11/01/19 @ 1120

0.00

0.00

3 days

Reg by paint

PLEASE NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Vic (LKKAuto)

From: Lawrence Teo <lawrenceteo@tanchong.com>
Sent: Tuesday, 22 January, 2019 10:39 AM
To: Shu Pei (LKKAuto); winnie.ho@axa.com.sg
Cc: Admin A; SUR; Vic (LKKAuto)
Subject: RE: ACCIDENT INVOLVING SLH3167Z & SDB88P ON 02.01.2018
INS/IC/LAW/0026/2019 DIRECT SETTLEMENT

Dear All,

This case revert to OD Recovery.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472
Email: lawrenceteo@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

From: Lawrence Teo
Sent: 21 January 2019 11:00
To: 'Shu Pei (LKKAuto)' <shupeil@lkkauto.com>; winnie.ho@axa.com.sg
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING SLH3167Z & SDB88P ON 02.01.2018 INS/IC/LAW/0026/2019 DIRECT
SETTLEMENT

Dear All,

Any update?

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472
Email: lawrenceteo@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: 14 January 2019 18:29
To: winnie.ho@axa.com.sg; Lawrence Teo <lawrenceteo@tanchong.com>
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>
Subject: FW: ACCIDENT INVOLVING SLH3167Z & SDB88P ON 02.01.2018 INS/IC/LAW/0026/2019 DIRECT
SETTLEMENT

Service Request Details

Claim

59M018W0

Reference

None 

Loss Date

2 January 2019

Request Date

10 January 2019

Due Date

17 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Incident Only

Services

Pending verification - Direct Settlement

10012019 @ 952am
Lawrence veh not in

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration

SLH3167Z

Make

TPVD

Service Address

...

Primary Contact/Insured

LIM MEE LIANG
102F PASIR PANJANG ROAD, #04-11, 118530, Singapore
81612888

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

[New Message](#)

Catherine Chong (LKK Auto)

From: Lawrence Teo <lawrenceteo@tanchong.com>
Sent: Thursday, 10 January, 2019 9:06 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey; SG AXA Insurance SM Claims Service Team
Subject: ACCIDENT INVOLVING SLH3167Z & SDB88P ON 02.01.2018
INS/IC/LAW/0026/2019 DIRECT SETTLEMENT
Attachments: 2019_0102_164459_041A (online-video-cutter.com).mp4; 1212_001.pdf
Categories: Shailendra

Dear Office In Charge,

Our customer, U'REN MAUREEN PRISCILLA the owner of SLH3167Z is insured with NTUC Insurance at the material time of the accident. The 3rd party SDB88P is insured with you at the material time of the accident.

Our customer holds your insured driver liable for the accident and would like to claim against your insured driver. On behalf of our customer, we hereby enquire whether you would like to have a Direct Settlement with our customer.

Our customer's claiming for Cost Of Repair and Loss Of Rental @\$100/Day.GIA Report / Estimate attached for your action.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472
Email: lawrenceteo@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

From: Singapore Printer <printsg@tanchong.org>
Sent: 09 January 2019 15:36
To: Lawrence Teo <lawrenceteo@tanchong.com>
Subject: Attached Image



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19000622/R1pb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:WINNIE

Date : 13-08-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDB 88P	Veh. Inspected	SLH 3167Z
Policy No.	P1688199	Coverage (\$)	0.00
Claim No.	S9M018W0	Excess (\$)	0.00
Assign From		Assign Date	10/01/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN QASHQAI 1.2	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	SJNFEAJ11U1720526	Colour	GREY
Odometer	17417	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	GOODYEAR	6 mm
L/H Front Tyre	215/60 R17	GOODYEAR	6 mm
R/H Rear Tyre	215/60 R17	GOODYEAR	6 mm
L/H Rear Tyre	215/60 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/01/2019	Inspection Date	11/01/2019
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911 BUKIT TIMAH ROAD SINGAPORE 589623		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 3167Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER LH REAR ARC (N) (CONSISTENT)	* CHECK	483.00	-
1	BRACKET -BUMPER RH (N) (CONSISTENT)	NOT NECESSARY	35.90	-
4	GROMMET BUMPER @\$2.50 (N) (CONSISTENT)	NECESSARY	10.00	10.00
1	RETAINER -BUMPER RH (N) (CONSISTENT)	NOT NECESSARY	23.80	-
2	CANOE RIVET BUMPER @\$6.50 (N) (CONSISTENT)	NECESSARY	13.00	13.00
1	RETAINER -BUMPER LH (N) (CONSISTENT)	NECESSARY	23.80	23.80
1	BRACKET -BUMPER LH (N) (CONSISTENT)	NECESSARY	35.90	35.90
1	STAY ASSY -REAR RH (N) (CONSISTENT)	NOT NECESSARY	126.00	-
1	STAY ASSY -REAR LH (N) (CONSISTENT)	* CHECK	126.00	-
1	REINF-BUMPER RR (N) (CONSISTENT)	* CHECK	619.20	-
1	ENERGY ABSORBER (N) (CONSISTENT)	* CHECK	126.40	-
3	CLIP BUMPER @\$7.4 (N) (CONSISTENT)	NECESSARY	22.20	22.20
4	CLIP BUMPER @\$1.20 (N) (CONSISTENT)	NECESSARY	4.80	4.80
1	FINISHER -REAR BUMPER TOW (N) (CONSISTENT)	NOT NECESSARY	16.80	-
1	FASCIA -RR BUMP (N) (CONSISTENT)	DEFORMED	717.00	717.00
	LESS 20% DISCOUNT		-476.76	-165.34
			1,907.04	661.36
SPECIAL NETT ITEMS				
1	SUNDRIES (SN) (CONSISTENT)	* CHECK	100.00	-
1	REVERSE SENSOR (J11 & T32) (SN) (CONSISTENT)	CUT	210.00	210.00
2	GROMMET BUMPER @\$2.20 (SN) (CONSISTENT)	NECESSARY	4.40	4.40
			314.40	214.40
LABOUR				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL .	NOT NECESSARY	240.00	-
	SUPPLY & INSTALL REVERSE SENSOR .		110.00	110.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	100.00	-
	REPAIR END PANEL AND RENEW REAR BUMPER.		900.00	250.00

Report Ref No. CC4/ASM19000622/R1pb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	S/PAINT REAR BUMPER (2 TONE) AND END PANEL		750.00	300.00
			2,100.00	660.00
GRAND TOTAL			4,321.44	1,535.76
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1183.68 NETT)				1,535.76

Report Ref No. CC4/ASM19000622/R1pb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
■ LKKInvoice1 (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
■ LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
■ LKKAdjustment1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
■ LKK PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
■ Email from TP ad 220119 .pdf	Letters and Correspondence	Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)	22 March 2019
■ LKK ACKNOWLEDGEMENT - CH - VIC.mng	Letters and Correspondence	Surveyor / Assessor	HO Winnie	16 January 2019
■ EMAIL.mng	Letters and Correspondence	Workshop	BATAN BHOSALE Pragal	14 January 2019
■ PRI FROM WORKSHOP WITH TP CIA SLH3167Z & ESTIMATE.mng	Forms / Claim Documents	Estimate / Quotation	KUMAR Shalindra	10 January 2019
■ P1688199_CI_00004_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	HO Winnie	4 January 2019
■ P1688199_BN_00004_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	HO Winnie	4 January 2019