

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

09034

u

10/01/19

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0026/2019
DATE : 09-JAN-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832 FAX : 64697472

OWNER'S NAME : MDM U'REN MAUREEN PRISCILLA
ADDRESS : 45 JALAN WAJEK

S(588497)
TELEPHONE NO : 64668585/96653646

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SDB88P
VEHICLE NO : SLH3167Z
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2301464A
CHASSIS NO : SJNFEAJ11U1720526
MILEAGE : 1 KM
DATE IN : 09/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 02/01/2019

Clk
cash

6748434

an
10/01/19
cash
RPT

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLH3167Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	X
2	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	/
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
4	ZZ/001	REPAIR END PANEL AND RENEW REAR BUMPER	900.00	340 370 250
5	ZZ/002	S/PAINT REAR BUMPER (2 TONE) AND END PANEL	750.00	250 300
TOTAL LABOUR CHARGES			2100.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLH3167Z

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN			100.00 <i>9</i>
2 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00 <i>cut</i>
3 FENDER LH REAR ARC	93829-4EA0A	483.00 <i>?</i>		
4 GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40 <i>me</i>
5 BRACKET-BUMPER RH	85220-4EA0A	35.90 <i>X</i>		
6 GROMMET BUMPER \$2.50 EA X 04	63846-5V000	10.00 <i>me</i>		
7 RETAINER-BUMPER RH	79184-4EA0A	23.80 <i>X</i>		
8 CANOE RIVET BUMPER \$6.50 EA X 02	76882-0M000	13.00 <i>me</i>		
9 RETAINER-BUMPER LH	79185-4EA0A	23.80 <i>me</i>		
10 BRACKET-BUMPER LH	85221-4EA0A	35.90 <i>me</i>		
11 STAY ASSY-REAR RH	H5210-4EAMA	126.00 <i>X</i>		
12 STAY ASSY-REAR LH	H5211-4EAMA	126.00 <i>?</i>		
13 REINF-BUMPER RR	H5030-4EAMA	619.20 <i>?</i>		
14 ENERGY ABSORBER	85090-4EA0B	126.40 <i>?</i>		
15 CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20 <i>me</i>		
16 CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80 <i>me</i>		
17 FINISHER-REAR BUMPER TOW	85071-4EA0A	16.80 <i>X</i>		
18 FASCIA-RR BUMP	85022-4EA0H	717.00 <i>DE</i>		
SUB TOTAL		2383.80	0.00	314.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		476.76	0.00	0.00
GRAND TOTAL		1907.04	0.00	314.40
OVERALL TOTAL		2221.44		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLH3167Z

TOTAL LABOUR CHARGES 2100.00
TOTAL SPARE PARTS CHARGES 2221.44

GRAND TOTAL 4321.44 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

*Resue - H990010068
11/01/19 @ 11:20*

3 days

Rey by print

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.