

ASS. REC. BY:

REF:

CS/CTI19000624/RSD36

Special Instructions:

Surveyor
Menmen

Rasul

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTI

Date/Time: 10/11/19 @ 11:19am

Estimated Cost:

Bill to:

OD ☒ IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC595U

Insured:

YL3072M

at Workshop m/s

Crown Asia Bus Builder

Tel: 6467 0956

of

14 Sungai Kendut Ave

Policy No:

DMCVSN7764201801

Claim No:

SNM19D200119

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/10/2018

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

11:31am 10/11/19

Person Contacted:

Jayden

Vehicle IN ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

PC595U-X

YL3072M-NA/CTI16007418/13

Sum: 21/10/2018

11/11/19-

vehicle was not in on 11/01/19.

05/07/19

@ 17:10 pm checked with Jayden (repairs?),
vehicle has not sent in for repair.

Carryover *Parm*

REF:

26669

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **PC 595U**
 at Workshop no/s: **CROWN ASIA**
 of: **No. 44, Jambel Kanan ST 1**

Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition) **10am - 12pm**

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **PC 595U** Vr Regn: **2016 APR**
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: **ISUZU LT 434P7-85MT** CC: **7790**
 Colour: **MULTI** A/C: _____ Insured / Std / NI / NA
 Sp Reading: **244449** T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: **JALLT 434 PF 7000 ISU**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **11R22.5**
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **TATONG**

Front: _____ Rear: _____
 R/Bal: **8** mm R/Bal: **8/8** mm
 L/Bal: **8** mm L/Bal: **8/8** mm
 D.O.A: **24/12/18** D.O.I: **24/01/19**

Survey held at: **CROWN ASIA**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected (due to collision)

Date / Time: _____ Action / Instruction: _____

RECEIVED 08 JUL 2019

Date/Time: File Base No:

08/07/19
Tyr-4

1) _____ Date/Time: File Return No:

2) _____

Report Format:

Print

Lump Sum / I.B.I: \$

Days Of Repair: **7**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp: \$

☐ Interview: \$

☐ Tech Insp: \$

☐ Weekend: \$

Survey Fee:

Transportation:

1. S + RE: \$

2. H: \$

3. Other: \$

4. \$

TOTAL

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins. Auth'd	Status
Main	10 Jan 2019		10 Jan 2019 11:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	UNKNOWN, Co. Reg. No.: NIL		
Vehicle Reg. No.:	PC595U	Date of Loss:	24/12/2018 00:00 - :59
Claim Type:	TP / SNM19D200119	Policy/Cover Note No.:	DMCVSN1764201801
Vehicle Reg. No. (Insured):	YL3072M	Policy No. (Claimant):	DMCVSN1764201801
		Excess:	S\$1.00
Repairer:	Crown Asia Bus Builder Pte Ltd (Sungei Kadut) (HQ) 44 Sungei Kadut Ave, 729667 Sungei Kadut - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/01/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Thursday, 10 January 2019 11:19 AM
To: Admin A; 'assignments'
Cc: claims@crownasia.com.sg
Subject: FW: Traffic accident involving PC595U and YL3072M on 24/12/2018 at Forth Chin Bee Road (HVP) - reported on 27.12.18

Dear LKK oic,

We refer to the above reference. Please attend to the PRI inspection

We will create in Merimen shortly

Thanks

Catherine Thia

Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Claims [mailto:claims@crownasia.com.sg]
Sent: Thursday, 10 January, 2019 10:29 AM
To: Catherine Thia <catherine.thia@sg.cntaiping.com>
Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: RE: Traffic accident involving PC595U and YL3072M on 24/12/2018 at Forth Chin Bee Road (HVP) - reported on 27.12.18

Dear Catherine,

We select LKK as SJE

Thanks and Best Regards,
Jayden



Crown Asia Bus Builder Pte Ltd
Tel: 6467 0956 (ext. 112) Fax: 6469 4319
Email: jayden@crownasia.com.sg
44 Sungei Kadut Ave, Singapore 729667

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Wednesday, 9 January, 2019 4:52 PM
To: claims@crownasia.com.sg
Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: RE: Traffic accident involving PC595U and YL3072M on 24/12/2018 at Forth Chin Bee Road (HVP) - reported on 27.12.18

Dear Jayden

We refer to the above reference.

Tried to call you, but no one picked up. We only have LBS and LKK to choose from. Kindly let us know which one you prefer. We will assign immediately

Thanks

Catherine Thia
Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd, except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Claims Dept of CTI
Sent: Wednesday, 9 January, 2019 12:24 PM
To: Catherine Thia <catherine.thia@sg.cntaiping.com>
Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: Traffic accident involving PC595U and YL3072M on 24/12/2018 at Forth Chin Bee Road (HVP) - reported on 27.12.18

From: Claims [mailto:claims@crownasia.com.sg]
Sent: Saturday, January 05, 2019 11:09 AM
To: Claims Dept of China Taiping Insurance <e-claims@sg.cntaiping.com>
Subject: Traffic accident involving PC595U and YL3072M on 24/12/2018 at Forth Chin Bee Road (HVP) - reported on 27.12.18

Dear Sirs,

Reminder.

Thanks and Best Regards,
Jayden



Crown Asia Bus Builder Pte Ltd
Tel: 6467 0956 (ext. 112) Fax: 6469 4319
Email: jayden@crownasia.com.sg
44 Sungei Kadut Ave, Singapore 729667

From: Claims <claims@crownasia.com.sg>
Sent: Friday, 28 December, 2018 12:04 PM
To: 'e-claims@sg.cntaiping.com' <e-claims@sg.cntaiping.com>
Subject: Traffic accident involving PC595U and YL3072M on 24/12/2018 at Forth Chin Bee Road (HVP)

Dear Sirs,

We would like to submit a Traffic accident involving PC595U and YL3072M on 24/12/2018 at Forth Chin Bee Road (HVP)

Please find all the attached documents for your reference.

Kindly provide to us a list of 10 surveyors to choose as SJE

Thanks and Best Regards,
Jayden



Crown Asia Bus Builder Pte Ltd
Tel: 6467 0956 (ext. 112) Fax: 6469 4319

Email: jayden@crownasia.com.sg
44 Sungei Kadut Ave, Singapore 729667

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/12/2018 14:13
Date Of Accident	24/12/2018 12:40
Exact Location Of Accident	AT FORTH CHIN BEE RD (HEAVY VEHICLE CARPARK)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	PC595U
Insured/Policyholder	
Name Of Registered Owner	MILLENNIUM TOURS COACH SERVICE PTE. LTD.
Co Reg No	201108666G
Email Address	OPERATION@RUIFENG.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64670956
Vehicle Particulars	
Manufacturer	ISUZU
Model	LT434P 7.8 SMT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5083349398-02
Cover Note Number	
Driver	
Name of Driver	ZHANG QIANG
Passport No/FIN	G2594811X
Date Of Birth	01/05/1984
Occupation	OUTDOOR
Date Of Driving Pass	09/11/2015
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91308911
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NA
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL3072M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ONG WEY SONG
NRIC/Passport Number	S7146945Z
Contact Number	97356528
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A → PC 505 U
B → YL 3072M



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time: 24 Dec 2018, 1240 am

Accident Location: At Footh Chin Bee Rd (Heavy Vehicle Carpark)

I parked my vehicle at the above-mentioned location. I was in my vehicle, preparing to go when suddenly I felt an impact from the side of my vehicle. I noted that veh B had collided onto my vehicle while making a reverse.

☐ Reporting Only ☐ Own Damage ☐ Third Party ☒ Claim at other workshop (OO/TP)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

IMPORTANT NOTE:

You have been advised by the workshop that in the event that you wish to claim against your own policy (Own Damage Claim), there is a FOURTEEN (14) days claim window. The claim must be made within the stipulated timeframe from the day of occurrence.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



**CROWN ASIA BUS BUILDER PTE. LTD.** (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667

Tel: (65) 6469 3319, Fax: (65) 6902 6758

GST ID No : 201023449R

Repair Estimate**No. : QT-000025**

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

C/O LKK AUTO CONSULTANTS PTE LTD

Your Ref. :

Our D/O No. :

Terms : C.O.D.

Date : 24-01-2019

Page : 1 of 2

TEL :

FAX :

Item	Tax Code	Description	Qty	UOM	U/ Price S\$	Disc.	Total S\$
OS		THIRD PARTY CLAIM - REPAIR ESTIMATE FOR PC595U Traffic accident on 24/12/2018 involving PC 595 U and YL 3072M at Forth Chin Bee Road (Heavy Vehicle Carpark)					
Parts Required:							
1.	OS	REAR RIGHT BOTTOM BUMPER X ^{mm}	1.00		1,500.00		1,500.00
2.	OS	REAR RIGHT BUMPER STRUCTURAL FRAME ASSY X ^{mm}	1.00		1,000.00		1,000.00
3.	OS	REAR RIGHT LID COVER ASSY LH - Repair ^{LH - RH} 1/2	1.00		2,650.00	700.00	5,300.00
4.	OS	LESS: 10% TRADE DISCOUNT	1.00		-780.00		-780.00
5.	OS	LABOUR CHARGES - TO SPRAY FOAM, KNOCK AND REPAIR ALL NECESSARY PARTS INCLUDING CHANGING OF ALL DAMAGED PARTS	1.00		2,450.00		2,450.00
6.	OS	LABOUR CHARGES TO PUTTY AND SPRAY PAINTING FOR REAR BUMPER, REAR STRUCTURE ASSY AND TWO REAR RIGHT LID COVER, RIGHT BODY STRUCTURE	1.00		2,800.00		2,800.00

NOTE: THIS ESTIMATE IS BASED ON VISIBLE DAMAGE ONLY. SHOULD ANY HIDDEN PARTS AND/OR LABOUR CHARGES REQUIRED DURING WORKS IN PROGRESS. IT WILL BE NOTIFIED ACCORDINGLY.

PRICE QUOTED IS SUBJECT TO 7% GST.

**CROWN ASIA BUS BUILDER PTE. LTD.** (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667

Tel: (65) 6469 3319, Fax: (65) 6902 6758

GST ID No : 201023449R

Repair Estimate**No. : QT-000025**

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Your Ref. :

C/O LKK AUTO CONSULTANTS PTE LTD

Our D/O No. :

Terms : C.O.D.

Date : 24-01-2019

Page : 2 of 2

TEL :

FAX :

Item	Tax Code	Description	Qty	UOM	U/ Price S\$	Disc.	Total S\$
------	----------	-------------	-----	-----	-----------------	-------	--------------

Resul
Ap 90010068 28/1/19

7 days

P/P

24/01/19 @ 1110

Resurvey 64 point

LKKAuto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE DOLLAR TWELVE THOUSAND TWO HUNDRED SEVENTY ONLY

Sub Total (Excluding GST) **12,270.00**GST payable @ 7% on 0.00 **0.00**Total (Inclusive of GST) **12,270.00****Notes :**

1. All cheques should be crossed and made payable to CROWN ASIA BUS BUILDER PTE. LTD.
2. Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

GST Summary**Amount(S\$)****Tax(S\$)****Authorised Signature**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jan 2019		10 Jan 2019 11:53 Edit Adj Rpt	S\$4,785.00 Edit Estimates	S\$4,785.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	0, Co. Reg. No.: 0								
Main Claimant:	UNKNOWN, Co. Reg. No.: NIL								
Vehicle Reg. No.:	PC595U	Date of Loss:	24/12/2018 00:00 - :59 [32 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200119	Policy/Cover Note No.:	DMCVSN1764201801						
Vehicle Reg. No. (Insured):	YL3072M	Policy No. (Claimant):	DMCVSN1764201801						
		Excess:	S\$1.00						
Repairer:	Crown Asia Bus Builder Pte Ltd (sungel Kadut) (HQ) 44 Sungel Kadut Ave, 729667 Sungel Kadut - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC595U (SNM19D200119)
[YL3072M]






































TP














UNKNOWN

Dec 24 2018 12:00AM


[0]







Crown Asia Bus Builder Pte Ltd (sungei Kadut)




Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
2	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
3	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
4	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
5	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
6	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
7	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
8	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
9	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
10	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
11	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
12	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
13	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
14	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
15	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
16	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
17	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
18	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
19	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
20	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
21	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
22	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
23	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
24	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
25	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
26	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
27	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
28	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
29	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
30	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
31	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
32	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
33	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
34	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
35	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
36	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>
37	08/07/19 14:16	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
48	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
49	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
50	08/07/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	27/12/18 16:09	Accident Statement	 Load HTM		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	27/12/18 16:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	27/12/18 16:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	27/12/18 16:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	27/12/18 16:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	27/12/18 16:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	27/12/18 16:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	27/12/18 16:07	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	27/12/18 16:07	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	27/12/18 16:07	LIC	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19000624/R1SD3E2

Date: 16/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1764201801

Claimant Vehicle No: PC595U Insured Vehicle No: YL3072M

Date of Loss: 24/12/2018 Nature of Claim: TP Claim No: SNM19D200119

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC595U

Make & Model: ISUZU LT434P 7.8 SMT, 7.8 D (M) Engine No: 6HK1674648

Reg. Date: 22/04/2016 (Man. Year: 2015) Chassis No: JALLT434PF7000150

Colour: Multi-colour Odometer: 244449 km

Engine Capacity: 7790 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11R22.5 Rear Tyre Size: 11R22.5 (D)

Front Left Side: TAITONG 8 mm Rear Left Side: TAITONG 8/8 mm

Front Right Side: TAITONG 8 mm Rear Right Side: TAITONG 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,020.00	2,385.00	4,635.00	66.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	2,400.00	2,850.00	54.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,270.00	4,785.00	7,485.00	61.00
+ GST 7.00/7.00% (S\$)	858.90	334.95	523.95	61.00
Nett Amount (S\$)	13,128.90	5,119.95	8,008.95	61.00

INSPECTION

Date of Assignment: 10/01/2019

Date Inspected: 24/01/2019 Inspected At: Crown Asia Bus Builder Pte Ltd (Sungei Kadut) (HQ)
44 Sungei Kadut Ave
Singapore 729667

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,385.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Jul 2019)	
Parts:	N/A	ISUZU LT434P 7.8 SMT 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC595U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RIGHT BOTTOM BUMPER	Not Necessary	1,500.00 FL	*- FL
2	1		*REAR RIGHT BUMPER STRUCTURAL FRAME ASSY	Not Necessary	1,000.00 FL	*- FL
3	1		*REAR RIGHT LID COVER ASSY	O/s Bent/N/s *Check	5,300.00 FL	*2,650.00 FL
					Sub Total (S\$)	7,800.00 2,650.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	780.00 265.00
					Total Parts (S\$)	7,020.00 2,385.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY PAINTING FOR REAR BUMPER,REAR STRUCTURE ASSY AND TWO REAR RIGHT LID COVER,RIGHT BODY STRUCTURE	New	2,800.00	1,400.00
2	TO SPRAY FOAM,KNOCK AND REPAIR ALL NECESSARY PARTS INCLUDING CHANGING OF ALL DAMAGED PARTS	New	2,450.00	1,000.00
Gross Labour Cost (\$\$)			5,250.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >