

05/2010

Richard CCY, XA1900 0625, Agibh<sup>SR</sup>

LKK:  
IDAC:

INS. CASE OWNER:

Adrian

ASSIGNMENT

DOI: 10/1/19

Date / Time:

10/1/19

Surveyor:

Registered in Merimen:

Pre-assign / CCU / FTE

SGF 9818J

Claim No.:

SAM RATE 9854



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(YES / NO)

HP:

D.O.A:

Nature of Accident:

(V/L) (YES) (NO)

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO  
Insured Liability: % Final? Yes / No



INRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Chew motor



INRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/Time	STAGE	DATE / PIC
10/1/19	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION				Adrian
Repair Cost:	SS 10,600.00	(10 days) Reduction:	215/197.45 % 69	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 31/1/19 4PM	Confirm with:	(SUCU)	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 50	(Agreed / Assessed) BOLA S/N No.:	NIL	
Repair Cost:	SS \$10,600			
Loss of Rental (LOR):	SS 5,300.00			
Loss of Use (LOU):	SS 300	(S 50 x 12 days)		
Loss of Income (LOI):	SS -	(S x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	<input checked="" type="checkbox"/> LOR + LOU	<input type="checkbox"/> LOR + LO		
GIA/LTA Search	SS 7.45			
Medical:	SS -	(e.g. Tow/Independent)		
Disbursement:	SS -			
Legal Cost	SS -			
Total:	SS 5600.00	Global Sum SS:	5600.00	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL PAYMENT	Date/Time:	Confirm with:		
Payee 1:	SS 5600.00	Name 1:	Chew Motor Pte Ltd	
Payee 2: (Strike if N.A.)	SS -	Name 2:		
Payee 3: (Strike if N.A.)	SS -	Name 3:		

COPY SENT

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: \$350/-





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19000625/Ajb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 10-01-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGF 9818J	Veh. Inspected	SKL 51J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/01/2019
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/01/2019	Inspection Date	10/01/2019
Survey held at	CHEW MOTOR PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

AXA. Adrian. LEE



# CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883  
 Tel: 6509 5545 Fax: 6509 5567  
 Website: www.chewmotor.com  
 Registration No.: 201718369R

10/01/2019

Blk 1 Kaki Bukit Ave 6  
 # 01-43  
 Singapore 417883

TP AXA  
 Joy

Accident date: 08/01/2019

Estimated repair cost for vehicle no: SKL51J TOYOTA WISH 1.8 X A '08

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>Defend</i>		\$481.85 ✓
2	8	Front Bumper Clip <i>re</i>	\$6.50	\$52.00 30
3	1	Front L/H Bumper Side Retainer <i>re</i>		\$78.00 45
4	1	Front L/H Head Lamp <i>ut</i>		\$586.00 ✓
5	1	Front L/H Fender <i>Distorted</i>		\$585.20 ✓
6	1	Front L/H Fender Signal Lamp <i>not re</i>		\$65.10 X
7	1	Front L/H Fender Cowling <i>Defend</i>		\$135.10 ✓
8	8	Front L/H Fender Cowling Clip <i>re</i>	\$6.50	\$52.00 30
9	1	Front L/H Door <i>Distorted</i>		\$980.20 ✓
10	2	Front L/H Door Hinge <i>Bent</i>	\$132.00	\$264.00 178
11	1	Front L/H Door Lock Clutch <i>not re</i>		\$186.60 X
12	1	Front L/H Door Inner Lock <i>not re</i>		\$578.20 X
13	1	Front L/H Door Inner Rubber <i>ut</i>		\$272.60 ✓
14	1	Front L/H Door Inner Trim Board <i>crackd.</i>		\$781.10 481
15	1	Front L/H Door Gear Motor Assy <i>Damage</i>		\$987.30 290
16	1	Front L/H Door Side Mirror Assy <i>not re</i>		\$980.20 X
17	1	Front L/H Rim <i>ut</i>		\$850.00 480(SN)
18	1	Front L/H Tyre <i>cut</i>		\$350.00 150(SN)
19	1	Front L/H Lower Arm <i>Bent</i>		\$371.45 ✓
20	1	Front L/H Knuckle Arm <i>Bent</i>		\$281.90 ✓
21	1	Front L/H Knuckle Arm Bearing <i>re</i>		\$191.60 ✓
22	1	Front L/H Shock Absorber <i>Bent</i>		\$374.45 ✓
23	1	Front L/H Drive Shaft <i>Damage</i>	1266.50	\$1,712.40 ✓
24	1	Front Steering Rack <i>Bent</i>		\$1,718.30 ✓
25	1	Front Crossmember <i>Bent</i>		\$972.45 ✓
26	1	Rear Bumper <i>re</i>		\$625.20 X
27	8	Rear Bumper Clip <i>not re</i>	\$6.50	\$52.00 +
28	1	Rear L/H Bumper Side Retainer <i>re</i>		\$132.10 +

29	1	Rear L/H Door	Dented		\$980.30	✓
30	2	Rear L/H Door Hinge	None	\$132.00	\$264.00	+
31	1	Rear L/H Door Pillar	Dented		\$781.35	✓
32	1	Rear L/H Door Inner Lock			\$578.20	+
33	1	Rear L/H Door Inner Rubber			\$272.60	+
34	1	Rear L/H Door Inner Trim Board	New		\$781.10	+
35	1	Rear L/H Door Gear Motor Assy			\$987.30	+
36	1	Rear L/H Fender	Repair		\$972.45	+
37	1	Rear L/H Rim	lit		\$850.00	agw/sw
38	1	Rear L/H Tyre	None		\$350.00	+
39	1	Rear L/H Shock Absorber			\$282.25	+
40	1	Rear L/H Axle Bearing			\$581.60	+
41	1	Rear Axle			\$2,821.70	+
42	1	R/H Rocker Panel	Repair		\$897.30	+

Subtotal :- \$26,097.45

10032.45

S. n 1110

8274.18

**Labour charges**

To remove & refit front & rear L/H door, glass, lock, rubber, trim board & gear motor	<del>\$380.00</del> 160
To remove & refit front dashboard	<del>\$380.00</del> 220
To remove & refit reverse sensor	<del>\$100.00</del> +
To remove & refit front L/H undercarriage	<del>\$380.00</del> 220
To remove & refit drive shaft, steering rack & crossmember	<del>\$450.00</del> 250
To remove & refit rear axle	<del>\$380.00</del> +
To check wheel alignment	<del>\$150.00</del> 80
To check wiring	<del>\$100.00</del> 30
Tuff kote	<del>\$150.00</del> 80
Towing fee	<del>\$100.00</del> 60
Panel beating	<del>\$1,800.00</del> 1400
Spray painting	<del>\$1,800.00</del> 1400

3900 .

**Subtotal :-** \$6,170.00

**Total:-** \$32,267.45

total 13284.18

2/s : 106K

1008 Days .

10.6K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

 [> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 9128Z

**Vehicle Details**

Vehicle No.: SKL51J  
Vehicle to be Exported: No  
Intended Deregistration Date: 09 Jan 2019  
Vehicle Make: TOYOTA  
Vehicle Model: WISH 1.8X A  
Primary Colour: Black  
Manufacturing Year: 2007  
Engine No.: 1ZZ2994115  
Chassis No.: ZNE100387944  
Maximum Power Output: 97.0 kW (130 bhp)  
Open Market Value: \$17,069.00  
Original Registration Date: 05 Aug 2008  
First Registration Date: 05 Aug 2008  
Transfer Count: 1  
Actual ARF Paid: \$17,069.00

**Intended PARF Rebate Details**

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 31 May 2028  
COE Category: E - Open Category  
COE Period(Years): 10  
PQP Paid: \$38,712.00  
COE Rebate Amount: \$36,360.00

**Total Rebate Amount: \$36,360.00**

The information contained herein is correct as at 09 Jan 2019

OK



## ◀ Service Request Details

Claim

S9M019TE

Reference

None 

Loss Date

8 January 2019

Request Date

9 January 2019

Due Date

16 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Incident Only

Services

Pending verification - Direct Settlement

*09/01/2019 @ 1136pm  
Subst veh in  
Adrian*

### Actions

Next Step

Agree to perform service

### Vehicle Information

Incident Vehicle Registration #

SKL51J

Make

TPVD

Service Address

---

...

Primary Contact/Insured

---

HO CHONG TSE IVAN

437 TANJONG KATONG ROAD, #26-04, 437147, Singapore

ANDREWTC@ACORNINT.COM

Claim Handler

---

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

NON REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

## **Catherine Chong (LKK Auto)**

---

**From:** Chew Motor Pte. Ltd. <claims@chewmotor.com>  
**Sent:** Wednesday, 9 January, 2019 12:24 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Subject:** SKL51J CLAIMING AGAINST SGF9818J DOA:08.01.19  
**Attachments:** SKL51J PRI.pdf

**Categories:** Pragati

Hi Motor Claims Department,

Please send your surveyor list,thanks.

\*\*\*Please take note this claim under Chew Motor Pte Ltd\*\*\*

**Please kindly take note that we have a mutual agreement on the selection of appointed surveyor from your panel surveyor's list. We hope that there will not be any further changes to the finalised repair cost after confirmation with your appointed surveyor or at the stage of LOD.**

Regards,

Sukyi Chong

***Chew Motor Pte Ltd***  
1 Kaki Bukit Ave 6  
Blk A #01-11 Autobay  
Singapore 417883  
T : 6747 9241  
F : 6741 7276



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

11 January, 2019

**HO CHONG TSE IVAN**  
437 TANJONG KATONG ROAD, #26-04,  
Singapore 437147

Dear Sir,

**OUR REF : CC4/ASM19000625/Ajb3**  
**YOUR REF : SGF 9818J**  
**ACCIDENT INVOLVING SGF 9818J & SKL 51J ON 08/01/2019 ALONG/AT**  
**AMBER ROAD**

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)

- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) or deliver it by hand to 51 Ubi Avenue 1, #01-25 Paya Ubi Ind. Park S(408933).

You should also IMMEDIATELY forward us by hand any letters or Courts Summons received from the other party involved in the accident. You should not negotiate, admit liability or offer payment to them.

We would like to bring to your attention that under Policy Condition, your insurer shall have full discretion in the process and settlement of the said third party claim subject to the merits of the case and according to the rights afforded under the policy.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter. In accordance with the policy conditions, your insurer reserve the right to repudiate the said claim to you should you not give proper notice to us of any occurrence which may give rise to it.

Kindly contact us at 6841 2409 if you have any further enquiries.

Yours sincerely,  
Claim Department

This is a computer generated letter and no signature is required.

CC : AXA INSURANCE PTE LTD  
Motor Claim Department

⏪ **Re:RE: Re:TP's claim**

Type

🔔 Question

Message

Hi, pls proceed at 50%. Do get OI's consent on the settlement. TY.

Reply



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 22/07/2019

### Survey Details:

Date of loss	8-Jan-19
Date of appointment	10-Jan-19
Date of survey	10-Jan-19
Location of survey	CHEW MOTOR PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SKL 51J
Make and Model	TOYOTA WISH
Date of registration	5/8/2008
Excess	
Market Value	\$50,000
Parf Rebate	\$36,400
Nett Loss	\$13,600

### Repair details:

Initial Estimate	\$	32,267.45
------------------	----	-----------

### Proposed/Revised repair cost:

Parts	\$	9,384.18
Check items (estimate)	\$	-
Labour	\$	3,900.00
<b>Total</b>	<b>\$</b>	<b>13,284.18</b>
<b>Lump Sum(if applicable)</b>	<b>\$</b>	<b>10,600.00</b>

Number of days for repair		10
---------------------------	--	----



**Remarks:**

10 RECOMMENDED REPAIR DAYS + 1SUNDAY + 1PRS = 12 DAYS

**Mandate:**

Liability(TP)	50%	100%
Proposed repair cost (W/GST)	\$ 5,300.00	\$ 10,600.00
Loss of use (12days x \$60)	\$ 360.00	\$ 720.00
Loss of rental	-	\$ -
Loss of income	-	\$ -
LTA search fees	\$ 7.45	\$ 7.45
Others	-	\$ -
<b>Proposed Total</b>	<b>\$ 5,607.45</b>	<b>\$ 5,667.45</b>



## <MANDATE IA> - S9M019TE {ACCIDENT INVOLVING SGF 9818J (OI) & SKL 51J (TP) ON 08/01/2019

Type

 Question

Message

LIABILITY: 50% INFORMED OI ABOUT TP CLAIM AND AGREED TO SETTLE BASE ON 50% DUE TO NO CONCRETE EVIDENCE FROM BOTH PARTIES. WE SEEK YOUR MANDATE AT \$5667.45 (CLAIMING LOU) - BASED ON 50/50. MANDATE IA HAD BEEN UPLOADED IN SMARTCLAIMS. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA 22/07/2019

Reply



# Re:<MANDATE IA> - S9M019TE {ACCIDENT INVOLVING SGF 9818J (OI) & SKL 51J (TP) ON 08/01/2019

Type

🔗 Question

Message

Hi, pls proceed as per mandate. TY.

Reply

Our Reference : CM1902-0024 / SKL51J  
Your Reference : SGF9818J

14<sup>th</sup> February 2019

**AXA Insurance Singapore Pte Ltd**  
8 Shenton Way,  
#B1-01,  
Singapore 068811



**CHEW MOTOR PTE. LTD**

WITHOUT PREJUDICE

Dear Sir/Madam

**ACCIDENT INVOLVING SKL51J & SGF9818J ON 08.01.2019 ALONG AMBER ROAD AT 19:32HRS**

We are instructed by **KHOR TZOONG HEIN** to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **SKL51J** damaged by vehicle **SGF9818J** driven by your insured at the material time.

We are informed that the said accident was caused by your insured's negligence. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows: -


➤ Repair Costs	\$ 10,600.00
➤ Loss of Use for 12 days (10 + 2 Weekends)	\$ 1,200.00
➤ LTA Search Fees	\$ 7.45
➤ Total	\$ 11,807.45

A copy of each supporting documents are enclosed for your perusal.

- GIA Report
- Invoice
- LTA Search Receipt

Please let us have your cheque for the sum of **\$11,807.45** made payable to us, **CHEW MOTOR PTE. LTD.** within the next 14 days.

Yours Sincerely,

A handwritten signature in black ink is written over a horizontal line. To the right of the signature is a circular stamp with the text "CHEW MOTOR PTE. LTD." around the perimeter and a star in the center.

**CHEW MOTOR PTE. LTD.**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

AXA INSURANCE PTE LTD

Ref : CC4/ASM19000625/Agb3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN: RICHARD ANG

Date : 08-08-2019



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGF 9818J	Veh. Inspected	SKL 51J
Policy No.	VA1/GA337856	Coverage (\$)	0.00
Claim No.	S9M019TE	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	10/01/2019

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	ZNE100387944	Colour	BLACK
Odometer	342996	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	MICHELIN	6 mm
L/H Front Tyre	205/55R16	MICHELIN	6 mm
R/H Rear Tyre	205/55R16	MICHELIN	6 mm
L/H Rear Tyre	205/55R16	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	08/01/2019	Inspection Date	10/01/2019
Survey held at	CHEW MOTOR PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 51J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	481.85	481.85
8	FRONT BUMPER CLIP @ \$6.50 (CONSISTENT)	NECESSARY	52.00	30.00
1	FRONT L/H BUMPER SIDE RETAINER (CONSISTENT)	NECESSARY	78.00	45.00
1	FRONT L/H HEAD LAMP (CONSISTENT)	CUT	586.00	586.00
1	FRONT L/H FENDER (CONSISTENT)	DISTORTED	585.20	585.20
1	FRONT L/H FENDER SIGNAL LAMP (CONSISTENT)	NOT NECESSARY	65.10	-
1	FRONT L/H FENDER COWLING (CONSISTENT)	DEFORMED	135.10	135.10
8	FRONT L/H FENDER COWLING CLIP @ \$6.50 (CONSISTENT)	NECESSARY	52.00	30.00
1	FRONT L/H DOOR (CONSISTENT)	DISTORTED	980.20	980.20
2	FRONT L/H DOOR HINGE @ \$132.00 (CONSISTENT)	BENT	264.00	178.00
1	FRONT L/H DOOR LOCK CATCH (CONSISTENT)	NOT NECESSARY	186.60	-
1	FRONT L/H DOOR INNER LOCK (CONSISTENT)	NOT NECESSARY	578.20	-
1	FRONT L/H DOOR INNER RUBBER (CONSISTENT)	CUT	272.60	272.60
1	FRONT L/H DOOR INNER TRIM BOARD (CONSISTENT)	CRACKED	781.10	481.00
1	FRONT L/H DOOR GEAR MOTOR ASSY (CONSISTENT)	DAMAGED	987.30	290.00
1	FRONT L/H DOOR SIDE MIRROR ASSY (CONSISTENT)	NOT NECESSARY	980.20	-
1	FRONT L/H LOWER ARM (CONSISTENT)	BENT	371.45	371.45
1	FRONT L/H KNUCKLE ARM (CONSISTENT)	BENT	281.90	281.90
1	FRONT L/H KNUCKLE ARM BEARING (CONSISTENT)	NECESSARY	191.60	191.60
1	FRONT L/H SHOCK ABSORBER (CONSISTENT)	BENT	374.45	374.45
1	FRONT L/H DRIVE SHAFT (CONSISTENT)	DAMAGED	1,712.40	1,265.50
1	FRONT STEERING RACK (CONSISTENT)	BENT	1,718.30	1,718.30
1	FRONT CROSSMEMBER (CONSISTENT)	BENT	972.45	972.45
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	625.20	-
8	REAR BUMPER CLIP @ \$6.50 (CONSISTENT)	NOT NECESSARY	52.00	-
1	REAR L/H BUMPER SIDE RETAINER (CONSISTENT)	NOT NECESSARY	132.10	-
1	REAR L/H DOOR (CONSISTENT)	DENTED	980.30	980.30
2	REAR L/H DOOR HINGE @ \$132.00 (CONSISTENT)	NOT NECESSARY	264.00	-
1	REAR L/H DOOR PILLAR (CONSISTENT)	DENTED	781.35	781.35

Report Ref No. CC4/ASM19000625/Agb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR L/H DOOR INNER LOCK (CONSISTENT)	NOT NECESSARY	578.20	-
1	REAR L/H DOOR INNER RUBBER (CONSISTENT)	NOT NECESSARY	272.60	-
1	REAR L/H DOOR INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	781.10	-
1	REAR L/H DOOR GEAR MOTOR ASSY (CONSISTENT)	NOT NECESSARY	987.30	-
1	REAR L/H FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	972.45	-
1	REAR L/H TYRE (CONSISTENT)	NOT NECESSARY	350.00	-
1	REAR L/H SHOCK ABSORBER (CONSISTENT)	NOT NECESSARY	282.25	-
1	REAR L/H AXLE BEARING (CONSISTENT)	NOT NECESSARY	581.60	-
1	REAR AXLE (CONSISTENT)	NOT NECESSARY	2,821.70	-
1	R/H ROCKER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	897.30	-
	LESS 25% DISCOUNT		-	-2,758.07
			24,047.45	8,274.18
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT L/H RIM (SN) (CONSISTENT)	CUT	850.00	480.00
1	FRONT L/H TYRE (SN) (CONSISTENT)	CUT	350.00	150.00
1	REAR L/H RIM (SN) (CONSISTENT)	CUT	850.00	480.00
			2,050.00	1,110.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & REFIT FRONT & REAR L/H DOOR, GLASS, LOCK, RUBBER, TRIM BOARD & GEAR MOTOR.		380.00	160.00
	TO REMOVE & REFIT FRONT DASHBOARD.		380.00	220.00
	TO REMOVE & REFIT REVERSE SENSOR.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIT FRONT L/H UNDERCARRIAGE.		380.00	220.00
	TO REMOVE & REFIT DRIVE SHAFT, STEERING RACK & CROSSMEMBER.		450.00	250.00
	TO REMOVE & REFIT REAR AXLE.	NOT NECESSARY	380.00	-
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	80.00
	TOWING FEE.		100.00	60.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR L/H FENDER AND R/H ROCKER PANEL.		1,800.00	1,400.00

Report Ref No. CC4/ASM19000625/Agb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,800.00	1,400.00
			6,170.00	3,900.00
<b>GRAND TOTAL</b>			<b>32,267.45</b>	<b>13,284.18</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>10,600.00</b>

Report Ref No. CC4/ASM19000625/Agb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.