

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7827E**AAD1901-066***Not Notified
1/10/19?*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 7827E

KL1LA69RJB101315

CHEVROLET

EPICA 2.0

8.1.2019

EQ

31/10/2012

PART**LIST**

1	1	Rear Bumper	\$	<i>B</i> 1,202.00	—
2	1	Rear Bumper Beam	\$	<i>B</i> 239.94	—
3	1	Rear Bumper Centre Absorber	\$	<i>CM</i> 260.00	—
4	1	Rear Bumper Side Retainer RH	\$	<i>CM</i> 68.76	—
5	1	Rear Bumper Side Retainer LH	\$	<i>SL</i> 68.76	X
6	1	Rear Bumper Reflectors RH	\$	<i>CM</i> 119.74	—
7	1	Rear Bumper Reflectors LH	\$	<i>CM</i> 119.74	—
8	1	Rear Bumper Tow Hook Cover	\$	<i>SL</i> 93.00	X
9	1	Rear End Panel Outer	\$	<i>Bu</i> 623.76	—
10	1	Rear End Panel Inner Trim	\$	<i>SL</i> 263.84	X
11	1	Rear Luggage Floor Panel	\$	<i>R</i> 1,946.00	X
12	1	Rear Luggage Floor Panel Insulator	\$	<i>SL</i> 63.50	X
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>SL</i> 378.00	Λ
14	1	Bootlid	\$	<i>Bu</i> 973.00	—
15	1	Bootlid inner trim board	\$	<i>SL</i> 400.00	X
16	1	Bootlid Weatherstrip	\$	<i>Dis/Cor</i> 344.28	<i>50% SL 172.14 SL</i>
17	1	Bootlid Lock - Top	\$	<i>R</i> 466.56	X
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>SL</i> 120.62	—
19	1	Bootlid Logo	\$	<i>SL</i> 138.84	—
20	1	Bootlid 'EPICA LT' Badge	\$	<i>SL</i> 119.84	—
21	1	Bootlid Reflector Centre	\$	<i>SL</i> 217.97	} X
22	1	Bootlid Reflector RH	\$	<i>SL</i> 128.40	
23	1	Bootlid Reflector LH	\$	<i>SL</i> 128.40	
24	1	Rear Tail Lamp RH	\$	<i>SL</i> 479.30	
25	1	Rear Tail Lamp LH	\$	<i>SL</i> 479.30	
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00	

Trans-cab Auto Services Pte Ltd**AAD1901-066**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7827E

TOTAL	\$	10,553.55
10%	\$	1,055.36
	\$	9,498.20

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	na	40.00	X
2	1Set	Rear Bumper Parking Sensor	\$	sn	300.00	X
3	1Set	Rear Bumper Fastener Clip	\$	na	44.00	✓
4	1Set	Rear Fender Inner Trim Clip LH	\$	na	30.00	X
5	1Set	Rear Bumper End Dust Cover Clip	\$	na	30.00	X
6	1	Rear Exhaust Mounting	\$	sn	300.00	X
7	2	Rear Windscreen Sealant	\$	na	80.00	X
8	1	Rear Windscreen Inner Sponge Seal	\$	sn	100.00	X
9	1	Rear boot sticker 'Trans-cab'	\$	na	80.00	30sn
10	1	Rear boot sticker '6555-3333'	\$	na	80.00	30sn ✓

TOTAL	\$	1,084.00
--------------	-----------	-----------------

TOTAL PARTS	\$	10,582.20
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 3,500.00 600L

To Check Electrical Lighting Concerned.

\$ 170.00 20L

To Rust-Proofing Of The Affected Areas.

\$ 170.00 60L

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 600L

To reinstall rear bumper parking sensor.

\$ 170.00 50L

Trans-cab Auto Services Pte Ltd**AAD1901-066**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7827E

To transfer of end panel fittings and conduct
water seepage test. \$ 170.00 *601*

To transfer of boot fittings and conduct water
seepage test. \$ 170.00 *601*

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair. \$ *nn* 380.00 *X*

To check steering geometry and computer wheel
alignment \$ *nn* 220.00 *X*

\$ **7,950.00**

TOTAL \$ 18,532.20

Repair Days (LUMP SUM)~~**10 DAYS**~~*5 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: