

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Irene Wong Lee Ping
Blk 191 Boon Lay Drive
#06-212
Singapore 640191

Not Authorized
CIR 833004
Preserving After Pain
3 days

Estimate Cost Of Repair

QTY	DESCRIPTION	UNIT PRICE	TOTAL
1 pc	Front o/s door assy	\$1,286.90	✓
1 pc	Front o/s door weatherstrip	\$249.10	X
1 pc	Front o/s door frame black sticker	\$85.20	✓
1 pc	Front o/s door inner trim board	\$655.10	X
1 pc	Front o/s door inner lock	\$539.70	X
1 pc	Front o/s door glass regulator	\$299.10	X
1 pc	Front o/s door glass regulator motor	\$538.70	✓
2 pcs	Front o/s door hinge	\$85.10	X
1 pc	Front o/s door view mirror	\$1,187.60	✓
1 pc	Front o/s door view mirror outer cover	\$86.70	✓
1 p	Front o/s door glass	\$5,098.30	4070.60
1 p	Front o/s fender emblems	\$1,274.57	1,017.65
		\$3,823.73	3052.95
	Labour Charges		

Remove/renew the above parts. Knock out & straighten n/s door centre pillar etc

\$800.00 3501

To putty & spray paint on accident affected portion.

\$800.00 5201

Check/reconnect wiring.

\$30.00 201

To spray anti rust on accident affected portion.

\$100.00 301

Remove/refit front & rear n/s door glass, mechanism, inner lock, trim board to new door.

\$180.00 601

Total

\$5,733.73

6,46326

6903.05

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Fax : 64816131

Irene Wong Lee Ping
Blk 191 Boon Lay Drive
#06-212
Singapore 640191

Vehicle No : SLW 3083 C
Make : Toyota Altis
Year : 2016

MR053RE1410
4555249

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Supplementary Part

1 pc	Front o/s door power window control switch	681.80	\$972.70 ✓
		Less 25 %	\$243.17
			<u>\$729.53</u>

Hi Kenneth

Part - 3,052.95
Supplementary - 729.53
Labour - 980.00
4,762.48

Lease fee ~~3,800.00~~ - 3 days