

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



*14 Jan 2019
14 Spray and
repair*

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

09 JAN 2019

Estimate No. : b1 49699	Page No. : 1 of 5
Date Estimated : 09/01/2019	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Chia Choon Kee 2 Meng Suan Road Singapore 779205	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK1591R	D291541	13/06/2013	520iA	0

DESCRIPTION	VALUE
Replace rear boot lid, rear bumper and remove front bumper attachment etc include conduct accident repairs	2125 2,550.00
Spray painting front bumper, rear bumper and rear boot lid	2802 3,114.00
To supply front and rear emboss number plate.	165.00
To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.	250. 295.00
To carry out body cavity preservation. (Per panel).	100? 118.00
Sundries.	? 150.00
Total Labour 1:	6,392.00

DESCRIPTION	QTY	PRIC	VALUE
BLIND RIVET NUT M6	3	2.55	7.65
BOOTLID	1	1,642.45	1,642.45
SET MOUNTS PDC SENSOR REAR (PDC)	1	58.60	58.60
RR BUMPER BOTTOM CENTRE GUIDE	1	60.45	60.45
RR BUMPER CTR GUIDE	1	69.05	69.05
RR BUMPER CARRIER	1	772.05	772.05
RR BUMPER PANEL PRIMED (PDC)	1	1,563.25	1,563.25
RR BUMPER TOW HOOK COVER PRIMED	1	47.60	47.60
LH PROTECTION FOIL	1	15.55	15.55
RH PROTECTION FOIL	1	15.55	15.55
PROTECTION FOIL L=55MM	2	4.75	9.50
RR BUMPER ADAPTER	1	50.65	50.65
EMBLEM GROMMET	2	0.80	1.60
MODEL LETTERING 520I	1	64.10	64.10
BMW EMBLEM	1	71.25	71.25
TRIGGER CONTACT	1	135.25	135.25
BOOTLID SEALING	1	115.25	115.25

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740159W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49699	Page No. : 2 of 5
Date Estimated : 09/01/2019	
Prepared By : Chua Kee Sin	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK1591R	D291541	13/06/2013	520iA	0

DESCRIPTION	QTY	PRIC	VALUE
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
BUMPER PDC SENSOR (SCHWARZ)	4	236.85	947.40
Total Parts :			5,667.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 17/1/19 @ 2:10pm Excess S\$ _____

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 97245729 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tanjiah@lkkauto.com

No. of Working Days Recommend 5-6 days

Labour 1	:	6,392.00
Parts	:	5,667.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	844.16
Grand Total	:	12,903.56

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **