

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 29 Jan 2019

Preliminary Advice

Vehicle No	: SFX295T	Accident Date	: 08/01/2019
Make	: BMW 116I	Policy No.	: B27798857SMP
Assignment Date	: 10/01/2019	Excess	: S\$1,000.00
Date of Inspection	: 24/01/2019	Est. Duration of Repair	: 7 days
Inspection At	: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,492.20
Revised Amount	:S\$	15,863.80
Check Items (Estimated)	:S\$	77.00
Total	:S\$	15,940.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	54,602.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,398.00

Remarks

(X) The vehicle is economical for repair. Repairer able to undertake the repair cost not exceeding \$ 14,000.00 on part by part basis.

() The above survey was conducted on a 'without prejudice' basis.