

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 14 Jan 2019

Preliminary Advice

Vehicle No	: SFX295T	Accident Date	: 08/01/2019
Make	: BMW 116I	Policy No.	: B27798857SMP
Assignment Date	: 10/01/2019	Excess	: S\$1,000.00
Date of Inspection	: 11/01/2019	Est. Duration of Repair	: 12 days
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,903.31
Revised Amount	:S\$	23,989.40
Check Items (Estimated)	:S\$	6,555.70
Total	:S\$	30,545.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	54,602.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,398.00

Remarks

- () The vehicle is economical/not economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.
- (X) Other Comments : We are pending repair cost from repairer.