

ASS. REC. BY:

REP CS / MSG 19000640 / R1sd302S. Y. YOUNG
M. M. M. M.

R. S. S. S.

ASSIGNMENT (Office)

From (Person):

Jacelyn Ng

of

MSG

Date/Time

10/1/19 @ 4:34pm

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8FX 295T

Insured:

at Workshop m/s

Vin's Motor

Tel:

6453 2121

of

160 Sin Ming Drive #03-03

Policy No:

B277988575mp

Claim No:

581809

Sum Insured:

Excess:

\$1000.00

Make of Veh:

(Client's Record)

D.O.A.

08/01/2019

CA / (REV) /

REP. / REV 24 HRS

Date/Time:

10/1/19 @

Person Contacted:

Raymond

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	8FX 295T - (CA/AXA 11020635/Ghd) DOA: 1/10/2011
	Received at V.I.S on 24/01/19
22/01/19	@ 17:38 p.m. authorize approval via email.
29/01/19	@ 16:17 p.m. revert authorize repair to Raymond (repairer) via email.
29/01/19	@ 16:47 p.m. revised IA to Jacelyn Ng via messenger.

ASS. REC BY:

REF

es/MSG19000640/Rlsd3

Special Instructions:

Surveyor

Merimen

From (Person)

Raisul
Jocelyn Ng

ASSIGNMENT (Office)

of MSIG

Date/Time 10/1/19 @ 4:34pm

Estimated Cost

Bill to

OD/TP/WS/TP RES/OD RES/EVA/ENV/MV/CS

To Inspect Vehicle No.

8FX 295T

Insured:

at Workshop m/s

performance

Tel:

91165700

of

303 Alexander Road

Policy No: B27798857SMP

Claim No:

Sum Insured

Excess: \$1,000.00

Make of Veh:

(Client's Record)

D.O.A. 08/01/2019

11/1/19

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

5:04pm @ 10/1/19

Person Contacted

Mr. Hen

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate pls check Brake & tyre condition and
8FX 295T-X revert with market value.

14/01/19

@ 15:46 p.m. revised IA to Jocelyn Ng sh'n Bus
via merimen.

15/01/19

@ 10:58 a.m. mandate requested authorize repair to
Jocelyn Ng via merimen.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jan 2019 12:17		10 Jan 2019 16:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: PHUA CHIA WI , ID: S7440164C, Tel: +6597767655	Date of Loss: 08/01/2019 17:00 - :59 [50 Months and 8 Days From LTA Reg Date (Man Yr)]
Vehicle Reg. No.: SFX295T	Policy/Cover Note No.: B27798857SMP (Comprehensive) Coverage: 31/10/2018 - 30/10/2019
Claim Type: OD	Excess: S\$1,000.00
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174	
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/01/2019]	
Driver/Custodian: CHU YI CHING (42 / Female), NRIC: S7641428I, Tel: +6591733489	
Adj Asg. Remarks: Car is in. Please check brake & tyre condition and revert with market value. Thank you.	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Han Kwan Yong <han.kwan.yong@simedarby.com.sg>
Sent: Tuesday, 15 January 2019 10:51 AM
To: Rasul (LKKAuto); sur@lkkauto.com
Subject: RE: SFX 295T DOA : 08/01/19

Dear Rasul,

Feedback from our workshop we are unable to repair limit at 15K course the cost of the parts require to replace already exceeded 15k.

Please arrange with the insured for the vehicle to be tow out soonest possible.

Thank you.

Regards,

Han K.Y.

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Monday, January 14, 2019 9:10 AM
To: Han Kwan Yong <han.kwan.yong@simedarby.com.sg>
Subject: SFX 295T DOA : 08/01/19

Hi Han,

Repair limit to repair this vehicle is 15K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Rasul
LKK Auto Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Monday, 14 January, 2019 9:10 AM
To: 'Han Kwan Yong'
Subject: SFX 295T DOA : 08/01/19

Hi Han,

Repair limit to repair this vehicle is 15K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 14 Jan 2019

Preliminary Advice

Vehicle No	: SFX295T	Accident Date	: 08/01/2019
Make	: BMW 116I	Policy No.	: B27798857SMP
Assignment Date	: 10/01/2019	Excess	: S\$1,000.00
Date of Inspection	: 11/01/2019	Est. Duration of Repair	: 12 days
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,903.31
Revised Amount	:S\$	23,989.40
Check Items (Estimated)	:S\$	6,555.70
Total	:S\$	30,545.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	54,602.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,398.00

Remarks

- () The vehicle is economical/not economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.
- (X) Other Comments : We are pending repair cost from repairer.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740155W GST Reg. No M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Karpong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/310 (Motorrad)
Fax. 64794601 (AfterSales)
64794624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49707
Date Estimated : 09/01/2019
Prepared By : Han Kwan Yong

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -
Phua Chia-Wi (Pan Jiawei)
2 Lincoln Road
#27-01

Singapore 308342

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFX295T	P580278	31/10/2014	116iA/5	0

DESCRIPTION

VALUE

To tow accident vehicle to PML workshop.

195.00

To replace front bumper & attachments, bonnet, front right fender, front cross link, right headlight support arm, front center air duct, front right wheel house supporting strut including to pull & straighten front right wheel house supporting strut before cutting and to knock out dented area caused by the accident

7225 8,500.00

To respray front bumper, front right fender, front left fender, bonnet and front right wheel house

4099 4,554.00

To replace radiator assembly, fan housing with fan including to conduct pressure test, bleed bleed cooling system and check for leak. (For all models except 7 series).

702 828.00

To mount accident vehicle on speed bench to facilitate pulling & re-alignment of body/chassis according to BMW specification

564 664.00

To remove and install fuse box to facilitate front section repairs.

451 531.00

To replace left headlight.

408 481.00

To replace right headlight.

408 481.00

To diagnose and replace right headlight control unit/modules include programming and conducting tests for proper function

7226 256.00

To replace air con condenser including to vacuum system, top up freon gas and check for leak. (For all models except for 7 series).

852 1,003.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49707
Date Estimated : 09/01/2019
Prepared By : Han Kwan Yong

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFX295T	P580278	31/10/2014	116iA/5	0

DESCRIPTION

Sundries.

VALUE

150.00

Total Labour 1: 17,828.00

DESCRIPTION

HOSE CLAMP ?
COVER (INTEGRATED MODULE) ?
BRACKET (INTEGRATED MODULE) ?
Hose clamp ?
INTAKE SILENCER ?
INTAKE DUCT ?
INTAKE DUCT ?
FILTERED AIR PIPE ?
INTAKE MANIFOLD FRONT ?
BRACKET UPPER ?
SUPPORT SLEEVE ?
RADIATOR MODULE MOUNT LH ?
RADIATOR MODULE MOUNT RH ?
MODULE MOUNTING ?
RADIATOR UPPER SEALING ?
BRACKET FOR MODULE LH ?
BRACKET FOR MODULE RH ?
RADIATOR ?
RADIATOR EXPANSION TANK ?
FAN HOUSING WITH FAN 300W ?
RH SUPPORTING STRUT WHEEL HOUSE INT ?
FRT RH FENDER *na* ✓
BONNET *na* ✓
CLOSING PLATE CARRIER SUPPORT *CR* ✓
FRT RH 2 SIDE PANEL BRACKET *na* ✓
FRT RH 2 SIDE PANEL BRACKET *na* ✓
BONNET RH HINGE ?
RIVET ?
FRT RH SIDE PANEL SUPPORT *na* ✓
FRT BUMPER SHOCK ABSORBER *CR* ✓
FRT BUMPER TOP MOUNT ?
FRT BUMPER RH INSERT ?
FRT BUMPER FLAP TOWING EYE P *SC* ✓
FRT BUMPER PANEL PRIMED (SRA) *TD* ✓
FRT LH GRILLE (BASIS) *MS* ✓
FRT RH GRILLE (BASIS) *MS* ✓
EMBLEM GROMMET *na* ✓
RIVET *na* ✓
LH LOWER PART OF HOOK LOCK ?
RH LOWER PART OF HOOK LOCK *na* ✓
TWIST PROTECTION ?
BONNET CATCH BRACKET *na* ✓
STOP BUFFER *na* ✓

QTY

PRIC

VALUE

1	4.70	4.70
1	50.55	50.55
1	51.70	51.70
1	9.85	9.85
1	436.75	436.75
1	69.25	69.25
1	69.25	69.25
1	143.65	143.65
1	31.50	31.50
2	21.85	43.70
2	3.65	7.30
1	77.60	77.60
1	77.60	77.60
2	15.35	30.70
1	35.45	35.45
1	35.80	35.80
1	35.80	35.80
1	780.55	780.55
1	197.60	197.60
1	1,186.90	1,186.90
1	264.30	264.30
1	559.65	559.65
1	1,172.85	1,172.85
1	99.85	99.85
1	34.25	34.25
1	34.25	34.25
1	74.75	74.75
10	0.50	5.00
1	12.50	12.50
1	45.60	45.60
1	378.10	378.10
1	7.60	7.60
1	38.95	38.95
1	862.90	862.90
1	90.65	90.65
1	90.65	90.65
2	0.80	1.60
10	0.45	4.50
1	87.95	87.95
1	87.95	87.95
2	5.45	10.90
1	25.75	25.75
2	13.90	27.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 137401559W GST Reg. No M2-0020081-X



302, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

118, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796626 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49707
Date Estimated : 09/01/2019
Prepared By : Han Kwan Yong

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFX295T	P580278	31/10/2014	116iA/5	0

DESCRIPTION	QTY	PRIC	VALUE
FRONT PANEL V STRUT M ✓	1	112.15	112.15
RH SUPPORT	1	55.30	55.30
LH MOUNT FOR HOOD ?	1	8.20	8.20
RH MOUNT FOR HOOD	1	8.20	8.20
FRONT CROSSLINK M ✓	1	168.25	168.25
LOCK PANEL ?	2	9.70	19.40
C CLIP NUT ✓	14	1.30	18.20
FRT RH WHEEL HOUSING COVER FRT SECT ?	1	104.90	104.90
AIR DUCT RADIATOR ✓	1	61.50	61.50
AIR DUCT BOTTOM ?	1	55.95	55.95
SUPPORT FRT END ?	1	16.35	16.35
ADJUSTER ?	4	6.30	25.20
FRONT ENGINE HOOD SEALING ✓	1	38.85	38.85
PLAQUE 82MM ✓	1	71.25	71.25
# RH TELESCOPIC NOZZLE ?	1	159.85	159.85
# LH BI-XENON HEADLIGHT ✓	1	1,801.75	1,801.75
RH BI-XENON HEADLIGHT ✓	1	1,801.75	1,801.75
DRIVER MODULE FOR HEADLIGHT ?	1	763.70	763.70
# CONTROL UNIT XENON LIGHT ?	1	867.85	867.85
CONDENSER AIR CONDITIONING M ✓	1	1,028.45	1,028.45
# (DG/SL) ADHESIVE GLUE ✓	1	326.80	326.80
PUNCH RIVET N5 ✓	25	0.55	13.75
(DG) CLEANER R1 (100ML) ✓	1	26.15	26.15
(S/L) SEAM SEAL 300ML ✓	2	33.80	67.60
ANTI-FREEZE 1.5 LITRES ✓			59.25

LKK Auto Consults is hereby
the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Revised:

15,075.10

Claims OD 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 11/01/19 @ 1540 Excess S\$ _____
Surveyor's Name Rasul Sign _____
Surveyor's Tel 90010068 Authorised Yes (X)
Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR (Yes/No) PML Yes/No
Surveyor's E-mail rasul@lkkauto-jem
No. of Working Days Recommended 12 days

Resurvey 34 part

Labour 1	:	17,828.00
Parts	:	15,075.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,303.22
Grand Total	:	35,206.32

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

120, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : **b1 49707**
Date Estimated : **09/01/2019**
Prepared By : **Han Kwan Yong**

Page No. : **4 of 6**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFX295T	P580278	31/10/2014	116iA/5	0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

160, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63198888 (AfterSales)
Fax: 63449773

119, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/535 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 49707**
Date Estimated : **09/01/2019**
Prepared By : **Han Kwan Yong**

Page No. : **5 of 6**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFX295T	P580278	31/10/2014	116iA/5	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
 - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
 - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

117, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190128 (AfterSales)
63190531/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 49707**
Date Estimated : **09/01/2019**
Prepared By : **Han Kwan Yong**

Page No. : **6 of 6**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFX295T	P580278	31/10/2014	116iA/5	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- put his request in writing;
 - provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- put his request in writing by way of an email sent to the Vendor;
 - provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer
Performance Motors Limited

Address:
Sime Darby Performance Centre
303 Alexandra Road
Singapore 159941

Email address:
dataprotection@pml.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0164C
Vehicle Details	
Vehicle No.:	SFX295T
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116i A/T ABS D/AIRBAG 2WD 5DR HID DSC
Primary Colour:	Orange
Manufacturing Year:	2014
Engine No.:	A387J833N13B16A
Chassis No.:	WBA1A12040P580278
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$25,061.00
Original Registration Date:	31 Oct 2014
First Registration Date:	31 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$17,086.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2024
PARF Rebate Amount:	\$12,814.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$72,201.00
COE Rebate Amount:	\$41,788.00
Total Rebate Amount:	\$54,602.00

The information contained herein is correct as at 10 Jan 2019

OK

> Back to OneMotoring



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0164C
Vehicle Details	
Vehicle No.:	SFX295T
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jan 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116I A/T ABS D/AIRBAG 2WD 5DR HID DSC
Primary Colour:	Orange
Manufacturing Year:	2014
Engine No.:	A387J833N13B16A
Chassis No.:	WBA1A12040P580278
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$25,061.00
Original Registration Date:	31 Oct 2014
First Registration Date:	31 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$17,086.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2024
PARF Rebate Amount:	\$12,814.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$72,201.00
COE Rebate Amount:	\$41,710.00
Total Rebate Amount:	\$54,524.00

The information contained herein is correct as at 14 Jan 2019

OK

70,000
54,524
15,476

15K

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 8 March 2019 10:30 AM
To: 'Admin @ VAuG'
Cc: SUR; Rasul (LKKAuto); Veron Chen (LKKAuto)
Subject: RE: SFX295T Finalization

Dear Raymond,

Confirmed final fig \$14,000.00 (part by part) @ 7 days of repairs before excess \$1,000/- & GST.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin @ VAuG [mailto:admin@vinsautogroup.com.sg]
Sent: Friday, 8 March 2019 9:39 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; rasul@lkkauto.com; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: SFX295T Finalization

Good morning,
Please advise.
Thanks!
Best Regards
Raymond Teo

On Wed, Feb 27, 2019 at 1:31 PM Admin @ VAuG <admin@vinsautogroup.com.sg> wrote:

Good afternoon,
Can we confirm the final amount @ \$14000 before excess and GST?
Thanks!
Best Regards
Raymond Teo

On Thu, Feb 14, 2019 at 10:06 AM Admin @ VAuG <admin@vinsautogroup.com.sg> wrote:

Good morning,
Can we finalize this case @ \$14000 before excess?
Thanks!
Best Regards
Raymond Teo



Sin Ming AutoCity
160 Sin Ming Drive
Singapore 575722
Showroom/Office: #03-03
Workshops: #08-08/09
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **
** w.e.f 20th November 2017, we have changed our email address! **

--



Sin Ming AutoCity
160 Sin Ming Drive
Singapore 575722
Showroom/Office: #03-03
Workshops: #08-08/09
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **
** w.e.f 20th November 2017, we have changed our email address! **

--



Sin Ming AutoCity
160 Sin Ming Drive

Singapore 575722
Showroom/Office: #03-03
Workshops: #08-08/09
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 29 January 2019 4:17 PM
To: 'Admin @ VAuG'
Cc: 'SUR'
Subject: SFX 295T OD (MSIG)

Dear Raymond,

As instructed by our client, please proceed at repair cost not exceeding \$ 14,000.00 (inclusive supplementary) to repair the insured vehicle **SFX 295T (Excess \$ 1000/-)** on part by part basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 25 January 2019 12:34 PM
To: 'Jocelyn Ng'; assignments
Cc: SUR; 'Eng Huey Ni'
Subject: RE: MSIG REF: 581809; VEH NO: SFX295T; DOA: 08/01/2019

Hi Jocelyn,

Noted.

Dear Assignment Team,

Kindly assist.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jocelyn Ng [mailto:jocelyn_ng@sg.msig-asia.com]
Sent: Friday, 25 January 2019 12:18 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>
Subject: RE: MSIG REF: 581809; VEH NO: SFX295T; DOA: 08/01/2019

Hi Shirley,

As spoken, please arrange to survey the vehicle at Vin's Motor Pte Ltd. No Audatex required for this case.

Thank you

Have a great week ahead!

Jocelyn Ng

Executive, Claims Services

D: +65 6594 2539 | F: +65 6225 7402 | jocelyn_ng@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Jocelyn Ng
Sent: Tuesday, 22 January, 2019 5:38 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>
Subject: RE: MSIG REF: 581809; VEH NO: SFX295T; DOA: 08/01/2019

Hi Shirley,

Vehicle will be repaired at Vin's Motor Pte Ltd at \$14,000 part-by part basis (including check items & supp parts).

Thank you
Have a great week ahead!

Jocelyn Ng
Executive, Claims Services
D: +65 6594 2539 | F: +65 6225 7402 | jocelyn_ng@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Wednesday, 16 January, 2019 3:30 PM
To: Jocelyn Ng <jocelyn_ng@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>; Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>
Subject: RE: MSIG REF: 581809; VEH NO: SFX295T; DOA: 08/01/2019

Hi Jocelyn,

We have checked with repairer, they are unable to accept the repair limit at \$ 15,500.00.

They required \$ 28,000.00 to repair this vehicle.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jocelyn Ng [mailto:jocelyn_ng@sg.msig-asia.com]
Sent: Wednesday, 16 January 2019 3:11 PM
To: ShirleyHiew@lkkauto.com
Cc: SUR <sur@lkkauto.com>; Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>
Subject: MSIG REF: 581809; VEH NO: SFX295T; DOA: 08/01/2019

Hi Shirley,

Please offer the repair limit at \$15,500 including check items and supplementary parts, subject to excess \$1,000.00.

Thank you

Have a great week ahead!

Jocelyn Ng

Executive, Claims Services

D: +65 6594 2539 | F: +65 6225 7402 | jocelyn_ng@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

View Received Message

This mail is associated with :

SFX295T (581809)

OD

Jan 8 2019 5:00PM

[PHUA CHIA WI]

Vin's Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 07/03/2019 19:35 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14000.00) - SFX295T - Claim Handler: Jocelyn Ng Shin Bun

Approved:14000.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 04 Mar 2019

Preliminary Advice

Vehicle No	: SFX295T	Accident Date	: 08/01/2019
Make	: BMW 116I	Policy No.	: B27798857SMP
Assignment Date	: 10/01/2019	Excess	: S\$1,000.00
Date of Inspection	: 11/01/2019	Est. Duration of Repair	: 7 days
Inspection At	: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,492.20
Revised Amount	:S\$	14,000.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,000.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	54,602.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,398.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 29 Jan 2019

Preliminary Advice

Vehicle No	: SFX295T	Accident Date	: 08/01/2019
Make	: BMW 116I	Policy No.	: B27798857SMP
Assignment Date	: 10/01/2019	Excess	: S\$1,000.00
Date of Inspection	: 24/01/2019	Est. Duration of Repair	: 7 days
Inspection At	: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,492.20
Revised Amount	:S\$	15,863.80
Check Items (Estimated)	:S\$	77.00
Total	:S\$	15,940.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	54,602.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,398.00

Remarks

- (X) The vehicle is economical for repair. Repairer able to undertake the repair cost not exceeding \$ 14,000.00 on part by part basis.
- () The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/01/2019 16:59
Date Of Accident	08/01/2019 17:30
Exact Location Of Accident	CTE TO SLE 0.1KM LAMP POST 618
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFX295T
Insured/Policyholder	
Name Of Registered Owner	PHUA CHIA WI
NRIC No	S7440164C
Email Address	JOEPHUA@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91733489
Alternative Phone No	OTHERS-97767655
Vehicle Particulars	
Manufacturer	BMW
Model	1 SERIES 116I AT
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27798857SMP
Cover Note Number	
Driver	
Name of Driver	CHU YI CHING
NRIC No	S7641428I
Date Of Birth	29/12/1976
Occupation	INDOOR
Date Of Driving Pass	20/04/1995
Driving Experience	23 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91733489
Fax Number	
Contact Number	
Email Address	QUYIXIN@YAHOO.COM.SG

Address	6 LINCOLN RD #19-11
Postcode	308345
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS2252X
Vehicle Make/Model/Colour	VOLVO XC60 BROWN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HERINCKX MIRIAM
NRIC/Passport Number	S7486250J
Contact Number	92334077
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 9 Jan 2020



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


There was a prior accident and vehicle GBB7829X was blocking the right lane of CTE towards SE 0.1 km near lamp post 616. Vehicle SKS 2252X was in front of me and managed to stop, ~~but~~ the bend where there was a bend in the road. I saw the cars stopped in front of me too late around the bend and could not stop in time ^{as the road was wet}. My vehicle SFX 2957 knocked into the rear of SKS 2252X. No one was injured. The road railings were already damaged ~~for~~ when we stopped and we made no contact with those railings.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

X 

Policyholder's Signature
Date & Time:

X 

Driver's Signature
(If driver is not the policyholder)
Date & Time:

9 Jan 3:30pm



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



AUTOMOTIVE GROUP

Our Ref : OD/012019/3749
Accident date: 8/1/2019
Your Ref : SFX295T

A Sin Ming Auto City
160 Sin Ming Drive #03-03
Singapore 575722
E 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
www.vinsautogroup.com.sg

Tax Invoice:

Date : 23/1/2019

Motor Claim Department
MSIG INSURANCE (SINGAPORE) PTE LTD
No.4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

ESTIMATE COST OF REPAIRS TO BMW 116I SFX295T

1 pc Front bonnet <i>BT</i>	\$ 900.00
2 pcs Front bonnet hinge @ \$60.00 <i>X SUC</i>	\$ 120.00
2 pcs Front bonnet absorber @ \$70.00 <i>X SUC</i>	\$ 140.00
1 pc Front bonnet insulator <i>X SUC</i>	\$ 190.00
8 pcs Front bonnet insulator clips @ \$3.00 <i>X SUC</i>	\$ 24.00
2 pcs Front bonnet lower lock @ \$165.00 <i>BT</i>	\$ 330.00
2 pcs Front headlamp @ \$1450.00 <i>BT</i>	\$ 2,900.00
2 pcs Front headlamp "HID" bulb @ \$240.00 <i>BT</i>	\$ 480.00
<i>(1/2)</i> 2 pcs Front headlamp brackets @ \$70.00 <i>BT</i>	\$ 140.00
2 pcs Front headlamp ECU @ \$630.00 <i>BT</i>	\$ 1,260.00
1 pc Front bumper <i>BT</i>	\$ 750.00
1 pc Front bumper towing cover <i>BT</i>	\$ 20.00
2 pcs Front bumper retainer @ \$10.00 <i>BT</i>	\$ 20.00
1 pc Front bumper reinforcement <i>BT</i>	\$ 340.00
1 pc Front bumper sponge <i>BT</i>	\$ 40.00
2 pcs Front bumper bracket @ \$70.00 <i>BT</i>	\$ 140.00
1 pc Front support (plastic) <i>CR</i>	\$ 110.00
1 pc Front air dust <i>CR</i>	\$ 130.00
1 pc Front top panel <i>BT</i>	\$ 180.00
1 pc Front V bar <i>BT</i>	\$ 100.00
1 pc Front ECU bracket (plastic) <i>CR</i>	\$ 480.00
2 pcs Front grille @ \$85.00 <i>CR</i>	\$ 170.00
1 pc Front oil cooler <i>BT</i>	\$ 630.00
1 pc Front air condensor <i>BT</i>	\$ 810.00
1 pc Front air cond pipe No 1 <i>X SUC</i>	\$ 270.00
1 pc Front air cond pipe No 2 <i>BT</i>	\$ 280.00
1 pc Front radiator <i>BT</i>	\$ 520.00
Balance b/d	\$ 11,474.00

Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

T 6453 2121 (4 lines) / 6458 1111 (24 hrs)

F 6459 9795 / 6459 0433

E admin@vinsautogroup.com.sg

W www.vinsautogroup.com.sg

Our ref: OD/052018/3575

Page 2

	Balance c/f	\$ 11,474.00
1 pc	Front radiator top hose <i>at-</i>	\$ 90.00
1 pc	Front radiator lower hose <i>at-</i>	\$ 140.00
1 pc	Front radiator fan assy <i>cat-</i>	\$ 900.00
1 pc	Front radiator top cover <i>? cat-</i>	\$ 70.00
1 pc	Front air cleaner box <i>cat-</i>	\$ 440.00
1 pc	Front air cleaner hose <i>X sue</i>	\$ 70.00
1 pc	Front RH fender <i>at-</i>	\$ 400.00
1 pc	Front RH fender inner fibric <i>X sue</i>	\$ 90.00
6 pcs	Front RH fender inner fibric clips @ \$3.00 <i>at-</i>	\$ 18.00
1 pc	Front RH fuse box <i>cat-</i>	\$ 370.00
1 pc	Front no plate <i>at-</i>	\$ 40.00
		<u>\$ 14,102.00</u>
	Add 10%	\$ 1,410.20
		<u>\$ 15,512.20</u>

To refill air cond gas
To repair front damages
To spray painting

1500
\$ 120.00 *100*
\$ 880.00 *700*
\$ 980.00 *700*
\$ 17,492.20

VIN'S MOTOR PTE LTD

14517.80
1500.00
16017.80

repair cost 14K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3/11/19
Resue
Hp 9001.001
7 days
P/P
24/01/19 @ 1200
Res by paint

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2019 17:30 Sendback Est	23 Jan 2019 17:35 S\$17,492.20	10 Jan 2019 16:34 Edit Adj Rpt	S\$14,000.00 Edit Estimates	S\$14,000.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: PHUA CHIA WI , ID: S7440164C, Tel: +6597767655									
Vehicle Reg. No.: SFX295T		Date of Loss: 08/01/2019 17:00 - 1:59 [50 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 581809		Policy/Cover Note No.: B27798857SMP (Comprehensive) Coverage: 31/10/2018 - 30/10/2019							
		Excess: S\$1,000.00							
Repairer: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 09/02/2019]									
Driver/Custodian: CHU YI CHING (42 / Female), NRIC: S76414281, Tel: +6591733489 Email: QUYIXIN@YAHOO.COM.SG									
Adj Asg. Remarks: Car is in. Please check brake & tyre condition and revert with market value. Thank you.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (07/03/2019): Alert - Adj Mandate Approved (S\$14000.00) - SFX295T - Claim Handler: Jocelyn Ng ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SFX295T (581809)
OD
Jan 8 2019 5:00PM
[PHUA CHIA WI]
Vin's Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	09/01/19 17:05	Video - Accident [Linked Accident Report Documents]	Load AVI	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	09/01/19 17:08	Accident Statement	Load HTM	
			Thumbnail	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	14/01/19 15:46	Adjuster Immediate Advice	Load HTM	
2	29/01/19 16:47	Adjuster Immediate Advice	Load HTM	
3	04/03/19 11:29	Adjuster Immediate Advice	Load HTM	
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	23/01/19 17:35	Repairer Estimates	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/01/19 15:51	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	14/01/19 15:51	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
4	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
5	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
6	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
7	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
8	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
9	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
10	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
11	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
12	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
13	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
14	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
15	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
16	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
17	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
18	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
19	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
20	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
21	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
22	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
23	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
24	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
25	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
26	14/01/19 15:51	General View	Load JPG	<input checked="" type="checkbox"/>
27	14/01/19 15:51	General View	Load JPG	


Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
				<input checked="" type="checkbox"/>
28	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
48	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
49	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
50	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
51	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
52	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
53	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
54	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
55	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
56	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
57	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
58	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
59	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
60	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
61	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
62	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
63	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
64	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
65	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
66	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
67	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
68	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
69	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
70	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
71	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
72	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
73	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
74	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
75	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
76	14/01/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
77	14/01/19 15:51	General View		<input checked="" type="checkbox"/>
78	14/01/19 15:51	General View		<input checked="" type="checkbox"/>
79	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
80	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
81	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
82	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
83	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
84	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
85	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
86	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
87	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
88	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
89	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
90	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
91	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
92	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
93	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
94	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
95	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
96	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
97	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
98	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
99	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
100	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
101	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
102	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
103	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
104	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
105	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
106	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
107	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
108	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
109	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
110	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
111	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
112	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
113	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
114	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
115	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
116	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
117	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
118	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
119	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
120	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
121	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
122	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
123	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
124	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
125	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
126	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
127	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
128	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
129	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
130	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
131	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
132	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
133	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
134	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
135	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
136	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
137	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
138	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
139	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
140	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
141	01/03/19 11:12	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/01/19 12:18	PARF COE		<input type="checkbox"/>
2	10/01/19 12:18	Transfer Fee Details		<input type="checkbox"/>
3	10/01/19 12:26	Estimate Repair Cost + GIA Report + CI + IC (OI) + IC + DL (OID)		<input type="checkbox"/>
4	10/01/19 12:28	TP GIA Report - SKS2252X		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/01/19 14:38	ESTIMATE.pdf		<input type="checkbox"/>
2	29/01/19 16:51	ESTIMATE (VIN'S).pdf		<input type="checkbox"/>
3	04/03/19 11:24	ESTIMATE MARKED.pdf		<input type="checkbox"/>

Linked Accident Report Documents

			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	09/01/19 17:05	Video - Accident	Load AVI	<input checked="" type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	09/01/19 17:08	Accident Statement	Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	09/01/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
14	09/01/19 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	09/01/19 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	09/01/19 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	09/01/19 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	09/01/19 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	09/01/19 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
20	09/01/19 17:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	09/01/19 17:04	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19000640/R1SD3E2

Date: 12/03/2019

REFERENCE

Insured/Claimant: PHUA CHIA WI Policy No: B27798857SMP
Date of Loss: 08/01/2019 Nature of Claim: OD Claim No: 581809

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFX295T
Make & Model: BMW 116i, 1.6 ABS D/AIRBAG 2WD 5DR HID DSC (A) Engine No: A387J833N13B16A
Reg. Date: 31/10/2014 (Man. Year: 2014) Chassis No: WBA1A12040P580278
Colour: Red Odometer: 40067 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$70,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,512.20	14,440.80	1,071.40	6.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	800.00	200.00	20.00
Paintwork Labour	980.00	700.00	280.00	28.57
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,492.20	15,940.80	1,551.40	8.87
Approved Total (Overridden) (S\$)		14,000.00		
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	16,492.20	13,000.00	3,492.20	21.17
+ GST 7.00/7.00% (S\$)	1,154.45	910.00	244.45	21.17
Nett Amount (S\$)	17,646.65	13,910.00	3,736.65	21.17

INSPECTION

Date of Assignment: 10/01/2019 Present Location: Vin's Motor Pte Ltd (Sin Ming)
Date Inspected: 11/01/2019 Inspected At: Vin's Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive, #03-03, Sin Ming
AutoCity
Singapore 575722
Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2019)
Parts:	144	BMW 116i 1.6 ABS D/AIRBAG 2WD 5DR HID DSC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFX295T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bonnet (WCP)	Bent	900.00 F	*900.00 F
2	2		*Front bonnet hinge @ \$60.00 (WCP)	Serviceable	120.00 F	*- F
3	2		*Front bonnet absorber @ \$70.00 (WCP)	Serviceable	140.00 F	*- F
4	1		*Front bonnet insulator (WCP)	Serviceable	190.00 F	*- F
5	8		*Front bonnet insulator clips @ \$3.00 (WCP)	Serviceable	24.00 F	*- F
6	2		*Front bonnet lower lock @ \$165.00 (WCP)	Bent	330.00 F	*330.00 F
7	2		*Front headlamp @ \$1450.00 (WCP)	Broken	2,900.00 F	*2,900.00 F
8	2		*Front headlamp HID bulb @ \$240.00 (WCP)	Not Working	480.00 F	*480.00 F
9	1		*Front headlamp brackets @ \$70.00 (2PCS)(WCP)	Bent-1pc only	140.00 F	*70.00 F
10	2		*Front headlamp ECU @\$630.00 (WCP)	Not Working	1,260.00 F	*1,260.00 F
11	1		*Front bumper (WCP)	Deformed	750.00 F	*750.00 F
12	1		*Front bumper towing cover (WCP)	Missing	20.00 F	*20.00 F
13	2		*Front bumper retainer @ \$10.00 (WCP)	Necessary	20.00 F	*20.00 F
14	1		*Front bumper reinforcement (WCP)	Bent	340.00 F	*340.00 F
15	1		*Front bumper sponge (WCP)	Cracked	40.00 F	*40.00 F
16	2		*Front bumper bracket @ \$70.00 (WCP)	Necessary	140.00 F	*140.00 F
17	1		*Front support (plastic) (WCP)	Cracked	110.00 F	*110.00 F
18	1		*Front air dust (WCP)	Cracked	130.00 F	*130.00 F
19	1		*Front top panel (WCP)	Bent	180.00 F	*180.00 F
20	1		*Front V bar (WCP)	Bent	100.00 F	*100.00 F
21	1		*Front ECU bracket (plastic) (WCP)	Cracked	480.00 F	*480.00 F
22	2		*Front grille @ \$85.00 (WCP)	Cracked	170.00 F	*170.00 F
23	1		*Front oil cooler (WCP)	Bent	630.00 F	*630.00 F
24	1			Bent	810.00 F	*810.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*Front air condensor (WCP)			
25	1		*Front air cond pipe No 1 (WCP)	Serviceable	270.00 F	*- F
26	1		*Front air cond pipe No 2 (WCP)	Bent	280.00 F	*280.00 F
27	1		*Front radiator (WCP)	Bent	520.00 F	*520.00 F
28	1		*Front radiator top hose (WCP)	Cut	90.00 F	*90.00 F
29	1		*Front radiator lower hose (WCP)	Cut	140.00 F	*140.00 F
30	1		*Front radiator fan assy (WCP)	Cracked	900.00 F	*900.00 F
31	1		*Front radiator top cover (WCP)	Cracked	70.00 F	*70.00 F
32	1		*Front air cleaner box (WCP)	Cracked	440.00 F	*440.00 F
33	1		*Front air cleaner hose (WCP)	Serviceable	70.00 F	*- F
34	1		*Front RH fender (WCP)	Bent	400.00 F	*400.00 F
35	1		*Front RH fender inner fibric (WCP)	Serviceable	90.00 F	*- F
36	1		*Front RH fender inner fibric clips @ \$3.00 (WCP)	Necessary	18.00 F	*18.00 F
37	1		*Front RH fuse box (WCP)	Cracked	370.00 F	*370.00 F
38	1		*Front no plate (WCP)	Bent	40.00 F	*40.00 F

F=Franchise part.

Sub Total (\$\$)	14,102.00	13,128.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,410.20	1,312.80
Total Parts (\$\$)	15,512.20	14,440.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray painting	New	980.00	700.00
<u>Labour Items</u>				
2	To refill air cond gas	New	120.00	100.00
3	To repair front damages	New	880.00	700.00
Gross Labour Cost (S\$)			1,980.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >