

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 16 Jan 2019

## **Preliminary Advice**

|                    |                                                                                                                                  |                         |              |
|--------------------|----------------------------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SKN8036R                                                                                                                       |                         |              |
| TP Vehicle No      | : SJM973E                                                                                                                        | Accident Date           | : 09/01/2019 |
| Make               | : NISSAN SYLPHY                                                                                                                  | Assignment Date         | : 11/01/2019 |
| Date of Inspection | : 11/01/2019                                                                                                                     | Est. Duration of Repair | : 10 days    |
| Inspection At      | : Torque 5 Bodyworks Pte Ltd (Kaki Bukit)<br>8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit<br>Singapore 415875 |                         |              |

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 32,294.67 |
| Revised Amount              | :S\$ | 14,856.64 |
| Check Items (Estimated)     | :S\$ | 13,491.95 |
| Total                       | :S\$ | 28,348.59 |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis. Some parts items pending parts prices.