

2/10/2019

ASS. REC. BY:

REF:

CS/MSG19000663/Bsd301

assignment @ Torque 5

Special Instruction:

Lucas

Surveyor

manman

Mr. Jim

ASSIGNMENT (Office)

From (Person):

Pauline Tham

of

MSG

Date/Time:

11/11/19 @ 9:04am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 973G

Insured:

SKN 8036R

at Workshop m/s

Torque 5

Tel:

6452 4457

931 6518

of

8 kuki Bkt Ave 4 # 01-19 / 50

Policy No:

80457436QMX

Claim No:

581816

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/01/2019

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9:54am 11/11/19

Person Contacted:

peach

Vehicle

IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SJM 973G - NA / AIG 19000445 / h4

DOA: 9/1/19

SKN 8036R - X

16/01/19

@ 09:33 a.m. revised IA to Pauline Tham via manman

- See my remarks

7/11/19
10413

REF: MSIG

ASSIGNMENT

From: Date: 11/01/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJM 973E

at Workshop n/s: Torque 5

at 8 Lecki Bukit Ave 4 # 01-19 / 50 perrier

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

10

days

Res:

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS upi

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SJM 973E

Yr Regn: 20/12/2008

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SUBARU

C.C. 1498

Colour: BLACK

A/C: Insured / Std / NI / NA

Sp. Reading: 93761

T/Radio: Insured / Std / NI / NA

Eng/No: EL15D591918

C/No: JF1GE3KS59G002984

Gen. Cond: Good / Fair / Poor / BurntSteering: Knotted / Jammed / Leaked / Burnt orBrake: Knotted / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65/15

R: 195/65/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A. 09/1/19

D.O.I. 11/1/19 1200

Survey held at

TORQUE 5

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
04/03/19	Confirmed L/S \$10,800/- @ 10 days with LTG (\$21,669.59 Red - 67%) MV 25,000/2 PV 13,615/2 NV 11,385/2

offer \$10,800/2 accepted by N/S

RECEIVED 29 MAR 2019

Date/Time, File Pass to?

24/03/19

1) Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.I: (\$ 10,800/- L/S)

Days Of Repair: 10

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

) S + RE: \$

) Photos

) Others

TOTAL

10

260

18/3/2019

Tajim
14/1/19

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Iss Auth'd	Status
Main	09 Jan 2019		11 Jan 2019 09:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	LEE TZE KEE, ID: S0143395D		[Created by insurer]	
Main Claimant:	MARIAM BTE HALIM, ID: S1565974B			
Vehicle Reg. No.:	SJM973E	Date of Loss:	09/01/2019 07:00 - :59 [53 Months and 21 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP	Policy/Cover Note No.:	80457936QMX Coverage: 29/05/2018 - 18/07/2019	
Vehicle Reg. No. (Insured):	SKN8036R	Policy No. (Claimant):		
		Excess:		
Repairer:	Torque 5 Bodyworks Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 64524457			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/01/2019]			
Adj Asg. Remarks:	LIABILITY CLEAR, TP AGREE WITH SJE -ASSIGN LKK AUTO CONSULTANTS PTE LTD.			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 5974B

Vehicle Details

Vehicle No.: SJM973E
Vehicle to be Exported: No
Intended Deregistration Date: 11 Jan 2019
Vehicle Make: SUBARU
Vehicle Model: IMPREZA 4DR 1.5R AWD 4AT ABS AIRBAG
Primary Colour: Black
Manufacturing Year: 2008
Engine No.: EL15D591918
Chassis No.: JF1GE3KS59G002984
Maximum Power Output: 79.0 kW (105 bhp)
Open Market Value: \$13,863.00
Original Registration Date: 20 Dec 2008
First Registration Date: 20 Dec 2008
Transfer Count: 0
Actual ARF Paid: \$13,863.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 19 Dec 2023
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$13,786.00
COE Rebate Amount: \$13,615.00
Total Rebate Amount: \$13,615.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 Jan 2019

OK


Subaru Impreza WRX 2.0A
(COE till 01/2023)
\$30,800

\$7,620 /yr

24-Jan-2008

1,994 cc

173,000 km

Sports

Available

A Car Without A Need For An Introduction! In Perfect Condition, Well Maintained! Flexible Loan Scheme Available, Trade In Welcome. Consignment Unit, Call Our Sales Team Now To Arrange Viewing.

CONSIGNMENT

Car Search:

Posted: 03-Jan-2019

Tags: 2008 Subaru Impreza, 2008 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru


Subaru Impreza SD 1.5R
(OPC)

-

N/A

30-Sep-2009

1,498 cc

-

Hatchback

Available
Auction Closing Time: 14th Jan 2019 at 05:00 PM

Rebate Amount As At 21-01-19 Is \$6223, Road Tax Till 29/9/2018.
NO FROM VIEW

Posted: 02-Jan-2019

Tags: 2009 Subaru Impreza, 2009 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru


Subaru Impreza 4D 1.5R
\$19,800

\$7,790 /yr

29-Jul-2010

1,498 cc

148,000 km

Sedan

Available

1 Owner Only With Low Mileage Done. In House Loan Available. Spacious And Neat Interior. Ideal For Short Term Drive Or Renewal Of COE In Future. Please Call Or Visit Us Now For Further Details.

Pure Motors Pte Ltd

Posted: 31-Dec-2018

Tags: 2010 Subaru Impreza, 2010 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru


The best car deals without the hassle!

We have over a thousand consignment cars available for sale at highly attractive prices. All without the need to do paperwork. Pick out your favourite car today.

Find out more!


Subaru Impreza 4D 2.0A R-S
(New 5-yr COE)
\$36,888

\$7,370 /yr

05-Dec-2009

1,994 cc

116,069 km

Sedan

Available

100% Accident Free. Clean And Neat Interior With Good Paint Job. All Our Cars Have Gone Through Complete Checks And All Necessary Repairs Done. Backed By Our Own In-House Workshop 6 Months Warranty O...

PREMIUM LIST

Posted: 31-Dec-2018

Tags: 2009 Subaru Impreza, 2009 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru


Subaru Impreza WRX 2.5M
(COE till 08/2022)
\$25,888

\$7,240 /yr

08-Aug-2007

2,457 cc

190,000 km

Sports

Available

Meticulously Maintained By Pro Subaru Workshop, Low Engine Mileage, Hassle Free. Serious Buyers Call/Whatsapp To Enquire.

DIRECT OWNER

Posted: 29-Dec-2018

Tags: 2007 Subaru Impreza, 2007 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru


Subaru Impreza 4D 1.5R
(OPC)
\$14,000

\$5,320 /yr

03-Apr-2010

1,498 cc

-

Sedan

Available

Well Maintenance, New Paint.

DIRECT OWNER

Posted: 28-Dec-2018

Tags: 2010 Subaru Impreza, 2010 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru


Subaru Impreza 5D 1.6i-S
\$75,000

\$8,090 /yr

14-Jun-2017

1,600 cc

6,580 km

Hatchback

Available

Subaru Impreza 1.6 AWD, Registered At 14 June 2017, 13 Months Old, Mileage 6580 Only. Well Maintained Unit. Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.

CONSIGNMENT

Carro

Posted: 28-Dec-2018

Tags: 2017 Subaru Impreza, 2017 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru


Subaru Impreza 4D 1.5R
\$13,800

\$6,550 /yr

18-Dec-2009

1,498 cc

143,000 km

Sedan

Available

Manual Lovers! Genuine Low Mileage! Ready To Drive Off Immediately! Best In The Market! Contact/SMS Our Appointed Sales Person Directly For Enquiries, Viewing And Testing Immediately!

Posted: 27-Dec-2018

Tags: 2009 Subaru Impreza, 2009 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru


Subaru Impreza 4D 2.0A R-S
\$12,800

N/A

19-Feb-2009

1,994 cc

195,000 km

Sedan

Available

Car Is In Pristine Condition, Owner Has Taken Care Of Car Very Well, No Repairs Needed, Owner Selling Due To Upgrade, Car Is Really Ideal For Renewal, Consignment Unit, Coe Loan Can Be Arranged, Insur...

Premi Roy Motoring

Posted: 26-Dec-2018

Tags: 2009 Subaru Impreza, 2009 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru


Subaru Impreza 1.6A (COE till 06/2022)
\$26,800

\$7,860 /yr

08-Jun-2007

1,597 cc

80,000 km

Sedan

Available

Immaculate Condition. Owner Is A Car Enthusiast, Fully Done Up With Receipts. Comes With Many Free Gifts And Further Accessories. Please Call To View This Beauty.

CONSIGNMENT

Premi Roy Motoring

Posted: 24-Dec-2018

Tags: 2007 Subaru Impreza, 2007 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru

Compare


Subaru Impreza WRX 2.0M
 (COE till 05/2027)

\$67,888

\$8,110 /yr

24-May-2007

1,994 cc

175,000 km

Sports

Available

Well Known Car In The Early 2000s! The Best Time To Own This Car! At About \$8k Depreciation, Be A Legend! A Car That Speaks For Itself, Daily Driven With The Feel Of A Rally Car, With The Infamous St...

Prem Roy Motoring

Posted: 21-Dec-2018

Tags: 2007 Subaru Impreza, 2007 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru

EXPRESS CAR


Subaru Impreza 4D 1.5R

\$16,500

\$8,500 /yr

20-Jan-2010

1,498 cc

165,000 km

Sedan

Available

Always Parked Under Sheltered, Quiet And Smooth Engine, Regularly Timely Serviced, 2nd Car In The Family. Hassle Free And Accident Free. No Repair Needed, Sincere Buyers Please Come Forward To Contact...

Posted: 21-Dec-2018

Tags: 2010 Subaru Impreza, 2010 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru

EXPRESS CAR


Subaru Impreza 5D 1.5R (New 5-yr COE)

\$25,800

\$3,160 /yr

22-Dec-2008

1,498 cc

118,000 km

Hatchback

Available

\$0 Down Payment Available, We Only Select The Best Unit To Sell. All Our Car Come With New Paintwork To Ensure You Drive A Nice Car For Another 5 Or 10 Years Down The Road. Trade In Welcomed. Buy With...

Taxis

Posted: 19-Dec-2018

Tags: 2008 Subaru Impreza, 2008 subaru impreza, Subaru Impreza, subaru impreza, Subaru, Impreza, impreza, Used Subaru

Save this search criteria, to get email alerts whenever a match is found.

Home Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

< Back (1 2 3 4) Next >

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Subaru Impreza, Subaru Impreza Singapore, used Subaru Impreza Singapore, used Subaru Impreza, used vehicles Singapore or even buy used Subaru Impreza Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Shirley Hiew (LKK Auto)

From: Torque 5 Assessment <assessment@torque5.com>
Sent: Friday, 29 March 2019 12:25 PM
To: 'Shirley Hiew (LKK Auto)'
Cc: 'Torque 5 Assessment'; claims@torque5.com; sam.chang@torque5.com
Subject: RE: SJM 973 E - After Repair Photo And Finalisation .

Dear Shirley ,



We hereby confirm the COR \$ 10800 with 10 days .

Thank You .

*Warmest Regards,
Lucas Chow*

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584
Mobile (65) 8131 6518
Email lucas.chow@torque5.com
Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 29 March 2019 11:27 AM
To: 'Torque 5 Assessment'
Cc: claims@torque5.com; sam.chang@torque5.com; Admin-D (LKKAuto)
Subject: RE: SJM 973 E - After Repair Photo And Finalisation .
Attachments: image022.wmz; ESTIMATE MARKED .pdf

Dear Lucas,

Confirmed final fig \$10,800.00 (lump sum) @ 10 days of repairs before GST.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Torque 5 Assessment [mailto:assessment@torque5.com]
Sent: Friday, 25 January 2019 6:02 PM
To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: 'Torque 5 Assessment' <assessment@torque5.com>; claims@torque5.com; sam.chang@torque5.com
Subject: SJM 973 E - After Repair Photo And Finalisation .

Dear All ,

Please kindly check the attach .

As spoken early , the Limit Repair COR \$ 10800 with 10 repair days .



Please kindly confirm .

Thank you .

Warmest Regards,

Lucas Chow

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

REVIVE YOUR D

Shirley Hiew (LKK Auto)

From: Torque 5 Assessment <assessment@torque5.com>
Sent: Friday, 25 January 2019 6:02 PM
To: Admin A; Admin-D (LKKAuto)
Cc: 'Torque 5 Assessment'; claims@torque5.com; sam.chang@torque5.com
Subject: SJM 973 E - After Repair Photo And Finalisation .
Attachments: image010.wmz; 20190125182008609.pdf; After Repair Photo.zip

Dear All ,

Please kindly check the attach .
As spoken early , the Limit Repair COR \$ 10800 with 10 repair days .



Please kindly confirm .

Thank you .

Warmest Regards,

Lucas Chow

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584
Mobile (65) 8131 6518
Email lucas.chow@torque5.com
Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875
www.torque5.com





LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 16 Jan 2019

Preliminary Advice

Insured Vehicle No	: SKN8036R	Accident Date	: 09/01/2019
TP Vehicle No	: SJM973E	Assignment Date	: 11/01/2019
Make	: NISSAN SYLPHY	Est. Duration of Repair	: 10 days
Date of Inspection	: 11/01/2019		
Inspection At	: Torque 5 Bodyworks Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4., #01-49/50/51/52/53/54 Premier @ Kaki Bukit Singapore 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,294.67
Revised Amount	:S\$	14,856.64
Check Items (Estimated)	:S\$	13,491.95
Total	:S\$	28,348.59

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. Some parts items pending parts prices.

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 09/01/2019 (dd/mm/yy) Time of Accident: 07:30 (24-HR-FORMAT)

Vehicle No.: SJM 973E Vehicle Make & Model: SUBARU IMPREZA

Exact location of Accident: CTE TOWARDS AYE AFTER ANG MO KIO AVE 5 EX17

Policyholder's Name / IC No.: MARIAM HAUM S1565974B

Driver's Name / IC No.: _____ (As Above) ☒

Driver's Contact No.: 97541904

Company Contact No: _____

Driver's Address: BK 33 MARILING DRIVE #11-357 S(730033)

Insurance Company: NTUC

Email address (if any): _____

Relationship between Owner & Driver: (Please **CIRCLE** one only)

☒ Owner / ☐ Spouse / ☐ Children / ☐ Friend / ☐ Parents / ☐ Sibling / ☐ Relative / ☐ Employee / ☐ Hirer or Others specify: _____

What do you wish to claim? (Please **TICK** one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

Occupation (nature of job) ☐ Indoor / ☒ Outdoor

☒ Private use / ☐ Work purpose

No. of Passengers (Including Driver): 02

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: SKN 8036R ⑤

Driver's Contact No: _____ Insurance Company (If any): _____

2. Driver's Name / IC No: _____ Vehicle No: SLB 1756T ⑥

Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

* If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date / time, I was travelling along the stated venue.

As I was travelling straight in my lane, veh B (SKN 8036 R) suddenly hit onto mine, the great impact pushed my car forward and hit onto veh C (SLB 1756 T), causing damages. It was a chain collision of 3 vehicles.

Passenger name: Saiful Andri Bin Sabrawi (male)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No: 201313221G

ESTIMATION REPORT

Vehicle No : SJM973E
Make & Model : SUBARU, IMPREZA 4DR 1.5R AWD 4AT ABS
AIRBAG, JF1GE3KS59G002984
Year of Manufacture : 2008

Estimation No. : E19010008
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	REAR BUMPER CRU ✓	1.00	0.00	0.00 762.00 ✓
2	REAR BUMPER RETAINER - SHORT } BR ✓	2.00	0.00 78.30	0.00 156.60 ✓
3	REAR BUMPER RETAINER - LONG } BT ✓	2.00	0.00 102.20	0.00 204.40 ✓
4	REAR BUMPER REINFORCEMENT BT ✓	1.00	0.00	0.00 362.60 ✓
5	REAR BUMPER REFLECTOR LAMP (LH+RH) NNX LHX? RH BR ✓	2.00	0.00 260.80	0.00 521.60 ✓
6	REAR BUMPER TOWING CAP CUT ✓	1.00	0.00	0.00 54.40 ✓
7	BOOT LID DD ✓	1.00	0.00 692.80	0.00 1158.00 ✓
8	BOOT LID HINGE ? ✓ BT @ 111.00	2.00	0.00 222.00	0.00 444.00 ✓
9	BOOT LID RUBBER BEADING ? ✓ NCC	1.00	0.00 188.20	0.00 211.60 ✓
10	BOOT LID EMBLEM - LOGO } NE CV	1.00	0.00 68.40	0.00 138.00 ✓
11	BOOT LID EMBLEM - SUBARU } NE CV	1.00	0.00 36.00	0.00 120.30 ✓
12	BOOT LID EMBLEM - IMPREZA } NE CV	1.00	0.00 40.00	0.00 115.70 ✓
13	BOOT LID CHROME GARNISH ? X-cut NNX	1.00	0.00	0.00 470.60 ✓
14	BOOT LID LOCK ? ✓ BT	1.00	0.00	0.00 190.30 ✓
15	BOOT LID LOCK CATCH ? X NNX	1.00	0.00	0.00 82.00 ✓
16	BOOT LID LOCK SWITCH ? NNX	1.00	0.00	0.00 0.00 ✓
17	BOOT LID INSULATOR ? ✓ CUT ✓	1.00	0.00	0.00 262.80 ✓
18	LICENSE LAMP BR ✓ @ 121.00	2.00	0.00 242.00	0.00 295.20 ✓
19	TAIL LAMP (LH+RH) BR ✓ RH NNX, LH-BR	2.00	0.00 622.00	0.00 1244.00 ✓
20	TAIL LAMP INNER PANEL (LH+RH) ? X RH NNX, LH-PDV	2.00	0.00 45.60	0.00 91.20 ✓
21	REAR END PANEL ? ✓ DDV	1.00	0.00	0.00 535.10 ✓
22	REAR END PANEL TOP GARNISH PL ✓	1.00	0.00 125.00	0.00 145.20 ✓
23	SPARE TYRE PANEL ? ✓ DDV	1.00	0.00	0.00 659.70 ✓
24	SPARE TYRE PANEL TOP BOARD ? ✓ CUT ✓	1.00	0.00	0.00 450.20 ✓

Continue on next page...

6286.80



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM973E
Make & Model : SUBARU, IMPREZA 4DR 1.5R AWD 4AT ABS
AIRBAG, JF1GE3KS59G002984
Year of Manufacture : 2008

Estimation No. : E19010008
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
25	SPARE TYRE SPONGE TOOL BOX ? X NN X	1.00	0.00	0.00 442.30
26	REAR EXHAUST MUFFLER ? ✓ BT NN X	1.00	0.00	0.00 479.84
27	REAR EXHAUST HEAT SHIELD ? X R X	1.00	0.00	0.00 130.30
28	FRONT BUMPER CRU ✓	1.00	✓ 0.00708.50	0.00 1053.20
29	FRONT BUMPER RETAINER } BT	1	✓ 0.00 64.00	0.00 182.60
30	FRONT BUMPER REINFORCEMENT	1.00	✓ 0.00 388.00	0.00 461.20
31	FRONT BUMPER SPONGE ? ✓ BR ✓	1.00	✓ 0.00 140.00	0.00 156.30
32	FRONT BUMPER LOWER GRILLE BR ✓	1.00	0.00	0.00 180.30 ✓
33	RADIATOR GRILLE BR ✓	1.00	0.00	0.00
34	RADIATOR GRILLE CHROME MOULDING BR ✓	1.00	0.00	0.00 785.80
35	RADIATOR GRILLE EMBLEM - LOGO NEC ✓	1.00	0.00	0.00
36	FOG LAMP (LH+RH) LH only, RH - NN X	1	✓ 0.00 364.00	0.00 821.20
37	FRONT BUMPER BRACKET NEC ✓ @ 85.30	2.00	0.00	0.00
38	BONNET DD ✓	1.00	0.00	0.00 1037.20
△ 39	BONNET HINGES BT ✓ LH, RH - NN	2.00	0.00 88.30 ✓	0.00 176.60 ✓
△ 40	BONNET DAMPER BT ✓ LH, RH - NN	2.00	0.00 146.50 ✓	0.00 293.00 ✓
41	BONNET LOCK BT	1.00	0.00	0.00 164.30
✓ 42	BONNET INSULATOR ? ✓ CUT	1.00	✓ 0.00 121.60	0.00 190.50
43	HEAD LAMP (LH+RH) BR ✓ @ 900.00	2.00	0.00 1180.30	0.00 2360.00
✓ 44	HEAD LAMP BRACKET ? ✓ BR ✓ @ 95.00	2.00	0.00 148.30	0.00 296.60
45	FRONT FENDER (LH+RH) DD ✓ @ 300.00	2.00	0.00 358.20	0.00 716.40
46	FRONT FENDER INNER SHIELD (LH+RH) ? TN ✓	2.00	✓ 0.00 176.40	0.00 352.80 ✓
47	FRONT SUPPORT PANEL ? ✓ BT ✓	1.00	✓ 0.00 495.70	0.00 695.70
48	HEAD LAMP PANEL (LH+RH) R X	2.00	0.00	-0.00
49	FRONT SUPPORT PANEL TOP GARNISH BR ✓	1.00	✓ 0.00 212.00	0.00 236.20

7627.90

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM973E
Make & Model : SUBARU, IMPREZA 4DR 1.5R AWD 4AT ABS
AIRBAG JF1GE3KS59G002984
Year of Manufacture : 2008

Estimation No. : E19010008
DOA : 09/01/2019

3900.94
35003.952

No	Description	Qty	U/P	Amt
50	FRONT DOOR (RH) R X	1.00	✓ 0.00 350.30	0.00 1134.50 ✓
51	A/C CONDENSER ? ✓ BTW	1.00	✓ 0.00 720.30	0.00 855.20
52	RADIATOR ? ✓ BRV	1.00	✓ 0.00 864.00	0.00 1052.90
53	RADIATOR TOP HOSE ? ✓	1.00	✓ 0.00 40.00	0.00 80.40
54	RADIATOR LOWER HOSE ? ✓ CUT ✓	1.00	✓ 0.00 40.00	0.00 78.60
55	RADIATOR FAN MOTOR COWLING SET ? ✓ BRV ✓	1.00	✓ 0.00 487.00	0.00 579.00 ✓
56	A/C FAN MOTOR COWLING SET ? ✓ BRV ✓	1.00	✓ 0.00 386.30	0.00 550.00 ✓
57	RADIATOR SPARE TANK ? ✓ BRV ✓	1.00	0.00 94.00	0.00 116.00
58	WASHER TANK ? ✓ BRV ✓	1.00	0.00	✓ 0.00 124.20 ✓
59	WASHER TANK MOTOR ? X UNX	1.00x2	0.00 80.80	0.00 161.60
60	A/C COMPRESSOR ? ✓ JMW NNX	1.00	0.00	0.00 1360.20
61	ALTERNATOR ? ✓ BRV	1.00	✓ 0.00 1710.00	0.00 1720.30 ✓
62	POWER STEERING PUMP ? ✓ JMW NNX	1.00	0.00	0.00 1340.50
63	ENGINE MAIN PULLEY ? ✓ JMW NNX	1.00	0.00	0.00 470.00
64	FAN BELTING SET ? ✓	1.00	0.00 25.00	0.00 150.00 ✓
65	FAN BELT TENSIONER ? ✓ CUT ✓	1.00	0.00	0.00 165.00 ✓

5997.6

Amt S\$ 0.00 30,169.7
Discount (20.00%) S\$ 0.00 24534.67
Subtotal S\$ 0.00

15,929.84

Section: Special Nett Items

66	REVERSE SENSOR SET CUT	1.00	250.00	-250.00
67	REVERSE CAMERA NNX	1.00	500.00	-500.00
68	REAR BUMPER CLIP SET	1.00	45.00	-45.00 30
69	TAIL LAMP CLIP SET	1.00	30.00	30.00 30
70	BOOT LID INSULATOR CLIP SET	1.00	45.00	-45.00 30

} NEC ✓

Continue on next page...

14470



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Torque 5 Pte Ltd

ESTIMATION REPORT

Vehicle No : SJM973E
Make & Model : SUBARU, IMPREZA 4DR 1.5R AWD 4AT ABS
AIRBAG, JF1GE3KS59G002984
Year of Manufacture : 2008

Estimation No. : E19010008
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
71	REAR END PANEL TOP GARNISH CLIP SET <i>NEC ✓</i>	1.00	30.00	30.00
72	EXHAUST MUFFLER MOUNTING SET ? <i>NECV ✓</i>	1.00	120.00 <i>80.00</i>	120.00 ✓
73	REAR END PANEL SEALANT <i>NEC ✓</i>	1.00	50.00	50.00 <i>30</i>
74	SPARE TYRE PANEL INSULATOR MATT ? <i>NECV ✓</i>	1.00	250.00	250.00 ✓
75	REAR NUMBER PLATE & CASING <i>BRV</i>	1.00	45.00	45.00 }
76	FRONT NUMBER PLATE & CASING <i>BRV</i>	1.00	45.00	45.00 } <i>50.00</i> ✓
77	FRONT BUMPER CLIP SET <i>NECV ✓</i>	1.00	45.00	45.00 <i>30</i>
78	BONNET INSULATOR CLIP SET <i>NECV ✓</i>	1.00	45.00	45.00 <i>30</i>
79	FRONT FENDER INNER SHIELD CLIP SET (LH) <i>NECV ✓</i>	1.00	45.00	45.00 <i>30</i>
80	FRONT FENDER INNER SHIELD CLIP SET (RH) <i>NECV ✓</i>	1.00	45.00	45.00 <i>30</i>
81	ENGINE COOLANT <i>NECV ✓</i>	1.00	80.00	80.00 <i>50.00</i>
82	AUTO TRANSMISSION FLUID 2L <i>NECV ✓</i>	1.00	160.00	160.00 <i>80.00</i>
83	RADIATOR HOSE CLIP SET <i>NECV ✓</i>	1.00	30.00	30.00 <i>20</i>
84	POWER STEERING FLUID 2L <i>NECV ✓</i>	1.00	120.00	120.00 <i>80.00</i>

Amt S\$ 1,980.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,980.00

1240

Section: Labour Items

85	TO R&R REAR BUMPER REVERSE SENSOR	1.00	80.00	80.00 <i>60.00</i>
86	TO CHECK WIRING & LIGHTING SYSTEM	1.00	120.00	120.00 <i>80.00</i>
87	TO CONDUCT HEAD LAMP FOCUS	1.00	60.00	60.00 <i>30.00</i>
88	TO SUPPLY UNDERCOATING/PUTTY ON PARTS REPLACED	1.00	100.00	100.00 <i>60.00</i>
89	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	1.00	60.00	60.00 ✓
90	TO R&R REAR TRIMS, GARNISH ASSY	1.00	180.00	180.00 <i>100.00</i>
91	TO R&R REAR EXHAUST ASSY	1.00	200.00	200.00 <i>100.00</i>

70 490.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM973E
Make & Model : SUBARU, IMPREZA 4DR 1.5R AWD 4AT ABS
AIRBAG, JF1GE3KS59G002984
Year of Manufacture : 2008

Estimation No. : E19010008
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
92	TO R&R RADIATOR & A/C CONDENSER ASSY	1.00	250.00	250.00 150.00 ✓
93	TO R&R A/C COMPRESSOR, ALTERNATOR, P/S PUMP & BELTING	1.00	350.00	350.00 2150 ✓
94	TO TOP UP 134A REFRIGERANT	1.00	100.00	100.00 60.00 ✓
95	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS	1.00	2,000.00	2,000.00 1400.00
96	TO SPRAY PAINTING ON AFFECTED AREAS	1.00	1,800.00	1,800.00 1200.00
97	TO DIAGNOSTIC CHECK & ERASE FAULT CODE MEMORIES	1.00	160.00	160.00 80.00
98	TO PERFORM WATER SEEPAGE TEST AFTER REPAIRS	1.00	150.00	150.00
99	TO CAR WASH & POLISHING VEHICLE AFTER REPAIRS	1.00	120.00	120.00
100	SUNDRIES	1.00	50.00	50.00

Amt S\$ 5,780.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 5,780.00

3040.00

[Signature]
21/1/19

32469.39

? Photo

liu

TG Liu
11/1/19 1200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

377047

Repair day 10

liu

1200

List Items Subtotal	S\$ 0.00
Special Nett Items	S\$
Subtotal	1,980.00
Labour Items Subtotal	S\$
	5,780.00
Total	S\$
	7,760.00



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM973E
 Make & Model : SUBARU, IMPREZA 4DR 1.5R AWD 4AT ABS
 Year of Manufacture : 2008
 AIRBAG, JF1GE3KS59G002984

Estimation No. : E19010008
 DOA : 09/01/2019

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	REAR BUMPER	1.00	0.00	0.00 954.20
2	REAR BUMPER RETAINER - SHORT	2.00	0.00 78.30	0.00 156.60
3	REAR BUMPER RETAINER - LONG	2.00	0.00 102.20	0.00 204.40
4	REAR BUMPER REINFORCEMENT	1.00	0.00	0.00 362.60
5	REAR BUMPER REFLECTOR LAMP (LH+RH)	2.00	0.00 260.80	0.00 521.60
6	REAR BUMPER TOWING CAP	1.00	0.00	0.00 54.40
7	BOOT LID	1.00	0.00	0.00 1158.00
8	BOOT LID HINGE	2.00	0.00 213.20	0.00 426.40
9	BOOT LID RUBBER BEADING	1.00	0.00	0.00 211.60
10	BOOT LID EMBLEM - LOGO	1.00	0.00	0.00 138.00
11	BOOT LID EMBLEM - SUBARU	1.00	0.00	0.00 120.30
12	BOOT LID EMBLEM - IMPREZA	1.00	0.00	0.00 115.70
13	BOOT LID CHROME GARNISH	1.00	0.00	0.00 470.60
14	BOOT LID LOCK	1.00	0.00	0.00 190.30
15	BOOT LID LOCK CATCH	1.00	0.00	0.00 82.00
16	BOOT LID LOCK SWITCH	1.00	0.00	0.00
17	BOOT LID INSULATOR	1.00	0.00	0.00 262.80
18	LICENSE LAMP	2.00	0.00 147.60	0.00 295.20
19	TAIL LAMP (LH+RH)	2.00	0.00 622.00	0.00 1244.00
20	TAIL LAMP INNER PANEL (LH+RH)	2.00	0.00 115.60	0.00 231.20
21	REAR END PANEL	1.00	0.00	0.00 535.10
22	REAR END PANEL TOP GARNISH	1.00	0.00	0.00 195.20
23	SPARE TYRE PANEL	1.00	0.00	0.00 659.70
24	SPARE TYRE PANEL TOP BOARD	1.00	0.00	0.00 450.20

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM973E
 Make & Model : SUBARU, IMPREZA 4DR 1.5R AWD 4AT ABS
 Year of Manufacture : 2008
 AIRBAG, JF1GE3KS59G002984

Estimation No. : E19010008
 DOA : 09/01/2019

No	Description	Qty	U/P	Amt
25	SPARE TYRE SPONGE TOOL BOX ? NNX	1.00	0.00	0.00 442.30
26	REAR EXHAUST MUFFLER ? BT ✓	1.00	0.00	0.00 979.84
27	REAR EXHAUST HEAT SHIELD ? RX	1.00	0.00	0.00 120.30
28	FRONT BUMPER CRU ✓	1.00	0.00	0.00 1053.20
29	FRONT BUMPER RETAINER } BT	2.00	0.00 66.30	0.00 132.60
30	FRONT BUMPER REINFORCEMENT	1.00	0.00	0.00 461.20
31	FRONT BUMPER SPONGE ? BR ✓	1.00	0.00	0.00 156.30
32	FRONT BUMPER LOWER GRILLE BR ✓	1.00	0.00	0.00 180.30
33	RADIATOR GRILLE BR ✓	1.00	0.00	0.00
34	RADIATOR GRILLE CHROME MOULDING BR ✓	1.00	0.00	0.00 785.80
35	RADIATOR GRILLE EMBLEM - LOGO NEC ✓	1.00	0.00	0.00
36	FOG LAMP (LH+RH) LH only	1 -2.00	0.00 410.60	0.00 821.20
37	FRONT BUMPER BRACKET NEC ✓	2.00	0.00 109.20	0.00 218.40
38	BONNET DD ✓	1.00	0.00	0.00 1037.20
39	BONNET HINGES BT ✓	2.00	0.00 88.30	0.00 176.60
40	BONNET DAMPER BT ✓	2.00	0.00 146.50	0.00 293.00
41	BONNET LOCK BT	1.00	0.00	0.00 164.30
42	BONNET INSULATOR ? NEC ✓	1.00	0.00	0.00 194.50
43	HEAD LAMP (LH+RH) BR ✓	2.00	0.00 1180.30	0.00 2360.00
44	HEAD LAMP BRACKET ? BR ✓	2.00	0.00 144.30	0.00 288.60
45	FRONT FENDER (LH+RH) DD ✓	2.00	0.00 358.20	0.00 716.40
46	FRONT FENDER INNER SHIELD (LH+RH) ?	2.00	0.00 176.40	0.00 352.80
47	FRONT SUPPORT PANEL ? BT ✓	1.00	0.00	0.00 695.70
48	HEAD LAMP PANEL (LH+RH) RX	2.00	0.00	0.00
49	FRONT SUPPORT PANEL TOP GARNISH BR ✓	1.00	0.00	0.00 236.70

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM973E
 Make & Model : SUBARU, IMPREZA 4DR 1.5R AWD 4AT ABS
 Year of Manufacture : 2008
 AIRBAG, JF1GE3KS59G002984

Estimation No. : E19010008
 DOA : 09/01/2019

No	Description	Qty	U/P	Amt
50	FRONT DOOR (RH) R X	1.00	0.00	0.00/134.50
51	A/C CONDENSER ? BT ✓	1.00	0.00	0.00 855.20
52	RADIATOR ? BR ✓	1.00	0.00	0.00 1052.90
53	RADIATOR TOP HOSE ? } CUT ✓	1.00	0.00	0.00 80.40
54	RADIATOR LOWER HOSE ? } CUT ✓	1.00	0.00	0.00 78.60
55	RADIATOR FAN MOTOR COWLING SET ? BR ✓	1.00	0.00	0.00 579.00
56	A/C FAN MOTOR COWLING SET ? BR ✓	1.00	0.00	0.00 550.00
57	RADIATOR SPARE TANK ? BR ✓	1.00	0.00	0.00 116.00
58	WASHER TANK ? BR ✓	1.00	0.00	0.00 124.20
59	WASHER TANK MOTOR ? NNX	1.00x2	0.00 80.80	0.00 161.60
60	A/C COMPRESSOR ? JAM ✓	1.00	0.00	0.00 1360.20
61	ALTERNATOR ? BR ✓	1.00	0.00	0.00 1720.30
62	POWER STEERING PUMP ? JM ✓	1.00	0.00	0.00 1340.50
63	ENGINE MAIN PULLEY ? CUT ✓	1.00	0.00	0.00 470.00
64	FAN BELTING SET ? } CUT	1.00	0.00	0.00 150.00
65	FAN BELT TENSIONER ? } CUT	1.00	0.00	0.00 165.00
				Amt \$5 0.00
				Discount (20.00%) \$5 0.00
				Subtotal \$5 0.00

Section: Special Nett Items

66	REVERSE SENSOR SET CUT	1.00	250.00	200.00
67	REVERSE CAMERA NNX	1.00	500.00	500.00
68	REAR BUMPER CLIP SET	1.00	45.00	45.00
69	TAIL LAMP CLIP SET	1.00	30.00	30.00
70	BOOT LID INSULATOR CLIP SET } NEC ✓	1.00	45.00	45.00

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM973E
Make & Model : SUBARU, IMPREZA 4DR 1.5R AWD 4AT ABS
Year of Manufacture : 2008
AIRBAG: JF1GE3KS59G002984

Estimation No. : E19010008
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
71	REAR END PANEL TOP GARNISH CLIP SET <i>NEC ✓</i>	1.00	30.00	30.00
72	EXHAUST MUFFLER MOUNTING SET <i>? NEC</i>	1.00	120.00	120.00
73	REAR END PANEL SEALANT <i>NEC ✓</i>	1.00	50.00	50.00
74	SPARE TYRE PANEL INSULATOR MATT <i>? NEC</i>	1.00	250.00	250.00
75	REAR NUMBER PLATE & CASING <i>} BRV</i>	1.00	45.00	45.00
76	FRONT NUMBER PLATE & CASING <i>} BRV</i>	1.00	45.00	45.00
77	FRONT BUMPER CLIP SET <i>} NEC ✓</i>	1.00	45.00	45.00
78	BONNET INSULATOR CLIP SET <i>} NEC ✓</i>	1.00	45.00	45.00
79	FRONT FENDER INNER SHIELD CLIP SET (LH) <i>} NEC ✓</i>	1.00	45.00	45.00
80	FRONT FENDER INNER SHIELD CLIP SET (RH) <i>} NEC ✓</i>	1.00	45.00	45.00
81	ENGINE COOLANT <i>NEC ✓</i>	1.00	80.00	80.00 50.00
82	AUTO TRANSMISSION FLUID 2L <i>NEC ✓</i>	1.00	160.00	160.00 80.00
83	RADIATOR HOSE CLIP SET <i>NEC ✓</i>	1.00	30.00	30.00
84	POWER STEERING FLUID 2L <i>? NEC</i>	1.00	120.00	120.00 80.00
				Amt S\$ 1,980.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,980.00

Section: Labour Items

85	TO R&R REAR BUMPER REVERSE SENSOR	1.00	80.00	80.00 60.00
86	TO CHECK WIRING & LIGHTING SYSTEM	1.00	120.00	120.00 80.00
87	TO CONDUCT HEAD LAMP FOCUS	1.00	60.00	60.00 30.00
88	TO SUPPLY UNDERCOATING/PUTTY ON PARTS REPLACED	1.00	100.00	100.00 60.00
89	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	1.00	60.00	60.00 ✓
90	TO R&R REAR TRIMS, GARNISH ASSY	1.00	180.00	180.00 100.00
91	TO R&R REAR EXHAUST ASSY	1.00	200.00	200.00 100.00

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM973E
 Make & Model : SUBARU IMPREZA 4DR 1.5R AWD 4AT ABS
 Year of Manufacture : 2008
 AIRBAG JF1GE3K559G002984

Estimation No. : E19010008
 DOA : 09/01/2019

No	Description	Qty	U/P	Amt
92	TO R&R RADIATOR & A/C CONDENSER ASSY	1.00	250.00	250.00 150.00
93	TO R&R A/C COMPRESSOR, ALTERNATOR, P/S PUMP & BELTING	1.00	350.00	350.00 150.00
94	TO TOP UP 134A REFRIGERANT	1.00	100.00	100.00 60.00
95	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS	1.00	2,000.00	2,000.00 1400.00
96	TO SPRAY PAINTING ON AFFECTED AREAS	1.00	1,800.00	1,800.00 1200.00
97	TO DIAGNOSTIC CHECK & ERASE FAULT CODE MEMORIES	1.00	160.00	160.00 80.00
98	TO PERFORM WATER SEEPAGE TEST AFTER REPAIRS	1.00	150.00	150.00
99	TO CAR WASH & POLISHING VEHICLE AFTER REPAIRS	1.00	120.00	120.00
100	SUNDRIES	1.00	50.00	50.00
				Amt S\$ 5,780.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 5,780.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Repair day 10

List Items Subtotal	S\$ 0.00
Special Nett Items Subtotal	S\$ 1,980.00
Labour Items Subtotal	S\$ 5,780.00
Total	S\$ 7,760.00



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : SJM973E
Make & Model : SUBARU, IMPREZA 4DR 1.5R AWD 4AT ABS
AIRBAG, JF1GE3KS59G002984
Year of Manufacture : 2008

Estimation No. : E19010012
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Engine timing cover set <i>BR ✓ NIX</i>	1.00	0.00	0.00
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

Resurvey 14/1/19

LIM TEOW GUAN
Min

Parts : 27951.40 - 20% AAA
= 22361.12

S/N = 1280

Labour = 3530

Ptstl = 27171.12 - 20% L/S
= 21736.90

List Items Subtotal S\$ 0.00
Total S\$ 0.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2019		11 Jan 2019 09:04 Edit Adj Rpt	S\$10,800.00 Edit Estimates	S\$10,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LEE TZE KEE , ID: S0143395D									
Main Claimant: MARIAM BTE HALIM , ID: S1565974B									
Vehicle Reg. No.: SJM973E		Date of Loss: 09/01/2019 07:00 - :59 [120 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 581816		Policy/Cover Note No.: A80457936QMX (Comprehensive) Coverage: 29/05/2018 - 18/07/2019							
Vehicle Reg. No. (Insured): SKN8036R		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: Torque 5 Bodyworks Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 64524457									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 10/02/2019]									
Adj Asp. Remarks: LIABILITY CLEAR. TP AGREE WITH SJE -ASSIGN LKK AUTO CONSULTANTS PTE LTD.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJM973E (581816)
[SKN8036R]
TP
MARIAM BTE HALIM
Jan 9 2019 7:00AM
[LEE TZE KEE]
Torque 5 Bodyworks Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	16/01/19 09:33	Adjuster Immediate Advice						Load HTM	
Photos/Images							3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	18/03/19 11:42	General View							☒
2	18/03/19 11:42	General View							☒
3	18/03/19 11:42	General View							☒
4	18/03/19 11:42	General View							☒
5	18/03/19 11:42	General View							☒
6	18/03/19 11:42	General View							☒
7	18/03/19 11:42	General View							☒
8	18/03/19 11:42	General View							☒
9	18/03/19 11:42	General View							☒
10	18/03/19 11:42	General View							☒
11	18/03/19 11:42	General View							☒
12	18/03/19 11:42	General View							☒
13	18/03/19 11:42	General View							☒
14	18/03/19 11:42	General View							☒
15	18/03/19 11:42	General View							☒
16	18/03/19 11:42	General View							☒
17	18/03/19 11:42	General View							☒
18	18/03/19 11:42	General View							☒
19	18/03/19 11:42	General View							☒
20	18/03/19 11:42	General View							☒
21	18/03/19 11:42	General View							☒
22	18/03/19 11:42	General View							☒
23	18/03/19 11:42	General View							☒
24	18/03/19 11:42	General View							☒
25	18/03/19 11:42	General View							☒
26	18/03/19 11:42	General View							☒
27	18/03/19 11:42	General View							☒
28	18/03/19 11:42	General View							☒
29	18/03/19 11:42	General View							☒
30	18/03/19 11:42	General View							☒
31	18/03/19 11:42	General View							☒
32	18/03/19 11:42	General View							☒
33	18/03/19 11:42	General View							☒
34	18/03/19 11:42	General View							☒

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
35	18/03/19 11:42	General View		Load JPG	☒
36	18/03/19 11:42	General View		Load JPG	☒
37	18/03/19 11:42	General View		Load JPG	☒
38	18/03/19 11:42	General View		Load JPG	☒
39	18/03/19 11:42	General View		Load JPG	☒
40	18/03/19 11:42	General View		Load JPG	☒
41	18/03/19 11:42	General View		Load JPG	☒
42	18/03/19 11:42	General View		Load JPG	☒
43	18/03/19 11:42	General View		Load JPG	☒
44	18/03/19 11:42	General View		Load JPG	☒
45	18/03/19 11:42	General View		Load JPG	☒
46	18/03/19 11:42	General View		Load JPG	☒
47	18/03/19 11:42	General View		Load JPG	☒
48	18/03/19 11:42	General View		Load JPG	☒
49	18/03/19 11:42	General View		Load JPG	☒
50	18/03/19 11:42	General View		Load JPG	☒
51	18/03/19 11:42	General View		Load JPG	☒
52	18/03/19 11:42	General View		Load JPG	☒
53	18/03/19 11:42	General View		Load JPG	☒
54	18/03/19 11:42	Odometer Reading		Load JPG	☒
55	29/03/19 13:24	Chassis Number		Load JPG	☒
56	29/03/19 13:24	Reinspection Photo		Load JPG	☒
57	29/03/19 13:24	Reinspection Photo		Load JPG	☒
58	29/03/19 13:24	Reinspection Photo		Load JPG	☒
59	29/03/19 13:24	Reinspection Photo		Load JPG	☒
60	29/03/19 13:24	Reinspection Photo		Load JPG	☒
61	29/03/19 13:24	Reinspection Photo		Load JPG	☒
62	29/03/19 13:24	Reinspection Photo		Load JPG	☒
63	29/03/19 13:24	Reinspection Photo		Load JPG	☒
64	29/03/19 13:24	Reinspection Photo		Load JPG	☒
65	29/03/19 13:24	Reinspection Photo		Load JPG	☒
66	29/03/19 13:24	Reinspection Photo		Load JPG	☒
67	29/03/19 13:24	Reinspection Photo		Load JPG	☒
68	29/03/19 13:24	Reinspection Photo		Load JPG	☒
69	29/03/19 13:24	Reinspection Photo		Load JPG	☒
70	29/03/19 13:24	Reinspection Photo		Load JPG	☒
71	29/03/19 13:24	Reinspection Photo		Load JPG	☒
72	29/03/19 13:24	Reinspection Photo		Load JPG	☒
73	29/03/19 13:24	Reinspection Photo		Load JPG	☒
74	29/03/19 13:24	Reinspection Photo		Load JPG	☒
75	29/03/19 13:24	Reinspection Photo		Load JPG	☒
76	29/03/19 13:24	Reinspection Photo		Load JPG	☒
77	29/03/19 13:24	Reinspection Photo		Load JPG	☒
78	29/03/19 13:24	Reinspection Photo		Load JPG	☒
79	29/03/19 13:24	Reinspection Photo		Load JPG	☒
80	29/03/19 13:24	Reinspection Photo		Load JPG	☒
81	29/03/19 13:24	Reinspection Photo		Load JPG	☒
82	29/03/19 13:24	Reinspection Photo		Load JPG	☒
83	29/03/19 13:24	Reinspection Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	29/03/19 13:24	Reinspection Photo		☒
85	29/03/19 13:24	Reinspection Photo		☒
86	29/03/19 13:24	Reinspection Photo		☒
87	29/03/19 13:24	Reinspection Photo		☒
88	29/03/19 13:24	Reinspection Photo		☒
89	29/03/19 13:24	Reinspection Photo		☒
90	29/03/19 13:24	Reinspection Photo		☒
91	29/03/19 13:24	Reinspection Photo		☒
92	29/03/19 13:24	Reinspection Photo		☒
93	29/03/19 13:24	Reinspection Photo		☒
94	29/03/19 13:24	Reinspection Photo		☒
95	29/03/19 13:24	Reinspection Photo		☒
96	29/03/19 13:24	Reinspection Photo		☒
97	29/03/19 13:24	Reinspection Photo		☒
98	29/03/19 13:24	Reinspection Photo		☒
99	29/03/19 13:24	Reinspection Photo		☒
100	29/03/19 13:24	Reinspection Photo		☒
101	29/03/19 13:24	Reinspection Photo		☒
102	29/03/19 13:24	Reinspection Photo		☒
103	29/03/19 13:24	Reinspection Photo		☒
104	29/03/19 13:24	Reinspection Photo		☒
105	29/03/19 13:24	Reinspection Photo		☒
106	29/03/19 13:25	Reinspection Photo		☒
107	29/03/19 13:25	Reinspection Photo		☒
108	29/03/19 13:25	Reinspection Photo		☒
109	29/03/19 13:25	Reinspection Photo		☒
110	29/03/19 13:25	Reinspection Photo		☒
111	29/03/19 13:25	Reinspection Photo		☒
112	29/03/19 13:25	Reinspection Photo		☒
113	29/03/19 13:25	Reinspection Photo		☒
114	29/03/19 13:25	Reinspection Photo		☒
115	29/03/19 13:25	Reinspection Photo		☒
116	29/03/19 13:25	Reinspection Photo		☒
117	29/03/19 13:25	Reinspection Photo		☒
118	29/03/19 13:25	Reinspection Photo		☒
119	29/03/19 13:25	Reinspection Photo		☒
120	29/03/19 13:25	Reinspection Photo		☒
121	29/03/19 13:25	Reinspection Photo		☒
122	29/03/19 13:25	Reinspection Photo		☒
123	29/03/19 13:25	Reinspection Photo		☒
124	29/03/19 13:25	Reinspection Photo		☒
125	29/03/19 13:25	Reinspection Photo		☒
126	29/03/19 13:25	Reinspection Photo		☒
127	29/03/19 13:25	Reinspection Photo		☒
128	29/03/19 13:25	Reinspection Photo		☒
129	29/03/19 13:25	Reinspection Photo		☒
130	29/03/19 13:25	Reinspection Photo		☒
131	29/03/19 13:25	Reinspection Photo		☒
132	29/03/19 13:25	Reinspection Photo		☒
133	29/03/19 13:25	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	29/03/19 13:25	Reinspection Photo		☒
135	29/03/19 13:25	Reinspection Photo		☒
136	29/03/19 13:25	Reinspection Photo		☒
137	29/03/19 13:25	Reinspection Photo		☒
138	29/03/19 13:25	Reinspection Photo		☒
139	29/03/19 13:25	Reinspection Photo		☒
140	29/03/19 13:25	Reinspection Photo		☒
141	29/03/19 13:25	Reinspection Photo		☒
142	29/03/19 13:25	Reinspection Photo		☒
143	29/03/19 13:25	Reinspection Photo		☒
144	29/03/19 13:25	Reinspection Photo		☒
145	29/03/19 13:25	Reinspection Photo		☒
146	29/03/19 13:25	Reinspection Photo		☒
147	29/03/19 13:25	Reinspection Photo		☒
148	29/03/19 13:25	Reinspection Photo		☒
149	29/03/19 13:25	Reinspection Photo		☒
150	29/03/19 13:25	Reinspection Photo		☒
151	29/03/19 13:25	Reinspection Photo		☒
152	29/03/19 13:25	Reinspection Photo		☒
153	29/03/19 13:25	Reinspection Photo		☒
154	29/03/19 13:25	Reinspection Photo		☒
155	29/03/19 13:25	Reinspection Photo		☒
156	29/03/19 13:25	Reinspection Photo		☒
157	29/03/19 13:25	Reinspection Photo		☒
158	29/03/19 13:25	Reinspection Photo		☒
159	29/03/19 13:25	Reinspection Photo		☒
160	29/03/19 13:25	Reinspection Photo		☒
161	29/03/19 13:25	Reinspection Photo		☒
162	29/03/19 13:25	Reinspection Photo		☒
163	29/03/19 13:25	Reinspection Photo		☒
164	29/03/19 13:25	Reinspection Photo		☒
165	29/03/19 13:25	Reinspection Photo		☒
166	29/03/19 13:25	Reinspection Photo		☒
167	29/03/19 13:25	Reinspection Photo		☒
168	29/03/19 13:25	Reinspection Photo		☒
169	29/03/19 13:25	Reinspection Photo		☒
170	29/03/19 13:25	Reinspection Photo		☒
171	29/03/19 13:25	Reinspection Photo		☒
172	29/03/19 13:25	Reinspection Photo		☒
173	29/03/19 13:25	Reinspection Photo		☒
174	29/03/19 13:25	Reinspection Photo		☒
175	29/03/19 13:25	Reinspection Photo		☒
176	29/03/19 13:25	Reinspection Photo		☒
177	29/03/19 13:25	Reinspection Photo		☒
178	29/03/19 13:25	Reinspection Photo		☒
179	29/03/19 13:25	Reinspection Photo		☒
180	29/03/19 13:25	Reinspection Photo		☒
181	29/03/19 13:25	Reinspection Photo		☒
182	29/03/19 13:25	Reinspection Photo		☒
183	29/03/19 13:25	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
184	29/03/19 13:25	Reinspection Photo		☒
185	29/03/19 13:25	Reinspection Photo		☒
186	29/03/19 13:25	Reinspection Photo		☒
187	29/03/19 13:25	Reinspection Photo		☒
188	29/03/19 13:25	Reinspection Photo		☒
189	29/03/19 13:25	Reinspection Photo		☒
190	29/03/19 13:25	Reinspection Photo		☒
191	29/03/19 13:25	Reinspection Photo		☒
192	29/03/19 13:25	Reinspection Photo		☒
193	29/03/19 13:25	Reinspection Photo		☒
194	29/03/19 13:25	Reinspection Photo		☒
195	29/03/19 13:25	Reinspection Photo		☒
196	29/03/19 13:25	Reinspection Photo		☒
197	29/03/19 13:25	Reinspection Photo		☒
198	29/03/19 13:25	Reinspection Photo		☒
199	29/03/19 13:25	Reinspection Photo		☒
200	29/03/19 13:25	Reinspection Photo		☒
201	29/03/19 13:25	Reinspection Photo		☒
202	29/03/19 13:25	Reinspection Photo		☒
203	29/03/19 13:25	Reinspection Photo		☒
204	29/03/19 13:25	Reinspection Photo		☒
205	29/03/19 13:25	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/01/19 13:07	OI SKN8036R E-FILE REPORT		
2	10/01/19 13:07	SJM973E e-file report		
3	10/01/19 13:07	TP PRI Request EMAIL		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/04/19 16:37	Supplementary		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19000663/BSD3E2

Date: 09/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80457936QMX

Claimant Vehicle
No : SJM973E

Insured Vehicle No : SKN8036R

Date of Loss: 09/01/2019

Nature of Claim: TP

Claim No: 581816

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM973E**
 Make & Model: SUBARU IMPREZA, 1.5 R AWD 4AT ABS AIRBAG (A) Engine No: EL15D591918
 Reg. Date: 20/12/2008 (Man. Year: 2008) Chassis No: JF1GE3KS59G002984
 Colour: Black Odometer: 93761 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,073.95	15,724.48	11,349.47	41.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,730.00	3,490.00	2,240.00	39.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,803.95	19,214.48	13,589.47	41.43
Approved Total (Overridden) (S\$)		10,800.00		
(S\$)	32,803.95	10,800.00	22,003.95	67.08
+ GST 7.00/7.00% (S\$)	2,296.28	756.00	1,540.28	67.08
Nett Amount (S\$)	35,100.23	11,556.00	23,544.23	67.08

INSPECTION

Date of Assignment: 11/01/2019

Date Inspected: 11/01/2019 Inspected At:

Torque 5 Bodyworks Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: Lim Teow Guan**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2019)
Parts:	143	SUBARU IMPREZA 1.5 R AWD 4AT ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM973E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	954.20 FL	*762.00 FL
2	2		*REAR BUMPER RETAINER - SHORT	Broken	156.60 FL	*156.60 FL
3	2		*REAR BUMPER RETAINER - LONG	Broken	204.40 FL	*204.40 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	362.60 FL	*362.60 FL
5	1		*REAR BUMPER REFLECTOR LAMP (LH+RH)	N/S Not Necessary/O/S Broken	521.60 FL	*260.80 FL
6	1		*REAR BUMPER TOWING CAP	Cut	54.40 FL	*54.40 FL
7	1		*BOOT LID	Dented	1,158.00 FL	*692.80 FL
8	2		*BOOT LID HINGE	Bent	426.40 FL	*222.00 FL
9	1		*BOOT LID RUBBER BEADING	Necessary	211.60 FL	*188.20 FL
10	1		*BOOT LID EMBLEM - LOGO	Necessary	138.00 FL	*68.40 FL
11	1		*BOOT LID EMBLEM - SUBARU	Necessary	120.30 FL	*36.00 FL
12	1		*BOOT LID EMBLEM - IMPREZA	Necessary	115.70 FL	*40.00 FL
13	1		*BOOT LID CHROME GARNISH	Not Necessary	470.60 FL	*- FL
14	1		*BOOT LID LOCK	Bent	190.30 FL	*190.30 FL
15	1		*BOOT LID LOCK CATCH	Not Necessary	82.00 FL	*- FL
16	1		*BOOT LID LOCK SWITCH (NPA)	Not Necessary	0.00 FL	*- FL
17	1		*BOOT LID INSULATOR	Cut	262.80 FL	*262.80 FL
18	2		*LICENSE LAMP	Broken	295.20 FL	*242.00 FL
19	1		*TAIL LAMP (LH+RH)	O/S Not Necessary/N/S Broken	1,244.00 FL	*622.00 FL
20	1		*TAIL LAMP INNER PANEL (LH+RH)	O/S Not Necessary / N/S Dented	231.20 FL	*115.60 FL
21	1		*REAR END PANEL	Dented	535.10 FL	*535.10 FL
22	1		*REAR END PANEL TOP GARNISH	Dislodged	195.20 FL	*125.00 FL
23	1		*SPARE TYRE PANEL	Dented	659.70 FL	*659.70 FL
24	1		*SPARE TYRE PANEL TOP BOARD	Cut	450.20 FL	*450.20 FL
25	1		*SPARE TYRE SPONGE TOOL BOX	Not Necessary	442.30 FL	*- FL
26	1		*REAR EXHAUST MUFFLER	Not Necessary	979.84 FL	*- FL
27	1		*REAR EXHAUST HEAT SHIELD	Repair	120.30 FL	*- FL
28	1		*FRONT BUMPER	Crumpled	1,053.20 FL	*708.50 FL
29	1		*FRONT BUMPER RETAINER (2PCS)	Bent-1pc only	132.60 FL	*64.00 FL
30	1		*FRONT BUMPER REINFORCEMENT	Bent	461.20 FL	*388.00 FL
31	1		*FRONT BUMPER SPONGE	Broken	156.30 FL	*140.00 FL
32	1		*FRONT BUMPER LOWER GRILLE	Broken	180.30 FL	*180.30 FL
33	1		*RADIATOR GRILLE	Broken	400.00 FL	*400.00 FL
34	1		*RADIATOR GRILLE CHROME MOULDING	Broken	785.80 FL	*162.80 FL
35	1		*RADIATOR GRILLE EMBLEM - LOGO	Necessary	65.00 FL	*65.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FOG LAMP (LH+RH)	N/S Broken / O/S Not Necessary	821.20 FL	*364.00 FL
37	2		*FRONT BUMPER BRACKET	Necessary	171.60 FL	*171.60 FL
38	1		*BONNET	Dented	1,037.20 FL	*648.50 FL
39	1		*BONNET HINGES	N/S Bent / O/S Not Necessary	176.60 FL	*88.30 FL
40	1		*BONNET DAMPER	N/S Bent / O/S Not Necessary	293.00 FL	*146.50 FL
41	1		*BONNET LOCK	Bent	164.30 FL	*94.30 FL
42	1		*BONNET INSULATOR	Cut	194.50 FL	*121.60 FL
43	2		*HEAD LAMP (LH+RH)	Broken	2,360.00 FL	*1,800.00 FL
44	2		*HEAD LAMP BRACKET	Broken	288.60 FL	*190.00 FL
45	2		*FRONT FENDER (LH+RH)	Dented	757.40 FL	*600.00 FL
46	2		*FRONT FENDER INNER SHIELD (LH+RH)	Torn	352.80 FL	*352.80 FL
47	1		*FRONT SUPPORT PANEL	Bent	695.70 FL	*495.70 FL
48	2		*HEAD LAMP PANEL (LH+RH) (NPA)	Repair	0.00 FL	*- FL
49	1		*FRONT SUPPORT PANEL TOP GARNISH	Broken	236.70 FL	*212.00 FL
50	1		*FRONT DOOR (RH)	Repair	1,134.50 FL	*- FL
51	1		*A/C CONDENSER	Bent	855.20 FL	*720.30 FL
52	1		*RADIATOR	Broken	1,052.90 FL	*864.00 FL
53	1		*RADIATOR TOP HOSE	Cut	80.40 FL	*40.00 FL
54	1		*RADIATOR LOWER HOSE	Cut	78.60 FL	*40.00 FL
55	1		*SET RADIATOR FAN MOTOR COWLING	Broken	579.00 FL	*487.00 FL
56	1		*SET A/C FAN MOTOR COWLING	Broken	550.00 FL	*386.30 FL
57	1		*RADIATOR SPARE TANK	Broken	116.00 FL	*94.00 FL
58	1		*WASHER TANK	Broken	124.20 FL	*124.20 FL
59	2		*WASHER TANK MOTOR	Not Necessary	161.60 FL	*- FL
60	1		*A/C COMPRESSOR	Not Necessary	1,360.20 FL	*- FL
61	1		*ALTERNATOR	Broken	1,720.30 FL	*1,710.00 FL
62	1		*POWER STEERING PUMP	Not Necessary	1,340.50 FL	*- FL
63	1		*ENGINE MAIN PULLEY	Not Necessary	470.00 FL	*- FL
64	1		*SET FAN BELTING	Cut	150.00 FL	*25.00 FL
65	1		*FAN BELT TENSIONER	Cut	165.00 FL	*165.00 FL
66	1		*SET REVERSE SENSOR	Cut	250.00 FS	*200.00 FS
67	1		*REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
68	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
69	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*30.00 FS
70	1		*SET BOOT LID INSULATOR CLIP	Necessary	45.00 FS	*30.00 FS
71	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*30.00 FS
72	1		*SET EXHAUST MUFFLER MOUNTING	Necessary	120.00 FS	*84.00 FS
73	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS
74	1		*SPARE TYRE PANEL INSULATOR MATT	Necessary	250.00 FS	*250.00 FS
75	1		*REAR NUMBER PLATE & CASING}	Broken	45.00 FS	*50.00 FS
76	1		*FRONT NUMBER PLATE & CASING}		45.00 FS	*- FS
77	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
78	1		*SET BONNET INSULATOR CLIP	Necessary	45.00 FS	*30.00 FS
79	1		*SET FRONT FENDER INNER SHIELD CLIP (LH)	Necessary	45.00 FS	*30.00 FS
80	1		*SET FRONT FENDER INNER SHIELD CLIP (RH)	Necessary	45.00 FS	*30.00 FS
81	1		*ENGINE COOLANT	Necessary	80.00 FS	*50.00 FS
82	1		*AUTO TRANSMISSION FLUID 2L	Necessary	160.00 FS	*80.00 FS
83	1		*SET RADIATOR HOSE CLIP	Necessary	30.00 FS	*20.00 FS
84	1		*POWER STEERING FLUID 2L	Necessary	120.00 FS	*80.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
85	1		*SUNDRIES	Necessary	50.00 FS	*- FS
86	1		*SET ENGINE TIMING COVER (NPA)	Not Necessary	0.00 FL	*- FL
					Sub Total (S\$)	33,334.94 19,384.60
					- List Item Discount on L Items 20.00/20.00% (S\$)	6,260.99 3,660.12
					Total Parts (S\$)	27,073.95 15,724.48

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R REAR BUMPER REVERSE SENSOR	New	80.00	60.00
2	TO CHECK WIRING & LIGHTING SYSTEM	New	120.00	80.00
3	TO CONDUCT HEAD LAMP FOCUS	New	60.00	30.00
4	TO SUPPLY UNDERCOATING / PUTTY ON PARTS REPLACED	New	100.00	60.00
5	TO R&R REAR TRIMS, GARNISH ASSY	New	180.00	60.00
6	TO R&R REAR EXHAUST ASSY	New	200.00	100.00
7	TO R&R RADIATOR & A/C CONDENSER ASSY	New	250.00	150.00
8	TO R&R A/C COMPRESSOR, ALTERNATOR, P/S PUMP & BELTING	New	350.00	150.00
9	TO TOP UP 134A REFRIGERANT	New	100.00	60.00
10	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS	New	2,000.00	1,400.00
11	TO SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	1,200.00
12	TO DIAGNOSTIC CHECK & ERASE FAULT CODE MEMORIES	New	160.00	80.00
13	TO PERFORM WATER SEEPAGE TEST AFTER REPAIRS	New	150.00	0.00
14	TO CAR WASH & POLISHING VEHICLE AFTER REPAIRS	New	120.00	0.00
15	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	60.00
Gross Labour Cost (S\$)			5,730.00	3,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >