

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0047/2019/PH
Date : 11-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SDN 185 D**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Vickrum Muthsamy P
Address : 24 Mugliston Road
: (S) 437728
Telephone : HP +65 96908217
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SDB 9330 E**
Model Code : Audi A4 Sedan 2.0 TFSI (A)
Model / Year : 12/7/2018
Engine No : CVK 061246
Chassis No : WAUZZZF41JA165172
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Jan-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDB 9330 E .

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N	\$ 360.00	✓
2	To dismantle and renew rear bumper. Re-organize crash management components. Reinstall all parts removed.		\$ 900.00	500
3	To respray rear bumper		\$ 800.00	550
4	To carry out diagnostic check.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	\$ 2,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDB 9330 E.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>selend</i>	\$ 2,015.00	✓
2	REAR BUMPER FIXING PARTS <i>2</i>	\$ 66.00	✓
3	SECURING PLATE <i>3 new</i>	4 \$ 60.00	+
4	SECURING STRIP	\$ 203.00	+
5	REAR BUMPER SPOILER <i>at</i>	\$ 227.00	✓
6	REAR BUMPER CARRIER <i>?</i>	\$ 819.00	?
7	SEAL <i>2 new</i>	2 \$ 25.00	+
8	GUIDE SECTION	\$ 40.00	✓
9	REAR BUMPER GUIDE SECTION - RH <i>2 new</i>	\$ 41.00	+
10	REAR BUMPER GUIDE SECTION - LH/RH	2 \$ 40.00	✓
11	REAR BUMPER SENSOR <i>2 new</i>	2 \$ 462.00	+
12	REAR BUMPER SENSOR SEAL	4 \$ 16.00	+
13	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 4,314.00	
TOTAL LABOUR CHARGES		\$ 2,252.00	
GRAND TOTAL		\$ 6,566.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King,
Surveyed Date : 11/01/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 03800-1/5.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant