

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0044/2019/JE
Date : 10-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **WC 4947 D**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Liang Wee Seah
Address : 101 Prince Charles Crescent
: #13-02
: (S) 159017
Telephone : HP +65 9738 9191
Type of Claim : Third Party Claims
Policy No. : 1800051353
Vehicle No : **SCX 8998 G**
Model Code : Audi A4 Sedan 2.0 TFSI (A)
Model / Year : 10/5/2018
Engine No : CVK 059050
Chassis No : WAUZZZF41JA148503
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Dec-18

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCX 8998 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00	✓
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00	✓
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00	✓
4	To remove and reinstall rear seat, back rest, hat tray, abcs pillar trims, luggage compartment trims. Dislodge rood liner and disengage curtain airbaq etc.	S/N \$ 1,400.00	✓
5	To dismantle rear bumper and rear lid. Cut out and weld rhs rear fender. To renew rear bumper. Re-organize rear crash management components. Reinstall all parts removed.	S/N \$ 4,900.00	3000.
6	To respray rhs rear fender, rhs sill panel, rer bumper, door entrances, roof channel, drain panel, end panelling. To carry out stone chip treatment and joint sealer works.	\$ 3,900.00	2200.
7	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	X
8	To carry out diagnostic check.	S/N \$ 192.00	✓
SUB = TOTAL LABOUR CHARGES		: \$ 13,032.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCX 8998 G.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Repair</i>	\$ 2,015.00	X.
2	REAR BUMPER FIXING PARTS	\$ 66.00	X
3	REAR BUMPER SECURING PLATE	4 \$ 60.00	X
4	REAR BUMPER SECURING STRIP	\$ 203.00	X
5	REAR BUMPER REFLECTOR - RH REAR	\$ 38.00	X
6	REAR BUMPER GUIDE - RH	\$ 41.00	X
7	REAR QUARTER PANEL - RH <i>Dented</i>	\$ 2,443.00	✓
8	REAR WINDOW <i>New</i>	\$ 1,049.00	✓
9	PRIMER <i>New</i>	\$ 38.00	✓
10	REAR SIDE WINDOW - RH <i>New</i>	\$ 561.00	✓
11	REAR LED TAIL LIGHT - RH <i>cut</i>	\$ 931.00	✓
12	REAR TAIL LIGHT TRIM - RH <i>New</i>	\$ 27.00	X.
13	SUNDRIES ?	\$ 500.00	?
14	A/SEALANT	\$ 180.00	✓
15	C/WAX	\$ 140.00	✓
16	STONE CHIP	\$ 180.00	✓
17	METAL FILLER POWDER	\$ 280.00	✓
18	REAR WS SEALANT	\$ 200.00	✓
19	1/4 GLASS SEALANT	\$ 100.00	✓
20	RHS REAR RIMS <i>Not New</i>	TBC	X.
TOTAL SPARE PARTS CHARGES		\$ 9,052.00	
TOTAL LABOUR CHARGES		\$ 13,032.00	
GRAND TOTAL		\$ 22,084.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 15/01/19!
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, ¹² days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant