

INS. CASE OWNER:

CC 4/111 1900

0675, Riga3

LKK:
IDAC:

Surveyor:

Rasul

DOI:

21/1/19

Date / Time:

10-1-19

Registered in Merimen:

11-1-19

Pre-assign / CCU / FTE



Insured Vehicle No. : Site 8063E

Name of Insured : 07PL

Insured Tel No. : HP:

Excess Sec II :SS D.O.A : 21/1/19

Is driver the owner? (YES (NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SJP 1382M

INSRS:
WSP: Sy Ah Tee
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup) ☒
After call ltr to OI: ☒
Authorisation To Act: ☒
Release Voucher: ☒
Final Repair Bill: ☒
Car Rental Invoice: ☒
Towing Invoice: ☒
LTA / GIA : ☒
Medical Bill: ☒
PIR: ☒
Mandate/Reject Instruction: ☒
LOD: ☒
Payment Breakdown Form: ☒
Post-Repair Photos: ☒
Others: ☒

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Rasul

Repair Cost: 45 S\$ 2250.00 (5 days) Reduction: \$2618.24% 54

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 21/1/19

Confirm with: Sharon

Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 15

If NO or B 28, Ass. Lia :

Repair Cost: (WOSP) S\$ 2407.50

Loss of Rental (LOR): S\$ - (5 days)

Loss of Use (LOU): S\$ 300.00 (\$ 60 x 5 days)

Loss of Income (LOI): S\$ - (5 x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S\$ 7.45

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost S\$ -

Total: S\$ 2714.95

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$350/-

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1: S\$ 2714.95

Name 1: BNA WHITE MOTOR & GENERAL SERVICE PTE. LTD

Payee 2: (Strike if N.A.) S\$ -

Name 2:

Payee 3: (Strike if N.A.) S\$ -

Name 3:

COPY SENT
29/1/19

Form

REF: III

675/140

43460.
COR XEROX: 2019/1/19

ASSIGNMENT

From: Date: 21/01/2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No SJP 1382M
at Workshop m/s Sng Ah Tee
of Blk 3 pioneer Rd North #01-18

Insured

Policy No

Claims No

Sum Insured

Excess


(Client's Record)

Make of Veh

After 1pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 40K

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted

Vehicle: IN / OUT

Veh No: SJP 1382M

Vt Regn: 2009 / MAN

Type: M/C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit 1.34A

C.C. 1339

Colour: yellow

A/C Insured / Std / NI / NA

Sp. Reading: 125180

T/Radio: Insured / Std / NI / NA

Eng/No:

CNo: GE61144283

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F:

175/65 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 15 mm

R/Bal: 5 mm

L/Bal: 5 mm

L/Bal: 5 mm

D.O.A. 07/01/19

D.O.I. 21/01/19

Survey held at

SNG AH TEE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

reply (mit 1K. refer to email)

4/5 \$2250/-

(Red. \$2618.24 / 54%)

MV = 40K
Rebate = 25,266
NV = 14,734.00

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

Transportation

Add Fee: ☐ : Site Insp (\$

) \$ + RS 54

☐ Interview (\$

) Photos

☐ Tech. Invs (\$

) Other

☐ Week-end (\$

) TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004541

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

DATE : 21/01/2019
ACCIDENT DATE : 04/01/2019
VEHICLE NO : SJP1382M
CHASSIS/ENG.NO : GE61144283
VEHICLE MODEL : HONDA FIT
CLAIM NO :
POLICY NO :
REMARK : 1382INDIA TP AGST
SHC8063E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER <i>100% /</i>	497.50	20	398.00	398.00 ✓
2	8	PC	REAR BUMPER CLIPS <i>new /</i>	3.90	20	3.12	24.96 ✓
3	1	PC	REAR BUMPER RETAINER(RH) <i>new /</i>	16.50	20	13.20	13.20 ✓
4	1	PC	REAR BUMPER TOWING COVER <i>cut /</i>	13.30	20	10.64	10.64 ✓
5	1	PC	REAR BOOT LID <i>90% /</i>	771.50	20	617.20	617.20 ✓
6	1	PC	REAR BOOT LOCK <i>X NV</i>	189.50	20	151.60	151.60 X
7	2	PC	REAR WINDSCREEN MOULDING <i>new /</i>	36.80	20	29.44	58.88 ✓
8	1	PC	REAR END PANEL <i>repair</i>	276.50	20	221.20	221.20 ✓
9	1	PC	REAR END PANEL BRACKET RH <i>?</i>	16.50	20	13.20	13.20 X
10	1	PC	REAR END PANEL TOP GARNISH <i>?</i>	60.80	20	48.64	48.64 X
11	1	PC	REAR END PANEL RUBBER <i>X</i>	92.30	20	73.84	73.84 X
12	1	PC	REAR FENDER INNER TRIM RH <i>?</i>	250.00	20	200.00	200.00 X
13	1	PC	REAR TAILLAMP RH <i>?</i>	206.20	20	164.96	164.96 X
14	1	PC	REAR FENDER RH <i>repair</i>	652.40	20	521.92	521.92 X

SUB-TOTAL: 2,518.24

\$117.98

**** SPECIAL NETT PRICE ****

1	1	PC*	REAR BUMPER REVERSE SENSOR	280.00	<i>200% new</i>	280.00	280.00 ✓
2	1	PC	REAR WINDSCREEN SEALANT	40.00	<i>new</i>	40.00	40.00 ✓

SAM

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ004541

DATE 21/01/2019

ACCIDENT DATE : 04/01/2019

VEHICLE NO : SJP1382M

CHASSIS/ENG.NO : GE61144283

VEHICLE MODEL : HONDA FIT

CLAIM NO :

POLICY NO :

REMARK : 1382INDIA TP AGST
SHC8063E

S/N	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
-----	-----	------	-------------	-------	--------	-------------	-----------

SUB-TOTAL 320.00

** WORK LABOUR **

TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS

TO REMOVE & FIX REAR WINDSCREEN

TO CHECK WIRING

TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS

TO APPLY ANTI RUST COATING

~~800.00~~ 600 800.00

~~150.00~~ 120 150.00

30.00 30.00

~~850.00~~ 700 850.00

~~200.00~~ 40 200.00

SUB-TOTAL 2,030.00

Price

Ap 900 10068

\$1490/-

5 days

4/5

21/01/19 @ 1405

Repair after repair

Vehicle Renew COE.

1571
\$2852.18
155209
\$2252.30
\$2240
Lump sum etc?
Sharon 12/1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 4,868.24

ADD 7% GST. S\$ 340.78

GRAND TOTAL : S\$ 5,209.02

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations. Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004541

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION :

CONTACT : 62238122

FAX NO: 62244174

DATE 21/01/2019

ACCIDENT DATE : 04/01/2019

VEHICLE NO : SJP1382M

CHASSIS/ENG.NO : GE61144283

VEHICLE MODEL : HONDA FIT

CLAIM NO :

POLICY NO :

REMARK : 1382INDIA TP AGST
SHC8063E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER <i>10R2 /</i>	497.50	20	398.00	398.00
2	8	PC	REAR BUMPER CLIPS <i>new /</i>	3.90	20	3.12	24.96
3	1	PC	REAR BUMPER RETAINER(RH) <i>new /</i>	16.50	20	13.20	13.20
4	1	PC	REAR BUMPER TOWING COVER <i>cut /</i>	13.30	20	10.64	10.64
5	1	PC	REAR BOOT LID <i>9th /</i>	771.50	20	617.20	617.20
6	1	PC	REAR BOOT LOCK <i>X sue</i>	189.50	20	151.60	151.60
7	2	PC	REAR WINDSCREEN MOULDING <i>new /</i>	36.80	20	29.44	58.88
8	1	PC	REAR END PANEL <i>repair</i>	276.50	20	221.20	221.20
9	1	PC	REAR END PANEL BRACKET RH <i>? X sue</i>	16.50	20	13.20	13.20
10	1	PC	REAR END PANEL TOP GARNISH <i>? X sue</i>	60.80	20	48.64	48.64
11	1	PC	REAR END PANEL RUBBER <i>X sue</i>	92.30	20	73.84	73.84
12	1	PC	REAR FENDER INNER TRIM RH <i>? X sue</i>	250.00	20	200.00	200.00
13	1	PC	REAR TAILLAMP RH <i>? X sue</i>	206.20	20	164.96	164.96
14	1	PC	REAR FENDER RH <i>repair</i>	652.40	20	521.92	521.92

SUB-TOTAL: 2,518.24

** SPECIAL NETT PRICE **

1	1	PC	REAR BUMPER REVERSE SENSOR	280.00 <i>200? new /</i>		280.00	280.00
2	1	PC	REAR WINDSCREEN SEALANT	40.00		40.00	40.00

SAM

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004541

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION :

CONTACT : 62238122

FAX NO: 62244174

DATE : 21/01/2019
ACCIDENT DATE : 04/01/2019
VEHICLE NO : SJP1382M
CHASSIS/ENG.NO : GE61144283
VEHICLE MODEL : HONDA FIT
CLAIM NO :
POLICY NO :
REMARK : 1382INDIA TP AGST
SHC8063E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
SUB-TOTAL							320.00

** WORK LABOUR **

TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS

~~800.00~~ 600 800.00

TO REMOVE & FIX REAR WINDSCREEN

~~150.00~~ 120 150.00

TO CHECK WIRING

~~30.00~~ 30.00

TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS

~~850.00~~ 700 850.00

TO APPLY ANTI RUST COATING

~~200.00~~ 40 200.00

SUB-TOTAL 2,030.00

Price

Hp 900 10068

5 days

4/5

21/01/19 @ 1405

Resing after repair

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 4,868.24

ADD 7% GST. S\$ 340.78

GRAND TOTAL : S\$ 5,209.02

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	4346D
Vehicle Details	
Vehicle No.:	SJP1382M
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Yellow
Manufacturing Year:	2008
Engine No.:	L13A4158959
Chassis No.:	GE61144283
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,223.00
Original Registration Date:	12 Mar 2009
First Registration Date:	12 Mar 2009
Transfer Count:	3
Actual ARF Paid:	\$10,418.00
PARF Eligibility Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Mar 2019
PARF Rebate Amount:	\$5,209.00
COE/COE Rebate Details	
COE Expiry Date:	11 Mar 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$697.00
COE Rebate Amount:	\$13.00
Total Rebate Amount:	\$5,222.00

The information contained herein is correct as at 22 Jan 2019

OK

6500
5222
1278
(1K)

Rasul (LKKAuto)

From: Rasul (LKKAuto)
Sent: Tuesday, 22 January, 2019 2:45 PM
To: 'Sharon Sng'
Subject: SJP 1382M DOA : 07/01/19

Hi Sharon,

Repair limit for this vehicle is 1K only

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	4346D
Vehicle No:	SJP1382M
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Yellow
Manufacturing Year:	2008
Engine No:	L13A4158959
Chassis No:	GE61144283
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,223.00
Original Registration Date:	12 Mar 2009
First Registration Date:	12 Mar 2009
Transfer Count:	4
Actual ARF Paid:	\$10,418.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	11 Mar 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$25,525.00
COE Rebate Amount:	\$25,266.00
Total Rebate Amount:	\$25,266.00

The information contained herein is correct as at 15 Apr 2019

OK

Print Received Message

This mail is associated with :

*SJP1382M (MCT19010183)

[SHC8063E]

TP

XIE CHENG ZHONG ERIK

Jan 7 2019 8:00AM

[-]

Sng Ah Tee Motor & Panel Service Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 29/10/2019 12:33 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2714.95) - SJP1382M - Claim Handler: Sundari Nagarajan

Approved:2714.95:2008 model. Is it economical to repair the vehicle

check w Ratul
on repair limit.
Repair limit 1k.
Finalise \$2250 y/s ?
TP Renew COB.

Print Received Message

This mail is associated with :

***SJP1382M (MCT19010183)**

[SHC8063E]

TP

XIE CHENG ZHONG ERIK

Jan 7 2019 8:00AM

[-]

Sng Ah Tee Motor & Panel Service Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 23/10/2019 09:21 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SJP1382M - Claim Handler: Sundari Nagarajan

Approved:0.00:2008 model. Is it economical to repair the vehicle

NV: \$1K.
Owner renew COE.

Print Received Message

This mail is associated with :

***SJP1382M (MCT19010183)**

[SHC8063E]

TP

XIE CHENG ZHONG ERIK

Jan 7 2019 8:00AM

[-]

Sng Ah Tee Motor & Panel Service Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 07/11/2019 09:58 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2714.95) - SJP1382M - Claim Handler: Sundari Nagarajan

Approved:2714.95:Request TP WS to issue Tax invoice for Repairs in III's favour

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jan 2019 Edit Reg		10 Jan 2019 00:00 Edit Adj Rpt	S\$2,250.00 Edit Estimates	S\$2,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	XIE CHENG ZHONG ERIK, ID: S8414346D								
Vehicle Reg. No.:	SJP1382M	Date of Loss:	07/01/2019 08:00 - :59 [117 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19010183	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC8063E	Policy No. (Claimant):	DMPPHQ17-005912						
		Excess:							
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (07/11/2019): Alert - Adj Mandate Approved (S\$2714.95) - SJP1382M - Claim Handler: Sundari Nag... - III_SG (29/10/2019): Alert - Adj Mandate Approved (S\$2714.95) - SJP1382M - Claim Handler: Sundari Nag... - III_SG (23/10/2019): Alert - Adj Mandate Approved (S\$0.00) - SJP1382M - Claim Handler: Sundari Nagara... - III_SG (29/07/2019): Alert - Adj Mandate Approved (S\$0.00) - SJP1382M - Claim Handler: Sundari Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJP1382M (MCT19010183)
[SHC8063E]
TP
XIE CHENG ZHONG ERIK
Jan 7 2019 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Sng Ah Tee Motor & Panel Service Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Video				1 per page v	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	17/01/19 12:37	Video - Accident-TP		Load MP4	
2	17/01/19 13:38	Video - Accident-TP-Front		Load MP4	

Photos/Images				3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/10/19 14:19	General View		Load JPG	☒
2	17/10/19 14:19	General View		Load JPG	☒
3	17/10/19 14:19	General View		Load JPG	☒
4	17/10/19 14:19	General View		Load JPG	☒
5	17/10/19 14:19	General View		Load JPG	☒
6	17/10/19 14:19	General View		Load JPG	☒
7	17/10/19 14:19	General View		Load JPG	☒
8	17/10/19 14:19	General View		Load JPG	☒
9	17/10/19 14:19	General View		Load JPG	☒
10	17/10/19 14:19	General View		Load JPG	☒
11	17/10/19 14:19	General View		Load JPG	☒
12	17/10/19 14:19	General View		Load JPG	☒
13	17/10/19 14:19	General View		Load JPG	☒
14	17/10/19 14:19	General View		Load JPG	☒
15	17/10/19 14:19	General View		Load JPG	☒
16	17/10/19 14:19	General View		Load JPG	☒
17	17/10/19 14:19	General View		Load JPG	☒
18	17/10/19 14:19	General View		Load JPG	☒
19	17/10/19 14:19	General View		Load JPG	☒
20	17/10/19 14:19	General View		Load JPG	☒
21	17/10/19 14:19	General View		Load JPG	☒
22	17/10/19 14:19	General View		Load JPG	☒
23	17/10/19 14:19	General View		Load JPG	☒
24	17/10/19 14:19	General View		Load JPG	☒
25	17/10/19 14:19	General View		Load JPG	☒
26	17/10/19 14:19	General View		Load JPG	☒
27	17/10/19 14:19	General View		Load JPG	☒
28	17/10/19 14:19	General View		Load JPG	☒
29	17/10/19 14:19	General View		Load JPG	☒
30	17/10/19 14:19	General View		Load JPG	☒
31	17/10/19 14:19	General View		Load JPG	☒
32	17/10/19 14:19	General View		Load JPG	☒
33	17/10/19 14:19	General View		Load JPG	☒
34	17/10/19 14:19	General View		Load JPG	☒
35	17/10/19 14:19	General View		Load JPG	☒
36	17/10/19 14:19	General View		Load JPG	☒
37	17/10/19 14:20	General View		Load JPG	☒
38	17/10/19 14:20	General View		Load JPG	☒
39	17/10/19 14:20	General View		Load JPG	☒

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
40	17/10/19 14:20	General View		Load JPG	☒
41	17/10/19 14:20	General View		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/01/19 12:08	EMAIL		Load PDF	
2	11/01/19 12:08	TP GIA REPORT		Load PDF	
3	24/01/19 09:35	TP ESTIMATE - MARKED		Load PDF	
4	17/10/19 14:19	LOD AND OTHER DOCUMENTS		Load PDF	
5	21/10/19 14:46	WORKSHOP INVOICE		Load PDF	
6	21/10/19 14:46	LTA SEARCH		Load PDF	
7	21/10/19 14:46	LOD		Load PDF	
8	29/10/19 10:28	RENEWAL COE		Load PDF	
9	05/12/19 08:24	AUTHORISATION TO ACT FORM		Load PDF	
10	05/12/19 08:24	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	14/01/19 08:48	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19000675/R1GA3Q2

Date: 05/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant: SJP1382M Insured Vehicle No: SHC8063E
 Vehicle No: SJP1382M Date of Loss: 07/01/2019 Nature of Claim: TP Claim No: MCT19010183

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJP1382M
 Make & Model: HONDA FIT, 1.3 G (A) Engine No: L13A4158959
 Reg. Date: 12/03/2009 (Man. Year: 2008) Chassis No: GE61144283
 Colour: Yellow Odometer: 125180 km
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R14 Rear Tyre Size: 175/65 R14
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,838.24	1,362.88	1,475.36	51.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,490.00	540.00	26.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,868.24	2,852.88	2,015.36	41.40
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	4,868.24	2,250.00	2,618.24	53.78
+ GST 7.00/7.00% (S\$)	340.78	157.50	183.28	53.78
Nett Amount (S\$)	5,209.02	2,407.50	2,801.52	53.78
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,714.95		

INSPECTION

Date of Assignment: 10/01/2019
 Date Inspected: 21/01/2019 Inspected At: Sng Ah Tee Motor & Panel Service
 Pte Ltd (Pioneer)
 Blk 3 Pioneer Road North, #01-18
 Singapore 628457

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 21 Oct 2019)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SJP1382M)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	497.50 FL	*497.50 FL
2	8		*REAR BUMPER CLIPS	Necessary	31.20 FL	*31.20 FL
3	1		*REAR BUMPER RETAINER (RH)	Necessary	16.50 FL	*16.50 FL
4	1		*REAR BUMPER TOWING COVER	Cut	13.30 FL	*13.30 FL
5	1		*REAR BOOT LID	Bent	771.50 FL	*771.50 FL
6	1		*REAR BOOT LOCK	Not Necessary	189.50 FL	*- FL
7	2		*REAR WINDSCREEN MOULDING	Necessary	73.60 FL	*73.60 FL
8	1		*REAR END PANEL	Repair	276.50 FL	*- FL
9	1		*REAR END PANEL BRACKET RH	Not Necessary	16.50 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Not Necessary	60.80 FL	*- FL
11	1		*REAR END PANEL RUBBER	Not Necessary	92.30 FL	*- FL
12	1		*REAR FENDER INNER TRIM RH	Not Necessary	250.00 FL	*- FL
13	1		*REAR TAILLAMP RH	Not Necessary	206.20 FL	*- FL
14	1		*REAR FENDER RH	Repair	652.40 FL	*- FL
15	1		*REAR BUMPER REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
16	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	3,467.80	1,643.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	629.56	280.72
Total Parts (\$\$)	2,838.24	1,362.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK ,WELD ,DAMAGED & FIX ON ABOVE PARTS	New	800.00	600.00
2	TO REMOVE & FIX REAR WINDSCREEN	New	150.00	120.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	850.00	700.00
5	TO APPLY ANTI RUST COATING	New	200.00	40.00
Gross Labour Cost (S\$)			2,030.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >