

Adrian survey on 11/1/19
without estimate

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0062/2019/GW
Date : 14-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SLK 9639 Z**

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Ms. Punitha D/O Narendran Mrs. Punitha Ramanan
Address : 345 Upper Bukit Timah Road # 05-07
Singapore 588197
Telephone : HP +65 97927525
Type of Claim : Third Party Claims
Policy No. : P10072798R00
Vehicle No : **SLE 1110 R**
Model Code : A1 SB 1.0 TFSI
Model / Year :
Engine No :
Chassis No :
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Jan-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 1110 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	✓
2	To renew rear windscreen.	S/N \$ 480.00	✓
3	To remove and transfer rear lid's convenience lock system, wire harness for taillights and rear wiper assy.	S/N \$ 480.00	✓
4	To dismantle and renew rear bumper and rear lid. To inspect end panelling for further damages. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,800.00	1200.
5	To respray rear bumper and rear lid.	\$ 1,500.00	1200.
6	To remove and renew lhs rear exhaust silencer.	S/N \$ 480.00	?
7	To carry out diagnostic check.	S/N \$ 192.00	✓
SUB LABOUR CHARGES		: \$ 5,212.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 1110 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUM'PER <i>Rehanded</i>	\$ 1,306.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 68.00	+
3	REAR BUMPER SPOILER <i>Rehanded</i>	\$ 384.00	✓
4	REAR LIGHT REFLECTOR-LH <i>?</i>	\$ 27.00	?
5	REAR BUMPER CARRIER <i>?</i>	\$ 500.00	?
6	REAR BUMPER GUIDE SECTION-LH/RH <i>new</i>	2 \$ 88.00	+
7	REAR LID <i>Dented</i>	\$ 2,359.00	✓
8	REAR LID ATTACHMENT PARTS <i>?</i>	\$ 260.00	?
9	REAR LID HINGE-LH/RH <i>new</i>	2 \$ 242.00	+
10	REAR LID STOP BUFFER <i>new</i>	\$ 16.00	+
11	REAR LID LOCK <i>new</i>	\$ 164.00	+
12	REAR LID FLAP LOCK COVER CAP <i>new</i>	\$ 7.00	+
13	REAR LID STRIKER PLATE <i>new</i>	\$ 118.00	+
14	REAR LID GASKET FLAP <i>new</i>	\$ 141.00	+
15	PACKING ADHESIVE <i>new</i>	\$ 18.00	✓
16	CHAFE GUARD <i>?</i>	2 \$ 28.00	?
17	AUDI EMBLEM <i>2</i>	\$ 113.00	✓
18	REAR LID INSCRIPTION ' A1 ' <i>new</i>	\$ 87.00	✓
19	REAR LID INSCRIPTION ' TFSI ' <i>new</i>	\$ 87.00	✓
20	REAR WINDOW <i>new</i>	\$ 705.00	✓
SUB-TOTAL SPARE PARTS CHARGES		\$ 6,718.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 1110 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
20	PRIMER <i>new</i>	2 \$ 38.00	X
21	TAILLIGHT-LH <i>new</i>	\$ 1,151.00	X.
22	REAR CROSS PANEL TRIM <i>new</i>	\$ 220.00	X
23	REAR SENSOR ?	2 \$ 419.00	?
24	REAR LID TRIM PANEL <i>new</i>	\$ 371.00	X.
25	REAR SILENCER ?	\$ 618.00	?
26	REAR SILENCER BRACKET ?	\$ 55.00	?
27	REAR SILENCER DUAL CLIP ?	\$ 55.00	?
28	REAR BUMPER WIRING SET <i>new</i>	\$ 568.00	?
29	REAR NO. PLATE <i>new</i>	S/N \$ 25.00	X
30	REAR W/S SEALANT <i>new</i>	S/N \$ 200.00	✓
31	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		: \$ 10,938.00	
TOTAL LABOUR CHARGES		\$ 5,212.00	
GRAND TOTAL		\$ 16,150.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 11/01/19
Authorised Date :
Excess Cost :
Liability :
Remarks : not Authorised, 05 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant