

No. of Airtight
nails
2/6 1/2
11/11/19

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER FOUR

SINGAPORE 038986

SLS5690H

ESTIMATE

DATE : 10.01.2019

VEHICLE NO : SLR2702H

MAKE/MODEL : HYUNDAI ELANTR,

ACC DATE : 08.01.2019

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	\$\$	\$\$
1	1 REAR BOOT	1,620.40	1,620.40
2	2 REAR BOOT HINGE RH/LH	94.30	188.60
3	1 REAR BOOT RUBBER	115.80	115.80
4	1 REAR BOOT LOCK	135.80	135.80
5	1 REAR BOOT LOCK CATCH	15.20	15.20
6	1 REAR BOOT INNER TRIM	185.60	185.60
7	1 REAR BOOT EMBLEM 'H'	28.00	28.00
8	1 REAR BOOT EMBLEM 'ELANTRA'	48.80	48.80
9	1 REAR BOOT REFLECTOR RH	284.90	284.90
10	1 REAR TAILLAMP RH	362.60	362.60
11	1 REAR TAILLAMP PANEL HOUSING RH	193.10	193.10
12	1 REAR BUMPER	556.80	556.80
13	2 REAR BUMPER REFLECTOR RH/LH	48.80	97.60
14	1 REAR BUMPER LOWER LID	321.80	321.80
15	1 REAR BUMPER REINFORCEMENT	328.00	328.00
16	2 REAR BUMPER REINFORCEMENT TOP BRACKET RH/LH	28.50	57.00
17	2 REAR BUMPER SIDE RETAINER RH/LH	44.80	89.60
18	1 REAR EXHAUST BOX	793.40	793.40
19	1 REAR EXHAUST BOX HEAT SHIELD	189.50	189.50
20	3 REAR EXHAUST MOUNTING	29.10	87.30
21	1 REAR END PANEL	495.00	495.00
22	1 REAR END PANEL GARNISH	88.60	88.60
23	1 REAR SPARE TYRE PANEL	878.30	878.30
24	1 REAR SPARE TYRE PANEL TOOL FOAM	108.50	108.50
25	1 REAR SPARE TYRE PANEL CARDBOARD	280.20	280.20
26	1 REAR FENDER INNER TRIM RH	207.90	207.90
27	2 FRT HEADLAMP RH/LH	1,198.80	2,397.60
28	1 FRT GRILLE ASSY	560.20	560.20
29	1 FRT NUMBER PLATE GARNISH	45.20	45.20
30	1 FRT BUMPER	495.60	495.60
31	1 FRT BUMPER TOP RUBBER	29.40	29.40
32	1 FRT BUMPER TOP GARNISH	74.10	74.10
33	1 FRT BUMPER LOWER LID	294.80	294.80
34	1 FRT BUMPER FOAM	126.80	126.80
35	1 FRT BUMPER REINFORCEMENT	695.80	695.80
		BALANCE B/F	12,477.80

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
		BALANCE C/F	12,477.80
36	2 REAR BUMPER SIDE RETAINER RH/LH	38.80	77.60
37	1 FRT SUPPORT PANEL	949.30	949.30
			13,504.70
		LESS 20%	2,700.94
			10,803.76

SPECIAL NETT ITEMS

1	1 (SET) REAR INNER TRIM CLIP	45.00	45.00
2	1 (SET) REAR NUMBER PLATE WITH CASING	50.00	50.00
3	1 REAR WEEK END SEAL	16.05	16.05
4	1 (SE) REAR BUMPER REVERSE SENSOR	280.00	280.00
5	1 (SET) REAR BUMPER CLIP	35.00	35.00
6	1 (SET) FRT NUMBER PLATE WITH CASING	50.00	50.00
7	1 FRT WEEK END SEAL	16.05	16.05
8	1 (SET) FRT BUMPER CLIP	45.00	45.00
			537.10

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL, REAR SPARE TYRE PANEL, REPLACE FRT SUPPORT PANEL AND REPLACE ACCIDENT PARTS	2,000.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	1,600.00
3	TO CHECK FRONT AND REAR WIRING	50.00
4	TO REMOVE, REFIX CONDENSER AND REFILL GAS	100.00
5	TO REMOVE, REFIX CUSHION AND INNER TRIM	120.00
6	TO RESEAR FRONT AND REAR NUMBER PLATE	120.00
7	TO REMOVE, REPLACE REVERSE SENSOR	80.00
8	TO REMOVE, REPLACE REAR EXHAUST BOX	120.00
9	TO REMOVE, REFIX FUEL TANK	120.00
10	TO TUFF KOTE	90.00
		4,400.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 15,740.86

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

S.N - 4571
Lab - 3430