

1552010

INS. CASE OWNER:

CC 4/AXA1900

LKK:

IDAC:

Surveyor:

MR CUM

DOI:

ASSIGNMENT

11/1/19

Date / Time:

11/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 5115J

Name of Insured:

TAMS - LAB SERVICES INC

Insured Tel No.:

HP:

Excess Sec II :SS

\$5000

D.O.A.:

9/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

PERCIRA DENNIS

Driver Tel No.:

(V/L) YES / NO)

Claim No.:

99MOLAYN / 21806

Policy No.:

UPX / PIB 80320

Make / Model:

RENAULT

Place of Accident:

SLE TMS LITE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

torque

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

15/1/19
JC

9/1/19 - x

SHC 5115J - LCC/AXA1900/484 (SMBX: 15/1/19)

*Smurkshin - HX

25/1/19

TP got video taken OIP sumu
raku 11" rlu

25/1/19

File - Su + curd P. for

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	
Documentation Check List: Handler Typist	
Notification ltr (if non-pickup)	☐
After call ltr to OI:	☒
Authorisation To Act:	☒
Release Voucher:	☐
Final Repair Bill:	☒
Car Rental Invoice:	☒
Towing Invoice:	☒
LTA / GIA:	☒
Medical Bill:	☒
PIR:	☐
Mandate/Reject Instruction:	☒
LOD:	☒
Payment Breakdown Form:	☐
Post-Repair Photos:	☐
Others:	☐

PRELIMINARY ADVICE Date/Time:		Sent By:		Confirm by:	
FINALIZATION Date/Time:		Confirm with:		Confirm by:	
Repair Cost:	SS	days) Reduction:	%	Email ☐	Call ☐
FINAL SETTLEMENT Date/Time:		Confirm with:		Email ☐ Call ☐	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:		If NO or B 28. Ass. Lia:	
Repair Cost:	SS	33170.00		NIC.	
Loss of Rental (LOR):	SS	2300.00 (23 days)		X #100	
Loss of Use (LOU):	SS	(S x days)			
Loss of Income (LOI):	SS	(S x days)			
LOR only ☐ LOU only ☐		LOR + LOU ☐		[Tick only one]	
GIA/LTA Search	SS				
Medical:	SS				
Disbursement:	SS	220.00		(e.g. ☒ Independent)	
Legal Cost	SS				
Total:	SS	Global Sum SS: 35000.00 (0.5 per AXA)			
FINAL PAYMENT Date/Time:		Confirm with:		Email ☐ Call ☐	
Payee 1:	SS	35000.00		Name 1: Torque 5 Pte Ltd	
Payee 2: (Strike if N.A.)	SS			Name 2:	
Payee 3: (Strike if N.A.)	SS			Name 3:	

GIA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19000683/hb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 11-01-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 5115J		Veh. Inspected	SLT 3177G
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	11/01/2019
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/01/2019		Inspection Date	
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Front bumper	121	1.00 901.70 0.00 1025.00 0.00	BRV
2	Front bumper retainer (LH)		1.00 25.00 0.00 35.00 0.00	} NECV
3	Front bumper retainer (RH)		1.00 25.00 0.00 35.00 0.00	
4	Front bumper towing cap		1.00 ✓ 0.00 25.00 0.00	MIS ✓
5	Front bumper reinforcement	244	1.00 321.00 0.00 400.00 0.00	? BTV
6	Front bumper lower grille		1.00 ✓ 0.00 125.00 0.00	MIS ✓
7	Front bumper fog lamp garnish (LH)		1.00 ✓ 0.00 67.00 0.00	CRV
8	Front bumper fog lamp garnish (RH)		1.00 ✓ 0.00 67.00 0.00	? CRV
9	Fog lamp (LH)		1.00 ✓ 0.00 430.00 0.00	BRV
10	Fog lamp (RH)		1.00 ✓ 0.00 430.00 0.00	? BRV
11	Front bumper lower lip	352	1.00 ✓ 0.00 400.00 0.00	BRV
12	Radiator grille	408	1.00 360.00 0.00 790.00 0.00	BRV
13	Radiator grille moulding		1.00 75.00 0.00 160.00 0.00	BRV
14	Radiator grille emblem - Logo		1.00 234.00 0.00 50.00 0.00	NECV
15	Front bumper undercover		1.00 189.10 0.00 432.70 0.00	CRV
16	Front bumper lower lip rubber strip		1.00 50.00 0.00 50.00 0.00	MIS ✓
17	Front bumper bracket (LH)		1.00 ✓ 0.00 32.00 0.00	} NECV
18	Front bumper bracket (RH)		1.00 ✓ 0.00 32.00 0.00	
19	Bonnet	801	1.00 685.00 0.00 980.00 0.00	CRV
20	Bonnet hinge (LH)		1.00 ✓ 0.00 60.00 0.00	} BTV
21	Bonnet hinge (RH)		1.00 ✓ 0.00 60.00 0.00	
22	Bonnet lock		1.00 ✓ 0.00 120.00 0.00	BTV
23	Bonnet insulator		1.00 150.00 0.00 198.00 0.00	NECV
24	Bonnet weather strip set		1.00 0.00 100.00 0.00	TV
25	Head lamp (LH)	1260	1.00 1784.50 0.00 1460.00 0.00	BRV

Continue on next page...

6427.10



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
26	Head lamp (RH)	1256	1.00	0.00 1784.50 0.00 BR ✓
27	Head lamp bracket (LH)	1.00	0.00	60.00 0.00 CRA ✓
28	Head lamp bracket (RH)	1.00	0.00	60.00 0.00 }
29	Head lamp ECU (LH)	1.00	0.00	-0.00 }
30	Head lamp ECU (RH)	1.00	0.00	-0.00 } NNX
31	Head lamp ballast (LH)	1.00	0.00	-0.00 }
32	Head lamp ballast (RH)	1.00	0.00	-0.00 } NNX
33	Front fender (LH)	615	1.00	0.00 550.00 0.00 650.00
34	Front fender (RH)	615	1.00	0.00 550.00 0.00 650.00
35	Front fender inner shield (LH)	1.00	0.00	130.00 0.00 130.00
36	Front fender inner shield (RH)	1.00	0.00	130.00 0.00 130.00
37	Front protector (LH) (Fender)	1.00	0.00	200.00 0.00 200.00
38	Front protector (RH) (Fender)	1.00	0.00	200.00 0.00 200.00
39	Front emblem - Hybrid (LH) (Fender)	1.00	0.00	62.90 0.00 110.00
40	Front emblem - Hybrid (RH) (Fender)	1.00	0.00	62.90 0.00 110.00
41	Front fender inner garnish (LH)	1.00	0.00	191.10 0.00 250.00
42	Front fender inner garnish (RH)	1.00	0.00	191.10 0.00 250.00
43	Front fender inner panel A (LH)	1.00	0.00	195.00 0.00 240.00
44	Front fender inner panel A (RH)	1.00	0.00	195.00 0.00 240.00
45	Front fender inner panel B (LH)	1.00	0.00	195.00 0.00 240.00
46	Front fender inner panel B (RH)	1.00	0.00	195.00 0.00 240.00
47	Front support panel	494	1.00	0.00 576.00 0.00 672.40
48	Front support panel air guide (LH)	1.00	0.00	150.00 0.00 370.00
49	Front support panel air guide (RH)	1.00	0.00	150.00 0.00 370.00
50	Front support panel top garnish	1.00	0.00	162.30 0.00 284.00
51	Front support panel lock bracket	1.00	0.00	0.00 0.00 NNX

5990.80

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of : 2017
Manufacture :

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
52	Front support panel top panel	1.00	0.00	0.00 ? BTV NNX
53	Front support panel air duct	1.00	0.00	0.00 ? NNX
54	A/C Condenser	1.00	538.50	0.00 670.00 ? BTV
55	Radiator	1.00	1,150.10	0.00 1,610.00 ? BRV
56	Radiator fan motor & cowling set	1.00	483.00	0.00 774.00 ? NNX
57	Air-cond fan motor & cowling set	1.00	0.00	0.00 ? NNX
58	Radiator spare tank	1.00	62.50	0.00 110.00 ? BRV
59	Washer tank	1.00	75.00	0.00 36.00 ? BRV
60	Washer tank motor	2.00	0.00	0.00 ? NNX
61	Side mirror assy (LH)	1.00	0.00	747.50 0.00 ? CRV
62	Side mirror assy (RH)	1.00	0.00	747.50 0.00 ? CRV
63	Front door (LH)	1.00	1080.50	0.00 1536.00 ? DDV
64	Front door hinge top & bottom (LH)	1.00	0.00	98.00 0.00 ? BTV
65	Front door checker (LH)	1.00	88.60	0.00 122.40 ? BTV
66	Front door lock (LH)	1.00	310.00	0.00 392.00 ? CUTV
67	Front door inner trim board (LH)	1.00	0.00	560.00 0.00 ? BRV
68	Front door inner trim rubber beading long (LH)	1.00	117.00	0.00 187.50 ? NEC
69	Front door inner trim rubber beading short (LH)	1.00	117.00	0.00 187.50 ? NEC
70	Front door outer handle (LH)	1.00	0.00	440.00 0.00 ? NNX
71	Front door outer handle bracket (LH)	1.00	0.00	0.00 0.00 ? NNX
72	Front door inner handle (LH)	1.00	0.00	270.00 0.00 ? NNX
73	Front door inner handle bracket (LH)	1.00	0.00	0.00 0.00 ? NNX
74	Front door power window regulator (LH)	1.00	382.00	0.00 480.00 ? BTV
75	Front door power window motor (LH)	1.00	0.00	460.00 0.00 ? NNX
76	Front door window frame (LH)	1.00	0.00	230.00 0.00 ? BTV
77	Front door window glass (LH)	1.00	394.00	0.00 450.00 ? NNX

Continue on next page...

7118.70



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
78	Front door inner pillar (LH)	1.00	0.00 1035.00	0.00 RX
79	Front door inner pillar rubber beading (LH)	1.00	✓ 0.00 190.00	0.00 NEC✓
80	Rocker panel garnish (LH)	1.00	✓ 0.00 470.00	0.00 BTP✓
81	Rear door (LH)	1.00 1.00	0.00 330.60 0.00 1025.00	0.00 RX
82	Rear door lock (LH)	1.00	0.00 310.00	0.00 NNX
83	Rear door side weather strip (LH)	✓ 1.00	67.00 0.00 67.00	0.00 CuTV
84	Rear door checker (LH)	1.00	0.00 110.00	0.00 NNX
85	Rear door hinge top & bottom (LH)	1.00	0.00 100.00	0.00 NNX
86	Rear fender (LH)	1.00	0.00 1055.00	0.00 NNX
87	Rear fender protector (LH)	— 1.00	260.00 0.00 260.00	0.00 CuTV
88	Rear corner bumper (LH)	— 1.00	381.80 0.00 381.80	0.00 CuTV
89	Rear bumper	1.00	900.00 0.00 990.00	0.00 ? CRU✓
90	Rear bumper reflector (LH)	1.00	0.00 169.00	0.00 ? NNX
91	Rear fender inner shield (LH)	1.00	0.00 180.00	0.00 NNX
92	Front door (RH)	834. 1.00	1080.50 0.00 1536.00	0.00 CRU✓
93	Front door hinge top & bottom (RH)	1.00	✓ 0.00 98.00	0.00 BTV
94	Front door checker (RH)	1.00	83.60 0.00 123.40	0.00 BTV
95	Front door lock (RH)	1.00	310.00 0.00 342.00	0.00 JM✓
96	Front door inner trim board (RH)	1.00	✓ 0.00 560.00	0.00 ? BR✓
97	Front door inner rubber beading long (RH)	1.00	117.00 0.00 187.50	0.00 CuTV
98	Front door inner rubber beading short (RH)	1.00	117.00 0.00 187.50	0.00 CuTV
99	Front door outer handle (RH)	1.00	350.00 0.00 440.00	0.00 JM✓
100	Front door outer key lock (RH)	1.00	0.00	0.00 JM✓ NNX
101	Front door inner handle (RH)	1.00	0.00 270.00	0.00 ? NNX
102	Front door inner handle bracket (RH)	1.00	0.00	0.00 ? NNX
103	Front door power window regulator (RH)	1.00	394.00 0.00 420.00	0.00 BTV✓

Continue on next page...

5672.70



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt	
104	Front door power window motor (RH)	1.00	382.00	0.00	460.00 JM✓
105	Front door power window main switch (RH)	1.00		0.00	0.00 ? NNx
106	Front door window frame (RH)	1.00	✓	0.00	230.00 0.00 BT✓
107	Front door window glass (RH)	1.00		0.00	450.00 0.00 ? NNx
108	Front door inner pillar (RH)	1.00	✓	0.00	1035.00 0.00 BT✓
109	Front door inner pillar rubber beading (RH)	1.00	✓	0.00	190.00 0.00 CuT✓
110	Rear door (RH)	890 1.00	930.00	0.00	1025.00 0.00 DD✓
111	Rear door lock (RH)	1.00	✓	0.00	310.00 0.00 ? JM✓
112	Rear door outer handle (RH)	1.00	350.00	0.00	410.00 0.00 ? CuT✓
113	Rear door window frame (RH)	1.00	230.00	0.00	230.00 0.00 BT✓
114	Rear door hinge top & bottom (RH)	1.00	✓	0.00	100.00 0.00 BT✓
115	Rear door checker (RH)	1.00	✓	0.00	110.00 0.00 BT✓
116	Rear door inner trim board (RH)	1.00	✓	0.00	600.00 0.00 ? BR✓
117	Rear power window regulator (RH)	1.00	382.00	0.00	420.00 0.00 BT✓
118	Rear power window motor (RH)	1.00	382.00	0.00	440.00 0.00 ? JM✓
119	Rear power window switch (RH)	1.00		0.00	0.00 ? JM✓
120	Rear door inner rubber beading long (RH)	1.00	117.00	0.00	200.00 0.00 CuT✓
121	Rear door inner rubber beading short (RH)	1.00	117.00	0.00	200.00 0.00 CuT✓
122	Rear door weather strip (RH)	1.00	50.00	0.00	67.00 0.00 CuT✓
123	Rear power window glass (RH)	1.00		0.00	0.00 ? NNx
124	Rocker panel (RH)	1.00		0.00	0.00 BR✓
125	Rocker panel garnish (RH)	1.00		0.00	470.00 0.00 BR✓
126	Rear door pillar rubber beading (RH)	1.00		0.00	190.00 0.00 ? CuT✓
127	Rear door inner centre pillar (RH)	1.00		0.00	Rx 0.00 BT✓
128	Rear fender (RH)	615 1.00	615.40	0.00	1055.00 0.00 DD✓
129	Rear fender protector (RH)	1.00	225.00	0.00	260.00 0.00 BR✓

Continue on next page...

6926.3



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of : 2017
Manufacture

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
130	Rear fender inner shield (RH)	1.00	✓ 0.00 180.00	0.00 TN ✓
131	Rear fender QTR garnish	2.00	0.00	0.00 NN X
132	Front windscreen	1.00	0.00	0.00 NN X
133	Front windscreen moulding	1.00 120.00	0.00 120.00	0.00 NEC ✓
134	Wiper garnish	1.00 281.58	0.00 281.58	0.00 ? CTV
135	Front absorber (RH)	345 1.00 501.20	0.00 550.00	0.00 BT ✓
136	Front absorber top ^{mounting} moulding (RH)	1.00 45.00	0.00 45.00	0.00 NEC ✓
137	Front knuckle arm (RH)	244 1.00	✓ 0.00 500.00	0.00 2 BT ✓
138	Front knuckle bearing (RH)	1.00	✓ 0.00 240.00	0.00 2 JM ✓
139	Front lower arm (RH)	285 1.00	✓ 0.00 400.00	0.00 BT ✓
140	Front absorber linkage (RH)	1.00	0.00	0.00 ? NN X
141	Front absorber (LH)	1.00 501.58	0.00 550.00	0.00 BT ✓
142	Front absorber top mounting (LH)	1.00 45.00	0.00	0.00 NEC ✓
143	Front knuckle arm (LH)	244 1.00	✓ 0.00 500.00	0.00 BT ✓ BT ✓
144	Front knuckle bearing (LH)	1.00	✓ 0.00 240.00	0.00 JM ✓
145	Front lower arm (LH)	285 1.00	✓ 0.00 400.00	0.00 BT ✓
146	Front absorber linkage (LH)	1.00 55.00	0.00 45	0.00 ? BT ✓
147	Front wheel house panel (LH)	1.00	0.00	0.00 RX
148	Front wheel house panel (RH)	1.00	0.00	0.00 RX
149	Front cross member	1.00	0.00	0.00 ? BT ✓ RX
150	Steering rack	1.00	0.00 RX	0.00 ? JM ✓
151	Rack end set	1.00 89.00	0.00 89	0.00 ? BT ✓
152	Tie rod end set	1.00 72.00	0.00 72	0.00 ? JM ✓
153	Rear axle	1.00 1030.00	0.00 1000.00	0.00 ? BT ✓
154	Rear absorber (LH)	1.00 280.80	0.00 420.00	0.00 ? BT ✓
155	Rear absorber (RH)	1.00 280.80	0.00 420.00	0.00 ? BT ✓

Continue on next page...

5761.96



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
156	Rear wheel bearing (LH)	179 1.00	245.00	0.00 397.00 0.00 } JM ✓
157	Rear wheel bearing (RH)	139 1.00	245.00	0.00 397.00 0.00 }
158	Wheel rim	4.00	300.00	0.00 300.00 0.00 CUT ✓
159	Front ABS sensor	2.00	165.00	0.00 165.00 0.00 ? CUT ✓
160	Fan relay box	1.00	385.00	0.00 385.00 0.00 BR ✓
161	Air cleaner resonator	1.00	185.00	0.00 185.00 0.00 ? BR ✓
162	Drive-shaft (LH)	45 1.00	800.00	0.00 800.00 0.00 } JM ✓
163	Drive-shaft (RH)	45 1.00	800.00	0.00 800.00 0.00 }
164	Driver door harness wire set	1.00	100.00	0.00 100.00 0.00 ? } CR ✓
165	Rear door harness wire set (RH)	1.00	100.00	0.00 100.00 0.00 ? }

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

3925.00

Section: Special Nett Items

166	Wiper garnish clip set	1.00	45.00	30.00 45.00 } NEC ✓
167	Front bumper clip set	1.00	50.00	30.00 50.00 }
168	Front number plate & casing	1.00	45.00	45.00 45.00 BR ✓
169	Front bumper undercover clip set	1.00	45.00	30.00 45.00 }
170	Bonnet insulator clip set	1.00	45.00	30.00 45.00 }
171	Support panel top garnish clip set	1.00	30.00	30.00 30.00 }
172	Front fender inner shield clip set (LH)	1.00	50.00	30.00 50.00 } NEC ✓
173	Front fender inner shield clip set (RH)	1.00	50.00	30.00 50.00 }
174	Rear fender inner shield clip set (LH)	1.00	50.00	20.00 50.00 }
175	Rear fender inner shield clip set (RH)	1.00	50.00	30.00 50.00 }
176	Front fender protector clip set (LH)	1.00	40.00	25.00 40.00 }
177	Front fender protector clip set (RH)	1.00	40.00	25.00 40.00 }

335.00

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
178	Rocker panel garnish clip set (LH)	1.00	50.00	50.00
179	Rocker panel garnish clip set (RH)	1.00	50.00	50.00
180	Rear fender protector clip set (LH)	1.00	45.00	45.00
181	Rear fender protector clip set (RH)	1.00	45.00	45.00
182	Driver door inner trim board clip set	1.00	50.00	50.00
183	Passenger door inner trim board clip set	1.00	50.00	50.00
184	Rear door inner trim board clip set (RH)	1.00	50.00	50.00
185	Door visor set	1.00	120.00	120.00
186	Engine coolant	1.00	120.00	120.00
187	Auto transmission fluid 2 Liter	1.00	220.00	220.00
188	215/60/16 Dunlop tyre	2 PCS	200.00	400.00
189	Tyre air valve	2 PCS	10.00	20.00
190	Horn set	1.00	160.00	160.00
191	Front windscreen sealant	1.00	60.00	60.00
192	Front windscreen tinted	1.00	200.00	200.00
193	Front fender inner panel sealant (LH)	1.00	50.00	50.00
194	Front fender inner panel sealant (RH)	1.00	50.00	50.00
195	Front support panel sealant	1.00	50.00	50.00
196	Drive door sound speaker	1.00	800.00	800.00
197	Passenger door sound speaker	1.00	800.00	800.00
198	Rear door sound speaker (RH)	1.00	800.00	800.00
199	Front windscreen inner seal	1.00	50.00	50.00

Amt S\$ 5,200.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 5,200.00

1330.00

Section: Labour Items

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
200	To R&R rear bumper reverse sensor	1.00	60.00	60.00 360.00 ✓
201	To conduct head lamp focus	1.00	100.00	100.00 50.00 ✓
202	To remove and refix wiring system and check for proper function	1.00	100.00	100.00 80.00 ✓
203	To supply undercoating / putty on parts replaced	1.00	120.00	120.00 60.00 ✓
204	To perform anti rust treatment on affected areas	1.00	80.00	80.00 60.00 ✓
205	To conduct alignment after repair	1.00	100.00	100.00 60.00 ✓
206	To R&R A/C condenser, radiator assy	1.00	280.00	280.00 150.00 ✓
207	To R&R driver door mechanism	1.00	250.00	250.00 50.00 ✓
208	To R&R passenger door mechanism	1.00	250.00	250.00 150.00 ✓
209	To R&R rear door mechanism (RH)	1.00	250.00	250.00 150.00 ✓
210	To R&R front windscreen	1.00	280.00	280.00 100.00 ✓
211	To R&R fuel tank, ^{to} cut and weld	1.00	350.00	350.00 200.00 ✓
212	To R&R front under-carriage damaged parts	1.00	400.00	400.00 } 350.00 ✓
213	To R&R rear under-carriage damaged parts	1.00	300.00	300.00 } 350.00 ✓
214	To R&R wheel rims, tyres and balancing	1.00	120.00	120.00 60.00 ✓
215	To reset anti lock brake system	1.00	160.00	160.00 80.00 ✓
216	To reprogramming hybrid IMA system	1.00	900.00 400.00	900.00 600.00 ✓
217	To R&R interior, seats and garnishes	1.00	250.00	250.00 150.00 ✓
218	To R&R dashboard assy to cut and weld	1.00	500.00	500.00 250.00 ✓
219	To repair, replaced and realign damaged areas	1.00	2,500.00	2,500.00 1800.00 ✓
220	To spray painting on affected areas	1.00	2,200.00	2,200.00 1700.00 ✓
221	To perform water seepage test after repair	1.00	180.00	180.00 100.00 ✓
222	To car wash & polishing vehicle after repair	1.00	120.00	120.00 NNx ✓
223	To top up 134a refrigerant	1.00	80.00	80.00 ✓ ✓
224	Sundries	1.00	50.00	50.00 NNx ✓
225	Brake bleeding	1.00	100.00	100.00 50.00 ✓
				5990.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
				Amt S\$ 9,980.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 9,980.00

42141.85
@ 20% 33713.48

4/8 33,000/2

? Photo

Term

11/1/19

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Days of repair 20

64408.6 tax

List Items Subtotal S\$ 0.00
Special Nett Items S\$ 5,200.00
Subtotal
Labour Items Subtotal S\$ 9,980.00
Total S\$ 15,180.00



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : SLT3177G

Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483

Year of : 2017

Manufacture

Estimation No. : E19010011

DOA : 09/01/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Engine mounting rear <i>NNX</i>	1.00	0.00	0.00
2	Front brake ^{<i>caliper</i>} caliper (LH) <i>BT NNX</i>	1.00	0.00	0.00
3	Radiator bracket (LH) <i>} NEC ✓ 50.00</i>	1.00	0.00	0.00
4	Radiator bracket (RH) <i>} NEC ✓ 50.00</i>	1.00	0.00	0.00
5	A/C condenser bracket (LH) <i>} NEC ✓</i>	1.00	0.00	0.00 <i>43.00 ✓</i>
6	A/C condenser bracket (RH) <i>} NEC ✓</i>	1.00	0.00	0.00 <i>43.00 ✓</i>
7	Front brake steel hose (LH) <i>CRU ✓ 100.00</i>	1.00	0.00	0.00
8	Engine fuse box <i>BR ✓ 9.00.00</i>	1.00	0.00	0.00
9	Fog lamp harness wire set <i>CUT ✓ 100.00</i>	1.00	0.00	0.00

Amt	S\$ 0.00
Discount (0.00%)	S\$ 0.00
Subtotal	S\$ 0.00

Re survey 14/1/19

LIM TEOW GUAN

lim

@ 20%

12 86

1028.8

List Items Subtotal	S\$ 0.00
Total	S\$ 0.00

Pg 1	Pg 2	Pg 3	Pg 4	Pg 5	Pg 6	Pg 7	Pg 8	Pg 9	Pg 10	Supp
\$ 1,025.00	\$ 1,784.50	\$ 670.00	\$ 1,035.00	\$ 460.00	\$ 180.00	\$ 392.00	\$ 50.00	\$ 60.00	Total	\$ 50.00
\$ 35.00	\$ 60.00	\$ 1,610.00	\$ 190.00	\$ 230.00	\$ 120.00	\$ 392.00	\$ 50.00	\$ 100.00		\$ 50.00
\$ 35.00	\$ 60.00	\$ 774.00	\$ 470.00	\$ 450.00	\$ 281.58	\$ 300.00	\$ 45.00	\$ 100.00		\$ 43.00
\$ 25.00	\$ 650.00	\$ 110.00	\$ 1,025.00	\$ 1,035.00	\$ 550.00	\$ 165.00	\$ 45.00	\$ 120.00		\$ 43.00
\$ 400.00	\$ 650.00	\$ 75.00	\$ 310.00	\$ 190.00	\$ 45.00	\$ 985.00	\$ 50.00	\$ 80.00		\$ 100.00
\$ 125.00	\$ 180.00	\$ 747.50	\$ 67.00	\$ 1,025.00	\$ 500.00	\$ 185.00	\$ 50.00	\$ 100.00		\$ 900.00
\$ 62.00	\$ 180.00	\$ 747.50	\$ 110.00	\$ 310.00	\$ 240.00	\$ 800.00	\$ 50.00	\$ 280.00		\$ 100.00
\$ 62.00	\$ 180.00	\$ 1,536.00	\$ 100.00	\$ 410.00	\$ 400.00	\$ 800.00	\$ 120.00	\$ 250.00		
\$ 430.00	\$ 212.00	\$ 98.00	\$ 1,055.00	\$ 230.00	\$ 550.00	\$ 100.00	\$ 120.00	\$ 250.00		
\$ 430.00	\$ 212.00	\$ 123.40	\$ 260.00	\$ 100.00	\$ 500.00	\$ 100.00	\$ 220.00	\$ 250.00		
\$ 400.00	\$ 110.00	\$ 392.00	\$ 381.80	\$ 110.00	\$ 240.00		\$ 800.00	\$ 280.00		
\$ 790.00	\$ 110.00	\$ 560.00	\$ 990.00	\$ 600.00	\$ 400.00	\$ 4,219.00	\$ 40.00	\$ 350.00		
\$ 160.00	\$ 250.00	\$ 187.50	\$ 169.00	\$ 420.00	\$ 55.00		\$ 160.00	\$ 400.00		
\$ 50.00	\$ 250.00	\$ 187.50	\$ 180.00	\$ 440.00	\$ 89.00	SN	\$ 60.00	\$ 300.00		
\$ 432.70	\$ 210.00	\$ 410.00	\$ 1,536.00	\$ 200.00	\$ 72.00	\$ 45.00	\$ 200.00	\$ 120.00		
\$ 50.00	\$ 210.00	\$ 270.00	\$ 98.00	\$ 200.00	\$ 1,600.00	\$ 50.00	\$ 50.00	\$ 160.00		
\$ 32.00	\$ 210.00	\$ 480.00	\$ 123.40	\$ 67.00	\$ 420.00	\$ 45.00	\$ 50.00	\$ 900.00		
\$ 32.00	\$ 210.00	\$ 460.00	\$ 392.00	\$ 470.00	\$ 420.00	\$ 45.00	\$ 50.00	\$ 250.00		
\$ 980.00	\$ 672.40	\$ 230.00	\$ 560.00	\$ 190.00		\$ 45.00	\$ 800.00	\$ 500.00		
\$ 60.00	\$ 370.00	\$ 450.00	\$ 187.50	\$ 1,055.00		\$ 30.00	\$ 800.00	\$ 2,500.00		
\$ 60.00	\$ 370.00		\$ 187.50	\$ 260.00		\$ 50.00	\$ 800.00	\$ 2,200.00		
\$ 120.00	\$ 284.00		\$ 410.00			\$ 50.00	\$ 50.00	\$ 180.00		
\$ 198.00			\$ 270.00			\$ 50.00		\$ 120.00		
\$ 100.00			\$ 480.00			\$ 40.00		\$ 80.00		
\$ 1,960.00						\$ 40.00		\$ 50.00		
\$ 8,053.70	\$ 7,424.90	\$ 10,118.40	\$ 10,587.20	\$ 8,452.00	\$ 6,662.58	\$ 4,709.00	\$ 4,660.00	\$ 10,080.00		\$ 1,286.00
						\$ 490.00				\$ 72,033.78