



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Front bumper	1.00	0.00	0.00 BRV
2	Front bumper retainer (LH)	1.00	0.00	0.00
3	Front bumper retainer (RH)	1.00	0.00	0.00 } NECV
4	Front bumper towing cap	1.00	0.00	0.00 MIS ✓
5	Front bumper reinforcement	1.00	0.00	0.00 ?
6	Front bumper lower grille	1.00	0.00	0.00 MIS ✓
7	Front bumper fog lamp garnish (LH)	1.00	0.00	0.00 MIS ✓
8	Front bumper fog lamp garnish (RH)	1.00	0.00	0.00 ?
9	Fog lamp (LH)	1.00	0.00	0.00 MIS ✓
10	Fog lamp (RH)	1.00	0.00	0.00 ?
11	Front bumper lower lip	1.00	0.00	0.00 BRV
12	Radiator grille	1.00	0.00	0.00 BRV
13	Radiator grille moulding	1.00	0.00	0.00 BRV
14	Radiator grille emblem - Logo	1.00	0.00	0.00 NECV
15	Front bumper undercover	1.00	0.00	0.00 CUT ✓
16	Front bumper lower lip rubber strip	1.00	0.00	0.00 MIS ✓
17	Front bumper bracket (LH)	1.00	0.00	0.00
18	Front bumper bracket (RH)	1.00	0.00	0.00 } NECV
19	Bonnet	1.00	0.00	0.00 CRU ✓
20	Bonnet hinge (LH)	1.00	0.00	0.00
21	Bonnet hinge (RH)	1.00	0.00	0.00 } BT ✓
22	Bonnet lock	1.00	0.00	0.00 BT ✓
23	Bonnet insulator	1.00	0.00	0.00 NECV
24	Bonnet weather strip set	1.00	0.00	0.00 TN ✓
25	Head lamp (LH)	1.00	0.00	0.00 BRV

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
52	Front support panel top panel	1.00	0.00	0.00 ?
53	Front support panel air duct	1.00	0.00	0.00 ?
54	A/C Condenser	1.00	0.00	0.00 ?
55	Radiator	1.00	0.00	0.00 BRV
56	Radiator fan motor & cowling set	1.00	0.00	0.00 ?
57	Air-cond fan motor & cowling set	1.00	0.00	0.00 ?
58	Radiator spare tank	1.00	0.00	0.00 ?
59	Washer tank	1.00	0.00	0.00 ?
60	Washer tank motor	2.00	0.00	0.00 ?
61	Side mirror assy (LH)	1.00	0.00	0.00 ?
62	Side mirror assy (RH)	1.00	0.00	0.00 ?
63	Front door (LH)	1.00	0.00	0.00 DDV
64	Front door hinge top & bottom (LH)	1.00	0.00	0.00 BTV
65	Front door checker (LH)	1.00	0.00	0.00 BTV
66	Front door lock (LH)	1.00	0.00	0.00 ?
67	Front door inner trim board (LH)	1.00	0.00	0.00 ?
68	Front door inner trim rubber beading long (LH)	1.00	0.00	0.00 ?
69	Front door inner trim rubber beading short (LH)	1.00	0.00	0.00 ?
70	Front door outer handle (LH)	1.00	0.00	0.00 NNX
71	Front door outer handle bracket (LH)	1.00	0.00	0.00 NNX
72	Front door inner handle (LH)	1.00	0.00	0.00 NNX
73	Front door inner handle bracket (LH)	1.00	0.00	0.00 NNX
74	Front door power window regulator (LH)	1.00	0.00	0.00 BTV
75	Front door power window motor (LH)	1.00	0.00	0.00 ?
76	Front door window frame (LH)	1.00	0.00	0.00 BTV
77	Front door window glass (LH)	1.00	0.00	0.00 NNX

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of : 2017
Manufacture

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
78	Front door inner pillar (LH)	1.00	0.00	0.00 RX
79	Front door inner pillar rubber beading (LH)	1.00	0.00	0.00 NECV
80	Rocker panel garnish (LH)	1.00	0.00	0.00 BTV
81	Rear door (LH)	1.00	0.00	0.00 RX
82	Rear door lock (LH)	1.00	0.00	0.00 NNX
83	Rear door side weather strip (LH)	1.00	0.00	0.00 CuTV
84	Rear door checker (LH)	1.00	0.00	0.00 NNX
85	Rear door hinge top & bottom (LH)	1.00	0.00	0.00 NNX
86	Rear fender (LH)	1.00	0.00	0.00 NNX
87	Rear fender protector (LH)	1.00	0.00	0.00 CuTV
88	Rear corner bumper (LH)	1.00	0.00	0.00 CuTV
89	Rear bumper	1.00	0.00	0.00 ?
90	Rear bumper reflector (LH)	1.00	0.00	0.00 ?
91	Rear fender inner shield (LH)	1.00	0.00	0.00 NNX
92	Front door (RH)	1.00	0.00	0.00 CRUV
93	Front door hinge top & bottom (RH)	1.00	0.00	0.00 BTV
94	Front door checker (RH)	1.00	0.00	0.00 BTV
95	Front door lock (RH)	1.00	0.00	0.00 JMV
96	Front door inner trim board (RH)	1.00	0.00	0.00 ?
97	Front door inner rubber beading long (RH)	1.00	0.00	0.00 CuTV
98	Front door inner rubber beading short (RH)	1.00	0.00	0.00 CuTV
99	Front door outer handle (RH)	1.00	0.00	0.00 JMV
100	Front door outer key lock (RH)	1.00	0.00	0.00 JMV
101	Front door inner handle (RH)	1.00	0.00	0.00 ?
102	Front door inner handle bracket (RH)	1.00	0.00	0.00 ?
103	Front door power window regulator (RH)	1.00	0.00	0.00 BTV

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
104	Front door power window motor (RH)	1.00	0.00	0.00 JMV
105	Front door power window main switch (RH)	1.00	0.00	0.00 ?
106	Front door window frame (RH)	1.00	0.00	0.00 BTV
107	Front door window glass (RH)	1.00	0.00	0.00 ?
108	Front door inner pillar (RH)	1.00	0.00	0.00 BTV
109	Front door inner pillar rubber beading (RH)	1.00	0.00	0.00 CUTV
110	Rear door (RH)	1.00	0.00	0.00 DDV
111	Rear door lock (RH)	1.00	0.00	0.00 ?
112	Rear door outer handle (RH)	1.00	0.00	0.00 ?
113	Rear door window frame (RH)	1.00	0.00	0.00 BTV
114	Rear door hinge top & bottom (RH)	1.00	0.00	0.00 BTV
115	Rear door checker (RH)	1.00	0.00	0.00 BTV
116	Rear door inner trim board (RH)	1.00	0.00	0.00 ?
117	Rear power window regulator (RH)	1.00	0.00	0.00 BTV
118	Rear power window motor (RH)	1.00	0.00	0.00 ?
119	Rear power window switch (RH)	1.00	0.00	0.00 ?
120	Rear door inner rubber beading long (RH)	1.00	0.00	0.00 CUTV
121	Rear door inner rubber beading short (RH)	1.00	0.00	0.00 CUTV
122	Rear door weather strip (RH)	1.00	0.00	0.00 CUTV
123	Rear power window glass (RH)	1.00	0.00	0.00 ?
124	Rocker panel (RH)	1.00	0.00	0.00 BRV RX
125	Rocker panel garnish (RH)	1.00	0.00	0.00 BRV
126	Rear door pillar rubber beading (RH)	1.00	0.00	0.00 ? CUTV
127	Rear door inner centre pillar (RH)	1.00	0.00	0.00 BTV
128	Rear fender (RH)	1.00	0.00	0.00 DDV
129	Rear fender protector (RH)	1.00	0.00	0.00 BRV

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of : 2017
Manufacture

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
130	Rear fender inner shield (RH)	1.00	0.00	0.00 TN ✓
131	Rear fender QTR garnish	2.00	0.00	0.00 NX
132	Front windscreen	1.00	0.00	0.00 NX
133	Front windscreen moulding	1.00	0.00	0.00 NEC ✓
134	Wiper garnish	1.00	0.00	0.00 ?
135	Front absorber (RH)	1.00	0.00	0.00 BT ✓
136	Front absorber top mounting moulding (RH)	1.00	0.00	0.00 NEC ✓
137	Front knuckle arm (RH)	1.00	0.00	0.00 BT ✓
138	Front knuckle bearing (RH)	1.00	0.00	0.00 JMV ✓
139	Front lower arm (RH)	1.00	0.00	0.00 BT ✓
140	Front absorber linkage (RH)	1.00	0.00	0.00 ?
141	Front absorber (LH)	1.00	0.00	0.00 BT ✓
142	Front absorber top mounting (LH)	1.00	0.00	0.00 NEC ✓
143	Front knuckle arm (LH)	1.00	0.00	0.00 BT ✓ BT ✓
144	Front knuckle bearing (LH)	1.00	0.00	0.00 JMV ✓
145	Front lower arm (LH)	1.00	0.00	0.00 BT ✓
146	Front absorber linkage (LH)	1.00	0.00	0.00 ?
147	Front wheel house panel (LH)	1.00	0.00	0.00 RX
148	Front wheel house panel (RH)	1.00	0.00	0.00 RX
149	Front cross member	1.00	0.00	0.00 ?
150	Steering rack	1.00	0.00	0.00 ?
151	Rack end set	1.00	0.00	0.00 ?
152	Tie rod end set	1.00	0.00	0.00 ?
153	Rear axle	1.00	0.00	0.00 ?
154	Rear absorber (LH)	1.00	0.00	0.00 ?
155	Rear absorber (RH)	1.00	0.00	0.00 ?

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
156	Rear wheel bearing (LH)	1.00	0.00	0.00
157	Rear wheel bearing (RH)	1.00	0.00	0.00
158	Wheel rim	4.00	0.00	0.00
159	Front ABS sensor	2.00	0.00	0.00
160	Fan relay box	1.00	0.00	0.00
161	Air cleaner resonator	1.00	0.00	0.00
162	Drive-shaft (LH)	1.00	0.00	0.00
163	Drive-shaft (RH)	1.00	0.00	0.00
164	Driver door harness wire set	1.00	0.00	0.00
165	Rear door harness wire set (RH)	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

166	Wiper garnish clip set	1.00	45.00	45.00
167	Front bumper clip set	1.00	50.00	50.00
168	Front number ^{plate} okate & casing	1.00	45.00	45.00
169	Front bumper undercover clip set	1.00	45.00	45.00
170	Bonnet insulator clip set	1.00	45.00	45.00
171	Support panel top garnish clip set	1.00	30.00	30.00
172	Front fender inner shield clip set (LH)	1.00	50.00	50.00
173	Front fender inner shield clip set (RH)	1.00	50.00	50.00
174	Rear fender inner shield clip set (LH)	1.00	50.00	50.00
175	Rear fender inner shield clip set (RH)	1.00	50.00	50.00
176	Front fender protector clip set (LH)	1.00	40.00	40.00
177	Front fender protector clip set (RH)	1.00	40.00	40.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
178	Rocker panel garnish clip set (LH)	1.00	50.00	50.00
179	Rocker panel garnish clip set (RH)	1.00	50.00	50.00
180	Rear fender protector clip set (LH)	1.00	45.00	45.00
181	Rear fender protector clip set (RH)	1.00	45.00	45.00
182	Driver door inner trim board clip set	1.00	50.00	50.00
183	Passenger door inner trim board clip set	1.00	50.00	50.00
184	Rear door inner trim board clip set (RH)	1.00	50.00	50.00
185	Door visor set	1.00	120.00	120.00 N/A
186	Engine coolant	1.00	120.00	120.00 60.00
187	Auto transmission fluid 2 Liter	1.00	220.00	220.00 80.00
188	215/60/16 Dunlop tyre	2 PCS 4.00	200.00	800.00 300.00
189	Tyre air valve	2 PCS 4.00	10.00	40.00 20.00
190	Horn set	1.00	160.00	160.00 ?
191	Front windscreen sealant	1.00	60.00	60.00 ✓
192	Front windscreen tinted	1.00	200.00	200.00 N/A
193	Front fender inner panel sealant (LH)	1.00	50.00	50.00 ✓
194	Front fender inner panel sealant (RH)	1.00	50.00	50.00 ✓
195	Front support panel sealant	1.00	50.00	50.00 ✓
196	Drive door sound speaker	1.00	800.00	800.00 ?
197	Passenger door sound speaker	1.00	800.00	800.00 ?
198	Rear door sound speaker (RH)	1.00	800.00	800.00 ?
199	Front windscreen inner seal	1.00	50.00	50.00 ✓

Amt S\$ 5,200.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 5,200.00

Section: Labour Items

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
200	To R&R rear bumper reverse sensor	1.00	60.00	60.00 ?
201	To conduct head lamp focus	1.00	100.00	100.00 50.00
202	To remove and refix wiring system and check for proper function	1.00	100.00	100.00 80.00
203	To supply undercoating / putty on parts replaced	1.00	120.00	120.00 60.00
204	To perform anti rust treatment on affected areas	1.00	80.00	80.00 60.00
205	To conduct alignment after repair	1.00	100.00	100.00 60.00
206	To R&R A/C condenser, radiator assy	1.00	280.00	280.00 150.00
207	To R&R driver door mechanism	1.00	250.00	250.00 150.00
208	To R&R passenger door mechanism	1.00	250.00	250.00
209	To R&R rear door mechanism (RH)	1.00	250.00	250.00
210	To R&R front windscreen	1.00	280.00	280.00 100.00
211	To R&R fuel tank, ^{to} yo cut and weld	1.00	350.00	350.00 200.00
212	To R&R front under-carriage damaged parts	1.00	400.00	400.00
213	To R&R rear under-carriage damaged parts	1.00	300.00	300.00
214	To R&R wheel rims, tyres and balancing	1.00	120.00	120.00 60.00
215	To reset anti lock brake system	1.00	160.00	160.00 ?
216	To reprogramming hybrid IMA system	1.00	900.00	900.00 600.00
217	To R&R interior, seats and garnishes	1.00	250.00	250.00 150.00
218	To R&R dashboard assy to cut and weld	1.00	500.00	500.00 250.00
219	To repair, replaced and realign damaged areas	1.00	2,500.00	2,500.00 1,800.00
220	To spray painting on affected areas	1.00	2,200.00	2,200.00 1,700.00
221	To perform water seepage test after repair	1.00	180.00	180.00 100.00
222	To car wash & polishing vehicle after repair	1.00	120.00	120.00 N/A
223	To top up 134a refrigerant	1.00	80.00	80.00 ✓
224	Sundries	1.00	50.00	50.00 N/A

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT3177G
Make & Model : HONDA, VEZEL HYBRID 1.5X A, RU31263483
Year of Manufacture : 2017

Estimation No. : E19010009
DOA : 09/01/2019

No	Description	Qty	U/P	Amt
				Amt S\$ 9,980.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 9,980.00

? photo

Torin line 11/1/19

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Days of repair 20

List Items Subtotal S\$ 0.00
Special Nett Items S\$ 5,200.00
Subtotal
Labour Items Subtotal S\$ 9,980.00
Total S\$ 15,180.00