



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFS8717S

Chhoi Feroze Adi

80 Bayshore Road
#17-27
Singapore 469992

Mobile: 97850609

Vehicle & Document Information

WIP No **30019**
Reg No/Reg Date **SFS8717S / 19/01/2015**
Date In/Mileage **/ 0**
Chassis No **WDD2050402R032010**
Engine No **27491030295067**
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**
Colour/Trim **027 775 Iridium sil/ 041 118 Alpaca grey**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	10/01/2019/ 18:12	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 13105180 // 10.01.19 DRIVE IN/EXCESS : 10.01.19 // TP CAR NO.: SFY829Z= <i>AXA</i> DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB DISASSEMBLE AND REPLACE ON FRONT BUMPER, RH FENDER				<i>960</i> 2400.00
A BPIRES RESPRAY ON FRONT BUMPER, RH FENDER				<i>1200</i> 1800.00
M FRONT BUMPER - <i>repair</i>	1.00	1536.50	00.00	1536.50

ESTIMATE

Rasul
Hp 90010068
4 days
13/02/19 @ 1540

Confirmed & accepted by

Nett **6,116.50**
7% GST on **6116.50** **428.16**
Total Payable 6,544.66

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg