

15/2/2011

INS. CASE OWNER:

CCY/LPC1900

LKK:

IDAC:

Surveyor:

Tantich.

DOI:

ASSIGNMENT

11/1/19

Date / Time:

11/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJK 716C

Name of Insured:

TIMOTHY FER FIEW PINH.

Insured Tel No.:

HP: 90924011

Excess Sec II :SS

D.O.A: 10/1/19

Is driver the owner?

(YES) / NO

Nature of Accident:

Claim No.:

15/11/19 1915/1024.

Policy No.:

7181518247

Make / Model:

TOYOTA

Place of Accident:

PUE DRY BRIDGE.

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) YES / NO

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

bm 1

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

2/1/19
24QA) VIP-R
SJK 716C - 11/1/19 1915/1024

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):
After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time: 15/10/19

Sent By: VIC

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: US

SS 4,750.00

(7 days)

Reduction: 56

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 03/02/2020

Confirm with:

NICOLE

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost: (w/loss)

SS 5,082.50

Loss of Rental (LOR):

SS

()

(days)

Loss of Use (LOU):

SS

480.00

(S x 8 days)

Loss of Income (LOI):

SS

(S x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/T Search

SS

36.45

Medical:

SS

-

Disbursement: TOWING

SS

60.00

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS 5,658.95

Global Sum SS:

5,650.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

5,650.00

Name 1:

EM-1 AUTO PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

1) Claim status: Norm/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 450.00

COPY SENT
11/1/2020



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19000691/T1jb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 11-01-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 216C	Veh. Inspected	GBJ 341P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/01/2019	Inspection Date	11/01/2019	
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBJ 341P
Vehicle Model : SUZUKI EVERY
Accident Date : 10.01.2019
Original Reg Date : 11.12.2018

Date : 10.01.2019

Chassis : DA17V261242

TP Ins. LONPAC

ESTIMATE

1	1 pc	Tailgate	✓			\$ 982.50
2	1 pc	Tailgate Badge	✓			\$ 65.20
3	1 pc	Tailgate Sticker EVERY	✓			\$ 62.00
4	1 pc	Tailgate Sticker "350kg"	✓			\$ 48.00
5	1 pc	Tailgate Windscreen Inner Seal	✓			\$ 60.00
6	1 pc	Tailgate Key Lock	✓			\$ 72.60
7	1 pc	Tailgate Outer Handle	✓			\$ 62.50
8	2 pcs	Tailgate Stopper	✓	② 22		\$ 44.00
9	1 pc	Tailgate Inner Trim Board	✓			\$ 182.00
10	1 pc	Tailgate Inner Handle Holder	✓			\$ 48.20
11	1 set	Tailgate Inner Trim Board Clips	✓			\$ 40.00
12	1 pc	Tailgate Inner Lock	✓			\$ 185.00
13	1 pc	Tailgate Auto Lock Actuator	✓			\$ 173.00
14	1 pc	Tailgate Lock Catch	✓			\$ 42.60
15	1 pc	Tailgate Weatherstrip	✓			\$ 169.20
16	2 pcs	Tailgate Hinges	✓	② 56		\$ 112.00
17	2 pcs	Tailgate Absorber	✓	② 183		\$ 366.00
18	1 pc	Rear Bumper	✓			\$ 795.50
19	2 pcs	Rear Bumper Side Retainers	✓	② 39		\$ 78.00
20	1 set	Rear Bumper Clips	✓			\$ 20.00
21	1 pc	Rear Bumper Number Plate Lamps	✓			\$ 28.00
22	2 pcs	Rear Bumper Lamps	✓	② 175.20		\$ 350.40
23	2 pcs	Rear Bumper Side Garnish Cover	✓	② 164.00		\$ 328.00
24	2 sets	Rear Bumper Side Garnish Cover Clips	✓	② 40.00		\$ 80.00
25	1 pc	End Panel (Outer)	✓			\$ 426.00
26	1 pc	End Panel (Inner)	✓			\$ 325.00
27	1 pc	Rear Floor Panel Top Insulator Cloth	✓			\$ 670.00
28	1 pc	Spare Tyre Carrier	✓	✓		\$ 187.50
29	1 pc	Spare Tyre Carrier Bolt	✓	✓		\$ 48.20
30	1 pc	Spare Tyre Carrier Nut	✓	✓		\$ 46.00

899.60

625

C/F

• To resurvey before/after spray painting
• To resurvey damaged part(s) during resurvey
• To spray and seal to confirmation
• Third party survey is on a "Without Prejudice" basis
• Third party survey is allowed

5643 (Name - any firm(s) must be resurveyed and
6 (H/P) 64575777 (P)

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GBJ 341P

1	1 pc	Rear Exhaust Silencer	?	✓	₹ 592.00
2	2 pcs	Rear Exhaust Mountings	?	④ 38 ✓	₹ 76.00
3	1 pc	Rear Exhaust Gasket	?	✓	₹ 46.00
4	1 pc	Rear Exhaust Heat Plate	2	✓	₹ 163.00

4,792.60.

Less 15%

5,773.71 -

4197.60
3567.96

Specials						
1	1 pc	Rear Number Plate with Cover	<i>out</i>	✓	45	45 70.00
2	1 pc	Tailgate Sticker 70km/h	<i>as is</i>	✓	15	15.00
3	1 set	Body Panel Joint Sealant	<i>no</i>	✓	40	40 120.00
4	1 pc	Rear Windscreen Sealant	<i>no</i>	✓	60	60.00

265

Panel Beating	900	900	1,500.00
Spray painting	900	900	1,500.00
Check Wiring	30	30	50.00
Anti rust	80	80	100.00
Remove and install rear winscreen.	120	120	140.00
Remove and install tailgate parts.	60	60	90.00
Remove and install carpet and seat.	60	60	120.00
Remove and install rear exhaust silencer.	80	80	120.00

2210.

10725.60%

Tanghul 9749549

3,420

9,658.71

U W
Lumpsum 11/1/19

3567.96

Reamy after epib

16e

54th E Wheaton, Wm

2210

tanja @ lila and a man

5937.96

7-8 days

45 | 4750

Confirm 154750, 7 days

7 days

from e-mpi

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBJ 341P
Vehicle Model : SUZUKI EVERY
Accident Date : 10.01.2019
Original Reg Date : 11.12.2018

Date : 10.01.2019
Chassis : DA17V261242
TP Ins. **LONPAC**

ESTIMATE

1	1 pc	Tailgate	vt		
2	1 pc	Tailgate Badge	un		
3	1 pc	Tailgate Sticker EVERY	ul		
4	1 pc	Tailgate Sticker "350kg"	ul		
5	1 pc	Tailgate Windscreen Inner Seal	ul		
6	1 pc	Tailgate Key Lock	x		
7	1 pc	Tailgate Outer Handle	at		
8	2 pcs	Tailgate Stopper	n		
9	1 pc	Tailgate Inner Trim Board	de		
10	1 pc	Tailgate Inner Handle Holder	x		
11	1 set	Tailgate Inner Trim Board Clips	ul		
12	1 pc	Tailgate Inner Lock	bt		
13	1 pc	Tailgate Auto Lock Actuator	x		
14	1 pc	Tailgate Lock Catch	Rx		
15	1 pc	Tailgate Weatherstrip	ul		
16	2 pcs	Tailgate Hinges	Rx		
17	2 pcs	Tailgate Absorber	Rx		
18	1 pc	Rear Bumper	de		
19	2 pcs	Rear Bumper Side Retainers	un		
20	1 set	Rear Bumper Clips	ul		
21	1 pc	Rear Bumper Number Plate Lamps			
22	2 pcs	Rear Bumper Lamps	LH-CR, RH-X		
23	2 pcs	Rear Bumper Side Garnish Cover	x LH-de, RH-X		
24	2 sets	Rear Bumper Side Garnish Cover Clips	x LH-ret, RH-X		
25	1 pc	End Panel (Outer)	bt		
26	1 pc	End Panel (Inner)	ul		
27	1 pc	Rear Floor Panel Top Insulator Cloth	x		
28	1 pc	Spare Tyre Carrier	Rx ?		
29	1 pc	Spare Tyre Carrier Bolt	Rx Rx ?		
30	1 pc	Spare Tyre Carrier Nut	Rx ?		

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GBJ 341P

B/F

1	1 pc	Rear Exhaust Silencer	?		
2	2 pcs	Rear Exhaust Mountings	?		
3	1 pc	Rear Exhaust Gasket	?		
4	1 pc	Rear Exhaust Heat Plate	X		

Less 15%

Special Nett

1	1 pc	Rear Number Plate with Cover	cut	45	70.00
2	1 pc	Tailgate Sticker 70km/h	as is		15.00
3	1 set	Body Panel Joint Sealant	new	40	120.00
4	1 pc	Rear Windscreen Sealant	new		60.00

Labour charge

Panel Beating		900	1,500.00
Spray painting		900	1,500.00
Check Wiring		30	50.00
Anti rust		80	100.00
Remove and install rear winscreen.		120	140.00
Remove and install tailgate parts.		60	90.00
Remove and install carpet and seat.		60	120.00
Remove and install rear exhaust silencer.		80	120.00

Tan Jie 97495449
- Mr
Lumpsum
Repay after repair
see @ lkhauto.com
tanjie @ lkhauto.com
7-8 days

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2524K
Vehicle Details	
Vehicle No.:	GBJ341P
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jan 2019
Vehicle Make:	SUZUKI
Vehicle Model:	EVERY VAN PC AUTO
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	R06A2145667
Chassis No.:	DA17V261242
Maximum Power Output:	-
Open Market Value:	\$14,062.00
Original Registration Date:	11 Dec 2018
First Registration Date:	11 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$704.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Dec 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,009.00
COE Rebate Amount:	\$26,774.00
Total Rebate Amount:	\$26,774.00

The information contained herein is correct as at 10 Jan 2019

OK



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/19/19/VP05/021314
Our ref: CC4/LPC19000691/T1hb3

Date: 15.10.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBJ 341P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11.01.2019 at the premises of M/s EM-1 AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	9,658.71
Revised Estimate Amount	: S\$	5,946.96
"Check" Items Amount	: S\$	-
Market Value	: S\$	48,000.00
LTA Reimbursement Value	: S\$	26,774.00
Nett Value	: S\$	21,226.00

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser


Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 10 January, 2019 5:16 PM
To: em1autopteltd@gmail.com; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: MT_Claim_SG TP
Subject: RE: Your Ref: GBJ341P Our Ref: 18/19/19/VP05/021314
Attachments: 10012019171307.pdf

Dear Catherine/Nivitha

Please refer to the attached and arrange Mohd Taufikh to conduct TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



10012019 @ 5:18pm
Mr. Chia veh in

From: ONG LI LI
Sent: Thursday, 10 January, 2019 4:44 PM
To: 'em1autopteltd@gmail.com'; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: MT_Claim_SG
Subject: Your Ref: GBJ341P Our Ref: TBA

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	

8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706




Shu Pei (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 16 January 2019 10:44 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: RE: Your Ref: GBJ341P Our Ref: 18/19/19/VP05/021314
Attachments: SJN216C 100119.pdf

Dear Shu Pei

Attached is our Insured's GIA report for your handling.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 15 January, 2019 6:36 PM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: RE: Your Ref: GBJ341P Our Ref: 18/19/19/VP05/021314

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GBJ 341P at M/s Em-1 Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:
- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,
Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 10 January 2019 5:18 PM

To: 'ONG LI LI' <long@lonpac.com>; Admin A <admin-a@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>

Subject: RE: Your Ref: GBJ341P Our Ref: 18/19/19/VP05/021314

Dear Li Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:long@lonpac.com>]

Sent: Thursday, 10 January, 2019 5:16 PM

To: em1autopteltd@gmail.com; assignments@lkkauto.com; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: Your Ref: GBJ341P Our Ref: 18/19/19/VP05/021314

Dear Catherine/Nivitha

Please refer to the attached and arrange Mohd Taufikh to conduct TP survey.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: ONG LI LI

Sent: Thursday, 10 January, 2019 4:44 PM

To: 'em1autopteltd@gmail.com'; assignments@lkkauto.com; 'Admin-D (LKKAuto)'

Cc: MT_Claim_SG

Subject: Your Ref: GBJ341P Our Ref: TBA

Without Prejudice

Save as to Costs


Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ☐
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
 Ong Li Li
 Senior Claims Executive | Lonpac Insurance Bhd
 300 Beach Road #17-04/07 The Concourse Singapore 199555
 Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19000691/T1ha3s2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 13-02-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 216C	Veh. Inspected	GBJ 341P	
Policy No.	Z18VP05018297	Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/021314	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	11/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	SUZUKI EVERY	c.c	658	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	DA17V261242	Colour	SILVER	
Odometer	1999	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	145/80 R12	YOKOHAMA	6 mm	
L/H Front Tyre	145/80 R12	YOKOHAMA	6 mm	
R/H Rear Tyre	145/80 R12	YOKOHAMA	6 mm	
L/H Rear Tyre	145/80 R12	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/01/2019	Inspection Date	11/01/2019	
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 341P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	BENT	982.50	899.60
1	TAILGATE BADGE	NECESSARY	65.20	65.20
1	TAILGATE STICKER EVERY	NECESSARY	62.00	62.00
1	TAILGATE STICKER "350KG"	NECESSARY	48.00	48.00
1	TAILGATE WINDSCREEN INNER SEAL	NECESSARY	60.00	60.00
1	TAILGATE KEY LOCK	NOT NECESSARY	72.60	-
1	TAILGATE OUTER HANDLE	CUT	62.50	62.50
2	TAILGATE STOPPER @ \$22.00	NOT NECESSARY	44.00	-
1	TAILGATE INNER TRIM BOARD	DEFORMED	192.00	192.00
1	TAILGATE INNER HANDLE HOLDER	NOT NECESSARY	48.20	-
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	40.00	40.00
1	TAILGATE INNER LOCK	BENT	185.00	185.00
1	TAILGATE AUTO LOCK ACTUATOR	NOT NECESSARY	173.00	-
1	TAILGATE LOCK CATCH	TO REPAIR SEE LABOUR	42.60	-
1	TAILGATE WEATHERSTRIP	CUT	169.20	169.20
2	TAILGATE HINGES @ \$56.00	TO REPAIR SEE LABOUR	112.00	-
2	TAILGATE ABSORBER @ \$183.00	TO REPAIR SEE LABOUR	366.00	-
1	REAR BUMPER	DEFORMED	795.50	625.00
2	REAR BUMPER SIDE RETAINERS @ \$39.00	NECESSARY	78.00	78.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER NUMBER PLATE LAMPS	NOT NECESSARY	58.00	-
2	REAR BUMPER LAMPS @ \$175.20	N/S CRACKED / O/S NOT NECESSARY	350.40	175.20
2	REAR BUMPER SIDE GARNISH COVER @ \$82.00	N/S DEFOORMED / O/S NOT NECESSARY	164.00	82.00
2	SETS REAR BUMPER SIDE GARNISH COVER CLIPS @ \$20.00	N/S NECESSARY / O/S NOT NECESSARY	40.00	20.00
1	END PANEL (OUTER)	BENT	426.00	426.00

Report Ref No. CC4/LPC19000691/T1ha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL (INNER)	TO REPAIR SEE LABOUR	325.00	-
1	REAR FLOOR PANEL TOP INSULATOR COLTH	NOT NECESSARY	670.00	-
1	SPARE TYRE CARRIER	BENT	187.50	187.50
1	SPARE TYRE CARRIER BOLT	BENT	48.20	48.20
1	SPARE TYRE CARRIER NUT	BENT	46.00	46.00
1	REAR EXHAUST SILENCER	BENT	592.00	592.00
2	REAR EXHAUST MOUNTINGS @ \$38.00	BENT 1PC ONLY	76.00	38.00
1	REAR EXHAUST GASKET	NECESSARY	46.20	46.20
1	REAR EXHAUST HEAT PLATE	NOT NECESSARY	163.00	-
	LESS 15% DISCOUNT		-	-629.64
			6,840.60	3,567.96
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE WITH COVER (SN)	CUT	70.00	45.00
1	TAILGATE STICKER 70KM/H (SN)	NECESSARY	15.00	15.00
1	SET BODY PANEL JOINT SEALANT (SN)	NECESSARY	120.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
			265.00	160.00
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILGATE LOCK CATCH, TAILGATE HINGES, TAILGATE ABSORBER AND END PANEL (INNER).		1,500.00	900.00
	SPRAY PAINTING.		1,500.00	900.00
	CHECK WIRING.		50.00	30.00
	ANTI RUST.		100.00	60.00
	REMOVE AND INSTALL REAR WINDSCREEN.		140.00	120.00
	REMOVE AND INSTALL TAILGATE PARTS.		90.00	60.00
	REMOVE AND INSTALL CARPET AND SEAT.		120.00	60.00
	REMOVE AND INSTALL REAR EXHAUST SILENCER.		120.00	80.00
			3,620.00	2,210.00
	GRAND TOTAL		10,725.60	5,937.96
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,750.00

Report Ref No. CC4/LPC19000691/T1ha3s2



Report Ref No. CC4/LPC19000691/T1ha3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.